HONDA CIVIC WORKSHOP SERVICE & REPAIR MANUAL
Model: Honda Civic 1.5L Turbo / 2.0L
Model Year: 2022
Document Type: Workshop Manual
Source: American Honda Motor Technical Information

SECTION 1: GENERAL MAINTENANCE & FLUID SPECIFICATIONS

Engine Oil Capacity: 3.5 Liters with filter replacement.
Recommended Viscosity: Genuine Honda 0W-20 Full Synthetic Motor Oil.
Coolant Specification: Honda Long Life Antifreeze / Coolant Type 2 (pre-mixed 50/50).
Brake Fluid: Genuine Honda Heavy Duty Brake Fluid DOT 3.

SECTION 2: COOLING SYSTEM DIAGNOSIS & BLEEDING

Engine Overheating Troubleshooting:

1. Check coolant reserve tank level when cold. If below MIN line, inspect for leaks.
2. If temperature gauge needle reaches H (Hot), turn off A/C and safely stop engine.
3. Radiator Fan Operation: Ensure both radiator fan and condenser fan activate when engine coolant temperature reaches 199 deg F (93 deg C).
4. Bleeding Air from Cooling System: Fill reserve tank to MAX. Loosen bleed bolt if equipped until coolant flows without air bubbles, then tighten to 7.2 lb-ft (10 N-m).

SECTION 3: STARTING SYSTEM & 12V BATTERY TESTING

Starting Symptom: Clicking Noise / No Engine Crank
- If starter solenoid clicks rapidly, 12V battery terminal voltage is below 10.0V.
- Clean corroded battery posts with sodium bicarbonate solution and wire brush.
- Parasitic Draw Inspection: Standard quiescent current must be under 35mA after security system arms and BCM enters sleep mode (allow 20 minutes).
- Starter Relay Check: Swap starter cut relay with horn relay in engine under-hood box.

SECTION 4: BRAKE SYSTEM WEAR LIMITS & INSPECTION

Brake Pad Thickness Specification:
- Front Brake Pad Standard Thickness: 9.5 mm to 10.5 mm.
- Service Wear Limit: 1.6 mm (replace pads immediately if below 2.0 mm).
- Brake Rotor Thickness Standard: 25.0 mm. Minimum Refinish Limit: 23.0 mm.
- Brake Squeak / Squeal Cause: Wear indicators contact rotor when pad thickness drops below 2.5 mm. Replace front pad set and lubricate caliper sliding pins.