

Ship/HULL NO.	Ship/HULL NAME	JON:	ICN: 38NBA10019	Rev: -	Key Op: A01
LCU-1651	NBU-7				

TITLE:

Mounting Stud for Pushbutton; replace

JOB SPECIFICATION

Anticipated Award Date: <u>12/04/2025</u> 5/01/2026		Production Completion Date: <u>10/21/2026</u> 8/29/2026		PREPARING ACTIVITY: SASEBO	
POP Start Date: <u>2/01/2026</u> 6/01/2026		POP End Date: <u>7/15/2027</u> 9/30/2026			
PREPARED BY: S.OOHIRA			4/9/2026 Avelino L. Reyes Jr.	CODE E 00	DATE 8/21/2025
APPROVED BY: S.MURAKAMI			<i>[Signature]</i>	CODE S225	
CONCURRED BY: A.OKA			<i>[Signature]</i>	CODE S233	
ASSIST PLANNER'S NAME:				CODE	
ASSIST PLANNER'S NAME:				CODE	
ASSIST PLANNER'S NAME:				CODE	
DESCRIPTION:					
JSN(S): CU51-1980		CASREP#			
S/F CONTACT: ORTEGA EN2 / KHULLAR GSCS		CWP #		CCNS #	
Approved by S300/S900		A. REYES PM, 5310 <i>[Signature]</i>		6C2 4/9/2026 AVL: 6B1 Avelino L. Reyes Jr.	Date: <u>9/29/29</u>
				LWC:	
Work Completed					
S/Force:		Rate:		Date:	
Ship Supt:		Date:		SRF CONTROL NO.: 1301357121	
WORK CERTIFICATION SIGNATURES					
COMPLETION OF WORK REVIEW:		BADGE NO.:	SHOP/CODE:	PHONE:	DATE:

Ship/HULL NO.	Ship/HULL NAME	JON:	ICN:	Rev:	Key Op:
LCU-1651	NBU-7		38NBA10019	-	A01

TITLE:

Mounting Stud for Pushbutton; replace

1. SCOPE:

1.1 Title: Mounting Stud for Pushbutton; replace

1.2 Location of Work:

1.2.1 Vehicle Deck

1.3 Identification:

1.3.1 Quantity (4 EA), Stud, Welding, 1/4-20UNC-2A, 1-1/2 inches length, Steel for Pushbutton, SYM 789, Machine Gun Station FWD STBD and Bow Ramp STBD Operating Station, Located in 1.2.1

2. REFERENCES:

2.1 Standard Items (FY26)

2.2 400-5104315 Rev A, Interior Communication System

3. REQUIREMENTS:

3.1 Remove each existing and install each new stud listed in 1.3.1, using 2.2 for guidance.

3.1.1 Chip and grind surfaces flush and smooth in way of removals.

3.1.2 Install each new welding stud listed in 1.3.1.

3.1.2.1 Accomplish the requirements of 009-12 of 2.1, including Table 4, Column A, Lines One through 7 for welding.

3.2 Accomplish the requirements of 009-32 of 2.1 for new and disturbed surfaces.

(V) (G) "VISUAL INSPECTION"

3.3 Accomplish a visual inspection of each newly installed welding stud listed in 1.3.1 including surface cleanliness. -S130

4. NOTES:

4.1 Initial Condition - While conducting an inspection of the alarm boxes onboard LCU 1651 it was observed that various alarm boxes on the vehicle deck around frame 16 are missing the studs and require replacement.

5. GOVERNMENT FURNISHED MATERIAL (GFM):

5.1 Government Furnished Materials.

Ship/HULL NO.	Ship/HULL NAME	JON:	ICN:	Rev:	Key Op:
LCU-1651	NBU-7		38NBA10019	-	A01

TITLE:

Mounting Stud for Pushbutton; replace

MATERIAL LIST									
ITE M NO.	PC NO.	REF NO.	M / C	DESCRIPTION	STOCK NUMBER	HAZ MAT	DOC NO.	QTY REQD/ UNIT	PARA NO.
001	-	-	M	STUD,WELDING, M24149/1-505 STEEL	9B 5307 016868498	N	5227B034	6/EA	3.1
002	-	-	C	STUD,WELDING, M24149/1-521 STEEL	9B 5307 012931808	N	5227B035	6/EA	-

u
u