CHAPTER

56

WINDOWS





CHAPTER 56 WINDOWS

| Subject/Page | Date | COC | Subject/Page | Date | COC | Subject/Page | Date | COC |
|--------------|-------------|-----|--------------|------|-----|--------------|------|-----|
| 56-EFFECTIVE | PAGES | | | | | | | |
| 1 | JUN 15/2016 | | | | | | | |
| 2 | BLANK | | | | | | | |
| 56-010-00-01 | SYS | | | | | | | |
| 1 | Jun 15/2015 | | | | | | | |
| 2 | Feb 15/2015 | | | | | | | |
| 3 | Feb 15/2015 | | | | | | | |
| 4 | Feb 15/2015 | | | | | | | |
| 56-030-00-01 | SYS | | | | | | | |
| 1 | Jun 15/2015 | | | | | | | |
| 2 | Feb 15/2015 | | | | | | | |
| 3 | Feb 15/2015 | | | | | | | |
| 4 | Feb 15/2015 | | | | | | | |
| 56-050-00-01 | SYS | | | | | | | |
| 1 | Jun 15/2015 | | | | | | | |
| 2 | Feb 15/2015 | | | | | | | |
| 3 | Oct 15/2015 | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |

 $A = Added, \ R = Revised, \ D = Deleted, \ O = Overflow, \ C = Customer \ Originated \ Change$

56-EFFECTIVE PAGES





| AIRLINI | AIRLINE CARD NO | | TITLE CONTROL CABIN SLIDING WINDOWS | | | BOEING CARD NO. 56-010-00-01 | | |
|-------------|----------------------|-------------|-------------------------------------|-------------|-------------------------------|---------------------------------|--|--|
| DATE | TASK LUBRICATE | | | | RELATED C | ARD | | |
| TAIL NUMBER | WORK AREA CREW CABIN | VERSION 1.1 | THRESHOLD 2 YR | REPEAT 2 YR | APPLICABILITY AIRPLANE ENGINE | | | |
| STATION | SKILL AIRPL | | | | 600 700 800 900 | ALL | | |
| | | ACCESS | | | ZONE 211 212 | | | |
| | | | | | | | | |

Lubricate the inside release mechanisms for the pilots and co-pilots #2 sliding windows. Lubricate the outside release mechanism for the co-pilots #2 sliding window.

A. References

| Reference | Title |
|----------------------|---|
| AMM 25-11-21-000-801 | Flight Compartment Forward Ceiling Panel Removal (P/B 201) |
| AMM 25-11-21-400-801 | Flight Compartment Forward Ceiling Panel Installation (P/B 201) |

B. Consumable Materials

| Reference | Description | Specification |
|-----------|--|---------------------------|
| D00091 | Oil - General Purpose, Low Temperature, Lubricating | MIL-PRF-7870 (NATO O-142) |
| D00113 | Lubricant - Solid Film, Liquid Dispersed | BMS3-8 |

| EFFECTIVITY AKS ALL | SOURCE MRB | CONTROL CABIN SLIDING WINDOWS | |
|---------------------|------------|-------------------------------|----------------------------|
| | | D633A109-AKS 56-010-00-01 | Page 1 of 4 Jun 15/2015 |



737-600/700/800/900 TASK CARDS

| DATE | TAIL NUMBER | STATION | AIRLINE CARD NO. | BOEING CARD NO. |
|------|-------------|---------|------------------|-----------------|
| | | | | 56-010-00-01 |

TASK 12-25-81-600-801

MECH INSP

1. No. 2 Sliding Window Lubrication

(Figure 1)

A. Prepare for No. 2 Sliding Window Lubrication

SUBTASK 12-25-81-020-001

(1) Remove the window lining, do this task: Flight Compartment Forward Ceiling Panel Removal, AMM TASK 25-11-21-000-801.

B. Procedure

(Table 1)

SUBTASK 12-25-81-640-001

(1) Lubricate the parts of the window in (Figure 1) with oil, D00091 or solid film lubricant, D00113, where noted:

Table 1 No. 2 Sliding Window Lubrication

| Item No. | Nomenclature | Lubricant | Method of Application | Number of Locations |
|----------|--|--|--------------------------|------------------------|
| 1 | Upper Bellcrank and Glide | oil, D00091 | Oil Can | 2 |
| 2 | Upper Track Inside Surface (entire length) | oil, D00091 or solid film lubricant, D00113 | Oil Can | 1 |
| 3 | Latch Mechanism Rod | oil, D00091 | Paint Brush | 1 |
| 4 | Lower Bellcrank Rod End, Guide Roller and Shaft | oil, D00091 | Oil Can | 3 |
| 5 | Window Open Latch | oil, D00091 | Oil Can | 2 |
| 6 | Handle Pivot Area | oil, D00091 | Oil Can | 2 |
| 7 | Window Release Guide Roller | oil, D00091 | Paint Brush | 1 |
| 8 | Trigger Hinge Pin | oil, D00091 | Oil Can | 1 |
| 9 | Guide Pin Track | oil, D00091 | Paint Brush | 1 |
| 10 | Lower Forward and Bellcrank Rod End | oil, D00091 | Paint Brush | 1 |
| 11 | Cam Shaft | oil, D00091 | Oil Can | 2 |
| 12 | External Release Handle Linkage | oil, D00091 | Oil Can | 4 |
| 13 | Lower Track Inside Surface (entire length) | oil, D00091 or solid film lubricant, D00113 | Oil Can | 1 |

C. Put the airplane back its usual condition.


SUBTASK 12-25-81-840-001

(1) Install the window lining, do this task: Flight Compartment Forward Ceiling Panel Installation, AMM TASK 25-11-21-400-801.


| END | OE: | TASK | |
|-----|-----|------|--|
| | UF | IASN | |

| EFFECTIVITY AKS ALL | SOURCE MRB | CONTROL CABIN SLIDING WINDOWS | |
|------------------------|---------------|-------------------------------|----------------------------|
| | | D633A109-AKS 56-010-00-01 | Page 2 of 4 Feb 15/2015 |













| AIRLIN | E CARD NO | TITLE CONTROL CABIN SLIDING WINDOWS | | | | BOEING CARD NO. 56-030-00-01 | | |
|-------------|-----------------------|-------------------------------------|----------------|-------------|------------------------|--|--|--|
| DATE | TASK OPERATIONAL | | | | RELATED C | ARD | | |
| TAIL NUMBER | WORK AREA CREW CABIN | VERSION 1.1 | THRESHOLD 4 YR | REPEAT 4 YR | APPLICABII AIRPLANE | LITY | | |
| STATION | SKILL AIRPL | | | | 600 700 800 900 | ALL | | |
| | | ACCESS | | | ZONE 211 212 | | | |
| | | | | | | | | |

Operationally check the inside release mechanisms for the pilots and co-pilots #2 sliding windows. Operationally check the co-pilots #2 sliding window from the outside.

A. References Reference Title AMM 56-12-11-300-803 Replace the No. 2 Window Handle Trigger Return Spring (P/B 201)

| EFFECTIVITY AKS ALL | SOURCE MRB | CONTROL CABIN SLIDING WINDOWS | |
|---------------------|---------------|-------------------------------|----------------------------|
| | | D633A109-AKS 56-030-00-01 | Page 1 of 4 Jun 15/2015 |



737-600/700/800/900 TASK CARDS


| | | | | | TAS | K CARDS | | | | | |
|---------------|--|--|------------------|----------------------------------|---------------|-------------------|---------------------------|--------------|------|------|--|
| [| DATE | | Т | TAIL NUMBER | | STATION | AIRLINE CARD NO. | BOEING C/ | | | |
| TAS | K 56- | 12-11 | -710-803 | | | | | | MECH | INSP | |
| 1. <u>No.</u> | 2 Ope | enabl | e Window | / Operationa | al Check | | | | | | |
| A. | Prep | Prepare for the No. 2 window operational check. | | | | | | | | | |
| | | | 2-11-710-012 | | | | | | | | |
| | WAF | WARNING: DO NOT TOUCH THE WINDOW UNLESS THE CIRCUIT BREAKERS ARE OPEN, AND THE WINDOW HEAT SWITCHES ARE OFF. ELECTRICAL SHOCK CAN CAUSE INJURIES TO PERSONNEL. | | | | | | | | | |
| | (1) | | | vitches on the RATE tags: | e pilot's ove | rhead panel to | the OFF position and a | ttach | | | |
| | | (a) | WINDOV | V HEAT L SI | DE | | | | | | |
| | | (b) | WINDOV | V HEAT R SI | DE | | | | | | |
| | | | 2-11-710-013 | rcuit breakers | and install | aafatu taga: | | | | | |
| | (2) | • | | System Pai | | salety tags. | | | | | |
| | | Rov | | Number | Name | | | | | | |
| | | В | 8 | C00393 | WINDOW | HEAT POWER | R RIGHT SIDE | | | | |
| | | F/O | Electrical | System Pai | nel. P6-12 | | | | | | |
| | | Rov | | | <u>Name</u> | | | | | | |
| | | В | 9 | C00392 | WINDOW | HEAT POWER | R LEFT SIDE | | | | |
| В. | Prod | cedur | е | | | | | | | | |
| | | | 2-11-710-010 | Ale e de el e | 4: | | | | | | |
| | (1) | Do а (а) | | the window o | | ke and that th | e handle turns freely wh | en vou null | | | |
| | | (a) | the trigge | | ndow dilloc | ns, and that th | e nandle turns freely wir | eri you puii | | | |
| | | (b) | Make sui | re that the wi | ndow move | s freely on the | tracks. | | | | |
| | | (c) | Make sui | re that the wi | ndow open | lock holds the | window open. | | | | |
| | | (d) | | | | | m the open position. | | | | |
| | | (e) | | re that the wi released. | ndow locks | shut when the | handle is fully forward a | and the | | | |
| | | (f) | | re that the loo of the (Figur | • | e handle fully e | engages the lockplate as | shown in | | | |
| | NOTE: Window is in the closed/locked position. Lower surface of the lock pin to be flush to lower surface of lockplate within +0.020 in. (0.508 mm)/-0.000 in. (0.000 mm). If window handle operation is not effected, then the clearance can greater than 0.020 in. (0.5080 mm) | | | | | | | | | | |
| | | | | ou can adjus he stiffener lo | | • | through the lockplate by | adjusting | | | |
| | | (g) | Make sui | re that the tri | gger returns | s fully when it i | s released. | | | | |
| | | | CTIVITY S ALL | | SOURCE MRB | CONTROL CA | BIN SLIDING WINDOWS | | | | |

D633A109-AKS 56-030-00-01 Page 2 of 4 Feb 15/2015



| DATE | | 1 | TAIL NUMBER | | STATION | AIRLINE CARD NO. | BOEING CARD NO. 56-030-00-01 | | | |
|------|---|--------------|--|-----------------------------------|--------------|-------------------|--|-------------|--------|------|
| | | | | ie trigger does SK 56-12-11-30 | | fully, replace th | ne trigger return spring | (AMM | MECH | INS |
| | SUBTA | SK 56-12 | 2-11-710-011 | | , . | | | | | |
| | (2) | | | the emergency | y exit relea | se mechanism | | | | |
| | (a) Make sure that the window unlocks and opens when the external release handle is pulled. | | | | | | | | | |
| | | (b) | Make sure that the external release handle is aligned with the skin when the handle is in the flight position. | | | | | | | |
| C. | Put the Airplane Back to its Usual Condition. | | | | | | | | | |
| | SUBTASK 56-12-11-860-010 | | | | | | | | | |
| | (1) | Rem | ove the sa | afety tags and | close thes | e circuit breake | ers: | | | |
| | | F/O | Electrical | System Pane | el, P6-11 | | | | | |
| | | Rov | <u>v Col</u> | Number N | <u>Name</u> | | | | | |
| | | В | 8 | C00393 V | WINDOW | HEAT POWER | RIGHT SIDE | | | |
| | | E/O | Electrical | System Pane | J D6-12 | | | | | |
| | | Rov | | - | Name | | | | | |
| | | <u>- 10-</u> | 9 | | | HEAT POWER | LEFT SIDE | | | |
| | SUBTA | SK 56-12 | 2-11-800-004 | | | | | | | |
| | (2) | | | O-NOT-OPER | ATE tags 1 | rom these swit | ches on the pilot's over | head panel: | | |
| | (2) Remove the DO-NOT-OPERATE tags from these switches on the pilot's overhead panel:(a) WINDOW HEAT L SIDE. | | | | | | | | | |
| | (a) WINDOW HEAT E SIDE. (b) WINDOW HEAT R SIDE. | | | | | | | | | |
| | | | | | | | | | | |
| | END OF TASK | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | l |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | CTIVITY S ALL | | SOURCE MRB | CONTROL CAE | BIN SLIDING WINDOWS | | | |
| | | | | | | CONTROL CAE | | | Page 3 | 3 of |









| AIRLINE | E CARD NO | CONTRO | TITLE L CABIN SLIDING V | BOEING CARD NO. 56-050-00-01 | | | |
|-------------|------------------------------|-------------|----------------------------|---------------------------------|-------------------------------------|---------------|--|
| DATE | TASK INSPECTION - GEN VISUAL | | | | RELATED C. | ARD | |
| TAIL NUMBER | WORK AREA CREW CABIN | VERSION 1.1 | THRESHOLD 4 YR | REPEAT 4 YR | | APPLICABILITY | |
| STATION | SKILL AIRPL | | | | AIRPLANE 600 700 800 900 NOTE | ALL | |
| | | ACCESS | | | ZONE 211 212 | | |
| | | | | | | | |

Perform a general visual inspection of the pilots and co-pilots #2 sliding window sill drain for obvious damage, clogging, condition, and security.

AIRPLANE NOTE: Applicable to airplanes line number 145 and on.

Applicable to airplanes line number 1 to 144 incorporating SB 737-56-1011.

SOURCE MRB CONTROL CABIN SLIDING WINDOWS

D633A109-AKS Page 1 of 3
56-050-00-01 Jun 15/2015




| | DATE | | | TAIL NUMBER | | STATION | AIRLINE CARD NO. | | BOEING CARD NO. 56-050-00-01 | | | |
|----|------------|---|---|------------------------|---------------|------------------------------|------------------------|--------------|--|------|--|--|
| | TAS | K 56- | 12-11 | -200-802 | ' | | | • | MECH | INSP | | |
| 1. | No. | 2 Op | enabl | e Window Sill Drain In | spection | | | | | | | |
| | (Figure 1) | | | | | | | | | | | |
| | A. | Perf | orm a | a general visual check | of the pile | ot's and co-pile | ot's no. 2 openable wi | ndow sill | | | | |
| | | drain for obvious damage, clogging, condition and security. SUBTASK 56-12-11-200-003 | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | (1) | Examine no. 2 openable window sill drain. (a) Examine no. 2 openable window sill drain for obvious damage, condition and | | | | | | | | | |
| | | | , , | security. | | | | | | | | |
| | | | (b) | Make sure the drain is | not blocke | ed and that wate | er has not accumulated | in the frame | | | | |
| | | | | ——— END OF TASK ——— | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | EFFE AK | CTIVITY S ALL | SOURCE MRB | CONTROL CAE | BIN SLIDING WINDOWS | | | | | |
| | | | 7111 | | IAII/D | | | | | | | |
| | | | | | | D633A109-AKS 56-050-00-01 | | | Page 2 eb 15/ | | | |

NOTE:




737-600/700/800/900 **TASK CARDS**

DATE TAIL NUMBER STATION AIRLINE CARD NO. BOEING CARD NO. 56-050-00-01



FLIGHT COMPARTMENT



No. 2 Openable Window Sill Drain Inspection Figure 1

EFFECTIVITY SOURCE **CONTROL CABIN SLIDING WINDOWS AKS ALL MRB** D633A109-AKS Page 3 of 3 Oct 15/2015 56-050-00-01