

CONDITION MONITORING INSPECTION REPORT #456

Section: Condition Monitoring Log

Inspection ID: INSP-456 | Asset Tag: P-101
Date: 15 August 2025 | Inspector: R. Jenkins (Reliability Lead)
Inspection Type: Routine Vibration Spectrum & Thermographic Survey
Observations: Abnormal vibration detected on pump drive-end bearing housing.
Measured Vibration Velocity: 6.8 mm/s RMS (exceeds warning threshold of 4.5 mm/s).
Spectral Peak: Prominent 1X and 2X shaft rotational speed harmonics.
Bearing Housing Temperature: 71°C (elevated above 60°C baseline).
Recommendation: Schedule lubrication oil sampling and check shaft alignment at next window.