

FAILURE INCIDENT & CORRECTIVE WORK ORDER #1189

Section: Incident Breakdown

Incident ID: INC-78 | Work Order Number: WO-1189 | Asset Tag: P-101
Failure Date: 22 February 2026 | Reported By: Unit 2 Lead Operator
Failure Mode: Drive-End Bearing Seizure and High Vibration Trip.
Root Cause: Chronic vibration elevation (previously noted in INSP-456) caused ball cage fatigue.
Impact: Unscheduled unit shutdown. Downtime: 18.5 hours.
Damage: Drive-end bearing inner race seized, minor scoring on pump shaft collar.
Corrective Action Taken: Emergency bearing replacement (SKF 6312), shaft polished, laser alignment verified (runout 0.02 mm), oil flushed with fresh ISO VG 46.