

Image Analysis Report

Generated: 2026-04-24 06:56:47Z | Source: corrosion.jpg | Report ID: 2c1a9ad8-f328-48d6-a789-5c269d1beef0

Executive Summary

The image exhibits severe corrosion characterized by heavy scaling and localized pitting, concentrated primarily along a horizontal seam or weld line. This level of degradation indicates significant metal loss and requires immediate NDT assessment to determine structural integrity.

Key Findings

#	Finding
1	Evidence of severe localized pitting and heavy iron oxide scale formation in the central region.
2	Preferential corrosion path along a horizontal linear feature, likely a weld bead or joint, suggesting potential weld decay.
3	Complete coating breakdown and widespread surface oxidation across the lower portion of the visible area.
4	Deep surface irregularities indicating substantial localized material loss.
5	Signs of 'rust blooming' or run-off below the primary corrosion sites.
6	Total remaining wall thickness cannot be determined from visual inspection alone.

Localized detections (VLM, approximate)

- Severe Pitting and Scaling (conf. 95%): x=0.340, y=0.120, w=0.350, h=0.700
- Linear Corrosion along Joint (conf. 88%): x=0.000, y=0.420, w=1.000, h=0.150

Recommendations

#	Recommendation
1	Perform immediate Ultrasonic Thickness (UT) gauging to determine the percentage of remaining wall thickness.
2	Execute mechanical cleaning (SSPC-SP3) followed by abrasive blast cleaning to Near-White Metal (SSPC-SP10) for thorough inspection.
3	Conduct Magnetic Particle Inspection (MPI) on the horizontal joint to check for surface-breaking cracks.
4	If wall loss exceeds engineering design margins, implement a structural reinforcement (e.g., composite wrap) or section replacement.
5	Re-apply a high-build epoxy coating system following verified surface preparation.
6	Establish a localized monitoring point for periodic UT measurement every 6-12 months.