NC

Technical Bulletin 6 Cyl. 1 Subject: Porsche Special Tool for Camshaft Timing 9551 - 9552 - 9553 - 9554 1505 9407

ATTENTION: Service Manager / Service Technician

Models Affected:

911 Carrera, Model Year 1995

Concern:

Due to tolerances in the hole pattern of the camshaft housing in isolated cases, a different procedure for adjusting the valve timing may be necessary.

General Information:

On page 15-25 in the Workshop Manual for the type 911 Carrera M.Y. 1995, the special tools 9551 and 9552 are shown with an elongated bore (6mm). This elongated bore is for centering the tool to the camshaft housing using special bolt 9554.

However, the special tools which were delivered had a 7mm diameter bore instead of the elongated bore and two 6mm bores.

Due to tolerances in the hole pattern of the camshaft housing, a different procedure for adjusting the valve timing may be necessary. A new adjustment description for the camshaft timing will be sent to you with the 5/94 Supplement of the Workshop Manual. Through this change an increased accuracy of the valve timing is being obtained.

Repair Information:

- Should the camshaft timing tools not fit with the two (2) special bolts (as outlined in the 5/94 Supplement of the Workshop Manual), only one special bolt and a standard M6 bolt should be used.
- 2. In extreme cases (where greater tolerance in the hole pattern is present), three standard M6 bolts should be used.
- Before special tools 9551 and 9552 are installed, the bolt holes should be checked for possible burrs. The special bolts must turn easily in the bolt holes.



