GREENBOTZ PLATFORM PVT LTD

Machine service report

Asset	Gbz-rx-1
Tag	G-Sensor-01
Location	Block - 01 / Ground floor
Model	Gbz-rx-1
Service date	30-07-2026
Type	Preventive
Vendor	In-house maintenance
Technician	R. Kumar
Shift	General, 09:30-12:10

Work done

- Stopped the machine and locked out before opening the guard.
- Cleaned the sensor mount and cable gland. Tightened the mounting bolts (were slightly loose).
- Checked coupling alignment with a straight edge. Shimmed the drive side by 0.2 mm.
- Greased both bearing housings (2 strokes each). No unusual noise after restart.
- Wiped the sensor face. Confirmed the cable is seated in the connector.

Parts replaced

None. Grease only (Mobilith SHC 100, about 30 g).

Readings (as measured on site)

Reading	Value	Unit
Vibration overall (before)	0.14	g
Vibration overall (after)	0.09	g
RPM at check	1450	rpm
Motor body temperature	46	C

Issues found

- Mounting bolts on the sensor bracket were loose.
- Slight coupling misalignment (drive side low).

Recommendations

- Re-check alignment and bolt torque in 90 days.
- If vibration overall goes above 0.10 g again, inspect the bearing and coupling before the next planned stop.

Next service due

30-10-2026

Cost

Nil (in-house). Grease from store.

Remarks

Machine was idle when we arrived. After tightening and alignment, vibration overall came down from 0.14 g to 0.09 g. Left the machine running and handed over to production. No breakdown.

Technician sign: R. Kumar
Date: 30-07-2026