METHOD STATEMENT

Beadmix — Iron-Free Spherical Glass Beads Blasting, Filler & Reflective

Project Name		**Document No.**	OMX-MS-BEADMIX
Main Contractor		**Revision**	01
Consultant		**Date of Issue**	Nov 2026
Product	Beadmix	**Status**	For Approval

1. Purpose

This method statement defines the procedure, sequence, resources, quality checks and safety measures for the supply and application of Beadmix on site. It ensures that the work is carried out safely, in line with the approved drawings and project specification, and achieves the performance stated in the O MIX Technical Data Sheet.

2. Scope of Work

This method statement covers the handling, use in blasting, recovery and use as drop-on reflective beads of Beadmix glass beads.

- Receipt and storage.
- Selection of grading.
- Use in blasting.
- Use as drop-on beads for road markings.
- Recovery, sieving and disposal.

3. Definitions

Term	Meaning
Glass bead blasting	Cleaning or finishing with spherical glass beads.
Drop-on beads	Beads applied onto wet road paint for reflectivity.
Grading	Particle size range of the beads.

4. Roles & Responsibilities

Role	Responsibility
Project Manager	Overall responsibility for planning, resources, approvals and coordination with the consultant and main contractor.
Site Engineer	Supervises the work daily; confirms substrate readiness, climate conditions, mixing, consumption and sequence; keeps daily records.

Role	Responsibility
QA/QC Inspector	Carries out inspections and tests at each stage, records results, raises inspection requests at hold points and signs the checklist.
HSE Officer	Conducts toolbox talks, checks PPE, ventilation, access and safe storage; stops work if unsafe conditions arise.
Foreman / Applicators	Carry out the work as per this method statement and report any deviation immediately.
Storekeeper	Receives, stores and issues materials in original packaging under the stated storage conditions; controls batch numbers.

5. Materials

Material	Description
Beadmix	Glass beads, 25 kg bags or 1 t big bags

5.1 Key product data

Property	Typical Value
Material	Soda-lime glass, iron-free
Shape	Spherical
Hardness	6 Mohs
Softening point	approx. 730 °C
Specific gravity	approx. 2.5
Bulk density	1.5 – 1.6 g/cm³
SiO_2	70 – 75 %
Na_2O	12 – 15 %

6. Tools & Equipment

- Blast cabinet or blasting unit
- Compressor
- Sieves
- Bead dispenser for road marking
- Thermo-hygrometer and surface thermometer (dew point check)
- Moisture meter
- Measuring buckets and scale
- Masking tape and protective sheeting
- Lighting and extension cables

6.1 Personal protective equipment

- Blasting hood / respirator
- Eye protection

- Gloves
- Ear protection

7. Storage & Handling

- Store dry, in closed bags, protected from moisture. Not hazardous for transport.
- Store on pallets, off the ground, in a dry, covered and ventilated area.
- Keep containers closed until use; use materials on a first-in, first-out basis.
- Store rolls and cartons flat, off the ground, protected from direct sunlight, heat, oil and mechanical damage.
- Handle with care to avoid damage to packaging; do not stack beyond the safe height.

8. Pre-Start Requirements

- Material submittal, this method statement and the inspection plan approved by the consultant.
- Work area handed over clean, free of other trades and with safe access.
- Adequate lighting, power supply and ventilation available.
- Climate conditions checked and recorded before work starts.
- A trial area prepared and approved where required by the project.
- Toolbox talk held with the work team covering this method statement and the safety measures.

9. Surface Preparation

1. Select the grading as per the required finish.
2. Check that blasting equipment and dust extraction are working.
3. Mask areas not to be blasted.
4. Run a trial on a sample part and approve the finish.

10. Preparation of Material

1. Check grading and batch on the bag label.
2. Keep beads dry; load into the blasting unit or dispenser.

11. Use

1. Blasting: adjust pressure and distance; blast evenly.
2. Road marking: apply drop-on beads into the wet paint immediately after application.
3. Inspect the finish or reflectivity.
4. Record grading, pressure and quantity used.

12. Recovery & Inspection

- Recover beads, sieve out fines and reuse.
- Dispose of spent fines as per local regulations.
- Clean the work area.

13. Quality Control & Inspection

Check	Stage	Acceptance Criteria	By
Material	On receipt	Correct grading, dry	Storekeeper
Finish	After blasting	Uniform silky-matt	QA/QC
Reflectivity	Road marking	As per specification	QA/QC

13.1 Inspection and test plan

Activity	Inspection / Test	Frequency	Record
Material receipt	Grading, dryness	Each delivery	Material inspection report
Trial	Finish approved	Each job	Trial record
Use	Pressure, finish / reflectivity	Daily	Daily report

14. Defects & Remedies

Defect	Likely Cause	Remedy
Uneven finish	Wrong pressure or distance	Adjust and re-blast
High breakage	Pressure too high	Reduce pressure
Low reflectivity	Late drop-on	Apply beads into wet paint immediately

15. Health, Safety & Environment

Hazard	Control Measures
Dust from blasting	Enclosed cabinet or respirator; extraction
Noise	Ear protection
Slips on spilled beads	Clean spills immediately
Compressed air	Inspected hoses and fittings

- Use blasting cabinets or approved respiratory protection during blasting.
- Wear eye protection.
- Spilled beads are slippery; clean immediately.
- Eyes: rinse with clean water; do not rub.
- Inhalation of dust: move to fresh air.

15.1 Waste & environment

- Collect empty containers and residues in designated bins.
- Do not discharge material or washings into drains or soil.
- Allow small quantities of leftover mixed material to cure before disposal; dispose of according to local regulations.

16. Cleaning

- Sweep or vacuum spilled beads immediately.

17. Limitations

- Keep beads dry.
- Any deviation from this method statement must be approved by the Site Engineer and the consultant.

Appendix A — Inspection Checklist

Inspection Item	Result	Remarks
Grading verified	☐ Yes ☐ No	
Equipment checked	☐ Yes ☐ No	
Trial approved	☐ Yes ☐ No	
Blasting / drop-on carried out	☐ Yes ☐ No	
Finish inspected	☐ Yes ☐ No	
Beads recovered and sieved	☐ Yes ☐ No	
Area cleaned	☐ Yes ☐ No	

Inspected by	Signature	Date