METHOD STATEMENT

Terra Flakes — Decorative Vinyl Flakes for Epoxy & PU Floors

Project Name		**Document No.**	OMX-MS-TERRAFLAKES
Main Contractor		**Revision**	01
Consultant		**Date of Issue**	Nov 2026
Product	Terra Flakes	**Status**	For Approval

1. Purpose

This method statement defines the procedure, sequence, resources, quality checks and safety measures for the supply and application of Terra Flakes on site. It ensures that the work is carried out safely, in line with the approved drawings and project specification, and achieves the performance stated in the O MIX Technical Data Sheet.

2. Scope of Work

This method statement covers the broadcasting of Terra Flakes into epoxy or polyurethane floor coatings and the preparation for the clear top coat in the Terra Flakes floor system.

- Checking the base coat readiness.
- Broadcasting the flakes to the specified coverage.
- Removal of loose flakes after curing.
- Preparation for the clear top coat.
- Inspection and handover.

3. Definitions

Term	Meaning
Broadcast	Throwing flakes evenly onto a wet coating.
Full broadcast	Broadcasting until the wet coat can take no more flakes (refusal).
Partial broadcast	Random distribution with the base colour visible.
Top coat	Clear coating sealing the flakes.

4. Roles & Responsibilities

Role	Responsibility
Project Manager	Overall responsibility for planning, resources, approvals and coordination with the consultant and main contractor.
Site Engineer	Supervises the work daily; confirms substrate readiness, climate conditions, mixing, consumption and sequence; keeps daily records.

Role	Responsibility
QA/QC Inspector	Carries out inspections and tests at each stage, records results, raises inspection requests at hold points and signs the checklist.
HSE Officer	Conducts toolbox talks, checks PPE, ventilation, access and safe storage; stops work if unsafe conditions arise.
Foreman / Applicators	Carry out the work as per this method statement and report any deviation immediately.
Storekeeper	Receives, stores and issues materials in original packaging under the stated storage conditions; controls batch numbers.

5. Materials

Material	Description
Terra Flakes	Vinyl flakes, 20 kg bags
Base coat	O-Mix SL or O MIX epoxy coating as specified
Clear top coat	As specified for the system

5.1 Key product data

Property	Typical Value
Material	Pigmented vinyl flakes
Density	1.4 – 1.6 g/cm³
Addition rate	10 – 40 % by weight of base coat
Colours	Standard blends; custom on request
Compatible systems	Epoxy and polyurethane floor coatings
Shelf life	24 months

6. Tools & Equipment

- Spiked shoes
- Flake blower or hand broadcast
- Scraper
- Industrial vacuum
- Thermo-hygrometer and surface thermometer (dew point check)
- Moisture meter
- Measuring buckets and scale
- Masking tape and protective sheeting
- Lighting and extension cables

6.1 Personal protective equipment

- Dust mask
- Gloves

- Goggles
- Spiked shoes

7. Storage & Handling

- 24 months in original, closed packaging. Store dry, away from heat and direct sunlight.
- Store on pallets, off the ground, in a dry, covered and ventilated area.
- Keep containers closed until use; use materials on a first-in, first-out basis.
- Store rolls and cartons flat, off the ground, protected from direct sunlight, heat, oil and mechanical damage.
- Handle with care to avoid damage to packaging; do not stack beyond the safe height.

8. Pre-Start Requirements

- Material submittal, this method statement and the inspection plan approved by the consultant.
- Work area handed over clean, free of other trades and with safe access.
- Adequate lighting, power supply and ventilation available.
- Climate conditions checked and recorded before work starts.
- A trial area prepared and approved where required by the project.
- Toolbox talk held with the work team covering this method statement and the safety measures.

9. Surface Preparation

1. Confirm the substrate, primer and base coat are applied as per their method statements.
2. Prepare flakes of one colour batch for each area.
3. Mark work bays to keep a wet edge.
4. Obtain QA/QC approval of the base coat before broadcasting.

10. Preparation of Material

1. Check the colour and batch of the flakes and record them.
2. Blend bags of the same colour batch in a clean container.

11. Broadcasting

1. Broadcast flakes into the wet base coat with an upward throw so they fall evenly.
2. Work bay by bay while the base coat is wet.
3. For full broadcast continue until refusal.
4. Record the quantity of flakes used per area.

12. Curing & Top Coat

- Allow the base coat to cure as per its datasheet.
- Scrape and vacuum loose flakes.
- Apply the clear top coat as specified.
- Protect the area from dust and traffic until the top coat has cured.

13. Quality Control & Inspection

Check	Stage	Acceptance Criteria	By
Base coat	Before broadcast	Wet, uniform thickness	Site Engineer
Coverage	During broadcast	As specified (partial / full)	QA/QC
Loose flakes	After curing	Removed completely	QA/QC
Finish	After top coat	Uniform, sealed	QA/QC + Consultant

13.1 Inspection and test plan

Activity	Inspection / Test	Frequency	Record
Material receipt	Colour, batch	Each delivery	Material inspection report
Base coat	Wet and uniform	Each bay	Daily report
Broadcast	Coverage uniformity	Each bay	Daily report
Final	Appearance after top coat	Each area	Handover checklist

14. Defects & Remedies

Defect	Likely Cause	Remedy
Uneven distribution	Throwing downward; base coat too dry	Broadcast upward into wet coat; work in bays
Loose flakes after top coat	Insufficient scraping / vacuuming	Sand, vacuum and recoat
Colour differences	Mixed batches	Use one batch per area

15. Health, Safety & Environment

Hazard	Control Measures
Fibres / dust irritation	Long sleeves, gloves, goggles, dust mask
Work at height	Approved access, harness where required
Manual handling of rolls	Correct lifting technique
Slips and trips	Housekeeping; barricades

- Wear a dust mask when blowing flakes.

- Avoid inhalation of fine particles.
- Follow the safety instructions of the base and top coats.
- Eyes: rinse with clean water.
- Inhalation: move to fresh air.

15.1 Waste & environment

- Collect empty containers and residues in designated bins.
- Do not discharge material or washings into drains or soil.
- Allow small quantities of leftover mixed material to cure before disposal; dispose of according to local regulations.

16. Cleaning

- Clean tools with a dry brush and vacuum.

17. Limitations

- Broadcast only into wet coatings.
- Follow the limits of the base and top coat datasheets.
- Any deviation from this method statement must be approved by the Site Engineer and the consultant.

Appendix A — Inspection Checklist

Inspection Item	Result	Remarks
Base coat approved	☐ Yes ☐ No	
Flakes of one batch	☐ Yes ☐ No	
Broadcast evenly	☐ Yes ☐ No	
Coverage as specified	☐ Yes ☐ No	
Loose flakes removed	☐ Yes ☐ No	
Top coat applied	☐ Yes ☐ No	
Final finish approved	☐ Yes ☐ No	

Inspected by	Signature	Date