METHOD STATEMENT

O-Prime ST — Surface-Tolerant Epoxy Primer for Steel, Light Metals & Concrete

Project Name		**Document No.**	OMX-MS-OPRIMEST
Main Contractor		**Revision**	01
Consultant		**Date of Issue**	Nov 2026
Product	O-Prime ST	**Status**	For Approval

1. Purpose

This method statement defines the procedure, sequence, resources, quality checks and safety measures for the supply and application of O-Prime ST on site. It ensures that the work is carried out safely, in line with the approved drawings and project specification, and achieves the performance stated in the O MIX Technical Data Sheet.

2. Scope of Work

This method statement covers surface preparation, mixing and application of O-Prime ST, a surface-tolerant epoxy primer, on structural steel, tanks, pipework, light metals and concrete, as the first coat of O MIX protective coating systems.

- Inspection and acceptance of the substrate and the work area.
- Surface preparation and repair of defects.
- Mixing and application of the material as described in this document.
- Curing, protection and handover of the completed area.
- Quality control, inspection and documentation of each stage.

3. Definitions

Term	Meaning
Pot life	Time the mixed material remains workable after Part A and Part B are combined.
Recoat interval	Minimum and maximum time between coats to achieve inter-coat adhesion.
WFT / DFT	Wet film thickness measured during application / dry film thickness after cure.
Dew point	Temperature at which moisture condenses; the substrate must be at least 3 °C above it.
Kit / set	Pre-weighed Part A and Part B supplied to be mixed completely.

4. Roles & Responsibilities

Role	Responsibility
Project Manager	Overall responsibility for planning, resources, approvals and coordination with the consultant and main contractor.

Role	Responsibility
Site Engineer	Supervises the work daily; confirms substrate readiness, climate conditions, mixing, consumption and sequence; keeps daily records.
QA/QC Inspector	Carries out inspections and tests at each stage, records results, raises inspection requests at hold points and signs the checklist.
HSE Officer	Conducts toolbox talks, checks PPE, ventilation, access and safe storage; stops work if unsafe conditions arise.
Foreman / Applicators	Carry out the work as per this method statement and report any deviation immediately.
Storekeeper	Receives, stores and issues materials in original packaging under the stated storage conditions; controls batch numbers.

5. Materials

Material	Description
O-Prime ST	Surface-tolerant epoxy primer, 20 kg and 5 kg sets (A + B), metal pails
Epoxy thinner	For spray thinning and cleaning of tools

5.1 Key product data

Property	Typical Value
Mixing ratio (A : B)	4 : 1 by weight
Finish	Semi-gloss
Colours	Grey, red, white
Solids content	85 %
Recommended DFT	100 – 1000 µm
Theoretical coverage	8.5 m²/L at 100 µm DFT
Pot life (25 °C)	2 hours
VOC	316 g/L

6. Tools & Equipment

- Wire brushes
- Power tools (grinder with wire wheel / sanding disc)
- Abrasive blasting unit where specified
- Slow-speed mixer
- Brushes
- Short-nap rollers
- Airless spray pump
- Wet-film comb
- DFT gauge
- Surface profile gauge

- Thermo-hygrometer and surface thermometer (dew point check)
- Moisture meter
- Wet-film thickness gauge
- Measuring buckets and scale
- Masking tape and protective sheeting
- Lighting and extension cables

6.1 Personal protective equipment

- Chemical-resistant gloves
- Safety goggles
- Overalls
- Respirator with organic vapour cartridges
- Safety shoes

7. Storage & Handling

- 12 months in original, unopened packaging. Store dry at +5 °C to +35 °C, away from direct sunlight, heat and ignition sources.
- Store on pallets, off the ground, in a dry, covered and ventilated area.
- Keep containers closed until use; use materials on a first-in, first-out basis.
- Keep Part A and Part B of each kit together and do not mix parts from different batches.
- Store away from heat, sparks and ignition sources.
- Handle with care to avoid damage to packaging; do not stack beyond the safe height.

8. Pre-Start Requirements

- Material submittal, this method statement and the inspection plan approved by the consultant.
- Work area handed over clean, free of other trades and with safe access.
- Adequate lighting, power supply and ventilation available.
- Climate conditions checked and recorded before work starts.
- A trial area prepared and approved where required by the project.
- Toolbox talk held with the work team covering this method statement and the safety measures.

9. Surface Preparation

1. Remove oil and grease by solvent cleaning before any mechanical preparation.
2. Steel: remove loose rust, mill scale and loose paint by hand or power tools to St 2 minimum; blast-clean to Sa 2½ where immersion or severe exposure is specified.
3. Feather the edges of sound existing coatings and roughen glossy surfaces.
4. Concrete: check age (≥ 28 days) and moisture (< 4 %); grind or shot blast to remove laitance and open the pores; vacuum all dust.
5. Remove all dust and abrasive residues with clean, dry compressed air or vacuum.

6. Measure substrate temperature, air temperature and relative humidity; confirm the substrate is at least 3 °C above dew point.
7. Protect adjacent surfaces, drains and fixtures with masking tape and sheeting.
8. Obtain QA/QC approval of the prepared surface before starting the next step.

10. Mixing

1. Condition materials to between +15 °C and +25 °C before mixing.
2. Check the batch numbers and expiry dates of both parts and record them.
3. Stir Part A thoroughly to disperse any settled pigment.
4. Add the complete Part B to Part A (4 : 1 by weight).
5. Mix 2 – 3 minutes with a slow-speed mixer until uniform in colour.
6. Add epoxy thinner only where needed for spray application, within the recommended limit.
7. Mix only the quantity that can be applied within the pot life.

11. Application

1. Apply a stripe coat by brush on welds, edges, bolts and corners.
2. Apply the full coat by brush, roller or airless spray at 0.18 – 0.20 kg/m² (100 µm DFT) or to the DFT specified for the system.
3. Measure wet film thickness continuously and adjust application to reach the specified DFT.
4. Apply additional coats where the specified total DFT exceeds the single-coat thickness.
5. Work in manageable bays, keeping a wet edge to avoid lap marks.
6. Check consumption by area and wet film thickness regularly during application and record the results.

12. Curing & Protection

- Pot life 2 hours at 25 °C; discard mixed material that has exceeded the pot life.
- Overcoat with the specified O MIX intermediate or top coat within the recoat window of the system.
- Protect from rain, condensation and dust until overcoated.
- Protect the applied area from water, dust, other trades and traffic until the stated cure times are reached.
- Barricade the area and display warning signs.

13. Quality Control & Inspection

Check	Stage	Acceptance Criteria	By
Surface cleanliness	After preparation	St 2 minimum / Sa 2½ where specified; free of oil and dust	QA/QC
Climate	Before and during work	Substrate ≥ +10 °C, 3 °C above dew point, RH ≤ 85 %	Site Engineer
Mixing	Each set	Complete set, 4 : 1 by weight, uniform colour	Site Engineer

Check	Stage	Acceptance Criteria	By
Film thickness	During and after application	WFT checked; DFT 100 µm or as specified	QA/QC
Appearance	After curing	Uniform, no runs, pinholes or dry spray	QA/QC

13.1 Inspection and test plan

Activity	Inspection / Test	Frequency	Record
Material receipt	Product, batch, expiry, packaging condition	Each delivery	Material inspection report
Climate	Air / substrate temperature, RH, dew point	Start of shift and every 4 hours	Daily climate log
Surface preparation	Visual, moisture, soundness	Each area	Inspection request (hold point)
Application	Consumption, thickness, appearance	Each coat / area	Daily progress report
Final inspection	Visual, continuity, finish	Each completed area	Handover checklist

14. Defects & Remedies

Defect	Likely Cause	Remedy
Pinholes / bubbles	Outgassing from porous substrate; air entrapped in mixing	Seal with primer; mix at low speed; de-aerate with spiked roller; sand and recoat
Blushing / tacky surface	High humidity or low temperature during cure	Wash and abrade; recoat in suitable conditions
Poor adhesion	Contaminated, weak or damp substrate; recoat window exceeded	Remove, re-prepare surface and reapply
Soft spots	Incorrect mixing or ratio	Remove affected area and reapply with full kits
Uneven colour / lap marks	Loss of wet edge; different batches	Abrade and apply a further coat from one batch

15. Health, Safety & Environment

Hazard	Control Measures
Skin and eye contact	Gloves, goggles, overalls; eye-wash available
Fire (solvent vapours)	No smoking or hot work; fire extinguisher on site
Inhalation of vapours / dust	Ventilation; masks as required
Slips and trips	Housekeeping; barricades and signs
Manual handling	Correct lifting technique; mechanical aids
Electrical tools	Inspected tools; protected cables

- Solvent-based: flammable. Keep away from heat, sparks and open flames; no smoking.

- Wear chemical-resistant gloves, safety goggles and overalls; use a respirator with organic vapour cartridges in enclosed spaces.
- Uncured epoxy may cause skin sensitisation; avoid skin and eye contact.
- Ensure good ventilation during application and curing.
- Eyes: rinse immediately with plenty of clean water for at least 15 minutes and seek medical advice.
- Skin: remove contaminated clothing and wash with soap and water; do not use solvents on skin.

15.1 Waste & environment

- Collect empty containers and residues in designated bins.
- Do not discharge material or washings into drains or soil.
- Allow small quantities of leftover mixed material to cure before disposal; dispose of according to local regulations.

16. Cleaning

- Clean tools and equipment immediately with epoxy thinner.

17. Limitations

- Substrate temperature: min. +10 °C.
- Substrate at least 3 °C above dew point.
- Do not apply in rain or when rain is expected before the material has set.
- Any deviation from this method statement must be approved by the Site Engineer and the consultant.

Appendix A — Inspection Checklist

Inspection Item	Result	Remarks
Oil and grease removed	☐ Yes ☐ No	
Surface prepared to St 2 / Sa 2½	☐ Yes ☐ No	
Dust and abrasive removed	☐ Yes ☐ No	
Climate conditions recorded	☐ Yes ☐ No	
Batch numbers recorded	☐ Yes ☐ No	
Complete sets mixed at 4 : 1	☐ Yes ☐ No	
Stripe coat applied on edges and welds	☐ Yes ☐ No	
WFT / DFT measured and recorded	☐ Yes ☐ No	
Coat uniform without defects	☐ Yes ☐ No	
Overcoated within recoat window	☐ Yes ☐ No	

Inspected by	Signature	Date