

Troubleshooting Guide







My measurements won't validate. What now?

- 1. The most common issue is short diagonal measurements. Our technology uses the diagonals to determine out of square for each window opening.
 - a. Confirm the diagonal extender of the tool is in the corner and the laser beam is fully in the opposing corner.
 - b. Confirm you are measuring on the same frame step.
 - c. Assess your frame for buildup in the corners: sheetrock texture, paint buildup or rounded corners. If these conditions exist, add .10" to EACH of the diagonal values and recheck. Do this 2 times at .10" increments. THIS WILL NOT AFFECT THE FIT OF YOUR INSERT.
- 2. Check the window frame surface. If the surface is too bright or too dark the laser beam may not read correctly. Place a piece of masking tape on the surface if this is an issue.
- 3. If you are keying in values to the portal from the worksheet, verify there are no transcription errors.
- 4. Review your width and height values pairing for the problem measurements. In general, height and/or width paired values are within ½" even though the window frame is out of square. It is unusual to see a left height of 35" and a right height of 36" on the same opening.
- 5. Verify that all values are numerical. Decimals and fractions are okay, other symbols are not. Ex. 24 ½ or 13.5 is okay. 13.5" is not. When using fractions there must be a space between the number and the fraction. Ex. 31 ½ is okay 31½ is not.
- 6. Make sure the "I used my own tools" check box is not checked unless you are not using the laser provided.
- 7. Make sure the Diagonal Extender is installed to the laser only when measuring diagonals.
- 8. If measuring diagonals with the H bar mullion profile installed, you will need to place the Diagonal Extender in the windows frame and measure to the corner where the bar meets with the window frame.

Once you've taken these steps, if the measurements still won't validate schedule a consultation at http://go.indowwindows.com/SMSupport