



Invoice

Follow-up Diagnostic Visit — CAN Bus / TCU / EZS

Tripoint Diagnostics Ltd

Company No. 17038307

Registered office: 476 Sidcup Road, London, United Kingdom, SE9 4HA

VAT No.: 515 7327 92 Website: tripointdiagnostics.co.uk

Email: contact@tripointdiagnostics.co.uk | Phone: [020 8058 6095](tel:02080586095)

WhatsApp: [Message us](#) | [Google Business](#)

INVOICE NUMBER

TPD-2026-0026

STATUS

UNPAID

INVOICE DATE

12 May 2026

DUE DATE

Due on receipt

PAYMENT TERMS

Due on receipt

BILL TO

John Wafula

SERVICE ADDRESS

BR8 8DZ

BR8 8DZ

Vehicle: Mercedes-Benz A-Class (RV13 WFR) **Odometer:** - **Job ID:** TPD-2026-0026 **PO:** -
Technician: Jamie Armoordon

DESCRIPTION	QTY	RATE	AMOUNT
FOLLOW-UP DIAGNOSTIC VISIT (VISIT 2)			
Additional Diagnostic Labour — Transmission / CAN Bus			
Follow-up visit focused on no-gear-selection condition:			
• Transmission power and ground feeds confirmed good • CAN communication scoped via oscilloscope at engine ECU and EZS (central gateway) • All bus signals indicate TCU as non-responding node • TCU previously bench-tested as functional — by elimination, fault now points to the EZS / central gateway failing to pass communication through to the TCU • Written diagnostic report & next-step recommendation provided			
	2 hrs	£85.00	£170.00

Subtotal	£170.00
Discount	None
VAT (20%)	£34.00
Total	£204.00
Amount paid	£0.00
Balance due	£204.00

Payment

Pay securely online via the link below, or by bank transfer using the details shown.

Bank transfer:

Tripont Diagnostics Ltd
Sort code: 04-06-05
Account: 30447065
Reference: TPD-2026-0026

[Pay £204.00 Online →](#)

Visit summary: Follow-up visit (Visit 2) on no-gear-selection fault. Transmission power and ground feeds confirmed good. CAN communication scoped using an oscilloscope at both the engine ECU and the EZS (Electronic Ignition Switch / central gateway). All signals on the bus point to the TCU as the non-responding node. As the TCU has already been bench-tested and returned as functional, by elimination the fault now points to the EZS failing to pass communication through to the TCU — a rare but known scenario on this platform.

Recommended next step: Before condemning the EZS (a costly, security-coded component), source a known-working second-hand TCU and plug it in to confirm whether communication can be established. If the swapped-in TCU also fails to communicate, the EZS becomes the confirmed fault. If it does communicate correctly, the original TCU bench-test result will need to be revisited.

This invoice: Covers Visit 2 additional labour only (2 hrs at £85.00/hr + VAT = £204.00 inc. VAT). Diagnostic report covering Visit 2 findings supplied separately.

[Cancellation & deposit policy](#) · [Terms of service](#) · [Privacy policy](#) · [Disclaimer](#)

Thank you for your business. Questions? Reply to this email or contact us at contact@tripointdiagnostics.co.uk

© 2026 Tripoint Diagnostics Ltd. All rights reserved.