

Corrective & Preventive Action Log

BioSCADA Monitored Parameters — Consolidated CAPA Records

Document No.	CAPA-LOG-2024	Revision	03
Period	Jan–Sep 2024	Status	Active
Owner	Quality Assurance	Classification	GxP Critical

This log consolidates corrective and preventive action records for excursions on BioSCADA-monitored parameters. Each record documents the problem, root-cause determination, corrective action, and effectiveness verification. These records are a primary retrieval source for the BioSCADA agent layer when a breach is predicted.

CAPA-2231 | Reactor Temperature — BR-12

Opened: 18-Apr-2024

Field	Detail
Problem	Reactor temperature exceeded 38.0 °C for 22 minutes during an Omez batch.
Root Cause	Heat-exchanger plate fouling reduced cooling capacity; coolant flow could not compensate.
Corrective Action	Cleaned heat-exchanger plate pack; reduced coolant setpoint by 4 percent during recovery; added a dP trending alarm at 30
Effectiveness	Effective — no recurrence in 14 subsequent batches.

CAPA-1987 | pH — BR-12

Opened: 09-Feb-2024

Field	Detail
Problem	pH drifted to 6.55, requiring a batch hold.
Root Cause	Base dosing pump P-2 actuation lag caused under-dosing during rapid CO2 accumulation.
Corrective Action	Replaced the P-2 actuator; revised SOP to stage dosing at 3 percent increments with QA e-signature.
Effectiveness	Effective — one minor recurrence in May 2024, within control.

CAPA-2104 | Differential Pressure — FIL-07

Opened: 14-Mar-2024

Field	Detail
Problem	Differential pressure rose to 116 kPa during filtration.
Root Cause	Progressive filter blockage; the filter had exceeded validated throughput.
Corrective Action	Filter changed; throughput limit added to the batch record as a mandatory check.
Effectiveness	Effective — no recurrence.

CAPA-2310 | Conductivity (WFI) — WFI-02

Opened: 21-Jun-2024

Field	Detail
Problem	WFI conductivity reached 965 µS/cm.
Root Cause	Feed composition error — incorrect salt concentration staged against recipe.
Corrective Action	Recipe verification step added with a second-person check before charging.
Effectiveness	Effective — no recurrence.

CAPA-2056 | Humidity (Cleanroom) — CR-A1

Opened: 25-Jan-2024

Field	Detail
Problem	Cleanroom RH fell to 34 percent during winter operation.
Root Cause	Cooling coil running warm combined with low outdoor humidity.
Corrective Action	HVAC control loop retuned; humidification setpoint seasonally adjusted.
Effectiveness	Partially effective — two minor recurrences in winter 2024; monitoring continues.