Sunlite USB Interface

Installing the driver and disabling USB power saving

This instruction has two parts. First we install the device driver while bypassing signature enforcement, then we remove everything that can switch the USB port off “to save power.” Part 1 is performed once; Part 2 should be gone through in full — it is the most frequent reason the interface disappears in the middle of a session.

> **IMPORTANT**
> You will need: the siudi-arm64.inf file, administrator rights, 10–15 minutes and one reboot. The checks after each step show exactly where something went wrong — do not skip them.

PART 1 INSTALLATION

STEP 1 Disable Secure Boot

Shut the virtual machine down completely (not “Pause” — a full shutdown). Then open Parallels Control Center → the gear icon next to your VM → Hardware → Boot Order → Advanced, and add the following line to the boot flags field:

```
vm.efi.secureboot=0
```

Start the VM and check: Win+R → msinfo32 → the “Secure Boot State” line must read “Off.”

✓ Secure Boot State — “Off.”

> Without this step the next one will not work: with Secure Boot active, Windows will not let you enable test mode.

STEP 2 Enable test mode

Open a command prompt as administrator and run:

```
bcdedit /set testsigning on
```

Reboot the computer. Check: the “Test Mode” watermark has appeared in the bottom-right corner of the desktop.

> This is normal and expected — do not be alarmed. The watermark stays up the whole time the mode is enabled, and it is not a sign of a fault.

STEP 3 Install the INF file

Copy the siudi-arm64.inf file into the virtual machine, for example into the C:\temp\ folder. Then, in an administrator command prompt:

```
cd C:\temp
pnputil /add-driver siudi-arm64.inf /install
```

Alternative method: right-click the siudi-arm64.inf file → “Install.”

✓ It must report “Driver package added successfully” and “Device installed successfully.”

> If the system complains about the driver signature, Step 2 did not take effect. Go back to it, make sure the “Test Mode” watermark is present, and repeat the installation.

STEP 4 Reconnect the device

Unplug the interface and plug it back in — or use Device Manager → the “Action” menu → “Scan for hardware changes.”

✓ The exclamation mark next to the device is gone. Under Properties → the “Driver” tab, the service listed is WinUSB.

STEP 5 Verify with Hardware Manager

Run Hardware Manager.exe (it is in the Sunlite folder). It should detect the interface and show the firmware. This check is independent of Sunlite: if the hardware is visible here, the driver binding has worked.

STEP 6 Sunlite Suite 2

Launch Sunlite Suite 2 and check whether the program sees the interface. If it does, installation is complete — move on to Part 2.

PART 2 POWER SAVING

By default Windows powers USB ports down when they are idle. For an interface that runs for hours on end, this is the main cause of sudden dropouts. We check and fix things in order: the items below do not duplicate one another, so none of them can be skipped.

2.1 USB Root Hubs

Device Manager → “Universal Serial Bus controllers.” For each “USB Root Hub”: right-click → Properties → the “Power Management” tab → clear the “Allow the computer to turn off this device to save power” checkbox.

✓ The checkbox is cleared on every hub — there are usually 2–4 of them.

Do the same for “Generic USB Hub” (Universal Serial Bus Hub) if any appear in the list.

> **IMPORTANT**
> Skip even one hub and the problem remains. That is exactly why “I did everything and it still did not help” happens so often.

2.2 Power plan

Control Panel → Power Options → “Change plan settings” → “Change advanced power settings.” In the list that opens:

- USB settings → “USB selective suspend setting” → “Disabled” — both for “On battery” and for “Plugged in.”
- Sleep → “Sleep after” → “Never.”
- Display → “Turn off display after” — you can leave this as it is; it does not affect how the interface works.

While you are there, set the plan itself to “High performance”: idle timers fire less often under it and USB behaves more consistently.

> **FINAL CHECK**
> Done. Reboot the VM and check the whole chain: the interface must be visible both in Hardware Manager and in Sunlite Suite 2. If the device still drops out, go back to section 2.1 and verify that the checkboxes are cleared on all hubs, including Generic USB Hub.