Docusign Envelope ID: AB602CD4-E5EE-49E5-836F-6B0CDF44DA1C

Received 2/3/2026 via OAQ Email

BP Products North America Inc.
Whiting Business Unit
2815 Indianapolis Blvd
P.O. Box 710
Whiting, IN 46394-0710

January 30, 2026

Submitted Electronically: AirCompl@idem.IN.gov

Indiana Department of Environmental Management
Compliance and Enforcement Branch, Office of Air Quality
100 North Senate Avenue, Room 13W
Indianapolis, Indiana 46204-2251

Re: Fourth Quarter 2025 – Quarterly Title V Deviation and CAM Report
BPPNA - Whiting Business Unit, Whiting IN (the "Refinery")
Part 70 Permit No.: T089-30396-00453 and T089-41271-00453 Reporting Period: October 1 to December 31, 2025

To Whom It May Concern:

Enclosed is the Quarterly Deviation Report required under C.22 (a) of the Part 70 (Title V) Operating Permits T089-30396-00453 (effective January 1, 2015 through November 3, 2025) and last updated by Significant Permit Modification (SPM) 089-46607-00453 (issued November 28, 2023) and T089-41271-00453 (effective November 4, 2025), issued by the Indiana Department of Environmental Management (IDEM).

The Refinery has continuing efforts to identify and remedy all existing engineered open-ended lines (OELs) throughout the site. There were three engineered OELs discovered during this reporting period.

The Leak Detection and Repair (LDAR) program continues to be an area of focus within the Refinery. During this reporting period the following deviations were identified:

- Six (6) pressure relief devices were found to be leaking outside of a pressure release event,
- Two (2) non-engineered open-ended line (OELs) were identified, and
- Seven (7) components found which were undocumented and unmonitored.

During the reporting period the following contributed to deviations at the Refinery:

- Coker Feed Tank TK-6254: The 12-month rolling H_2S exceedance that resulted from a fire in quarter 1 has been reported for quarters 1 through 4.
- Asphalt tanks (Opacity): Opacity was observed at the asphalt tanks during the duration of the biofilter study.
- FCU 500 and FCU 600 (Opacity): Multiple opacity events were observed. These events were associated with shell blasting of the power recovery train, a catalyst leak, and other startup activities following a fire incident at FCU 500.
- FCU 500 and FCU 600 (Limit Exceedances): Several limit exceedance deviations occurred during unit startup and due to additional equipment failures.
- Coker Heater F-201 PM10 test: Heater F-201 at the Coker failed PM_{10} testing in May 2025 and passed the retest on November 18, 2025.

Docusign Envelope ID: AB602CD4-E5EE-49E5-836F-6B0CDF44DA1C

- DDU Flare: Deviations occurred due to the shutdown of the Distillate Hydrotreater (DHT) for a turnaround and other maintenance activities.
- South Flare: Deviations occurred due to a power blip and a flare gas recovery unit (FGRU) trip triggered by freezing ambient temperatures.
- 4UF Flare: One deviation occurred due to a leak at the Cat Feed Hydrotreating Unit (CFHU).
- UIU Flare: Deviations occurred due to FCU 500 startup.
- GDU Fuel Gas System: One deviation was caused by a power blip event.
- Temporary Engines: Deviations occurred related to four (4) temporary engines that exceeded the insignificant activity threshold as reported in prior deviation reports.
- Fenceline Monitoring: One deviation not included in the 3Q2025 deviation report occurred due to delayed fenceline sampling at Station 26 because of inaccessibility caused by a flooding event in August 2025.
- IWWS: One deviation occurred due to a communication issue between the data system and the digital control system.
- Degreasing Operations: One deviation was related to labeling requirements on degreasing equipment, as identified during an unannounced IDEM air inspection on December 9, 2025.

In accordance with the 2012 Consent Decree, the refinery has elected to conduct a Leak Detection and Repair (LDAR) monitoring program (LMP) audit in 2025 for four process units: Lake George Tank Farm (LKGTK), Isomerization (ISOM), No. 4 Ultraformer (4UF), and Cat Feed Hydrotreating Unit (CFU). The primary objective of this audit is to identify any undocumented equipment subject to inspection requirements. The audit identified a total of 312 components as undocumented and unmonitored.

In addition, data required by 40 CFR Part 64 and 326 IAC 3-8 for compliance assurance monitoring ("CAM") is included in this report. Note that most of the information required for the CAM units has been included in other submissions made by the source. However, a specifically named CAM report for 4Q2025, including the information specified by 40 CFR 64.9(a) and 326 IAC 3-8, is included with this report.

In the case of CEMS performance, downtime is reported pursuant to 326 IAC 3-5-7.

This report was prepared in accordance with a system designed to assure that qualified personnel gathered and evaluated all reasonably available information relevant to deviations from the terms and conditions of the Part 70 permit over the periods covered by the reports and that they then reported to me their conclusions with respect to deviations. Based on my inquiry of such persons, I believe the contents of the enclosed reports to be true, accurate, and complete. However, that certification should not be read to imply that I have reviewed personally all documents, data or other information underlying the deviation determinations. Nor should it be read to imply that the persons responsible for gathering and evaluating the information relied on in making the certification have reviewed all information generated by the operations at the facility. As with any regulatory program, it is possible that there were deviations from permit conditions which may not be identified in the normal course of a good faith effort to implement the required compliance efforts under these programs.

In addition, this certification should not be construed as containing any admissions that the reported deviations or other events are violations of any applicable requirement. In some cases, applicable rules contain various defenses and/or exemptions which may excuse particular deviations. In other cases, the question of whether a particular event constituted a deviation or violation may be subject to interpretational

Docusign Envelope ID: AB602CD4-E5EE-49E5-836F-6B0CDF44DA1C

disputes. In still other cases, events may have been reported as deviations out of an abundance of caution despite the fact there is insufficient factual information to determine whether the deviation actually occurred.

If you have any questions regarding this certification or the information provided in this report, please contact Halle Brooks at Halle.Brooks@bp.com at (331)702-3103.

Sincerely,

Signed by:
Christopher DellaFranco
9B607A0F844646F...

Chris DellaFranco
VP of Refining – Whiting
BPPNA Whiting Business Unit

Enclosures

cc: Ramelito Biscocho - Electronic
Indiana Department of Environmental Management
RBiscoch@idem.IN.gov

Docusign Envelope ID: AB602CD4-E5EE-49E5-836F-6B0CDF44DA1C

Attachment 1

CAM Report

This report satisfies the reporting requirements of 40 CFR Part 64 and 326 IAC 3-8 as specified in Condition C.22 (a) of the site's Title V Permit. Specifically, for units subject to 40 CFR Part 64, any Compliance Assurance Monitoring (CAM) excursion or exceedance occurring during 4Q 2025 (including duration, cause, and corrective actions taken) are included in the associated Quarterly Title V Deviation Report. Additionally, a summary of the number, duration, and cause for monitoring downtime (other than downtime associated with zero and span or other daily calibration checks, if applicable) are reported in Attachment 2. The site and its CAM units are not subject to any Quality Improvement Plans (QIPs).

- The Sulfur Recovery Plant (SRP) Tail Gas Unit (TGU) A and TGU-B Sulfur Dioxide (SO_2) Continuous Emissions Monitoring System (CEM) is included in the quarterly CEM Summary Performance Report most recently submitted to IDEM by January 30, 2026 for the fourth quarter of 2025.
- The Remediation Unit thermal oxidizer controlling J-138 and J-140 is included in the Semiannual Compliance Report for the National Emission Standard for Hazardous Air Pollutants (NESHAP) 40 CFR 63, Subpart GGGGG - Site Remediation most recently submitted to EPA (through CEDRI) by January 30, 2026 for the reporting period from July 1, 2025 to December 31, 2025.[1]
- The Dissolved Nitrogen Flotation (DNF) System and DNF dewatering systems are included in the Quarterly 40 CFR 61, Subpart FF – Benzene Waste Operations NESHAP (BWON) most recently submitted to IDEM by January 30, 2026 for the fourth quarter of 2025.
- The Fluidized Catalytic Cracking (FCU) 500 and FCU 600 are included in the quarterly CEM Summary Performance Report most recently submitted by January 30, 2026 for the fourth quarter of 2025 for Indicator No. 1 – "Proper Operation of Electrostatic Precipitator (ESP)." A summary of the number, duration, and cause for parameter excursion for Indicator No. 2 – "Particulate loading at the ESP inlet" is included in the quarterly CEM Summary Performance Report most recently submitted by January 30, 2026 for the fourth quarter of 2025 and semi-annual Refinery MACT II Compliance Report (40 CFR 63.1575 of Subpart UUU) most recently submitted by January 30, 2026 for the reporting period from July 1, 2025 to December 31, 2025. A summary of the number, duration, and cause for monitoring downtime for Indicator No. 2 – "Particulate loading at the ESP inlet" is included as Attachment 2 to this report. There were no excursions for Indicator No. 3 – "Inspection and Maintenance" during the 4Q 2025 reporting period.

[1] Pursuant to 40 CFR 70.6(a)(3)(iii), submittal of reports of any required monitoring should be made at least every six (6) months. For CAM reporting obligations that are satisfied by the submission of already-required semi-annual reports, BP will provide notice of the most recently submitted semi-annual reports in its quarterly CAM Report.

Docusign Envelope ID: AB602CD4-E5EE-49E5-836F-6B0CDF44DA1C

Attachment 2

FCU 500 – Coke Burn-off (Indicator No. 2) – 4Q2025
FCU 600 – Coke Burn-off (Indicator No. 2) – 4Q2025

Docusign Envelope ID: AB602CD4-E5EE-49E5-836F-6B0CDF44DA1C

Compliance Assurance Monitoring Report

Facility Name: BP Products North America, Inc. **Location:** Whiting Refinery

Source: FCU 500

Parameter: Coke Burn

Data in the Reporting Period: 10/1/2025 to 12/31/2025

Monitor Downtime

Incid. No.	Start Date	End Date	Duration (hours)	Cause of Downtime (including Unknown Cause)	Indicator
1	10/24/2025 7:00	10/24/2025 11:59	5	a. Monitor Equipment Malfunction	Coke Burn - CO/CO2/O2 CEMS
2	11/11/2025 9:00	11/11/2025 9:59	1	d. Other Known Causes	Coke Burn - CO/CO2/O2 CEMS
3	12/12/2025 9:00	12/12/2025 9:59	1	d. Other Known Causes	Coke Burn - CO/CO2/O2 CEMS
4	12/19/2025 9:00	12/19/2025 9:59	1	d. Other Known Causes	Coke Burn - CO/CO2/O2 CEMS
5	12/30/2025 10:00	12/30/2025 10:59	1	d. Other Known Causes	Coke Burn - CO/CO2/O2 CEMS

Docusign Envelope ID: AB602CD4-E5EE-49E5-836F-6B0CDF44DA1C

Compliance Assurance Monitoring Report

Facility Name: BP Products North America, Inc.

Location: Whiting Refinery

Source: FCU 600

Parameter: Coke Burn

Data in the Reporting Period: 10/1/2025 to 12/31/2025

Monitor Downtime

Incid. No.	Start Date	End Date	Duration (hours)	Cause of Downtime (including Unknown Cause)	Indicator
1	12/3/2025 12:00	12/3/2025 17:59	6	a. Monitor Equipment Malfunction	Coke Burn - CO/CO2/O2 CEMS

Docusign Envelope ID: AB602CD4-E5EE-49E5-836F-6B0CDF44DA1C

Attachment 3

Title V Deviations – 4Q2025

Requirement (Permit Condition + Regulation)	Start Date	Duration	Units of Duration	Cause	Response
B.20	10/1/2025	34	Day(s)	During the reporting period, onsite engines exceeded the insignificant activity threshold in 326 IAC 2-7-1(19)(J)(i)(BB) (i.e., 2,000,000 BTU/hr of capacity) including two (2) engines at the cat pad (i.e., cat pad / cleaning pad) and two (2) air compressors at the Sulfur Recovery Unit (SRU).	Project is progressing to install electric engines for dewatering the cat pad. A pump utilization strategy is ongoing for the two (2) compressors at the SRU.
D.2.2(g)	10/1/2025	34	Day(s)	On May 29, 2025, during a PM performance test, Coker 2 furnace F-201 tested above PM10 (lb/MMBtu) limits. All runs were high in inorganic condensable particulate matter.	Retest of Coker 2 F-201 furnace passed on November 18, 2025.
D.2.2.(l)	10/1/2025	34	Day(s)	As a result of a fire in tank, TK-6254, on January 6, 2025, not all of the vapors from the Coker Feed Tank (TK-6254) was being routed to the Option 2 controls (i.e., South Flare Vapor Recovery System). In March 2025 the H2S 12- Rolling Total exceeded 2.84 tons/yr.	April 27, 2025 Tank 6254 was deinventoried for inspections and repairs.
D.5.1(a), D.5.1(b) F.9.2.3 - 40 CFR 60.592a F.9.3.5 - 40 CFR 60.482-4a	10/1/2025	34	Day(s)	At Vapor Recovery Unit 200 (VRU 200) on July 14, 2025, one (1) pressure relief device (RV T-573 in gas/vapor service) exceeded the leak definition outside of a pressure release event. This PRV began to leak above the leak definition on May 29, 2025.	RV T-573 will be repaired during the next unit outage.
D.5.1(a), D.5.1(b) F.9.2.3 - 40 CFR 60.592a F.9.3.5 - 40 CFR 60.482-4a	10/1/2025	34	Day(s)	At Vapor Recovery Unit 200 (VRU 200) on July 15, 2025, one (1) pressure relief device (PRV-537 in gas/vapor service) exceeded the leak definition outside of a pressure release event. This PRV began to leak above the leak definition on February 7, 2025.	RV-537 not able to be isolated due to a leak in the block valves. The valve was unable to be removed and will need to be repaired during the next unit outage.
D.5.1(a), D.5.1(b) F.9.2.3 - 40 CFR 60.592a F.9.3.5 40 CFR 60.482-4a	10/1/2025	34	Day(s)	Valve in closed vent service was inadvertently removed from service in January of 2023 following an MOC in the area and missed its annual inspection in 2024. Valve was rediscovered and inspected again in December of 2025.	Unit is actively working on solution for SV-1017 and the tentative plan is to isolate the valve.
D.5.1(a), D.5.1(b) F.9.2.3 - 40 CFR 60.592a F.9.3.5 40 CFR 60.482-4a	10/1/2025	34	Day(s)	At Vapor Recovery Unit 100 (VRU100) on September 24, 2025, one (1) pressure relief device (SV-40) (in gas/vapor service) exceeded the leak definition outside of a pressure release event.	Unit is actively working on solution for SV-40 and the tentative plan is to isolate the valve.
D.27.1(a), D.27.1(b) F.9.2.3 - 40 CFR 60.592a F.9.3.8 - 40 CFR 60.482-7a	10/1/2025	34	Day(s)	During area monitoring of South Tank Field, a technician found three new valves in an area used for collecting samples. LDAR team was not informed of their addition and therefore missed all monitoring since installation.They were inspected on November 15, 2025.	Components were tagged and monitored.
D.27.1(a), D.27.1(b) F.9.2.3 - 40 CFR 60.592a F.9.3.7 - 40 CFR 60.482-6a	10/1/2025	34	Day(s)	During area monitoring of South Tank Field, a technician found three new valves in an area used for collecting samples. The sample lines were "U" shaped and only had one block point and no way to drain the sample line to confirm no hydrocarbons were left in the line. Additionally a drain in the same area was found open to atmosphere with only one potential block valve.	Operations is working on corrective actions to change the configuration.
D.27.1(a), D.27.1(b) F.9.2.3 - 40 CFR 60.592a F.9.3.8 - 40 CFR 60.482-7a	10/1/2025	34	Day(s)	One component was accidentally removed from services during dual applicability review and missed monitoring. This component was found in the field during normal monitoring and placed back in service.	The component was added back into the database an monitored.
D.9.5(a), D.9.5(b) F.9.2.3 - 40 CFR 60.592a, F.9.3.8 - 40 CFR 60.482-7a	10/1/2025	34	Day(s)	At the Isomerization (ISOM) Unit a valve in closed vent service was inadvertently removed from service in January of 2023 and missed its annual inspection in 2024. Valve was rediscovered and inspected again on December 17, 2025.	Valves was found still in service during normal monitoring. Valve was added to the database and monitored.

C.22 H.2.2.16 - 40 CFR 63.658(e)(1)	10/1/2025	34	Day(s)	Due to site flooding, starting on August 22, 2025 and lasting for 11 days, the fenceline sample station 26 was inaccessible for longer than 15 calendar days. Section 8.4.3 of Method 325A states that sample sites that are not accessible due to extenuating circumstances, such as extreme weather, are allowed to go beyond the prescribed sampling period as long as they are retrieved as soon as there is safe access to the location. bp retrieved the sample station 26 tube as soon as it was safe to access the location. Although this safety-related language is in the method, it is not referenced in MACT CC and therefore this extended sampling period is being included in this report.	The Whiting Refinery retrieved the sample station 26 tube as soon as it was safe to access the location.
D.1.7(a), D.1.7(b) F.9.2.3 - 40 CFR 60.592a F.9.3.5 - 40 CFR 60.482-4a	10/1/2025	6	Day(s)	At 11 Pipe Still (11 PS) on September 7, 2025, one (1) pressure relief device (PRV C-138) (in gas/vapor service) exceeded the leak definition outside of a pressure release event.	The PRV C-138 was removed and repaired on October 6, 2025 and passed inspection on October 14, 2025.
D.21.3(d)	10/1/2025	1	Month(s)	At the Fluidized Catalytic Cracking Unit 500 (FCU 600), carbon monoxide (CO) exceeded the 179.6 tons per 12 consecutive month limit. This occurred during the startup of FCU 500 when the unit needed to combust torch oil as part of the startup process. While the unit was combusting torch oil the CO emissions were elevated.	Startup of the unit was progressed. CO emissions returned to normal levels.
D.9.5(a), D.9.5(b) D.16.5(a), D.16.5(b) D.19.5(a), D.19.5(b) F.9.2.3 - 40 CFR 60.592a F.9.3.8 - 40 CFR 60.482-7a F.9.3.11 - 40 CFR 60.482-10a	10/1/2025	Various	Day(s)	Pursuant to the LDAR Monitoring Program (LMP) audit scope agreed upon by the site and USEPA Region 5, three hundred twelve (312) components were found undocumented during the 2025 audit as detailed below: • 36 components were found in Isomerization Unit (ISOM) • 170 components were found in 4 Ultraformer (4UF) • 106 components were found in Cat Feed Hydrotreating Unit (CFU) The audit identified several areas for improvement within the LDAR monitoring program, including improper applicability determinations for process streams, inadequate management of removed or out-of-service equipment, and inconsistent tagging and documentation practices for similar process equipment. These issues are currently being addressed as part of ongoing efforts to enhance the program.	All components were added to the database or reactivated and returned to the required monitoring frequency. These components will continue to be addressed as part of inventory revalidation efforts in the LDAR program.
D.38.1(a)(5)	10/1/2025	34	Day(s)	During an unannounced IDEM air inspection of degreasing operations on December 9, 2025, the inspector flagged non-conformance with a requirement to have a permanent, conspicuous label that lists other operating requirements at each degreasing location visited (15 out of 16 locations).	A label was affixed to each of the sixteen (16) degreasing locations on December 10, 2025.
C.1.a	10/5/2025	6	Minute(s)	At the Fluidized Catalytic Cracking Unit 500 (FCU 500), on October 5, 2025, opacity exceeded 20% averaged over 1 six-minute period during shell blasting of the power recovery train.	Increased ammonia injection. Shell blasting activity was completed.
C.1.a	10/11/2025	3	Hour(s)	At Fluidized Catalytic Cracking Unit 500 (FCU 500), there was a catalyst leak on process equipment (CA-3B lower slide valve packing) on October 11, 2025. Evidence suggests that opacity exceeded 20% over one (or more) six-minute period. No Method 9 observation was conducted.	Unit moves were made so the CA-3B lower slide valve could be re-packed which stopped the leak.
D.35.8.F.29.b E.4.1.5 - 40 CFR 65.147(a) H.2.2.18 - 40 CFR 63.670(c)	10/12/2025	105	Minute(s)	The DDU Flare smoked for 105 minutes total over multiple two-hour periods, which is greater than the MACT CC limit of five minutes in a two-hour period. This occurred during the shutdown of the DHT unit for turnaround.	Steam flow was increased to eliminate the smoking flare.
C.1.a	10/13/2025	6	Minute(s)	At the Fluidized Catalytic Cracking Unit 500 (FCU 500), on October 13, 2025, opacity exceeded 20% averaged over 1 six-minute period during shell blasting of the power recovery train.	Increased ammonia injection. Shell blasting activity was completed.

D.5.1(a), D.5.1(b) F.9.2.3 - 40 CFR 60.592a F.9.3.5 - 40 CFR 60.482-4a	10/14/2025	3	Day(s)	At Vapor Recovery Unit 200 (VRU 200) on October 14, 2025, one (1) pressure relief device (RV T-0602) (in gas/vapor service) exceeded the leak definition outside of a pressure release event.	RV was reinspected and passed on October 17, 2025.
D.5.1(a), D.5.1(b) F.9.2.3 - 40 CFR 60.592a F.9.3.5 - 40 CFR 60.482-4a	10/14/2025	3	Day(s)	At Vapor Recovery Unit 200 (VRU 200) on October 14, 2025, one (1) pressure relief device (RV T-533) (in gas/vapor service) exceeded the leak definition outside of a pressure release event.	RV was reinspected and passed on October 17, 2025.
F.3.2.4 - 40 CFR 60.103a(h)	10/16/2025	105	Hour(s)	A weld rupture at the Cat Feed Hydrotreating Unit lead to an unplanned emergency shutdown of the CFHU and flaring at the 4UF flare. As a result of this, the 3-hour rolling H2S average limit of 162ppm was exceeded at the 4UF Flare for one hundred four (105) hours.	The board operator initiated a unit rapid depressurization due to a vapor cloud from the weld rupture. The fire department isolated the upstream block valve to the release which the stopped leak. Flaring at the 4UF flare continued as the CFHU was shutdown.
D.2.6(a), D.2.6(b) F.9.2.3 - 40 CFR 60.592a F.9.3.7 - 40 CFR 60.482-6a	10/22/2025	1	Day(s)	Operator making rounds at the Coker smelled fuel gas in the area. Operator found a pressure transmitter that was leaking fuel gas from an impulse line that was missing a 1/4 inch cap from the bleeder on the manifold-one OEL.	Pressure transmitter was repaired and monitored the following day.
D.35.8.F.29.b E.4.1.5 - 40 CFR 65.147(a) F.3.2.4 - 40 CFR 60.103a(h) H.2.2.18 - 40 CFR 63.670(c)	10/24/2025	Varies	Minute(s)	A power blip at the Refinery caused an upset throughout the refinery that caused flaring at the South flare. As a result of this, the 3-hour rolling H2S average limit of 162ppm was exceeded at the South Flare for three (3) hours and the South Flare smoked for 24 minutes in a two-hour period, which is greater than the MACT CC limit of five minutes in a two-hour period.	Emergency procedures were executed to stabilize the refinery.
D.35.8.F.29.b E.4.1.5 - 40 CFR 65.147(a) H.2.2.18 - 40 CFR 63.670(c)	10/27/2025	10	Minute(s)	Due to a refinery fuel gas imbalanced caused by the startup of FCU 500, the UIU flare had a flaring event. The UIU Flare smoked for 10 minutes over a two-hour periods, which is greater than the MACT CC limit of five minutes in a two-hour period.	Steam flow was increased to eliminate the smoking flare.
C.1(a)	10/27/2025	12	Minute(s)	At the Fluidized Catalytic Cracking Unit 500 (FCU 500), opacity exceeded 20% averaged over 2 six-minute periods during the startup of FCU 500. This was caused when the K-501 precipitator was energized but the ammonia injection system was not in service. There was a delay in energizing the K-502 precipitator while working to bring the ammonia injection system online.	Ammonia injection system was brought online and the K-502 precipitator was energized.
D.35.8.F.29.b E.4.1.5 - 40 CFR 65.147(a) H.2.2.18 - 40 CFR 63.670(c) H.2.2.18 - 40 CFR 63.670(e)	10/28/2025	Varies	Minute(s)	Due to a refinery fuel gas imbalanced caused by the startup of FCU 500, the UIU flare had a flaring event. During one (1) 15-minute period, while regulated material was being sent to the UIU Flare, the net heating value of flare combustion zone (NHVcz) dropped below 270 Btu/scf. The UIU Flare also smoked for 30 minutes over multiple two-hour periods, which is greater than the MACT CC limit of five minutes in a two-hour period.	Steam flow was increased to eliminate the smoking flare. Supplemental natural gas was added to increase the NHVcz.
F.7.2.3 - 40 CFR 60.472 (c)	11/3/2025	1	Day(s)	During an engineering study of the asphalt biofilter system, visible emissions were observed each day of the engineering study under different operating conditions.	The engineering study was performed to evaluate potential points within the collection /biofilter system, if any, may cause opacity or excess emissions from the asphalt storage tanks. An evaluation of the biofilter system is underway to determine methods for opacity reductions.

Requirement (Permit Condition + Regulation)	Start Date	Duration	Units of Duration	Cause	Response
B.20	11/4/2025	58	Day(s)	During the reporting period, onsite engines exceeded the insignificant activity threshold in 326 IAC 2-7-1(19)(J)(i)(BB) (i.e., 2,000,000 BTU/hr of capacity) including two (2) engines at the cat pad (i.e., cat pad / cleaning pad) and two (2) air compressors at the Sulfur Recovery Unit (SRU).	Project is progressing to install electric engines for dewatering the cat pad. A pump utilization strategy is ongoing for the two (2) compressors at the SRU.
D.2.2(g)	11/4/2025	15	Day(s)	On May 29, 2025, during a PM performance test, Coker 2 furnace F-201 tested above PM10 (lb/MMBtu) limits. All runs were high in inorganic condensable particulate matter.	Retest of Coker 2 F-201 furnace passed on November 18, 2025.
D.2.2.(l)	11/4/2025	58	Day(s)	As a result of a fire in tank, TK-6254, on January 6, 2025, not all of the vapors from the Coker Feed Tank (TK-6254) was being routed to the Option 2 controls (i.e., South Flare Vapor Recovery System). In March 2025 the H2S 12- Rolling Total exceeded 2.84 tons/yr.	April 27, 2025 Tank 6254 was deinventoried for inspections and repairs.
D.5.1(a), D.5.4 F.9.2.3 - 40 CFR 60.592a F.9.3.5 - 40 CFR 60.482-4a	11/4/2025	58	Day(s)	At Vapor Recovery Unit 200 (VRU 200) on July 14, 2025, one (1) pressure relief device (RV T-573 in gas/vapor service) exceeded the leak definition outside of a pressure release event. This PRV began to leak above the leak definition on May 29, 2025.	RV T-573 will be repaired during the next unit outage.
D.5.1(a), D.5.4 F.9.2.3 - 40 CFR 60.592a F.9.3.5 - 40 CFR 60.482-4a	11/4/2025	58	Day(s)	At Vapor Recovery Unit 200 (VRU 200) on July 15, 2025, one (1) pressure relief device (PRV-537 in gas/vapor service) exceeded the leak definition outside of a pressure release event. This PRV began to leak above the leak definition on February 7, 2025.	RV-537 not able to be isolated due to a leak in the block valves. The valve was unable to be removed and will need to be repaired during the next unit outage.
D.5.1(a), D.5.4 F.9.2.3 - 40 CFR 60.592a F.9.3.5 - 40 CFR 60.482-4a	11/4/2025	58	Day(s)	Valve in closed vent service was inadvertently removed from service in January of 2023 following an MOC in the area and missed its annual inspection in 2024. Valve was rediscovered and inspected again in December of 2025	Unit is actively working on solution for SV-1017 and the tentative plan is to isolate the valve.
D.5.1(a), D.5.4 F.9.2.3 - 40 CFR 60.592a F.9.3.5 - 40 CFR 60.482-4a	11/4/2025	58	Day(s)	At Vapor Recovery Unit 100 (VRU100) on September 24, 2025, one (1) pressure relief device (SV-40) (in gas/vapor service) exceeded the leak definition outside of a pressure release event.	Unit is actively working on solution for SV-40 and the tentative plan is to isolate the valve.
D.27.1(a), D.27.6 F.9.2.3 - 40 CFR 60.592a F.9.3.8 - 40 CFR 60.482-7a	11/4/2025	11	Day(s)	During area monitoring of South Tank Field, a technician found three new valves in an area used for collecting samples. LDAR team was not informed of their addition and therefore missed all monitoring since installation. They were inspected on November 15, 2025.	Components were tagged and monitored.
D.27.1(a), D.27.6 F.9.2.3 - 40 CFR 60.592a F.9.3.7 - 40 CFR 60.482-6a	11/4/2025	58	Day(s)	During area monitoring of South Tank Field, a technician found three new valves in an area used for collecting samples. The sample lines were "U" shaped and only had one block point and no way to drain the sample line to confirm no hydrocarbons were left in the line. Additionally a drain in the same area was found open to atmosphere with only one potential block valve.	Operations is working on corrective actions to change the configuration.
D.27.1(a), D.27.6 F.9.2.3 - 40 CFR 60.592a F.9.3.8 - 40 CFR 60.482-7a	11/4/2025	58	Day(s)	One component was accidentally removed from services during dual applicability review and missed monitoring. This component was found in the field during normal monitoring and placed back in service.	The component was added back into the database an monitored.
D.9.5(a), D.9.11 F.9.2.3 - 40 CFR 60.592a, F.9.3.8 - 40 CFR 60.482-7a	11/4/2025	43	Day(s)	At the Isomerization (ISOM) Unit a valve in closed vent service was inadvertently removed from service in January of 2023 and missed its annual inspection in 2024. Valve was rediscovered and inspected again on December 17, 2025	Valves was found still in service during normal monitoring. Valve was added to the database and monitored.

C.22 H.2.2 (a)(16) - 40 CFR 63.658(e)(1)	11/4/2025	58	Day(s)	Due to site flooding, starting on August 22, 2025 and lasting for 11 days, the fenceline sample station 26 was inaccessible for longer than 15 calendar days. Section 8.4.3 of Method 325A states that sample sites that are not accessible due to extenuating circumstances, such as extreme weather, are allowed to go beyond the prescribed sampling period as long as they are retrieved as soon as there is safe access to the location. bp retrieved the sample station 26 tube as soon as it was safe to access the location. Although this safety-related language is in the method, it is not referenced in MACT CC and therefore this extended sampling period is being included in this report.	The Whiting Refinery retrieved the sample station 26 tube as soon as it was safe to access the location.
D.21.3(d)	11/1/2025	2	Month(s)	At the Fluidized Catalytic Cracking Unit 500 (FCU 600), carbon monoxide (CO) exceeded the 179.6 tons per 12 consecutive month limit. This occurred during the startup of FCU 500 when the unit needed to combust torch oil as part of the startup process. While the unit was combusting torch oil the CO emissions were elevated.	Startup of the unit was progressed. CO emissions returned to normal levels.
D.38.1(a)(5)	11/4/2025	36	Day(s)	During an unannounced IDEM air inspection of degreasing operations on December 9, 2025, the inspector flagged non-conformance with a requirement to have a permanent, conspicuous label that lists other operating requirements at each degreasing location visited (15 out of 16 locations).	A label was affixed to each of the sixteen (16) degreasing locations on December 10, 2025.
F.7.2.3 - 40 CFR 60.472 (c)	11/4/2025	18	Day(s)	During an engineering study of the asphalt biofilter system, visible emissions were observed each day of the engineering study under different operating conditions.	The engineering study was performed to evaluate potential points within the collection /biofilter system, if any, may cause opacity or excess emissions from the asphalt storage tanks. An evaluation of the biofilter system is underway to determine methods for opacity reductions.
F.3.2.3 - 40 CFR 60.102a(g)(1)(ii)	11/4/2025	2	Hour(s)	Due to a power blip within the Refinery, various equipment tripped offline. As a result of this, the GDU fuel gas exceeded the 3-hour rolling 162 ppm H2S limit for two (2) hours.	All amine contactors were checked for level deviations and lean/rich amine flows. H2S Draeger samples were taken on all product strippers going to fuel gas with no immediate findings. Amine stripper temperatures were increased by 5 deg F.
C.1(a)	11/5/2025	12	Minute(s)	At the Fluidized Catalytic Cracking Unit 500 (FCU 500), opacity exceeded 20% averaged over 2 six-minute periods when a additional feed pump was started (due to saturated control valves) which led to a surge in fresh feed. This event caused increased coke burn which increased oxygen consumption in the regenerator and caused the inlet carbon monoxide (CO) process analyzers to exceed 5,000 ppm which caused the electrostatic precipitators (ESPs) to trip to prevent an unsafe condition.	Unit was stabilized and ESPs were re-energized.
F.3.2.3 - 40 CFR 60.102a(c)(1)(i) H.3.2.22 - 40 CFR 63, Subpart UUU, Table 2	11/8/2025	10	Hour(s)	At the Fluidized Catalytic Cracking Unit 500 (FCU 500), the 3-hour rolling electrostatic precipitator (ESP) primary power and secondary current floor limits went below the limits (established by the most recent performance test) for 10 and 9 hours, respectively. This was caused when there was a interface board failure on one of the transformer rectifier boards which caused the ESP total primary power and secondary current to dip. During these periods, there were no opacity deviations.	Board was replaced and the transformer rectifier was re-energized.
D.1.6(a), D.1.14 F.9.2.3 - 40 CFR 60.592a F.9.3.8 - 40 CFR 60.482-7a	11/10/2025	2	Day(s)	Following a pressure release event at the 11 Pipestill (PS) for one (1) RV in OHAP service was not monitored within 5 days.	RV was monitored on November 12, 2025 and was not leaking.
D.22.7(b)	11/16/2025	46	Day(s)	At the Fluidized Catalytic Cracking Unit 600 (FCU 600), nitrogen oxide (NOx) exceeded the 10 ppm (corrected to 0% oxygen) 365 day rolling limit. This occurred during the startup process when the B-1 air preheater was firing to heat up the regenerator.	Startup progressed. Unit is making adjustments to reduce daily NOx concentrations.

C.1(a)	11/21/2025	84	Minute(s)	At Fluidized Catalytic Cracking Unit 600 (FCU 600), opacity exceeded 20% over 14 six-minute periods after the startup of FCU 600. This occurred after the startup process when the selective catalytic reduction (SCR) bypass was being closed. Catalyst could not be fully cleared from the SCR catalyst beds while the unit was offline. When the bypass valve was closed, catalyst entrained in the SCR was released through the stack, resulting in the observed opacity exceedance.	After the SCR bypass valve was closed and flue gas was routed through the SCR, the entrained catalyst was dislodged from the catalyst bed and exited through the stack. Once the catalyst was cleared, opacity returned to normal levels.
F.3.2.3 - 40 CFR 60.102a(g)(1)(ii)	11/23/2025	6	Hour(s)	The Interim Waste Water Stripper (IWWS) began seeing H2S breakthrough on the scrubber system that led to the 3-hour rolling 162 ppm H2S limit being exceeded for 6 hours. There was a communication issue between the Data Acquisition Handling System and Digital Control System which delayed operation's response.	Operations were more aggressive in their caustic change outs on the scrubbers and eventually reduced the nitrogen rates going into the brine. The communication issue has since been resolved.
D.7.1(a), D.7.3 F.9.2.3 - 40 CFR 60.592a, F.9.3.8 - 40 CFR 60.482-7a	12/4/2025	8	Day(s)	One new component missed its initial 30 day inspection.	Component was tagged and monitored.
F.3.2.4 - 40 CFR 60.103a(h)	12/14/2025	18	Hour(s)	The Flare Gas Recovery Unit for the South flare tripped offline. It is believed that the freezing temperatures caused the FGRU to trip offline. As a result of this, the 3-hr rolling H2S average limit of 162ppm was exceeded at the South Flare for eighteen (18) hours.	The operations team troubleshot the tripped FGRU and successfully restarted the system. An investigation into the FGRU trip will be conducted.
E.4.1.5 - 40 CFR 65.147(a) H.2.2.18 - 40 CFR 63.670(e)	12/26/2025	15	Minute(s)	While prepping compressor K-301 for maintenance, nitrogen was sent to the DDU flare. During one 15-minute periods, while regulated material was being sent to the DDU Flare, the net heating value of flare combustion zone (NHVcz) dropped below 270 Btu/scf.	The nitrogen flow was reduced and supplemental natural gas was increased.

Docusign Envelope ID: AB602CD4-E5EE-49E5-836F-6B0CDF44DA1C

Attachment 4

Part 70 Operating Permit Certification
BP Products North America Inc.

Docusign Envelope ID: AB602CD4-E5EE-49E5-836F-6B0CDF44DA1C

PART 70 OPERATING PERMIT CERTIFICATION

Source Name:	BP Products North America Inc., Whiting Business Unit
Source Address:	2815 Indianapolis Blvd., Whiting, IN 46394
Mailing Address:	P.O. Box 710, Whiting, Indiana 46394-0710
Permit No.:	T089-30396-00453 Last updated on November 28, 2023 per SPM 089-46607-00453 and T089-41271-00453 issued on November 4, 2025

This certification shall be included when submitting monitoring, testing reports/results or other documents as required by this permit.
Please check what document is being certified:
☐ Annual Compliance Certification Letter
☐ Test Results (specify)
☒ Report (specify): Fourth Quarter 2025 – Quarterly Title V Deviation & CAM Report
☐ Notification (specify)
☐ Affidavit (specify)
☐ Other (specify)

I certify that, based on information and belief formed after reasonable inquiry, the statements and information in the document are true, accurate, and complete.	
Signature of Responsible Official:	Signed by: Christopher DellaFranco 9B607A0F844646F...
Printed Name:	Chris DellaFranco
Title/Position:	VP Refining, Whiting
Phone:	(219) 306-2898
Date:	1/30/2026

Docusign Envelope ID: AB602CD4-E5EE-49E5-836F-6B0CDF44DA1C

Attachment 5

Part 70 Operating Permit Certification + 4Q2025 Deviation Report Linde Inc.

Docusign Envelope ID: AB602CD4-E5EE-49E5-836F-6B0CDF44DA1C

PART 70 OPERATING PERMIT CERTIFICATION

Source Name:	Linde Inc.
Source Address:	2551 Dickey Road, East Chicago, IN 46312
Mailing Address:	P.O. Box 712, Whiting, Indiana 46394-0710
Permit No.:	T089-30396-00453, 089-46607-00453
	T089-41271-0045 (issued November 4, 2025)

Linde shall include this certification when submitting monitoring, testing reports/results or other documents to BP and requires BP RO certification.
Please check what document is being certified:
☐ Annual Compliance Certification Letter
☐ Test Results (specify)
☒ Report (specify): Quarterly Deviation and Compliance Monitoring Report – 4Q2025
☐ Notification (specify)
☐ Affidavit (specify)
☐ Other (specify)

I certify that, based on information and belief formed after reasonable inquiry, the statements and information in the document are true, accurate, and complete.	
Signature of Responsible Official:	Paul S. P
Printed Name:	Paul Piper
Title/Position:	Facility Manager
Phone:	(219) 378-4871
Date:	1/15/2026

Docusign Envelope ID: AB602CD4-E5EE-49E5-836F-6B0CDF44DA1C

INDIANA DEPARTMENT OF ENVIRONMENTAL MANAGEMENT
OFFICE OF AIR QUALITY
COMPLIANCE DATA SECTION

PART 70 OPERATING PERMIT
QUARTERLY DEVIATION AND COMPLIANCE MONITORING REPORT

Source Name:	BP Products North America, Inc., Whiting Business Unit
Source Address:	2815 Indianapolis Blvd, Whiting, Indiana 46394-0710
Mailing Address:	P.O. Box 712, Whiting, Indiana 46394-0710
Part 70 Permit No.:	T089-30396-00453, SPM089-46607-00453, T089-41271-00453 (issued November 4, 2025)

Months: October **to** December **Year:** 2025

This report shall be submitted quarterly based on a calendar year. Any deviation from the requirements, the date(s) of each deviation, the probable cause of the deviation, and the response steps taken must be reported. A deviation required to be reported pursuant to an applicable requirement that exists independent of the permit, shall be reported according to the schedule stated in the applicable requirement and does not need to be included in this report. Additional pages may be attached if necessary. If no deviations occurred, please specify in the box marked "No deviations occurred this reporting period".
X NO DEVIATIONS OCCURRED THIS REPORTING PERIOD.
THE FOLLOWING DEVIATIONS OCCURRED THIS REPORTING PERIOD.
Permit Requirement (specify permit condition #):
Date of Deviation: Duration of Deviation:
Number of Deviations:
Probable Cause of Deviation:
Response Steps Taken:

Form Completed by:	Paul Piper - Linde Inc.
Title/Position:	Facility Manager
Date:	1/15/2026
Phone:	(219) 378-4871

Attach a signed certification to complete this report.