

Advanced Evaporator Coil Maintenance: Thermodynamic Degradation, Chemical Restoration, and PMOC Compliance in HVAC/R Systems

The evaporator coil serves as the critical thermodynamic interface in any air conditioning, heat pump, or refrigeration cycle. As the site of phase change and enthalpy transfer, the structural integrity, surface cleanliness, and hydrodynamic efficiency of the coil dictate the absolute performance of the system. Over time, the aggressive operational environment—characterized by continuous condensation, high volumetric airflow, and varying thermal gradients—subjects the evaporator coil to severe biological fouling, mechanical degradation, and metallurgical corrosion. Maintaining this component is not merely a matter of aesthetic hygiene; it is a fundamental engineering requirement for preserving the system's Coefficient of Performance (COP), preventing catastrophic compressor failure through liquid flood-back, and ensuring compliance with stringent indoor air quality (IAQ) regulations.

This exhaustive technical analysis explores the physics of coil fouling, the complex chemistry of restorative treatments, system-specific mechanical maintenance protocols for diverse equipment architectures, and the rigorous documentation standards required for modern regulatory compliance.

1. Coil Fouling Science: The Physics and Microbiology of Degradation

The degradation of an evaporator coil is a multi-variable process involving particulate accumulation, biological colonization, lipid polymerization, and chemical corrosion. Understanding the underlying science is imperative for diagnosing performance failures and selecting the appropriate chemical and mechanical intervention strategies.

Thermodynamic Impact of Air-Side Fouling

Fouling fundamentally alters the thermodynamic equilibrium of the heat exchanger. The overall

heat transfer coefficient (U -value) of a coil is determined by the thermal resistance of the air boundary layer, the metal tube/fin interface, and the internal refrigerant flow.¹ As particulate matter, biological growth, and organic greases accumulate on the aluminum fins and copper

tubes, an additional layer of thermal resistance ($R_{fouling}$) is introduced to the system.³

Interestingly, empirical studies and laboratory simulations utilizing field-fouled coils have demonstrated a nuanced and sometimes counterintuitive relationship between fouling and heat transfer. In the earliest stages of dust accumulation, the microscopic particulate layer can act as an artificial surface roughness agent, locally inducing turbulent airflow which marginally

disrupts the laminar boundary layer and briefly *increases* the air-side effective heat transfer coefficient.³ However, as the accumulation progresses beyond a microscopic layer, this transient benefit is rapidly overwhelmed by severe aerodynamic penalties.


The predominant mechanism of system degradation caused by evaporator fouling is not the thermal insulation of the coil surfaces, but rather the exponential increase in air-side pressure

drop (ΔP_{sys}).³ The tight spacing of modern high-efficiency coils, typically ranging from 12 to 20 fins per inch (FPI), makes them highly susceptible to aerodynamic flow restriction.⁶ As the spaces between the fins bridge with debris, the volumetric airflow (measured in Cubic Feet per Minute, or CFM) across the coil decreases significantly.³

This reduction in airflow triggers a cascading thermodynamic failure across the entire vapor-compression cycle. First, the mass flow rate of air delivering sensible and latent heat to the coil drops, substantially reducing the total cooling capacity. Engineering models and laboratory data indicate that a 10% reduction in airflow across the heat exchanger can result in a 0.8% to 1.0% reduction in total capacity, while a severe 50% airflow reduction degrades capacity by up to 11%.⁵ Second, as static pressure increases across the fouled fin pack, constant-volume indoor blower motors must consume proportionally more electrical power (

W_{fe}) to maintain airflow, which directly degrades the Energy Efficiency Ratio (EER) and the Coefficient of Performance (COP).³ Even minor fouling profiles can decrease system COP by 10% to 13% over a standard operational season.⁴ Finally, the reduced heat absorption causes the refrigerant saturation temperature within the evaporator to drop. If the coil surface temperature falls below the dew point and approaches 32°F (0°C), the continuous stream of condensate begins to freeze. Ice formation radically accelerates the pressure drop, effectively choking the system and risking liquid refrigerant flood-back to the compressor cylinders, which can result in catastrophic mechanical failure.⁷

O Bloqueio Aerodinâmico Supera a Resistência Térmica em Serpentinhas Obstruídas



A degradação do *Energy Efficiency Ratio* (EER) e do Coeficiente de Desempenho (COP) do sistema é impulsionada principalmente pelo aumento exponencial da queda de pressão estática, que força o motor do ventilador a consumir significativamente mais energia. A resistência térmica real (degradação do valor U) permanece relativamente marginal, e em alguns cenários pode até registrar ganhos iniciais ligeiros devido à turbulência induzida.

Fontes de Dados: [Purdue University \(ASHRAE Lab Data\)](#), [OSTI.gov](#), [Taylor & Francis](#)

Microbiological Colonization: The EPS Biofilm Matrix

The dark, perpetually damp, and thermally active environment of an evaporator coil provides an ideal incubator for microbiological life.¹⁰ Particulate matter passing through low-efficiency upstream filters (e.g., MERV 8) adheres to the wet fin surfaces, providing essential organic nutrients.¹¹

This environment fosters the development of a complex microbial ecology. The process begins with pioneer bacteria adhering to the wet metal, which then provide a substrate for algae and

fungal spores to anchor. Over time, this community transitions into a mature, highly resilient structure known as a biofilm.¹¹ A biofilm is not simply a loose accumulation of slime; it is a sophisticated, cooperative community of microorganisms entirely enclosed within a protective, self-generated Extracellular Polymeric Substance (EPS) matrix.¹³

The EPS matrix serves multiple pathological functions within an HVAC system. Foremost is its remarkable chemical resistance. The dense EPS gel is highly impermeable, allowing the embedded bacterial and fungal colonies (frequently featuring pathogenic strains of *Aspergillus*, *Stenotrophomonas*, and *Exophiala*) to develop robust resistance to host defenses, standard household detergents, and mild disinfectants.¹² Application of basic sodium hypochlorite (bleach), for instance, may kill superficial spores on the surface but fundamentally fails to penetrate a mature EPS matrix, allowing the core colony to survive and rebound rapidly within days.¹⁶

Furthermore, the biofilm acts as a profound thermal insulator. Advanced thermodynamic investigations reveal that the thermal conductivity of a hydrated microbial biofilm is approximately 0.6 W/m-K, which is nearly identical to that of standing water.¹⁷ While water is a poorer insulator than trapped air, a thick, consistent layer of biofilm spanning the entire primary heat exchange surface introduces a massive thermal barrier that significantly depresses the heat transfer coefficient. Additionally, the sticky nature of the EPS matrix aggressively captures passing dust, pollen, and airborne grease, accelerating the mechanical bridging between coil fins and locking moisture into the condensate lines, which reliably leads to biological drain blockages.¹⁴

Grease Accumulation in Commercial Kitchens

In restaurant and commercial kitchen environments, the physical degradation of the coil is heavily exacerbated by lipid accumulation. Despite the presence of primary exhaust hoods, vaporized cooking oils and animal fats inevitably migrate into the ambient air and are drawn into the HVAC return grilles.²⁰ When these hot, volatile organic greases make contact with the chilled surface of the evaporator coil, they immediately condense and undergo polymerization. This creates a highly tacky, hydrophobic layer across the aluminum fins that acts as an aggressive adhesive for airborne dust.²⁰ Unlike water-soluble dirt, polymerized grease repels the natural rinsing action of the system's condensate, leading to a rapid, cement-like blockage of the fin pathways that standard detergents cannot penetrate.

Metallurgical Degradation: Formicary and Galvanic Corrosion

Beyond biological fouling and grease accumulation, the coil substrate itself is under continuous chemical attack. Modern coils typically utilize copper tubing expanded into aluminum fins to maximize heat transfer while minimizing weight and material cost. This bimetallic architecture creates inherent metallurgical vulnerabilities. Microscopic analysis of degraded coils reveals a complex, simultaneous attack occurring on two distinct fronts.

First, galvanic (electrochemical) corrosion occurs at the bimetallic junction.²¹ When two dissimilar metals—copper and aluminum—are placed in direct physical contact in the presence of an electrolyte, a galvanic cell is formed.²¹ The continuous condensation on an evaporator coil

serves as this electrolyte. In coastal, industrial, or heavily polluted environments where the condensate absorbs airborne salts or chlorides, the electrical conductivity of the moisture increases, drastically accelerating the reaction.²¹ Because aluminum is the more anodic (reactive) metal in this pairing, the aluminum fins act as a sacrificial anode. Over time, the fins exhibit heavy white oxidation, pitting, and literally crumble away, severing the vital thermal bond with the copper tube and permanently destroying the coil's ability to transfer heat.²² Simultaneously, the copper tubing itself is subjected to formicary corrosion.⁷ Airborne Volatile Organic Compounds (VOCs)—emanating from building materials, adhesives, cleaning agents, and cosmetics—are drawn into the return air stream. As these organic compounds interact with the wet coil, they undergo hydrolysis, forming weak organic acids (such as formic or acetic acid).⁷ These acids relentlessly attack the copper, creating microscopic, branching "ant-nest" tunnels deep within the tube wall.²¹ Because formicary corrosion occurs beneath the surface of the metal, it is often invisible to the naked eye, hidden beneath the translucent green and yellow layers of the EPS biofilm matrix, until the tunnels breach the interior pipe wall, resulting in slow, continuous, and irreparable refrigerant leaks.⁷

2. Cleaning Chemistry: Formulations and Interactions

The mechanical removal of surface debris via brushing is entirely insufficient for restoring a heavily fouled evaporator coil. To dissolve the EPS matrix, saponify embedded grease, and neutralize acidic deposits without destroying the delicate metal substrate, highly engineered chemical formulations are required. Coil cleaning chemistry is categorized into alkaline-based, acid-based, and enzymatic/biological cleaners. The selection, dilution, and application of these chemicals require a rigorous understanding of metallurgical compatibility and indoor safety protocols.

Alkaline-Based Cleaners (Sodium and Potassium Hydroxide)

Alkaline coil cleaners primarily utilize Potassium Hydroxide (KOH) or Sodium Hydroxide (NaOH) as their active ingredients.²⁴ High-quality formulations often favor potassium hydroxide due to its higher solubility in water, which allows for significantly faster and more complete rinsing—a vital characteristic when attempting to flush chemical residue out of dense, multi-row coil beds.²⁴

In heavy, concentrated dilutions, alkaline cleaners are highly reactive. They chemically etch the outermost microscopic layer of the aluminum fin.²⁴ This etching reaction actively produces hydrogen gas. The gas generation is trapped by synthetic detergents suspended within the chemical formulation, creating a highly volatile, rapidly expanding foam.²⁴ This thick foam forces itself deep into the center of the coil block, physically pushing embedded particulate matter and biological growth outward toward the surface where it can be rinsed away.²⁴

Alkaline agents are particularly superior at saponification—the chemical process of converting lipids and fats into water-soluble soaps. This makes heavy alkaline cleaners the absolute standard choice for units operating in commercial kitchens, where grease accumulation is the primary mode of failure.²⁰

However, the application of alkaline cleaners requires strict dilution management. While

concentrated alkaline cleaners (e.g., a 1:4 dilution ratio) generate excellent foaming action, they remain highly corrosive and pose severe risks if applied improperly to indoor evaporators.²⁴ An indoor evaporator coil is inherently difficult to rinse completely. If a heavy alkaline cleaner is applied indoors and not 100% neutralized, the subsequent operation of the system will draw condensate moisture out of the remaining residue.²⁴ This concentrates the residual hydroxide to extreme pH levels, leading to rapid pitting, electrolytic corrosion, and ultimately, total coil failure.²⁴ Therefore, for indoor applications, alkaline cleaners must be highly diluted (e.g., 1:20 ratio). At high dilutions, the solution loses its ability to actively etch the aluminum and produce hydrogen foam, acting instead as a mild, high-pH detergent that breaks down surface tension and dissolves light organic soils safely.²⁴

Acid-Based Cleaners (Phosphoric and Citric Acid)

When discussing acid cleaners, a strict delineation must be made between highly dangerous outdoor condenser acids and safer indoor formulations. Heavy-duty condenser cleaners rely on Hydrofluoric Acid (HF) or Ammonium Bifluoride (ABF).²⁴ These chemicals are violently corrosive, produce explosive hydrogen gas, and carry severe toxicity hazards; they must never, under any circumstances, be applied to an indoor evaporator coil.²⁴

For indoor evaporator coils requiring acidic treatment, the industry relies exclusively on Phosphoric Acid or Citric Acid-based formulations.²⁸ Phosphoric acid is an excellent descaling agent that effectively dissolves hard water mineral deposits, calcium carbonate scales, and heavy oxidation from the aluminum fins without the violent, exothermic gas production associated with hydrofluoric acid.²⁸ Phosphoric acid cleaners are chemically compatible with both aluminum fins and copper tubes, provided they are thoroughly rinsed with copious amounts of clean water immediately following the recommended dwell time.²⁸ These acids restore the bright, reflective finish of the metal, maximizing the surface area available for heat transfer.

Enzymatic, Biological, and Environmental Cleaners

For routine maintenance of indoor evaporator coils, the industry is increasingly shifting toward pH-neutral, enzymatic, or bio-active cleaners. These sophisticated formulations do not rely on metal etching, extreme pH shifts, or hydrogen gas generation.²⁴ Instead, they utilize specifically engineered enzymes (such as lipases for fats and proteases for proteins) designed to break the molecular bonds of the EPS biofilm matrix, completely dissolving biological growth and organic soils without risking any metallurgical damage to the aluminum or copper.

Because they are fundamentally non-corrosive, many enzymatic and biological cleaners are designed as "no-rinse" formulations.²⁸ Once applied via a low-pressure sprayer, the chemicals require a designated contact time (typically 7 to 10 minutes) to break down the biofilm structure.³¹ After the dwell time, the HVAC unit is re-energized. The natural production of condensate water across the cold evaporator coil gently and continuously rinses the dissolved debris, deactivated microbes, and the neutralizer down into the primary drain pan.³¹

Furthermore, modern facility management increasingly demands adherence to green building

standards. Chemical manufacturers now provide formulations that are explicitly VOC-free (Volatile Organic Compounds) and 100% biodegradable.²⁶ Utilizing VOC-free chemicals is particularly critical in healthcare facilities, schools, and commercial offices, where the introduction of aerosolized solvents into the supply air stream can trigger severe respiratory reactions among occupants.

3. Step-by-Step Cleaning Procedures by System Architecture

The physical architecture of the HVAC system dictates the complexity of the cleaning procedure. Technicians must balance the need for thorough chemical penetration against the risk of catastrophic water damage to surrounding electronics, interior finishes, and the structural integrity of the delicate aluminum fins.

Hydrodynamic Limits: Protecting the Fin Geometry

Regardless of the system type being serviced, applying liquid at high velocity is hazardous. The thin aluminum fins are highly susceptible to mechanical deformation.⁷ If an uncalibrated commercial pressure washer is used, the kinetic energy of the water jet will instantly fold the fins flat against the copper tubes, permanently destroying the aerodynamic airflow pathway and ruining the coil.³⁰

Strict hydrodynamic limits must be observed. Rinsing should only be performed with low-pressure delivery systems—strictly under 200 PSI, and ideally utilizing specialized, battery-operated HVAC coil sprayers outputting between 100 and 130 PSI.³⁰ The spray nozzle must maintain a minimum fan angle of 15 degrees, and the flow must always be directed perfectly parallel to the fin grain, never obliquely.³⁰

Wall-Mounted Split Indoor Units

Wall-mounted ductless split systems are ubiquitous in residential and light commercial applications. Cleaning these units requires specific containment strategies.

1. **Preparation and Disassembly:** Isolate electrical power. For a superficial clean, the outer casing may remain on, but for a comprehensive service, the entire plastic fascia, directional air louvers, and the primary condensate drain pan should be removed to expose the blower wheel and the rear sections of the coil.³⁶
2. **Dry Evacuation:** Before applying any liquids, use a soft-bristle brush and a high-efficiency particulate air (HEPA) vacuum to remove bulk, dry dust from the leading edge of the coil.³⁶ Adding liquid to a heavy layer of dry dust creates a cement-like mud that is exponentially harder to drive out of the fin pack.
3. **Containment:** A specialized, watertight catch-bib or funnel hood is strapped tightly around the chassis of the unit. This containment system channels all chemical runoff and rinse water safely into an external bucket, protecting the client's walls, electronics, and flooring.
4. **Chemical Sequence:** Apply the diluted enzymatic or mild alkaline cleaner using a low-pressure foaming wand. Crucially, the technician must work systematically from the

bottom of the coil to the top. Bottom-up application prevents the liquid cleaner from quickly running down over dry sections, ensuring maximum contact time (dwell time) across the entire surface area of the metal.²⁶ After the 10-minute dwell time, rinse thoroughly top-to-bottom with low-pressure water.

Cassette Units (4-Way Blow Ceiling Cassettes)

Ceiling cassettes present unique challenges due to their horizontal orientation and integrated condensate pumps.

1. **Fascia and PCB Protection:** Remove the central return grille, the filters, and the entire square aesthetic fascia. The Printed Circuit Board (PCB) is typically housed in a corner compartment; this must be heavily wrapped in waterproof plastic sheeting.
2. **Pump Evacuation:** Cassettes rely on an internal mechanical condensate pump to lift water out of the unit. Before applying large volumes of water, the technician must locate the manual drain plug on the pan and empty the standing water. Failing to do so can cause the pan to overflow during the cleaning process, or force harsh chemicals through the pump impeller, degrading its seals.
3. **Circular Application:** The coil in a cassette is often formed in a continuous square or circle. Chemicals must be applied radially, ensuring penetration into the deep corners where airflow is typically the lowest and biological buildup is the highest.

Concealed Ducted Units

Concealed ducted evaporators are hidden within ceiling plenums, making access notoriously difficult.

1. **Access Constraints:** Technicians must access the coil through dedicated ceiling hatches. Often, the return air plenum must be partially dismantled to view the upstream face of the coil.
2. **Static Pressure Considerations:** Because these units are connected to ductwork, they operate under higher static pressure than ductless units. Ensure that all access panels are hermetically resealed after cleaning. A loose access door will allow the blower to bypass the coil entirely, sucking hot, unfiltered ceiling cavity air directly into the supply duct.

VRF Indoor Units and Electronic Expansion Valve (EEV) Protection

Variable Refrigerant Flow (VRF) indoor units present a highly specialized maintenance challenge due to the presence of embedded Electronic Expansion Valves (EEVs). Unlike traditional mechanical Thermostatic Expansion Valves (TXVs), an EEV utilizes a precise, bipolar stepper motor to regulate refrigerant superheat and subcooling. Depending on the system capacity and operational mode, the main controller commands the EEV to open or close in minute volumetric increments, typically ranging from 0 to 500 pulses, or up to 2000 pulses in larger capacity modules.³⁸

The EEV assembly consists of two distinct components: the hermetically sealed brass valve body (which is brazed directly into the refrigerant piping) and the removable electromagnetic

stepper motor coil (the stator) that slips over the top of the valve body.⁴² During coil cleaning, the application of water and liquid chemicals poses a severe, immediate risk to the EEV. If moisture, conductive chemical residue, or dislodged biological slime penetrates the microscopic gap between the stepper motor and the valve body, or infiltrates the wiring harness, it can cause immediate electrical short circuits, loss of precise step calibration, or mechanical seizing of the internal needle.⁴⁵ A failed or seized EEV will either starve the coil of refrigerant (triggering low-pressure freeze-protection lockouts) or flood the compressor with liquid refrigerant.⁴⁶

VRF Cleaning Protocol:

1. **De-energize and Isolate:** Disconnect all electrical power to the indoor unit to prevent controller faults.⁴⁸
2. **Motor Removal:** Locate the EEV adjacent to the evaporator distributor. Carefully cut away any manufacturer-applied sound-dampening insulation or zip ties. Grasp the stepper motor coil and rotate it counter-clockwise while pulling upward to detach it completely from the valve body.⁴⁸
3. **Waterproofing:** Place the removed stepper motor inside a watertight plastic bag and secure it well away from the intended splash zone.
4. **Valve Body Restoration:** Inspect the exposed brass valve body. It is critical to clean this component independently. Use a fast-drying electronic contact cleaner (electro-cleaner) spray to blast away any oxidation, silicone adhesive residue, or moisture from the valve pin and exterior body. Wipe the assembly completely dry with a clean microfiber cloth.⁴⁸
5. **Coil Cleaning:** Proceed with the standard low-pressure evaporator coil cleaning sequence, ensuring the exposed brass EEV body is physically shielded from direct chemical spray.
6. **Reassembly:** Once the entire area is completely dry, remount the stepper motor onto the valve body, ensuring it clicks or locks firmly into its designated mechanical keyway. Screw it clockwise without over-tightening, and meticulously reapply the thermal and acoustic insulation.⁴⁸

Walk-In Cooler and Freezer Evaporators

Commercial refrigeration evaporators operate in a distinctly different thermodynamic regime than standard air conditioning units. Walk-in freezers must maintain ambient temperatures around 0°F (-18°C) to satisfy FDA requirements and inhibit pathogen growth in stored food products.²⁰ At these temperatures, the evaporator coil operates well below the freezing point of water, meaning airborne moisture continuously sublimates directly into solid frost on the fins.²⁰ Standard maintenance for low-temperature coils heavily involves mitigating this severe frost accumulation. Every freezer is equipped with a defrost mechanism—typically high-wattage electric resistance heaters strapped directly to the face and rear of the coil block.⁵⁰

Low-Temperature Maintenance Protocol:

1. **Defrost Diagnostics:** Before cleaning can commence, force the system into a manual defrost cycle. Verify that the defrost heaters draw the correct electrical amperage and

that the defrost termination thermostat accurately registers a rise in coil temperature. The thermostat must typically terminate the cycle only when the coil reaches 55°F to ensure all deep ice has cleared.⁵¹

2. **Ice Clearing:** If the coil is impacted into a solid block of ice (often caused by a failed defrost timer, a burned-out heater element, or a bypassed fan), it must be completely melted before chemical cleaning can begin. Technicians must *never* use sharp mechanical tools (like ice picks or flathead screwdrivers) to chip ice away from the fins, as this almost guarantees a punctured copper tube and a catastrophic loss of refrigerant. Instead, use low-pressure hot water or a commercial heat gun applied constantly across the surface to melt the blockage safely.⁵⁰
3. **Chemical Application:** Use only food-safe, non-acidic, FDA-approved coil cleaners in walk-in environments.²⁶ Apply the cleaner, brush the fins vertically with a soft brush, and flush thoroughly with clean water.
4. **Drain Line Heaters:** Low-temperature units feature an exposed condensate drain line that is highly susceptible to freezing. Inspect the drain line heater cable wrapped around the piping. A failed heater cable will allow meltwater from the defrost cycle to freeze solid inside the pipe, causing subsequent cycles to overflow the pan and cascade water onto the freezer floor, creating severe slip hazards and structural damage.⁵⁰
5. **Fan Delay Verification:** Upon system restart, verify the operation of the fan delay thermostat. The evaporator fans must remain locked out until the coil temperature drops back down to approximately +20°F. If the fans start immediately after a hot defrost cycle, they will blow warm, humid air and residual water droplets directly onto the frozen food product, causing freezer burn and spoilage.⁵⁶

4. Mechanical Fin Restoration and Component Longevity

The aerodynamic efficiency of the coil relies heavily on the geometric perfection of the aluminum fins. Bent or crushed fins—resulting from improper high-pressure washing, accidental mechanical impacts during filter changes, or hail damage on packaged rooftop units—create localized dead zones where air cannot pass, severely degrading heat transfer.³⁴

Fin Comb Restoration

Bent fins can be mechanically realigned using a specialized hand tool known as a fin comb. These tools feature precise, tooth-like projections designed to slide between the fins and lever them back into a parallel alignment.⁶⁰

Selecting the correct comb is paramount. Fin combs are highly specific to the FPI (Fins Per Inch) of the coil and are often color-coded for rapid identification in the field. For example, a yellow comb might align specifically with 9 and 15 FPI coils, while a red comb corresponds to the much tighter 18 and 20 FPI micro-channel coils.⁶⁰ Forcing an incorrectly sized comb through the fin pack will irreparably tear the soft aluminum.

The restoration technique must be performed meticulously. Technicians insert the comb into an undamaged section of the fin grain, slightly above or below the crushed area, and draw the

tool smoothly and slowly through the damaged zone.⁵⁹ Plastic fin combs are generally safer for routine grooming and dust removal.⁶¹ However, adjustable stainless-steel combs offer higher mechanical rigidity for prying up severely flattened sections, though they carry a significantly higher risk of scarring the metal or inadvertently puncturing the underlying copper tube if excessive force is applied.⁶¹

The Repair vs. Replacement Economic Threshold

Extensive fin damage, profound formicary corrosion, or repeated micro-leaks eventually push the coil past the point of viable maintenance. The HVAC industry relies on a standard economic lifecycle management metric to dictate replacement: if the projected cost of repairing the evaporator coil (which includes the labor of leak searching, brazing, chemical flushing, evacuation, and the increasingly expensive refrigerant recharge) exceeds 30% to 40% of the cost of a complete new system replacement, the coil should be condemned.⁷

Furthermore, physical degradation sets absolute limits on repairability. If more than 20% of the total coil face area exhibits severely crushed fins that cannot be combed, or if the bimetallic junctions show heavy, pervasive white oxidation indicating severe galvanic degradation, the aerodynamic and thermodynamic losses are permanent. In these scenarios, even if the coil is not actively leaking refrigerant, the loss of sensible cooling capacity and the spike in fan energy consumption justify a complete coil replacement.⁷

5. Biological Suppression and Antimicrobial Treatments

Chemically cleaning the coil effectively returns the system to its baseline condition, but the inherently dark, humid environment of the AHU will inevitably foster rapid microbiological recolonization. Preventive biological suppression is required to extend maintenance intervals and protect indoor air quality.

Antimicrobial Surface Coatings

Immediately post-cleaning, when the fins are bare and dry, the application of EPA-registered fungistatic and bacteriostatic coatings provides a vital residual chemical barrier against biofilm formation.¹² These specialized aerosol polymers bond directly to the aluminum fins at a molecular level, altering the surface tension to create a hydrophobic layer. This layer physically repels moisture and denies fungal spores the stationary anchor points they require to establish a new colony.¹² Because the continuous, high-volume flow of condensate water over the fins eventually erodes these chemical coatings, they are not permanent and must be reapplied during scheduled biannual or annual maintenance intervals.

UV-C Germicidal Irradiation (UVGI)

For high-risk environments where airborne pathogens pose a severe threat (such as surgical suites, pharmaceutical cleanrooms, and high-occupancy commercial offices), passive chemical coatings are often supplemented with active Ultraviolet Germicidal Irradiation (UVGI).¹⁰

UV-C lamp systems, engineered to emit radiation specifically at the 254-nanometer wavelength, are mounted permanently inside the AHU, shining continuously on the discharge face of the evaporator coil and the condensate pan.¹⁰ The physics of UVGI are highly effective: photons at the 254nm frequency penetrate the cell walls of passing bacteria, viruses, and established mold spores, aggressively disrupting their DNA and RNA sequencing by forming thymine dimers. This photolytic destruction completely prevents the microorganisms from replicating. By continuously bathing the coil in UV-C light, the system effectively sterilizes the surface and entirely inhibits the reformation of the EPS biofilm matrix, all without introducing harmful ozone or aerosolized volatile chemicals into the building's airstream.¹⁰

6. Condensate Management: Drain Pans and P-Traps

The primary byproduct of the evaporator coil's latent cooling capacity is the extraction of a massive volume of condensate water from the air. The hygienic management and efficient hydrodynamic evacuation of this water are as critical to system health as the coil maintenance itself.

Pan Sanitization and Bioslime Eradication

The condensate drain pan, situated directly beneath the coil block, catches all liquid runoff. If the coil is fouled, the organic debris, dust, and bacterial colonies wash directly into the pan, creating a stagnant pool of nutrient-rich water. This environment leads to profound, rapid growth of algae and highly viscous *Zoogloea* slime, which quickly migrates to the drain orifice and causes severe blockages.⁷

During maintenance, the pan must be aggressively scrubbed with a biocide and fully evacuated using a commercial wet-vacuum to remove all standing sludge.¹² To prevent interim blockages between service visits, slow-release algaecide and biocide tablets (often formulated with potent quaternary ammonium compounds) are placed in the pan near the drain outlet. As condensate water flows over the tablets, it dissolves a precise dosage of the chemical, providing continuous sanitization of the standing water.³⁴ Additionally, the condensate pump float switch must be manually actuated by the technician to ensure the electromechanical pump engages properly before the pan level rises to an overflow condition.¹²

The Hydrodynamics of the P-Trap

The condensate drain line must feature a properly engineered P-trap. In draw-through AHU configurations (where the blower fan is located downstream of the evaporator coil), the coil section operates under significant negative static pressure.⁶² Without a functional P-trap filled with water to act as a seal, the negative pressure acts as a powerful vacuum, sucking ambient air backward up the drain pipe and into the unit. This high-velocity counter-flow of air physically prevents the water from draining downward by gravity, causing the pan to overflow catastrophically into the building.⁶²

The depth of the P-trap is not an arbitrary plumbing decision; it is governed by a strict hydrodynamic formula based on the system's maximum external static pressure (measured in inches of water column, "WC"):

Minimum P-Trap Seal = Static Pressure (inches WC) × 1.5 + 1" ⁶⁴

For a standard commercial rooftop unit operating at 1.0" WC of external static pressure, the trap must provide a minimum liquid seal depth of 2.5 inches.⁶² Deeper traps are required for high-static systems. During preventive maintenance, technicians must visually inspect the trap for cracks, flush it with high-pressure water to clear accumulated biological slime, and manually prime it with clean water before restarting the system to re-establish the critical pneumatic seal.³⁴

7. PMOC Compliance, Photographic Evidence, and Maintenance Schedules

In modern facility management, executing the physical maintenance is only half the mandate; the execution must be rigorously documented to satisfy legal, environmental, and public health regulations.

Regulatory Mandates: The PMOC Framework

In specific international jurisdictions, the maintenance of commercial air conditioning systems is governed by strict federal legislation. A prime example is Brazil, where facilities operating HVAC systems with a cumulative capacity equal to or greater than 60,000 BTU/h (5 TR) are legally mandated to implement a formal Maintenance, Operation, and Control Plan (PMOC – *Plano de Manutenção, Operação e Controle*).⁶⁶

This stringent requirement is enforced by the Ministry of Health (Portaria 3.523/1998) and the National Health Surveillance Agency (ANVISA Resolução RE-09/2003).⁶⁶ The PMOC dictates specific, non-negotiable procedural frequencies, including the thorough chemical washing of evaporator coils, the verification of all electromechanical controls, and the biocide treatment of the condensate system.⁷² Furthermore, the PMOC must be overseen by a legally responsible technical professional (typically a mechanical engineer registered with the CREA board). Non-compliance with the PMOC documentation requirements and failure to maintain ANVISA RE-09 indoor air quality parameters can result in severe financial penalties levied by local health surveillance centers (such as the CVS in São Paulo), business interdiction, and potential civil and criminal liability in the event of an indoor airborne pathogen outbreak.⁶⁸

Photographic Evidence Standards

To definitively prove adherence to PMOC requirements and validate contractor performance to the client, detailed photographic documentation is absolutely mandatory.⁶⁶ Technicians must adhere to specific evidentiary standards when generating these reports:

- **The "Before/After" Imperative:** Photographs must be taken from the exact same vantage point before chemical application and immediately after the final rinse to demonstrate the efficacy of the cleaning.
- **Lighting and Angles:** Due to the inherently dark environments inside air handling units, high-lumen, broad-spectrum LED work lights must be utilized to illuminate the depth of the coil bed. Photos should be taken at an oblique angle (roughly 45 degrees) to the fin

face. Straight-on flash photography often washes out the image and fails to capture the depth of biological bridging between the fins.

- **Comprehensive Component Verification:** The photographic report must explicitly include close-up evidence of the sanitized condensate pan, the cleared and primed P-trap, and a macroscopic view of the straightened aluminum fins following comb restoration.³⁴

Strategic Maintenance Intervals

The frequency of evaporator coil maintenance cannot be universally standardized; it must be dynamically tailored to the specific environmental load and operational criticality of the facility. The following table outlines the industry-standard recommended intervals based on environment type:

Facility / Environment Type	Evaporator Cleaning Interval	Chemical Selection Protocol	Primary Operational Risk Factor
Healthcare / Hospitals	Monthly to Quarterly	Enzymatic (No-Rinse) + Continuous UV-C UVGI	Nosocomial pathogen aerosolization
Commercial Kitchens	Monthly	Diluted Alkaline (High pH KOH/NaOH)	Saponification of dense, polymerized grease layers
Data Centers	Biannually	Enzymatic (Dry-brush first, highly limited water)	Dust fouling; severe risk of water damage to servers
Coastal Environments	Quarterly	Mild Alkaline + Protective Hydrophobic Coatings	Galvanic oxidation of aluminum fins from saline intake
Standard Commercial Office	Biannually	Enzymatic or Mild Alkaline	Formicary corrosion from indoor VOC accumulation
Residential	Annually	Enzymatic	Basic

(Split/Unitary)		(Self-rinsing formulations)	particulate/dust and pet dander accumulation
-----------------	--	-----------------------------	--

The maintenance of an HVAC/R evaporator coil transcends basic mechanical servicing; it requires an integrated approach encompassing thermodynamics, microbiology, and applied chemistry. Recognizing that system degradation is primarily driven by the aerodynamic blockage caused by EPS biofilms and particulate bridging allows technicians to prioritize interventions that restore total volumetric airflow. By carefully selecting chemical agents based on strict metallurgical compatibility, enforcing hydrodynamic limits during rinsing, and adhering to rigorous PMOC documentation standards, facility managers can safeguard indoor air quality and maximize the operational lifecycle of critical refrigeration assets.

Referências citadas

1. AIR-TO-AIR ENERGY RECOVERY EQUIPMENT - ASHRAE, acessado em junho 13, 2026, https://www.ashrae.org/file%20library/technical%20resources/covid-19/si_s20_ch26.pdf
2. Equations, Data, and Rules of Thumb | HVAC, acessado em junho 13, 2026, <https://hvacvn.com/wp-content/uploads/2015/10/hvac-equations-data-and-rules-of-thumb.pdf>
3. The Impact of Evaporator Fouling on the Performance of Packaged Air Conditioners - Purdue e-Pubs, acessado em junho 13, 2026, <https://docs.lib.purdue.edu/cgi/viewcontent.cgi?article=1686&context=iracc>
4. THE ROLE OF FILTRATION IN MAINTAINING CLEAN HEAT EXCHANGER COILS - OSTI.GOV, acessado em junho 13, 2026, <https://www.osti.gov/servlets/purl/833362>
5. Fouling and Its Effects on Air-cooled Condensers in Split System Air Conditioners (RP-1705), acessado em junho 13, 2026, <https://www.tandfonline.com/doi/full/10.1080/23744731.2019.1605197>
6. Final Report - CALMAC.org, acessado em junho 13, 2026, <https://www.calmac.org/publications/2028.pdf>
7. Evaporator Coil Issues in HVAC Systems: Repair and Replacement, acessado em junho 13, 2026, <https://hvacrepairauthority.com/hvac-evaporator-coil-repair>
8. Sensitivity Analysis of Installation Faults on Heat Pump Performance - NIST Technical Series Publications, acessado em junho 13, 2026, <https://nvlpubs.nist.gov/nistpubs/TechnicalNotes/NIST.TN.1848.pdf>
9. How To Clean And Check AC Evaporator Coils After A Freeze Up - YouTube, acessado em junho 13, 2026, <https://www.youtube.com/watch?v=F07sbwZgcsI>
10. Mold/Bacteria Protection of an Air Conditioner Coil \$ - RGF Environmental Group, acessado em junho 13, 2026, <https://www.rgf.com/wp-content/uploads/2016/03/HVAC-Coil-article-reader.pdf>
11. Bacterial and fungal ecology on air conditioning cooling coils is influenced by

- climate and building factors - PubMed, acessado em junho 13, 2026,
<https://pubmed.ncbi.nlm.nih.gov/31845419/>
12. Biofilm in HVAC Systems: What It Is and How to Get Rid of It, acessado em junho 13, 2026,
<https://haderhvac.com/blog/biofilm-in-hvac-systems-what-it-is-and-how-to-get-rid-of-it/>
 13. Biofilm Growth in Commercial HVAC Systems - Power Vac America, acessado em junho 13, 2026,
<https://powervacamerica.com/biofilm-growth-in-commercial-hvac-systems/>
 14. Zoogloea Slime Removal for Oviedo AC Systems - R&A Industries, acessado em junho 13, 2026,
<https://randaindustries.com/blog/zoogloea-slime-removal-services-oviedo/>
 15. PNNL-23265, acessado em junho 13, 2026,
https://www.pnnl.gov/main/publications/external/technical_reports/PNNL-23265.pdf
 16. How to Tell If There's Mold in Your Air Conditioner: 7 Evidence-Based Signs - LifeTips, acessado em junho 13, 2026,
<https://lifetips.alibaba.com/tech-efficiency/how-to-tell-if-there-s-mold-in-your-air-conditioner-a>
 17. Using Thermal Shock to Inhibit Biofilm Formation in the Treated Sewage Source Heat Pump Systems - ResearchGate, acessado em junho 13, 2026,
https://www.researchgate.net/publication/315928494_Using_Thermal_Shock_to_Inhibit_Biofilm_Formation_in_the_Treated_Sewage_Source_Heat_Pump_Systems
 18. Assessment of the Impact of Temperature on Biofilm Composition with a Laboratory Heat Exchanger Module - PMC, acessado em junho 13, 2026,
<https://pmc.ncbi.nlm.nih.gov/articles/PMC8229324/>
 19. (PDF) In Situ Biofilm Monitoring Using a Heat Transfer Sensor: The Impact of Flow Velocity in a Pipe and Planar System - ResearchGate, acessado em junho 13, 2026,
https://www.researchgate.net/publication/388760580_In_Situ_Biofilm_Monitoring_Using_a_Heat_Transfer_Sensor_The_Impact_of_Flow_Velocity_in_a_Pipe_and_Planar_System
 20. Commercial Freezer Maintenance | Tips & Best Practices - GoFoodservice, acessado em junho 13, 2026,
<https://www.gofoodservice.com/blog/keep-it-clean-a-simple-guide-on-how-to-maintain-a-commercial-freezer>
 21. Preventing Coil Corrosion: Tips for Humid or Coastal Homes - The Furnace Outlet, acessado em junho 13, 2026,
<https://thefurnaceoutlet.com/blogs/hvac-tips/preventing-coil-corrosion-tips-for-humid-or-coastal-homes>
 22. What's Eating You? - Ecotech, acessado em junho 13, 2026,
<https://www.ecotech-hvacr.com/post/what-s-eating-you>
 23. Coil Corrosion Causes and Reduction | Just Venting - Goodway Technologies, acessado em junho 13, 2026,
<https://www.goodway.com/hvac-blog/2018/11/coil-corrosion-causes-and-reducti>

- [on/](#)
24. Different Types of Coil Cleaners – HB, acessado em junho 13, 2026,
<https://hydrobalance.com/different-types-of-coil-cleaners-2/>
 25. QV Catalog_1-14.indd – Winsupply, acessado em junho 13, 2026,
https://pimmedia.winsupplyinc.com/pim/CUT/062018/VAPCO_6606_VAP6606_CU T.pdf
 26. Safe, user-friendly, non-toxic HVACR chemicals – SuperCool, acessado em junho 13, 2026,
https://www.supercool.com.au/wp-content/uploads/2023/11/Viper_Catalogue_2020_Rev-1.05082020_WEB.pdf
 27. ALUMINUM COIL CLEANING APPROVED CLEANERS' LIST – HVACDirect.com, acessado em junho 13, 2026,
<https://hvacdirect.com/media/hvac/pdf/ARUF-Tech-Pub.pdf>
 28. Con-Coil Acid-Based Foaming Coil Cleaner – Removes Dirt & Oxides – MRCOOL DIY Direct, acessado em junho 13, 2026,
<https://mrcooldiymdirect.com/products/con-coil-acid-based-coil-cleaner>
 29. COIL CLEANER – Athea Laboratories, acessado em junho 13, 2026,
<https://www.athea.com/products/coil-cleaner/>
 30. Top 5 Maintenance Tasks for Ensuring Your HVAC Ducts Operate at Peak Performance, acessado em junho 13, 2026,
<https://www.ussupply.com/maintenance-tasks-for-ensuring-your-hvac-ducts-operate-at-peak-performance>
 31. Coil Cleaners: A Guide to Which Cleaners to Use in Various Applications – HVAC School, acessado em junho 13, 2026,
<http://www.hvacschool.com/coil-cleaners-a-guide-to-which-cleaners-to-use-in-various-applications/>
 32. Page 3-27 Acid cleaners, Bowl cleaners, Drain Openers, Concrete Truck Cleaners, Truck Trailer Cleaners 28-80 Aerosols, Battery c – Lyn Distributing, acessado em junho 13, 2026, https://www.lyndist.com/Lyn_Distributing_literature_2012b.pdf
 33. Condenser Coil Repair and Cleaning in HVAC Systems, acessado em junho 13, 2026, <https://hvacrepairauthority.com/hvac-condenser-coil-repair>
 34. Cooling & Heating Coil Maintenance Checklist (HVAC Efficiency Guide) – Oxmaint, acessado em junho 13, 2026,
<https://oxmaint.com/industries/hvac/cooling-heating-coil-maintenance-checklist-hvac-efficiency>
 35. Horizon™ Outdoor Air Unit – Trane, acessado em junho 13, 2026,
https://www.trane.com/content/dam/Trane/Commercial/global/products-systems/equipment/unitary/dedicated-air-solutions/OAU-SVX007C-EN_11082023.pdf
 36. How to Clean Evaporator Coils and Why – Trane®, acessado em junho 13, 2026,
<https://www.trane.com/residential/en/resources/troubleshooting/air-conditioners/how-to-clean-evaporator-coils/>
 37. How To Clean AC Coils | AC Coil Cleaner Tips & Maintenance – Carrier, acessado em junho 13, 2026,
<https://www.carrier.com/us/en/residential/hvac-resources/air-conditioners/ac-coil-cleaner-tips/>

38. HVAC Multi-Split Variable Refrigerant Flow (VRF) Systems - PDH Online, acessado em junho 13, 2026, <http://www.pdhonline.com/courses/m394/m394content.pdf>
39. HVAC Variable Refrigerant Flow (VRF) Systems - CEDengineering.com, acessado em junho 13, 2026, [https://www.cedengineering.com/userfiles/M03-014%20-%20HVAC%20Variable%20Refrigerant%20Flow%20\(VRF\)%20Systems%20-%20US.pdf](https://www.cedengineering.com/userfiles/M03-014%20-%20HVAC%20Variable%20Refrigerant%20Flow%20(VRF)%20Systems%20-%20US.pdf)
40. Service Manual - Carrier, acessado em junho 13, 2026, <https://www.shareddocs.com/hvac/docs/1001/Public/07/40VM-3SM.pdf>
41. Service Manual - Trane, acessado em junho 13, 2026, https://www.trane.com/content/dam/Trane/Commercial/lar/br/produtos-sistemas/equipamentos/Sistema_VRF/tvr-ultra/tvr-ultra---heat-recovery/manual-t%C3%A9cnico/outdoor-unit/TVR-Ultra-HR-Service-Manual-20210707.pdf
42. EEV Troubleshooting in 3D: A Guide for HVAC Techs - YouTube, acessado em junho 13, 2026, <https://www.youtube.com/watch?v=fd0kGzOXckE>
43. Electric Expansion Valve (EEV) Operation and Testing! HVAC Metering Device Training!, acessado em junho 13, 2026, <https://www.youtube.com/watch?v=LzvVjvUpOVM>
44. LEV/EEV Electric Expansion Valve Operation and Troubleshooting! HVAC Metering Devices! - YouTube, acessado em junho 13, 2026, https://www.youtube.com/watch?v=B_j73X0gxC0
45. Trane eev : r/HVAC - Reddit, acessado em junho 13, 2026, https://www.reddit.com/r/HVAC/comments/1dh8xtq/trane_eev/
46. Electronic Expansion Valve Troubleshooting - HVAC School, acessado em junho 13, 2026, <http://www.hvacrschool.com/electronic-expansion-valve-troubleshooting/>
47. VRF Not Cooling | Common Causes & What to Do, acessado em junho 13, 2026, <https://mountainmechanicalny.com/vrf-systems/vrf-not-cooling/>
48. Tutorial - Daikin - Cleaning EEV - YouTube, acessado em junho 13, 2026, https://www.youtube.com/watch?v=WFR0_3dDMXI
49. Comparison of parallel- and counter-flow circuiting in an industrial evaporator under frosting conditions, acessado em junho 13, 2026, <https://irc.wisc.edu/export.php?ID=189>
50. Walk in freezer best way to de-ice : r/HVAC - Reddit, acessado em junho 13, 2026, https://www.reddit.com/r/HVAC/comments/18t2mto/walk_in_freezer_best_way_to_deice/
51. Cold Storage Maintenance Best Practices for Food Processing Facilities, acessado em junho 13, 2026, <https://oxmaint.com/industries/food-manufacturing/cold-storage-maintenance-food-processing>
52. Commercial Walk-In Freezer Repair Detroit | Samco FM, acessado em junho 13, 2026, <https://www.samcofm.com/commercial-walk-in-freezer-repair-detroit/>
53. Preventative Maintenance List for Walk-in Refrigeration Systems - U.S. Cooler, acessado em junho 13, 2026, <https://www.uscooler.com/refrigeration-system-maintenance/>
54. Everything You Need to Know About Walk-In Freezer Repair - American Mortuary

- Coolers, acessado em junho 13, 2026,
<https://www.mymortuarycooler.com/blogs/news/everything-you-need-to-know-about-walk-in-freezer-repair>
55. Unit Coolers - Heatcraft Refrigeration Products, acessado em junho 13, 2026,
<https://www.heatcraftpd.com/dA/372b2b9e1e/H-IM-UC-HFC.pdf>
56. Installation, Operation & Maintenance Manual - American Panel, acessado em junho 13, 2026, <http://americanpanel.com/materials/man.pdf>
57. MK/MV Series Medium Profile Unit Coolers Operating and Installation Manual, acessado em junho 13, 2026,
https://www.krack.com/ns/Obsolete-Technical-Documents/MKMOV_Manual.pdf
58. Two-Piece Capsule Pak™ Refrigeration Systems Installation Manual - Norlake, acessado em junho 13, 2026,
<https://norlake.com/wp-content/uploads/2020/08/040086-Refrigeration-Systems-Installation-Manual-Two-Piece.pdf>
59. Service and Maintenance Instructions - Carrier, acessado em junho 13, 2026,
<https://www.sharedocs.com/hvac/docs/1005/Public/OE/48LC-4-6-02SM.pdf>
60. 6-Piece Fin Comb Set – Universal AC Condenser & Evaporator Cleaner & Straightene, acessado em junho 13, 2026,
<https://www.ebay.com/itm/286986147092>
61. Fin Comb Supplier - Miracle, acessado em junho 13, 2026,
<https://www.miracleref.com/fin-comb-supplier/>
62. AHU and Fan Coil Unit Maintenance Checklist: Complete Inspection Guide - Oxmaint, acessado em junho 13, 2026,
<https://oxmaint.com/industries/hvac/ahu-fan-coil-unit-maintenance-checklist>
63. Biofilm in HVAC Systems: Should You Be Worried? | Blog, acessado em junho 13, 2026,
<https://www.coolzoneair.com/blog/hvac/biofilm-in-hvac-systems-should-you-be-worried/>
64. HVAC Roof Curb Height Selection: 14" vs 16" vs 4x4 Rails - Industrial Monitor Direct, acessado em junho 13, 2026,
<https://industrialmonitordirect.com/blogs/knowledgebase/hvac-roof-curb-height-selection-14-vs-16-vs-4x4-rails>
65. Inspection Report: - Thrillshare, acessado em junho 13, 2026,
https://files-backend.assets.thrillshare.com/documents/asset/uploaded_file/4749/Mps/3bd55c6f-102c-4d17-b969-ff65dcb9b680/HVAC_Reports.pdf?disposition=inline
66. PMOC e ART - Exclusivo Ar Climatização, acessado em junho 13, 2026,
<https://exclusivoar.com.br/servicos/pmoc-e-art/>
67. P.M.O.C - Plano de manutenção, operação e controle em sistemas de climatização - NanoAr Ventilação e Antipoluição, acessado em junho 13, 2026,
<https://www.nanoar.com.br/p-m-o-c-plano-de-manutencao-operacao-e-controle-em-sistemas-de-climatizacao>
68. PMOC: Lei 13.589/18 e Portaria 3.523/98 | DYA | DYA, acessado em junho 13, 2026,
<https://www.dyaarclimatizacao.com.br/pmoc-ar-condicionado>
69. RESOLUÇÃO-RE Nº 09, DE 16 DE JANEIRO DE 2003 - Antigo Anvisa, acessado em

junho 13, 2026,

https://antigo.anvisa.gov.br/documents/10181/2718376/RE_09_2003_.pdf/8cca9c91-1437-4695-8e3a-2a97deca4e10

70. RESOLUÇÃO-RE Nº 09 - ANVISA - e Qualidade do Ar, acessado em junho 13, 2026,
<https://microambiental.com.br/analise-de-ar/como-garantir-a-qualidade-do-ar-com-a-resolucao-re-no-09-de-16-de-janeiro-de-2003/>
71. resolução-re nº 9, de 16 de janeiro de 2003 - Ministério da Saúde, acessado em junho 13, 2026,
https://bvsms.saude.gov.br/bvs/saudelegis/anvisa/2003/rdc0009_16_01_2003.html
72. GOVERNO DO ESTADO DO ESPÍRITO SANTO COMPANHIA ESPÍRITO SANTENSE DE SANEAMENTO - CESAN, acessado em junho 13, 2026,
https://compras.cesan.com.br/uploads/40091/ANEXO_VII_DESCRIC3%87%C3%83O%20DOS%20SERVIC3%87OS_NOVO.pdf
73. Análise da Qualidade do Ar em Ambientes Climatizados SP — RE, acessado em junho 13, 2026, <https://esengenharia.com/analise-da-qualidade-do-ar/sao-paulo>
74. Registro Fotográfico PMOC HDT 2023 | PDF - Scribd, acessado em junho 13, 2026,
<https://www.scribd.com/document/786895734/08-2023-relato-rio-fotografico-ar-cond>