

Comprehensive Maintenance and Diagnostic Manual for Variable Refrigerant Flow (VRF) Systems

The advent of Variable Refrigerant Flow (VRF) and Variable Refrigerant Volume (VRV) systems has fundamentally transformed the landscape of commercial and high-end residential climate control. By utilizing the refrigerant itself as the primary heat transfer medium and deploying a highly sophisticated network of microprocessors, electronic expansion valves (EEVs), and variable-speed inverter compressors, these systems achieve unprecedented thermodynamic efficiency and precise zonal control.¹ However, this sophisticated engineering necessitates a total paradigm shift in maintenance and diagnostic methodologies. Standard direct expansion (DX) troubleshooting techniques are frequently inadequate—and occasionally destructive—when applied to a VRF architecture. This manual provides an exhaustive, expert-level framework for the maintenance, diagnostics, and optimization of multi-zone VRF systems.

1. VRF System Architecture Review for Maintenance

To maintain a VRF system effectively, the technician must first understand the implications of its architecture. Unlike decentralized systems where a single compressor serves a single evaporator, a VRF system operates as a massive, interdependent thermodynamic ecosystem. A single outdoor condensing modular array might serve upwards of 64 distinct indoor fan coil units distributed across multiple floors of a commercial structure.³

The Implications of Shared Refrigerant Piping

The most critical maintenance implication of this design is the shared refrigerant piping network. In a conventional system, a catastrophic compressor burnout or a moisture-induced acid formation event is isolated to a single zone. In a VRF system, the entire building shares the same lifeblood. If a careless installation contractor fails to purge the copper lines with oxygen-free dry nitrogen during brazing, cupric and cuprous oxides will form on the interior walls of the piping.⁴ Upon system startup, the high-velocity refrigerant will strip this oxide scale, carrying it through the network where it will inevitably foul the microscopic orifices of dozens of electronic expansion valves and score the bearings of the multi-thousand-dollar inverter compressors.⁴ Therefore, maintaining absolute chemical purity within the piping network is the foundational rule of VRF maintenance.

Heat Recovery Architecture and Branch Selector Boxes

VRF systems are broadly categorized into Heat Pump (HP) models, which provide either uniform cooling or uniform heating, and Heat Recovery (HR) models, which are capable of simultaneous heating and cooling.¹ Heat recovery systems introduce a profound mechanical complexity multiplier. They utilize a three-pipe distribution network (high-pressure hot gas,

low-pressure suction gas, and high-pressure subcooled liquid) or an advanced two-pipe phase-separator system to route thermal energy precisely where it is demanded.⁵ This routing is managed by Branch Selector (BS) boxes or multi-port distribution controllers situated in the ceiling spaces above the occupied zones. These devices contain an array of solenoids and electronic expansion valves.⁶ From a maintenance perspective, the BS box allows the system to recover the thermal energy rejected from a room requiring cooling (such as a server room) and pump that heat directly into a room requiring heating (such as a perimeter office), entirely bypassing the outdoor condenser.¹ While this yields extraordinary energy savings, it means that a failure in a BS box solenoid can completely destabilize the temperatures in multiple zones, creating a diagnostic scenario where the symptom (a warm office) is geographically isolated from the mechanical fault (a stuck hot-gas bypass valve in a ceiling corridor).⁹

The Complexity Multiplier for Troubleshooting

The interconnected nature of VRF systems means that technicians cannot rely on traditional pressure-temperature charts alone to diagnose localized issues.² The variable-speed compressors are constantly adjusting their output frequency (Hz) based on the aggregate demand of the active indoor units. Consequently, the suction and head pressures are dynamic, shifting continuously as load profiles change.¹ Furthermore, an issue at one indoor unit—such as a failed thermistor communicating a false high-temperature reading to the central logic board—can cause the outdoor unit to ramp up unnecessarily, leading to overcooling in all other operational zones and excessive energy consumption.² Therefore, modern VRF maintenance relies heavily on analyzing digital data streams, interrogating the communication network, and interpreting proprietary diagnostic software outputs to pinpoint the root cause of system anomalies.

2. Refrigerant Management in VRF Systems

Because VRF networks utilize the refrigerant as the sole vector for transferring thermal energy across vast architectural distances, the volumetric precision and chemical purity of the total system charge are paramount. VRF systems are critically charged; a deviation of even a few percentage points from the engineered mass can severely degrade system performance and compromise compressor longevity.²

Total System Charge Verification

Unlike standard split systems where the refrigerant charge can be adjusted in the field by monitoring evaporator superheat and condenser subcooling at the service valves, VRF systems dynamically alter their internal active volume.² Measuring pressure and temperature at the outdoor unit provides only a snapshot of the current operating load, not an accurate reflection of the total system mass.¹²

The total required system charge is an absolute mathematical value. It is the sum of the factory pre-charge contained within the outdoor condensing unit(s) and an "Additional Refrigerant Charge" that must be calculated precisely based on the physical geometry of the installed field

piping.⁵ During initial commissioning, or when restoring a system after a catastrophic leak, the exact linear footage of every liquid line must be measured and multiplied by specific weight factors.

Standard calculation formulas utilize these precise weight multipliers per linear foot of liquid line, scaling upward as the pipe diameter increases:

Liquid Line Pipe Diameter	Refrigerant Weight Multiplier
1/4 inch	Total linear length (ft) × 0.015 lbs/ft
3/8 inch	Total linear length (ft) × 0.040 lbs/ft
1/2 inch	Total linear length (ft) × 0.081 lbs/ft
5/8 inch	Total linear length (ft) × 0.121 lbs/ft
3/4 inch	Total linear length (ft) × 0.175 lbs/ft
7/8 inch	Total linear length (ft) × 0.249 lbs/ft

Once the total weight of the liquid line volume is calculated, additional mathematical compensations must be applied.⁵ For Heat Recovery systems, a multiplier (frequently 1.02) is applied to the liquid line total.⁵ Finally, supplementary refrigerant charges are added based on the overall connection ratio of the system—which is the total capacity of the connected indoor units divided by the nominal capacity of the outdoor unit.⁵ When the total required mass is calculated, it must be weighed into the system in a liquid state using a highly calibrated digital scale while the system is under a deep vacuum.⁵ If the vacuum is insufficient to draw the entire charge, specialized "Additional Refrigerant Charge Modes" or "Auto Charge" sequences are initiated via the main PCB to pull the remaining mass into the active circuit.⁵

Leak Detection and Sectional Isolation Techniques

Due to the vast lengths of piping—often exceeding thousands of combined feet in large commercial applications—finding a microscopic refrigerant leak can be exceptionally difficult. Standard leak detection methods mandate a rigorous, multi-staged pressure test utilizing oxygen-free dry nitrogen (OFDN).

Protocolo de Teste de Pressão e Tripla Evacuação de Sistemas VRF



Sequência padrão para verificação de integridade da tubagem VRF. Os testes de pressão com nitrogénio devem contabilizar as flutuações da temperatura ambiente durante o período de retenção de 24 horas usando a fórmula de correção.

Fontes de dados: [Vertex Engineering](#), [Goodman Mfg \(Daikin\)](#)

The procedure is universally mandated to be staged to prevent violent ruptures and to ensure structural integrity across all brazed joints:

1. Pressurize the network to 150 PSIG and hold for 3 minutes to identify massive leaks or blown blowout plugs.
2. Increase pressure to 325 PSIG and hold for 5 minutes.
3. Elevate pressure to 550 PSIG (or the maximum manufacturer limit, e.g., 450 PSIG if specific air handlers are attached) and hold for a minimum of 24 hours.⁴

During the 24-hour hold period, ambient temperature changes will cause pressure fluctuations inside the copper piping according to the ideal gas law. A standard temperature fluctuation compensation formula must be applied to determine if a pressure drop is due to a leak or a

thermal contraction: $\text{Pressure Drop (PD)} = (T_p - T_c) \times 0.80$, where T_p is the

temperature when pressurized, and T_c is the ambient temperature when checked.⁵

If a leak is confirmed, locating it across a multi-story building is a massive undertaking. To mitigate this catastrophic downtime, best practices in VRF mechanical engineering now mandate "sectional isolation".¹⁴ By installing highly specialized, full-port refrigeration ball valves on the main riser branches and immediately prior to branch selector boxes, technicians can sequentially close off physical zones of the building.¹⁶ If the system loses pressure, isolating the branches allows the technician to observe which specific zone's pressure decays, drastically narrowing the search radius. This architectural foresight prevents the necessity of recovering hundreds of pounds of refrigerant from the entire facility to repair a single leaking flare nut.¹⁹

Refrigerant Charge Adjustment After Adding or Removing Units

Commercial buildings are subject to frequent tenant fit-outs, requiring the addition or removal of indoor fan coil units. When modifying the network, the technician cannot simply "top off" the system. The exact linear footage of the newly added or removed liquid line must be measured, and the specific weight factors mentioned previously must be recalculated. If indoor units are added, the supplementary trim charge must be weighed into the liquid line using a digital scale.² If units and piping are removed, the equivalent mass of refrigerant must be meticulously recovered into a certified cylinder to prevent an overcharge condition, which would elevate discharge pressures and temperatures, ultimately destroying the inverter compressor.²⁰

Oil Balancing Protocols and Level Sensor Diagnostics

VRF systems utilize Polyvinyl Ether (PVE) or Polyolester (POE) oils to lubricate the high-speed rotating scroll sets within the inverter compressors. Because refrigerant velocity is the sole mechanism for transporting and returning oil through the thousands of feet of piping, periods of low-load operation—where the inverter compressor slows down and refrigerant mass flow decreases—can result in oil pooling in the vapor lines and within inactive indoor unit evaporator coils.²²

If the compressor sump runs dry, bearing failure is imminent. To prevent this, VRF logic dictates

forced "Oil Recovery Cycles." When proprietary algorithms calculate that an excessive amount of oil has migrated away from the compressor sump based on runtime and frequency histories, the system overrides local thermostat demands. Electronic expansion valves in all indoor units are commanded to open completely, and the master compressor ramps up to a high frequency.²² This creates a high-velocity, high-pressure surge of refrigerant that violently scours the piping walls and flushes the pooled oil back to the accumulators and oil separators in the outdoor unit.²² This cycle typically lasts 3 to 6 minutes.²⁴

Older or standard systems must reverse cycle from heating to cooling to recover oil, temporarily blasting cold air into occupied spaces and disrupting comfort.²⁶ Advanced platforms circumvent this. Daikin's VRV systems feature specific bypassing technology for continuous heating during oil return.²⁶ LG's Multi V utilizes Smart Oil Control and HiPORTM (High-Pressure Oil Return) hardware to constantly scavenge oil and return it directly to the compressor via a dedicated inlet, virtually eliminating the need for timed, disruptive oil-recovery cycles.⁷

Diagnostics of the oil return system involve monitoring the compressor shell bottom thermistor via the service software.²⁸ A healthy compressor will maintain adequate sump superheat to boil off liquid refrigerant while retaining the heavier oil. Compressor sump superheat is calculated as the temperature of the compressor shell-bottom (typically measured 30mm above the foot shell) minus the condensing saturated vapor temperature.³⁰ Maintenance protocols dictate that this superheat value must remain above 10 Kelvin (10°C). If the resistance of the shell-bottom thermistor (which ranges predictably, e.g., ~15 kΩ at 0°C to ~3.1 kΩ at 40°C) indicates the shell is running too cold, it suggests liquid refrigerant is returning to the compressor, diluting the POE oil and leading to imminent mechanical failure.²⁹

3. Communication Network Maintenance

The nervous system of any VRF installation is its digital communication bus. The physical mechanical components are entirely useless without the high-speed data packets flowing between the indoor units, branch selector boxes, and the master outdoor condenser. A loss of data flow immediately halts operation and triggers system-wide error codes.

RS-485 Daisy-Chain Integrity Verification

Most VRF manufacturers employ proprietary communication protocols running over a robust RS-485 physical layer.³³ Daikin utilizes the DIII-Net protocol (terminals F1/F2), operating on a pulsed 16VDC to 24VDC non-polarized circuit.³⁶ Mitsubishi relies on M-Net, running at approximately 30VDC.³⁹

The physical topology of this network must be strictly maintained as a single, continuous "daisy-chain" configuration. Star topologies, T-taps, or homerun wiring configurations are strictly prohibited.³⁵ The necessity for this rigid structure lies in high-frequency transmission line theory. Any branches, splices, or stubs in the wiring cause signal reflections. When high-speed voltage pulses hit a split in the wire, a portion of the electrical energy reflects back toward the source, colliding with new data packets and causing destructive interference, ultimately resulting in communication faults and dropped nodes.⁴²

To further prevent these reflections, the ends of the daisy chain must be electrically matched to the characteristic impedance of the transmission cable. This is achieved by installing termination resistors. Standard shielded twisted-pair cables used in these networks (such as Belden 9841) have a characteristic impedance of 120Ω. Therefore, a 120Ω termination resistor must be placed exactly at the first node (often the outdoor unit or the centralized controller) and the final physical node on the chain.³ Over-termination—such as placing resistors at every indoor unit—will draw excessive current from the transceivers, pulling the differential voltage below the receiver's threshold and instantly crashing the network.⁴² Verification involves powering down the communication bus and measuring the resistance across the two data terminals; a properly terminated network with a 120Ω resistor at each end should measure approximately 60Ω in parallel.³

Shielding practices also require strict adherence to protocol. If a shielded cable is utilized, the drain wire must be continuously connected through the chain but grounded at **one end only** (typically at the master outdoor chassis). Grounding the shield at multiple points creates a ground loop, turning the protective shield into an enormous antenna that attracts electromagnetic interference from nearby high-voltage conduits rather than repelling it.³⁴

Address Conflict Resolution

Every logical node on a VRF network requires a unique network address to communicate properly. Address conflicts (duplicate addresses) are a pervasive issue during initial commissioning or when a technician replaces a failed indoor PCB without matching the previous settings.

If two fan coils share the identical address, the master controller will receive overlapping data packets when polling that specific address, resulting in garbled data and a system error. Modern network protocols detect this by sending Address Resolution Protocol (ARP) probes; if an unexpected hardware address responds to a probed Node address, a conflict error is flagged.⁴⁷ In VRF environments, addressing is often handled automatically upon the initial power-up initialization sequence, or manually assigned via rotary DIP switches on the PCBs.³⁹ When an address error occurs (such as LG's CH07 or Daikin's U5), the troubleshooting procedure requires a systematic isolation approach.²¹ The technician must physically split the daisy-chain network in half and power the system back up. By checking which segment retains the communication error, the technician can systematically perform a binary search, narrowing down the physical location of the duplicated switch setting or the faulty auto-assigned EEPROM address.⁷

Centralized Controller and BMS Gateway Maintenance

For large commercial facilities, the proprietary VRF network must interface with the broader Building Management System (BMS). This is achieved via integration gateways, which act as protocol translators, converting RS-485 data into open protocols like BACnet/IP, LonWorks, or Modbus TCP.³⁸

Gateway maintenance is heavily focused on IT and software administration rather than mechanical labor. Network configurations (such as static IP assignment, Subnet Masks, and

Gateway paths) must be maintained to ensure the facility's overarching IT network can continuously poll the VRF data points.⁵² For example, a Lennox VRF BACnet Gateway may feature a factory-set Eth0 interface address of 192.168.1.8 with default credentials that must be secured upon commissioning.⁵²

Furthermore, routine firmware update procedures are an essential maintenance consideration. Manufacturers frequently release software patches to address cybersecurity vulnerabilities or improve the translation mapping of sensor data points.⁵⁴ Updating a device like a VRF Smart Gateway involves downloading the manufacturer's specific Update Tool application to a local machine, securing the certified upgrade executable file (e.g., vrfsgsetup-1.2.0.exe), connecting directly to the gateway via Ethernet, and pushing the flash update through an elevated administrative web browser GUI.⁵⁵ Technicians must ensure an uninterrupted power supply and configure Windows firewall ports appropriately during the flash process; an interruption during a firmware write sequence can permanently brick the gateway hardware.⁵⁵

4. Branch Selector Box (BS Box) Maintenance

In Heat Recovery systems, the Branch Selector (BS) box—sometimes referred to as an MCU or mode selection box—is the critical mechanical junction that dictates whether an individual indoor unit receives high-pressure hot gas for heating or sub-cooled liquid for cooling.⁵

Because they sit directly above the occupied space and contain complex internal valving that handles severe high-pressure fluctuations, their maintenance is crucial for both thermal performance and acoustic comfort.

Solenoid Valve Diagnostics and Temperature Differentials

BS boxes direct refrigerant flow via multiple internal solenoid valves (e.g., hot gas supply, liquid pipe regulators, gas discharge valves, and equalizing valves).¹³ A common failure mode in a VRF system is a stuck or electrically open solenoid coil within these boxes.

When testing a BS box solenoid, the first step is a practical physical inspection. When the BS box is commanded by the central controller to switch a zone from cooling to heating, a distinct, sharp metallic "click" should be audible from the box as the magnetic coil pulls the pilot valve plunger upward, altering the internal pressure dynamics to shift the main valve body.⁹ If the click is absent, the coil may be electrically dead, or the internal plunger is mechanically jammed due to copper oxide scale or system debris.⁴

A functioning solenoid will also exhibit a distinct thermal signature. The coil itself will generate a small amount of ohmic heat when energized, making it warm to the touch. Furthermore, if the valve is actively metering or restricting flow, the technician should feel a distinct temperature differential across the brass valve body due to the Joule-Thomson expansion effect.

To test the coil electrically, technicians must power down the box, disconnect the coil plug from the PCB, and utilize a multimeter to check the resistance (ohms) across the windings. Standard 24VDC solenoids will read a specific resistance (e.g., 26 ohms or 47 ohms depending on the specific model and manufacturer design), while an open circuit (OL) reading definitively indicates a burnt-out coil that requires immediate replacement.⁵⁷

Electronic Expansion Valve (EEV) Testing Procedures

The EEV within the BS box meters the pressure drop to exact specifications. EEV testing requires checking the resistance across the internal stepper motor windings. Before testing, EEV coils must be disconnected from the PCB. Resistance across the phase windings generally ranges from 26Ω to 750Ω depending on the manufacturer and the specific valve footprint. An infinite reading (OL) indicates an open winding, resulting in a mechanically stuck valve that cannot respond to controller inputs.

Internally, an EEV consists of a magnetic coil surrounding a threaded rotor that drives a needle valve into a seating orifice in microscopic steps. When performing diagnostic measurements, the technician checks the resistance between the common wire and phases 1 through 4 on a standard 5-wire or 6-wire plug connector.²³ Equal resistance across all phase pairs confirms electrical integrity.²³ If the coil is electrically sound but the valve is stuck mechanically, specialized diagnostic actuators (like an EEVMate tool) can be plugged directly into the valve harness to bypass the system PCB. This allows the technician to manually "overdrive" or "turbo" the step motor, using high-frequency pulses to break free any particulate matter jamming the needle.²³

PCB Evaluation and Structural Access Considerations

The printed circuit board within the BS box manages the complex logic of valve actuation and communicates continuous telemetry back to the master condenser. Maintenance includes observing the diagnostic LEDs on the PCB. Normal operation is generally indicated by a steady, flashing green status LED, while fault codes are communicated via specific blink patterns.¹³ Structurally, because BS boxes manage highly disparate temperatures simultaneously (routing 180°F hot gas adjacent to 40°F sub-cooled liquid), the internal copper lines sweat profusely due to condensation. Maintenance requires inspecting the elastomeric insulation covering the gas and liquid pipes. The insulation must overlap perfectly at the braze joints without gaps, and wrapping high-pressure gas and liquid pipes together is strictly prohibited, as it causes parasitic heat transfer that subverts the system's delicate subcooling algorithms.⁶³

A frequently overlooked, yet critical, maintenance parameter is physical architectural access. BS boxes require substantial spatial clearance for service panels to allow a technician to access the PCB, remove the solenoid coils, or braze in a new valve body. Ceiling access panels must be verified during routine maintenance to ensure that future emergency component replacements can be executed without requiring destructive architectural demolition of the hard ceiling.⁶

5. Multi-Compressor Outdoor Unit Maintenance

The outdoor condensing unit is the mechanical heart of the VRF system. Large modular commercial setups may feature up to three massive chassis manifolded together, containing a complex mix of variable-speed inverter compressors and constant-speed slave compressors working in tandem.⁷

Compressor Staging and Performance Metrics

The master controller rotates the lead compressor status among the available modules to ensure equal runtime wear across all bearing sets.⁶⁵ When the thermal load of the building increases, the inverter compressor ramps up its frequency to maximum; if the load remains unsatisfied, the logic board engages the constant-speed slave compressors to provide bulk mass flow, while the inverter compressor drops back down to a lower frequency to "trim" the capacity perfectly to the required demand.⁷

Evaluating compressor health requires a concurrent analysis of electrical draw and thermodynamic output. Because VRF inverter compressors modulate their speed based on real-time load, standard nameplate amp draw checks are useless. Instead, the actual amp draw must be cross-referenced with the compressor's real-time operating frequency and discharge temperature using the manufacturer's diagnostic software.¹¹ If a compressor is operating at a low frequency but pulling abnormally high amperage, mechanical binding in the scroll set, severe liquid slugging, or an extreme overcharge condition is likely.¹¹

Discharge temperature is the single most critical longevity metric. The temperature of the superheated gas leaving the compressor must be strictly monitored to remain below roughly 225°F (107°C) to 239°F (115°C) depending on the specific manufacturer's safety parameters.⁷ Excessive discharge temperatures break down the chemical structure of the POE/PVE oil, causing it to carbonize, lose its lubricity, and coat the internal piping with an insulating sludge, leading to catastrophic internal bearing failure.²⁰ High discharge temperatures are typically caused by a lack of returning refrigerant (an undercharge leak), a restricted indoor EEV starving the compressor of cool suction gas, or excessively high condensing pressures due to fouled condenser coils.²

Inverter PCB and IGBT Evaluation

The inverter PCB is responsible for driving the variable-speed compressor. It converts incoming AC line voltage into high-voltage DC, filters it through massive capacitors, and then rapidly pulses it through a matrix of Insulated-Gate Bipolar Transistors (IGBTs) via pulse-width modulation to synthesize a simulated AC waveform of varying frequency.⁶⁷

IGBT failure is a leading cause of total system electrical downtime.⁶⁹ Technicians perform a 12-step forward/reverse bias diode test to verify the integrity of the IGBTs on the inverter board. After ensuring the massive DC bus capacitors are completely discharged to 0VDC to avoid lethal shock, the compressor leads (U, V, W) are removed from the board.

Using a multimeter in diode test mode, the rigorous diagnostic sequence is as follows:

1. Place the Red probe on the positive DC bus terminal (P+) and the Black probe on U, V, and W respectively. All should read Open Line (OL).
2. Place the Black probe on the negative DC bus terminal (N-) and the Red probe on U, V, and W. All should read OL.
3. Reverse the bias: Place the Red probe on the N- terminal and the Black probe on U, V, and W. The meter should read a forward voltage drop of approximately 0.4V to 0.5V.
4. Place the Black probe on the P+ terminal and the Red probe on U, V, and W. The meter

should again read a forward voltage drop of 0.4V to 0.5V.⁶⁷

If any reading deviates into a dead short (0V) or remains open (OL) when it should show the forward voltage drop, the internal semiconductor gates of the IGBT are fused or blown, and the entire high-voltage inverter PCB must be replaced.⁶⁷

Accumulators, Oil Separators, and Fan Motor Diagnostics

The mechanical flow path in the outdoor unit includes large accumulators and oil separators. The accumulator protects the compressor from catastrophic liquid slugging by trapping unevaporated liquid refrigerant and allowing only vapor to enter the suction port.⁷⁰ Routine maintenance requires checking the liquid line sight glass—if equipped on the main liquid or oil return lines—to verify the absence of flashing or a continuous liquid state, ensuring the accumulators are not flooded beyond capacity.

The oil separator is located immediately on the high-pressure discharge line to strip atomized oil from the hot discharge gas and return it directly to the sump.⁷⁰ Maintenance involves utilizing thermal imaging or highly accurate surface thermistors to measure the temperature differential across the oil separator body. A proper differential indicates oil is being stripped and returned successfully; a lack of temperature drop can indicate a blocked internal capillary tube or a failed internal float mechanism, which will rapidly drain the compressor of lubrication.⁷⁰

Finally, outdoor fan motor staging must be verified. VRF systems utilize variable-speed BLDC (Brushless DC) fan motors to maintain precise head pressure regardless of outdoor ambient temperatures. Diagnostic software should be used to verify that the fans modulate smoothly upward as high-side pressure increases; abrupt stops, irregular vibrations, or locked rotor errors (e.g., LG error CH67) indicate a failed fan stator or a jammed bearing, which will immediately cause the system to trip on high-pressure safeties.⁵¹

6. Seasonal Commissioning and Optimization

To maximize the life cycle and thermodynamic efficiency of the equipment, comprehensive seasonal pre-flight checks are mandatory. VRF efficiency drops drastically if the building heat load exceeds the network's ability to reject or absorb it.

Summer and Winter Preparation Protocols

Summer Preparation: The primary focus is heat rejection efficiency. The outdoor condenser coils must be chemically cleaned to remove debris and environmental scale. Because VRF systems often feature multi-sided coils with highly dense micro-channel or lanced-fin designs, aggressive chemical acids and high-pressure washing must be avoided to prevent folding the delicate aluminum fins.² Once cleaned, the system is run at peak ambient outdoor conditions, forcing all indoor units into maximum cooling demand via test-mode overrides. The technician evaluates total capacity, subcooling values at the main liquid line, and the peak amp draw of the inverter compressors to establish a baseline for the cooling season.²

Winter Preparation: The focus shifts to heat absorption and low-ambient hardware protection. The crankcase heaters, which wrap around the base of the compressors, must be tested for continuity. A standard 265V, 40-watt PTC (Positive Temperature Coefficient)

crankcase heater will have a cold resistance of approximately 1800 ohms.⁵⁶ These heaters keep the oil warm during off-cycles, boiling off any liquid refrigerant that migrates into the sump, thereby preventing it from washing out the bearings on startup.⁵⁶ Defrost cycles must be verified through the software override. If the system operates in extreme cold environments, the base pan heaters must be checked to ensure meltwater from the defrost cycle drains freely and does not refreeze, which could eventually crush the bottom rows of the condenser coil.²⁵ Furthermore, specialized low-ambient hardware—such as wind baffles and hail guards (e.g., Lennox V1LACB and V1BPNH modules)—must be inspected to ensure they are securely mounted, preventing freezing winds from crashing the required head pressures.²⁴

EEV Operation and Zone Temperature Balancing

VRF systems inherently save energy by utilizing variable speed components, but maximum efficiency is achieved through occupancy schedule optimization via the central controller. By programming strict temperature setbacks in unoccupied zones, the overall system capacity requirements drop, allowing the outdoor compressors to spin down to low frequencies where their Coefficient of Performance (COP) is at its absolute peak.¹

Zone temperature balancing is managed dynamically by the system algorithms, but consistent under-performance or over-cooling in a specific zone points to a sensor calibration drift or an EEV mechanical issue.¹⁰ If a zone is perpetually warm during cooling calls, the diagnostic sequence requires analyzing the four key thermistors associated with that indoor unit: Return Air, Discharge Air, Liquid Pipe Inlet, and Gas Pipe Outlet.²

By plotting the difference between the Liquid Pipe Inlet and Gas Pipe Outlet thermistors, the technician assesses the superheat of that specific evaporator coil. If the superheat is excessively high (e.g., 30°F), the EEV is starving the coil of refrigerant. If the EEV pulse output from the PCB indicates the valve is commanded to be fully open, but the superheat remains high, the EEV is mechanically stuck and must be serviced.² Conversely, if the Return Air thermistor has shifted out of calibration and reads a false low temperature, the control board will prematurely shut the EEV, believing the zone is satisfied, resulting in a hot room.¹⁰

7. Fault Code Quick-Reference and Maintenance Checklists

When VRF microprocessor logic detects a parameter operating outside of safe design limits, the system triggers a localized or system-wide lockout and outputs an alphanumeric fault code to the remote controllers and master PCB displays. Below are critical diagnostic fault code structures for the major VRF manufacturers.

Daikin VRV Fault Codes

Daikin categorizes faults logically by the first character of the code. 'A' and 'C' codes relate to the indoor units, 'E', 'F', 'H', 'J', and 'L' relate to the outdoor condensing unit hardware and sensors, and 'U' codes denote critical communication or system-wide configuration failures.²¹

Fault Code	Component Classification	Primary Diagnostic Meaning & Potential Cause
A1	Indoor Unit PCB	General failure of the indoor PCB; potential noise interference.
A3	Indoor Condensate	High water level detected; drain pump failure or float switch open circuit.
A9	Indoor EEV	EEV failure; defective step motor coil or indoor PCB output fault.
C4 / C5	Indoor Sensors	C4: Indoor coil thermistor open/short. C5: Suction pipe thermistor fault.
E3	Outdoor Safety	Activation of the high-pressure switch; check for overcharge or dirty condenser.
E4	Outdoor Safety	Activation of the low-pressure sensor; check for severe undercharge.
J3	Outdoor Sensors	Discharge pipe thermistor fault; sensor disconnected or out of calibration.
L5	Outdoor Inverter	Inverter instantaneous overcurrent (DC output); defective compressor coil or locked rotor.
U1	System Configuration	Power phase imbalance or open phase detected on

		the primary supply voltage.
U4	System Communication	Loss of communication between indoor and outdoor units; check RS-485 daisy chain.
U5	System Communication	Remote controller communication error; frequently caused by duplicate master controllers.

Mitsubishi City Multi Fault Codes

Mitsubishi utilizes a 4-digit numeric code system. Codes in the 1xxx range refer to refrigerant cycle abnormalities, 2xxx to water/condensate issues, 4xxx/5xxx to sensor and board failures, and 6xxx to M-Net communication drops.³²

Fault Code	Component Classification	Primary Diagnostic Meaning & Potential Cause
1102	Refrigerant Cycle	High compressor discharge temperature (>110°C); indicates shortage of refrigerant.
1301	Refrigerant Cycle	Low-pressure fault; check low-pressure sensor with analog gauge pressure.
1302	Refrigerant Cycle	High-pressure fault; confirm refrigerant service valves are fully open.
2500	Condensate System	Drain sensor submergence; condensate overflow in an indoor fan coil.

5101	Indoor Sensors	Return air temperature sensor (TH21) open/short circuit.
5201	Outdoor Sensors	High-pressure sensor fault (63HS1); cross-reference actual pressure with gauge.
6607	M-Net Communication	Communication error with a specific device. System cannot "see" the addressed unit.

LG Multi V Fault Codes

LG utilizes a "CH" prefix followed by a numeric designation. The algorithm frequently assigns a Level 3 warning, attempting self-correction up to 10 times before shifting to a Level 1 hard lockout requiring manual reset.⁷⁸

Fault Code	Component Classification	Primary Diagnostic Meaning & Potential Cause
CH01	Indoor Unit	Return air temperature sensor disconnected or shorted.
CH04	Indoor Unit	Drain pump/float switch error; drain line obstructed or pump failure.
CH05	Communication	Signal loss between outdoor and indoor PCB for >5 minutes. Check shielding/ground.
CH47	Outdoor Unit	Outdoor expansion valve (EEV) operating incorrectly; stuck needle or dead coil.

CH53	Communication	Communication failure between Main outdoor unit PCB and Sub outdoor unit PCB.
CH61	Outdoor Safety	Condenser coil temperature too high; high pressure protection triggered.
CH62 / CH65	Outdoor Inverter	Inverter heat sink temperature too high; check thermal paste or cooling airflow to board.
CH67	Outdoor Fan	BLDC fan motor lock error; motor unable to spin freely.

Comprehensive VRF Preventative Maintenance Checklist

To assure the longevity of the installation and prevent the escalation of minor sensor drifts into catastrophic compressor failures, technicians must execute a structured, preventative maintenance protocol. The following table dictates the critical inspection nodes.

System Domain	Preventative Maintenance Action Required	Diagnostic Target / Expected Value
Refrigerant Thermodynamics	Interrogate system via diagnostic software (LGMV, Service Checker) to record baseline data.	Compressor discharge temperatures remain < 225°F. Sump superheat > 10K.
Refrigerant Thermodynamics	Verify oil separator temperature differentials.	Distinct temperature drop across the separator body indicates proper function.
Refrigerant Thermodynamics	Check the total calculated refrigerant charge log on the service panel.	Ensure any field adjustments were mathematically documented based on line

		length.
Electrical & Comm. Integrity	Verify incoming main line voltage to the outdoor unit under full load.	Measure phase-to-phase balance to ensure deviation does not exceed 2%.
Electrical & Comm. Integrity	Inspect the RS-485/M-Net daisy chain topology and shield termination.	Shield grounded exclusively at the master outdoor unit chassis; no ground loops.
Electrical & Comm. Integrity	Verify termination resistors across the communication network.	120-ohm resistors installed only at the first and last physical nodes; parallel reads ~60Ω.
Branch Selector & Hardware	Force mode changes to physically test BS box solenoid actuation.	Distinct metallic click heard; sensible temperature drop across the valve body.
Branch Selector & Hardware	Measure EEV step-motor coil resistances if a zone fails to condition properly.	Target 26Ω to 750Ω (equal across all phase pairs); OL requires replacement.
Outdoor Unit Mechanics	Chemically wash outdoor condenser coils using low-pressure application.	Restoration of peak heat rejection capability without folding micro-channel fins.
Outdoor Unit Mechanics	Test the inverter IGBT components via the forward/reverse bias diode test.	Target 0.4V to 0.5V forward bias; Open Line (OL) reverse bias.
Outdoor Unit Mechanics	Measure the cold resistance of the compressor base pan/crankcase heaters.	Target ~1800 ohms for a standard 40W PTC heater element.
Outdoor Unit Mechanics	Verify accumulator sight glasses and BLDC fan	Vapor state confirmed in lines; fan spins freely without locked rotor faults

	motor staging sequence.	in the log.
--	-------------------------	-------------

By adhering strictly to this data-driven, systematic diagnostic framework, maintenance personnel can ensure that the highly complex thermodynamic and electronic matrices of modern VRF systems operate at peak efficiency for their full engineered lifespan.

Referências citadas

1. Variable Refrigerant Flow Heat Pumps: Engineering Reference - Big Ladder Software, acessado em junho 13, 2026, <https://bigladdersoftware.com/epx/docs/8-7/engineering-reference/variable-refrigerant-flow-heat-pumps.html>
2. Why VRF Diagnostics Demand a Systems-Level Approach - Trade Agent, acessado em junho 13, 2026, <https://www.thetradeagent.com/blog/advanced-vrf-system-diagnostics-guide>
3. Get Connected: How to Operate Your RS-485 Links without Termination - Texas Instruments, acessado em junho 13, 2026, <https://www.ti.com/document-viewer/lit/html/SSZTBA4>
4. Variable Refrigerant Flow (VRF) Installation and Commissioning - The Vertex Companies, acessado em junho 13, 2026, <https://vertexeng.com/insights/variable-refrigerant-flow-vrf-installation-and-commissioning/>
5. Daikin VRV Commissioning Guide Participant Guide, acessado em junho 13, 2026, <https://apps.goodmanmfg.com/training/files/54aeaf8f0ecccTB-VRV107-VRV-Commissioning-Only.pdf>
6. INSTALLATION INSTRUCTIONS - Lennox, acessado em junho 13, 2026, <https://www.lennox.com/dA/b1114b8a07/507886-04.pdf>
7. OPERATION AND MAINTENANCE MANUAL - LG Electronics, acessado em junho 13, 2026, https://media.us.lg.com/m/532a1f0c47275b65/original/OM_MULTI-V-5-OPERATION-MAINTENANCE-MANUAL_06_24-pdf.pdf
8. A Novel Variable Refrigerant Flow (VRF) Heat Recovery System Model: Development and Validation, acessado em junho 13, 2026, https://eta-publications.lbl.gov/sites/default/files/t_hong_a_novel_variable_refrigerant_flow_vrf_heat_recovery_system.pdf
9. How to rectify VRF air conditioner Control PCB no power light - YouTube, acessado em junho 13, 2026, <https://www.youtube.com/watch?v=arC2zW1hCeU>
10. Understanding and Troubleshooting VRF System Issues - Sarli Mechanical Services, acessado em junho 13, 2026, <https://sarlimechanicalservices.com/blog/troubleshooting-vrf-system-issues>
11. LG VRF - Help a brotha one more time? : r/HVAC - Reddit, acessado em junho 13, 2026, https://www.reddit.com/r/HVAC/comments/1s24ckh/lg_vrf_help_a_brotha_one_more_time/

12. Trouble determining lack of refrigerant on VRV and Inverter Systems : r/HVAC - Reddit, acessado em junho 13, 2026, https://www.reddit.com/r/HVAC/comments/16ebg6v/trouble_determining_lack_of_refrigerant_on_vrv/
13. Daikin VRV Service & Troubleshooting Participant Guide, acessado em junho 13, 2026, <https://apps.goodmanmfg.com/training/files/54aeaf37b9064TB-VRV104-VRVIII-S-T.pdf>
14. VRF Air Conditioning System Specifications | PDF | Pipe (Fluid Conveyance) - Scribd, acessado em junho 13, 2026, <https://www.scribd.com/document/967648603/Part-3-04B-ACMV-Specifications>
15. houston airport system - design standards manual, acessado em junho 13, 2026, https://downloads.ctfassets.net/fwldykjthzos/55yVy5F8V5k1O9nMaLzEww/4e72d921f4f9af6cec9b81d1d71084ff/HAS_Design_Manual.pdf
16. Small Animal (Rodent) Vivarium Design Standards | PDF | Water Heating - Scribd, acessado em junho 13, 2026, <https://www.scribd.com/document/373971684/Small-Animal-Rodent-Vivarium-Design-Standards-1>
17. Isolation Ball Valves - Parker EBVP Series, acessado em junho 13, 2026, <https://ph.parker.com/us/en/product-list/ebv-ball-valves-isolation-ball-valves>
18. Isolation Valves for HVAC Pipework Systems - Crane Fluid Systems, acessado em junho 13, 2026, <https://www.cranefs.com/isolation-valves-hvac/>
19. Best way to make a VRF service friendly is to have ball valves before on your mains and after on your branch lines on BC box : r/HVAC - Reddit, acessado em junho 13, 2026, https://www.reddit.com/r/HVAC/comments/tqjodp/best_way_to_make_a_vrf_service_friendly_is_to/
20. Compressor Discharge Temperature Reflects How Equipment is Operating - ACHR News, acessado em junho 13, 2026, <https://www.achrnews.com/articles/142619-compressor-discharge-temperature-reflects-how-equipment-is-operating>
21. Service Manual | Daikin, acessado em junho 13, 2026, <https://www.daikinbahrain.com/content/dam/DameaWebsite/ProductGroups/VRV/VRV-X/RXQ-ARYFK%20Service%20Manual.pdf>
22. Energy Conservation Program: Test Procedure for VRF Multi-Split Systems, acessado em junho 13, 2026, <https://www.federalregister.gov/documents/2021/12/10/2021-26288/energy-conservation-program-test-procedure-for-vrf-multi-split-systems>
23. Electronic Expansion Valve Troubleshooting - HVAC School, acessado em junho 13, 2026, <http://www.hvacrschool.com/electronic-expansion-valve-troubleshooting/>
24. SUBMITTAL DATA - VPD072S6M-5G VRF Heat Pump 460V - Lennox, acessado em junho 13, 2026, <https://www.lennox.com/dA/58fc2fe28f/VPD072S6M-5G.pdf>
25. SUBMITTAL DATA - VRD240S6M-5G VRF Heat Recovery 460V - Lennox, acessado em junho 13, 2026, <https://www.lennox.com/dA/6d709b72f5/VRD240S6M-5G.pdf>

26. Daikin VRV III Ductless & Ducted advanced Heating & Air conditioning systems, acessado em junho 13, 2026, https://pacificairconditioner.com/files/Daikin_VRVIII_Brochure.pdf
27. VRF Systems - Commercial Technology - LG Air Conditioning Technologies, acessado em junho 13, 2026, <https://lghvac.com/commercial/technology/>
28. City Multi error code.xlsx - Mitsubishi Electric Asia, acessado em junho 13, 2026, <https://www.mitsubishielectric.com.sg/getmedia/1e62eab7-7520-4a01-8f94-a9f0bebd0f7d/CityMultiErrorCode.pdf>
29. CITY MULTI Fault Code Troubleshooting Guide | PDF | Power Supply - Scribd, acessado em junho 13, 2026, <https://www.scribd.com/document/833402840/CityMultierrorCode>
30. V3 INVERTER SINGLE SCROLL - JE Hall, acessado em junho 13, 2026, <https://commercial.jehall.co.uk/files/www/ccu%20-%20technical-manuals/V3%20Inverter%20Single%20Scroll%20Technical%20Manual%2001.09.2021.pdf>
31. R407C Heat Pump Installation Manual | PDF | Air Conditioning | Pipe (Fluid Conveyance), acessado em junho 13, 2026, <https://www.scribd.com/document/564989758/puhp8ye>
32. Mitsubishi Fault Codes PDF | PDF | Power Inverter | Power Supply - Scribd, acessado em junho 13, 2026, <https://www.scribd.com/document/363198215/Mitsubishi-Fault-Codes-pdf>
33. RS-485 Termination - NI - National Instruments, acessado em junho 13, 2026, <https://www.ni.com/docs/en-US/bundle/ni-serial/page/rs-485-termination.html>
34. RS485 Daisy-Chain Wiring: Termination Resistor Requirements - Industrial Monitor Direct, acessado em junho 13, 2026, <https://industrialmonitordirect.com/blogs/knowledgebase/rs485-daisy-chain-topology-why-termination-resistors-matter>
35. INSTALLATION MANUAL WITH - LG HVAC, acessado em junho 13, 2026, https://lghvac.com/resource-service?filename=IM_MultiV5_LGRED_OutdoorUnits.pdf
36. Daikin D-Bus F1 & F2 Wiring Guide | PDF | Electromagnetic Interference - Scribd, acessado em junho 13, 2026, <https://www.scribd.com/document/896242003/Daikin-D-Bus-Communication>
37. Daikin Basic Control Wiring - DXS - Direct Expansion Solutions, acessado em junho 13, 2026, <https://dxseng.com/daikin-basic-control-wiring/>
38. Daikin VRV Installation & Commissioning Participant Guide, acessado em junho 13, 2026, <https://apps.goodmanmfg.com/training/files/54aeaea25242bTB-VRV101-VRV8I-I-C-16.pdf>
39. Mitsubishi Electric's M-Net Adaptors - Knowledge Base - Rfwel Engineering, acessado em junho 13, 2026, <https://support.rfwel.com/portal/en/kb/articles/mitsubishi-electric-s-m-net-adaptors>
40. Mitsubishi Electric Building Air Conditioning Control System, acessado em junho 13, 2026, <http://www.mitsubishitech.co.uk/Data/Accessories/Controls/PAC-SF46EPA/PAC-S>

[F46EPA_IM.pdf](#)

41. Common problems and solutions of RS485 - Ebyte, acessado em junho 13, 2026,
<https://www.cdebyte.com/news/662>
42. Termination resistor creating communication problem in RS485 MODBUS/TCP, acessado em junho 13, 2026,
<https://electronics.stackexchange.com/questions/242011/termination-resistor-creating-communication-problem-in-rs485-modbus-tcp>
43. RS-485 Basics: When Termination Is Necessary, and How to Do It Properly, acessado em junho 13, 2026,
<https://www.ti.com/document-viewer/lit/html/SSZTB23>
44. Fixing RS-485 Communication Errors: Termination Resistor Guide - Industrial Monitor Direct, acessado em junho 13, 2026,
<https://industrialmonitordirect.com/blogs/knowledgebase/rs-485-termination-resistor-troubleshooting-for-plc-networks>
45. Mitsubishi Electric PAC-SF46EPA-G Installation Manual, acessado em junho 13, 2026,
https://mitsubishi.kh.ua/wp-content/uploads/2021/11/Mitsubishi_Electric_PAC-SF46EPA-G_Installation_Manual_Eng.pdf
46. M-NET Interface, acessado em junho 13, 2026,
https://www.mitsubishitechinfo.ca/sites/default/files/MAC-399IF-E%28M-net_Interface%29.pdf
47. Troubleshoot Duplicate IP Address 0.0.0.0 Error Messages - Cisco, acessado em junho 13, 2026,
<https://www.cisco.com/c/en/us/support/docs/ios-nx-os-software/8021x/116529-problemsolution-product-00.html>
48. Duplicate IPs in the same VRF · netbox-community netbox · Discussion #17910 - GitHub, acessado em junho 13, 2026,
<https://github.com/netbox-community/netbox/discussions/17910>
49. How to Resolve City Multi VRF 6607 Communications Error | Mitsubishi Electric - YouTube, acessado em junho 13, 2026,
<https://www.youtube.com/watch?v=Q749ppWGN4I>
50. Service Manual - Daikin Comfort, acessado em junho 13, 2026,
[https://daikincomfort.com/docs/default-source/vrv-iv-x-heat-pump/sm-rxyq_xatja_xayda-\(sius34200\).pdf](https://daikincomfort.com/docs/default-source/vrv-iv-x-heat-pump/sm-rxyq_xatja_xayda-(sius34200).pdf)
51. LG Air Conditioning Error Codes – What They Mean - Be Cool Refrigeration, acessado em junho 13, 2026,
<https://becoolrefrigeration.co.uk/lg-air-conditioning-error-codes/>
52. BACnet Gateway - Lennox, acessado em junho 13, 2026,
<https://www.lennox.com/dA/020b57558a/507951-02.pdf>
53. BACnet Interface | Building Management Integration - Daikin Comfort, acessado em junho 13, 2026,
<https://daikincomfort.com/products/commercial-systems/commercial-controls/interface-for-use-bacnet>
54. Controls Software & Firmware Downloads | Trane Commercial HVAC, acessado em junho 13, 2026,

<https://www.trane.com/commercial/north-america/us/en/products-systems/smart-building-technology/building-controls-solutions/trane-controls-software-downloads.html>

55. Installing the VRF Smart Gateway 1.2.0 firmware upgrade file - Metasys - LIT-12013562, acessado em junho 13, 2026,
<https://docs.johnsoncontrols.com/bas/r/Metasys/en-US/VRF-Smart-Gateway-MU-T-User-Guide/Release-1.2.1/Installing-the-VRF-Smart-Gateway-1.2.0-firmware-upgrade-file>
56. Service and Troubleshooting - Daikin Comfort, acessado em junho 13, 2026,
<https://daikincomfort.com/docs/default-source/amst/sm-rs6200301.pdf>
57. Solenoid Operated Proportional Directional Control Valve (with Pressure Compensation, Multiple Valve Series) - Daikin hydraulic, acessado em junho 13, 2026,
https://www.hyd.daikin.com/-/media/Project/Daikin/hyd_daikin_co_jp/common/products00/catalogue/en/GK247D_J-072-pdf.pdf?rev=4712a0b7fe1c4fa4b97462012ead593b&sc_lang=en
58. Troubleshooting Hydraulic Solenoid Valves - All World Machinery Supply, acessado em junho 13, 2026,
<https://www.allworldmachinery.com/blog/943/hydraulic-valves>
59. How to check Motorized Valve Coil reading |Daikin inverter - YouTube, acessado em junho 13, 2026, https://www.youtube.com/watch?v=YzkVKWhM_3E
60. EEVMate Tool: Testing Electronic Expansion Valves (EEVs) in Mini Splits & VRF Systems, acessado em junho 13, 2026,
<https://www.youtube.com/watch?v=-lLL-60pjyg&v=en>
61. Electronic Expansion Valve (EEV) Coil Testing - (Fujitsu) General Australia and New Zealand, acessado em junho 13, 2026,
<https://assist.fujitsugeneral.com.au/support/solutions/articles/6000276914-electronic-expansion-valve-eev-coil-testing>
62. EEVMate Tool: Testing Electronic Expansion Valves (EEVs) in Mini Splits & VRF Systems, acessado em junho 13, 2026,
<http://www.hvacrschool.com/videos/eevmate-tool-testing-electronic-expansion-valves-eevs-in-mini-splits-vrf-systems/>
63. Variable Refrigerant Flow System - Outdoor Unit Series / Installation, Operation, and Maintenance - Trane, acessado em junho 13, 2026,
<https://www.trane.com/content/dam/Trane/Commercial/global/products-systems/equipment/ductless/variable-refrigerant-volume/vrf-svn34a-en.pdf>
64. – Your Daily Guide to Reliable VRF Operation - Hitachi Air Conditioning, acessado em junho 13, 2026,
<https://www.hitachiaircon.com/my/resources/vrf-systems/vrf/vrf-maintenance-guidelines>
65. Service Manual - Daikin Comfort, acessado em junho 13, 2026,
<https://daikincomfort.com/docs/default-source/vrv-iv-heat-pump/sm-hp-sius341615e--final.pdf>
66. The Professor: Understanding Compressor Amperage Curves | 2016-02-01 | ACHRNEWS, acessado em junho 13, 2026,

<https://www.achrnews.com/articles/131665-the-professor-understanding-compressor-amperage-curves>

67. Troubleshooting Inverter Boards - HVAC School, acessado em junho 13, 2026, <http://www.hvacrschool.com/troubleshooting-inverter-boards/>
68. How to Diagnose A Daikin VRV Inverter Board - YouTube, acessado em junho 13, 2026, https://www.youtube.com/watch?v=Fgx1_n1GeQE
69. VRV VRF Inverter PCB Failure Resolving - YouTube, acessado em junho 13, 2026, <https://www.youtube.com/watch?v=U26lwwozj9Q>
70. Understanding the Oil Return Circuit on VRV/F - YouTube, acessado em junho 13, 2026, <https://www.youtube.com/watch?v=tF6nWEifUOY>
71. DEFINING COMMON ERROR CODES - LG HVAC, acessado em junho 13, 2026, https://legacy.lghvac.com/resource-service?filename=DFS-TP-AH-001-US_012H10_LGTechPaper_ErrorCodes_LS_091-121_HSV.pdf
72. Evaluation of Variable Refrigerant Flow Systems Performance on Oak Ridge National Laboratory's Flexible Research Platform, acessado em junho 13, 2026, <https://info.ornl.gov/sites/publications/files/Pub69040.pdf>
73. Cooling season full and part load performance evaluation of Variable Refrigerant Flow (VRF) system using an occupancy simulated research building - Purdue e-Pubs, acessado em junho 13, 2026, <https://docs.lib.purdue.edu/cgi/viewcontent.cgi?article=2787&context=iracc>
74. Daikin Air Conditioner Fault Codes - Parts Town, acessado em junho 13, 2026, <https://www.partstown.com/cm/resource-center/guides/gd2/daikin-air-conditioner-fault-codes>
75. Simple Self-Diagnosis by Malfunction Code | Daikin, acessado em junho 13, 2026, https://www.daikin.com/-/media/Project/Daikin/daikin_com/products/ac/services/error_codes/pdf/sm-ts3_p1-6_errorcode-pdf.pdf?rev=-1&hash=EB9A47B35985182BC51091ECC254E40F
76. Daikin Trouble Shooting Guide - The Star Supply Company, acessado em junho 13, 2026, <https://www.star-supply.com/content/Daikin-Troubleshooting%20Codes.pdf>
77. Fault Code Check List - OrionAir, acessado em junho 13, 2026, https://orionair.co.uk/PDF/Mitsubishi_elec_Fault_codes.pdf
78. SERVICE MANUAL - Parts Town, acessado em junho 13, 2026, https://www.partstown.com/modelManual/LGAP-SM-MultiV-S-OutdoorUnits_spm.pdf?v=1729271452491
79. SERVICE MANUAL - Rackcdn.com, acessado em junho 13, 2026, https://a1ac1dcb67cc9f847a73-0b6da349d0197cd2922796e57d5f1d84.ssl.cf5.rackcdn.com/CMSFiles/PMAssets/PMAssets/Resource/general/1916/SM_MultiV_5_OutdoorUnits-%20Service%20manual%20208460V.pdf