

Advanced Infrared Thermography in HVAC/R Diagnostics: Principles, Methodologies, and NFPA/NETA Compliance

Infrared (IR) thermography has fundamentally transformed the landscape of Heating, Ventilation, Air Conditioning, and Refrigeration (HVAC/R) diagnostics. Evolving from a specialized, high-cost anomaly detection method into an accessible, foundational pillar of preventative and predictive maintenance, thermography empowers technicians to visualize the invisible. By non-intrusively converting emitted thermal radiation into a visible spectrum of temperature mapping, thermal imaging allows diagnosticians to observe complex thermodynamic processes, mechanical friction, fluid dynamics, and electrical resistance in real-time. This exhaustive analysis delineates the underlying physics of thermal imaging, equipment specifications, detailed diagnostic applications across mechanical, envelope, and electrical HVAC domains, and the rigorous methodological frameworks dictated by governing standards such as the National Fire Protection Association (NFPA) and the InterNational Electrical Testing Association (NETA).

1. Fundamentals of Infrared Thermography in HVAC Systems

To effectively deploy a thermal imaging camera in a complex HVAC environment, the operator must possess a profound understanding of the physical laws governing thermal radiation, the material properties of the equipment being inspected, and the internal architecture of the camera itself.

1.1 The Physics of Thermal Radiation and Emissivity

All physical objects with a temperature above absolute zero (0 Kelvin or -273.15° C) vibrate at the atomic level, consequently emitting energy in the form of infrared radiation. The total thermal energy radiated by an ideal blackbody surface is directly proportional to the fourth power of its absolute temperature, a foundational principle defined by the Stefan-Boltzmann Law¹:

$$j^{\star} = \sigma T^4$$

Where $j^{\star}$ represents the radiant emittance, T is the absolute temperature, and σ is the Stefan-Boltzmann constant ($5.670 \times 10^{-8} \text{ W} \cdot \text{m}^{-2} \cdot \text{K}^{-4}$).¹ However, the reality of

HVAC diagnostics is that perfect blackbodies do not exist in the field. Real-world components—such as copper pipes, aluminum fins, and steel enclosures—emit radiation at a fraction of the efficiency of a theoretical blackbody.

The efficiency with which an object emits its own internal infrared radiation relative to a perfect blackbody is known as its **emissivity** (ϵ), a dimensionless metric ranging from 0 (a perfect reflector) to 1.0 (a perfect emitter).² A profound understanding of emissivity is non-negotiable for the thermographer because thermal cameras do not measure temperature directly; rather, they measure the total incident infrared energy reaching the lens and then algorithmically calculate the temperature based on the user-defined emissivity setting and the reflected apparent temperature.²

In the context of HVAC systems, materials exhibit wildly varying emissivity characteristics that dictate the feasibility and methodology of a thermal inspection:

- **Copper Piping:** New, polished copper possesses an extremely low emissivity ($\epsilon \approx 0.07$), essentially acting as a thermal mirror that reflects the infrared energy of the surrounding room rather than emitting the temperature of the refrigerant inside it.² Conversely, heavily oxidized, aged copper tubing possesses a much higher emissivity ($\epsilon \approx 0.78$), making it highly suitable for direct thermal scanning.
- **Aluminum Components:** Bare aluminum, commonly found in condenser fins and microchannel coils, is notoriously difficult to measure due to its highly reflective nature and exceptionally low emissivity ($\epsilon \approx 0.04 - 0.09$).³ Diagnosticians must be acutely aware that they are often measuring the reflection of adjacent heat sources rather than the aluminum itself.
- **Painted Surfaces and Enclosures:** Painted metal surfaces, such as compressor shells, air handler cabinets, and electrical panel doors, exhibit high emissivity ($\epsilon \approx 0.90 - 0.95$), providing highly accurate and reliable thermal readings.⁴
- **Polymers and PVC:** Polyvinyl chloride (PVC) piping, commonly utilized for condensate drains and high-efficiency furnace venting, generally offers excellent emissivity for measurement ($\epsilon \approx 0.91 - 0.93$).

To accurately measure the temperature of low-emissivity components like a polished copper liquid line or a bare aluminum busbar, thermographers must physically modify the surface.

Applying high-emissivity black electrical tape ($\epsilon \approx 0.95$) or a small patch of flat black paint to the target area unifies the thermal signature, allowing the camera to accurately calculate the true surface temperature without reflective interference.⁴

1.2 Microbolometer Detector Technologies

The technological core of modern, uncooled HVAC thermal cameras is the microbolometer—a microscopic grid of temperature-sensitive resistors that alter their electrical resistance in direct

response to absorbed infrared radiation.⁵ Unlike early thermal cameras that required cryogenic cooling mechanisms, uncooled microbolometers operate at room temperature, dramatically reducing the size, weight, and cost of the equipment.

At the microscopic level, infrared radiation focused by the camera's germanium lens strikes the detector array. The radiation heats the suspended active layer within each pixel, which dynamically changes its electrical resistance.⁶ A crucial thermal isolation gap beneath this layer ensures this minute heat does not dissipate into the underlying silicon CMOS readout integrated circuit (ROIC) substrate, thereby maximizing the detector's sensitivity to external radiation.⁶

Microbolometer arrays are typically manufactured from two primary active materials, each with distinct advantages:

1. **Vanadium Oxide (VOx):** Originating from defense-sector developments in 1978, VOx technology currently commands approximately 70% of the commercial microbolometer market.⁵ VOx films exhibit a superior Temperature Coefficient of Resistance (TCR) compared to alternative materials, resulting in higher infrared radiation photo-conversion efficiency.⁷ VOx detectors are characterized by lower residual fixed-pattern noise, exceptional image stability, and high thermal sensitivity, often achieving noise equivalent limits capable of detecting **30 mK** temperature differences.⁵
2. **Amorphous Silicon (a-Si):** Introduced roughly a decade after VOx, amorphous silicon detectors are highly advantageous because their manufacturing process is natively compatible with standard CMOS semiconductor fabrication lines.⁷ While highly manufacturable and cost-effective, a-Si detectors generally possess slightly lower sensitivity (typically around **50 mK**) and display an order of magnitude higher residual fixed-pattern noise.⁷ This noise can sometimes result in images with a slight veiling glare, offering slightly less crisp clarity compared to premium VOx arrays.⁷

1.3 Resolution and Sensitivity Metrics (NETD)

When selecting and utilizing a thermal imager for HVAC diagnostics, the operator must balance two critical performance metrics: thermal sensitivity and spatial resolution.

The primary metric for thermal sensitivity is the **Noise Equivalent Temperature Difference**

(**NETD**), traditionally measured in milliKelvins (**mK**). NETD represents the smallest temperature difference a camera can distinguish from its own internal electronic noise floor.⁷ A lower NETD value indicates a more sensitive camera. For intricate building envelope diagnostics—where the thermographer is searching for subtle thermal bridging or minor

insulation voids hidden behind drywall—a highly sensitive camera with an NETD of **< 40 mK**

is essential.⁹ Conversely, a camera with a **100 mK** rating may be perfectly adequate for identifying severe, high-temperature electrical overloading, but it will likely fail to capture the delicate, low-contrast phase changes occurring across a microchannel evaporator coil.⁹

Spatial resolution, dictated by the pixel array dimensions (e.g., 160×120 vs. 320×240 vs. 640×480), determines the clarity and measurement accuracy of the image at a distance. The total number of pixels dictates the instantaneous field of view (IFOV), which represents the physical size of a single pixel projected onto the target.⁹ If a target (such as a small electrical wire) is smaller than the projected IFOV, the camera will average the temperature of the wire with the temperature of the background behind it, resulting in a wildly inaccurate measurement. High-resolution cameras allow technicians to maintain a safe distance from high-voltage equipment while still accurately measuring tiny, specific components.¹⁰

2. Electrical Diagnostics and Code Compliance

Electrical failures within HVAC infrastructure—spanning from main building switchgear to specific rooftop unit disconnects, blower motor starters, compressor contactors, and variable frequency drives (VFDs)—rarely occur instantaneously. The vast majority of these failures begin as unnoticeable, localized thermal events. The increased electrical resistance generated by loose mechanical connections, advanced oxidative corrosion, phase imbalances, or

overloading manifests physically as $I^2 R$ heating.¹⁰ Thermography detects this heating long before physical component failure, insulation melting, or catastrophic arc flash incidents occur.¹¹

2.1 The NFPA 70B Regulatory Shift

The paradigm of electrical preventative maintenance within facilities management shifted fundamentally with the publication of the 2023 revision of the NFPA 70B standard (Standard for Electrical Equipment Maintenance). For decades, NFPA 70B was regarded as a set of highly recommended best practices. However, the 2023 revision strictly elevated these practices to mandatory industry standards, officially requiring annual infrared thermographic inspections of all electrical equipment operating under load.¹⁰

This transition from a "recommended" activity to a "required" compliance mandate compels facility managers and HVAC contractors to treat thermography as mission-critical.¹⁰ The updated standard outlines highly specific procedures in section 7.4, specifying that thermal imaging inspections must utilize equipment calibrated to recognized standards, define precise testing distances and spatial resolutions, and require the meticulous documentation of the

temperature differential (ΔT) for every evaluated component.¹⁰ The explicit goal of this mandate is to proactively prevent equipment failures, devastating facility fires, and severe worker injuries through condition-based assessments rather than run-to-failure models.¹⁰

2.2 NETA and NFPA 70B Temperature Differential (ΔT) Criteria

To standardize the interpretation of thermal anomalies and remove subjective guesswork from electrical inspections, the InterNational Electrical Testing Association (NETA) Maintenance

Testing Specifications provide specific severity criteria based on measured temperature differentials.¹⁴ During an inspection of electrical panels, disconnects, and terminal blocks,

thermographers analyze ΔT via two primary comparative methodologies:

1. **Comparison to Similar Components:** This is the preferred method. It involves measuring the temperature rise of a suspect component against an identical component operating under the exact same load profile (e.g., comparing the lug on Phase A to the lugs on Phase B and Phase C of a three-phase breaker or contactor).¹⁵
2. **Comparison to Ambient Air:** When no identical comparison target is available (such as a single-phase motor feed), the technician measures the temperature rise of the component above the surrounding ambient air temperature within the enclosure.¹⁵

The resulting ΔT is cross-referenced against NETA severity classifications, heavily stratified to dictate the priority and urgency of maintenance intervention.

Priority Level	Severity Classification	ΔT Rise (vs. Similar Component)	ΔT Rise (vs. Ambient Air)	Typical Causes & Required Action
Priority 1	Minor	1°C –	1°C –	Slight connection looseness. Monitor for changes; warrants investigation; repair at the next scheduled outage. ¹²
Priority 2	Intermediate	4°C –	11°C –	Moderate resistance or partial corrosion. Probable deficiency; repair within 30-90 days; increase monitoring frequency. ¹²

Priority 3	Serious	N/A	21°C –	Significant deterioration, advanced corrosion, or overloading. Major deficiency; repair at the first available opportunity; reduce load immediately if possible. ¹²
Priority 4	Critical	>	>	Imminent failure, severe overload, or insulation breakdown. Immediate action required; consider safe de-energization to prevent fire. ¹²

Diagnostic Scenario: Thermal Image of a 3-Phase Blower Motor Contactor

A thermal survey is conducted on a rooftop unit's main electrical control cabinet. In the visual light spectrum, the 3-phase contactor for the 20-horsepower supply blower appears perfectly normal; there is no melted plastic or discoloration. However, the thermal image, utilizing an Ironbow palette, reveals a stark anomaly. The wire terminating at the L1 lug is glowing a bright, intense white, registering a localized temperature of 85°C. The adjacent L2 and L3 lugs are a deep purple, registering at 35°C. This indicates a ΔT (vs. similar component) of 50°C, placing it firmly in the **Priority 4 (Critical)** severity tier. The diagnostic interpretation is a severe loose connection at the L1 lug causing extreme localized I^2R heating. Without immediate intervention, the intense heat will eventually melt the contactor housing, cause a phase loss, and potentially trigger an arc flash or electrical fire.

2.3 The Load Factor and the Correction Formula

A significant limitation of utilizing a raw ΔT classification table is that the baseline metrics do not inherently account for the actual electrical load or the ambient environmental conditions imposed upon the equipment at the exact moment of the infrared inspection.¹⁴ For the NETA standards to be applied meaningfully, thermographers must establish the context of the load. NETA standard protocols strictly stipulate that a valid infrared inspection must be conducted with the electrical equipment carrying a minimum of 40% of its rated load, or at the highest normal operating load possible.¹⁴ If an HVAC system is operating at only 10% load during a mild shoulder season, a severely loose connection may not generate sufficient heat to break through the internal thermal mass and become detectable by the infrared camera. A heavily degraded connection can lay dormant and invisible under light loading, only to catastrophically fail when the system reaches peak demand during summer.¹⁴ To mathematically adjust a measured temperature to reflect what the component's temperature would be if it were operating at 100% load, diagnosticians must utilize the load correction equation (often referenced from Paul Gill's testing frameworks)¹⁴:

$$T_{allowable} = (T_{rated} - T_{ambient_rated}) \times \left(\frac{I_{measured}}{I_{rated}} \right)^{1.8} + T_{ambient_measured}$$

Where T_{rated} is the manufacturer's maximum temperature rating for the equipment, $I_{measured}$ is the actual current measured during the inspection, and I_{rated} is the maximum rated current.¹⁴ This non-linear mathematical adjustment reflects the physical reality that heat generation increases exponentially by the square of the current ($I^2 R$). By correcting for load, the thermographer ensures that components currently operating safely under a 45% partial load will not exceed critical thermal breakdown limits when the facility reaches maximum power demand.¹⁴

2.4 Safe Execution: Open Panel vs. IR Windows

The execution of electrical thermography is heavily governed by NFPA 70E (Standard for Electrical Safety in the Workplace). Because infrared radiation in the long-wave spectrum cannot penetrate solid steel panel covers, polycarbonate shields, or standard glass windows, historical thermography methods required technicians to physically remove energized panel covers to obtain a direct line-of-sight to the busbars and conductors.¹⁴

Taking measurements with covers removed creates extreme safety hazards. It exposes the thermographer to live conductors, necessitating the use of highly restrictive, arc-rated Personal Protective Equipment (PPE), establishing approach boundaries, and fundamentally increasing the risk of a deadly arc flash incident triggered by a dropped tool or shifting panel.¹⁹ Furthermore, a technician may be qualified to operate a thermal camera but legally unqualified

under NFPA 70E to open a specific energized cabinet.¹⁴

The modern, significantly safer, and highly efficient alternative is the installation of permanent Infrared Windows (IR Windows) into the equipment housings.¹⁹ These specialized access points utilize engineered optical crystals or robust polymer panes that transmit infrared wavelengths while maintaining the physical barrier of the electrical enclosure.¹⁹

- **Advantages of IR Windows:** Inspecting through an IR window completely eliminates the need for panel removal. This allows inspections to be conducted much faster, dramatically reduces the required PPE, and mitigates the risk of arc flash exposure to near zero.²⁰ Furthermore, from a diagnostic perspective, keeping the cabinet sealed prevents the sudden influx of cooler ambient air from altering the internal cooling dynamics of the components, leading to a more accurate representation of the equipment's true operating temperature.¹⁹
- **Polymer vs. Crystal:** Standard infrared panes made of thin polymers have low melting points; while they protect against accidental human contact, they afford very little physical protection in the event of an explosive arc fault.¹⁹ High-grade engineered IR windows provide a solid physical barrier explicitly designed to withstand the massive blast pressures and thermal energy of an arc flash, ensuring the operator's physical safety while allowing high-fidelity thermal transmittance.¹⁹

2.5 Before/After Documentation for Client Reports

A critical element of professional electrical thermography is the creation of defensible, code-compliant inspection reports. Thermographers must document their findings meticulously to protect both their clients and their professional licenses.¹¹ A high-quality report must explicitly provide before-and-after documentation. When a Priority 1 through Priority 4 anomaly is discovered, the initial report must document the exact thermal image, alongside a standard visible-light reference photo, to clearly identify the faulted component to the repair electrician.⁹

Following the repair (e.g., cleaning the corrosion and re-torquing the L1 lug to manufacturer specifications), a post-repair thermal scan must be conducted under similar load conditions. This "after" image serves as the definitive proof of remediation, demonstrating to the client and regulatory auditors that the thermal anomaly has been extinguished and the equipment has been restored to a normal baseline.⁹

3. Refrigerant Circuit Diagnostics

Thermography revolutionizes refrigeration circuit analysis by providing a holistic, visual macro-view of the entire thermodynamic cycle. Traditional diagnostics rely heavily on pressure manifolds and single-point temperature probes (like thermocouples), which only provide data at specific, isolated nodes. An infrared camera, conversely, allows the technician to visualize phase changes, heat transfer efficiency, and flow restrictions across the entire geometry of the system simultaneously.²⁴

3.1 Visualizing Evaporator Coil Temperature Distribution

In an optimally functioning evaporator coil, the cold liquid-vapor refrigerant mixture boils steadily as it travels through the copper circuits, absorbing sensible heat from the warm return air stream.²⁶ An infrared camera provides an unparalleled visual map of this heat transfer process.

- **Airflow Restrictions vs. Refrigerant Maldistribution:** A primary cause of poor cooling capacity is an uneven temperature distribution across the coil face. When inspecting the coil with a thermal imager, a technician can quickly isolate the root cause. If dust, lint, or biological growth blocks specific fin passages, it prevents warm air from passing over those specific tubes. The thermal scan will display distinct, abnormally cold patches where the refrigerant is not absorbing heat due to the lack of airflow.²⁶ Conversely, if the air side of the coil is perfectly clean, but the thermal image still shows patchy, disjointed hot and cold circuits, the diagnostic conclusion points to poor refrigerant distribution. This occurs when a multi-circuit distributor fails to feed liquid evenly into all capillary tubes, causing some circuits to flood while others starve.²⁸
- **The Starved vs. Flooded Coil:** If an evaporator is starved of refrigerant (due to a low system charge or a restricted metering device), the small amount of liquid refrigerant entering the coil boils off completely too early in the circuit. The thermal image will show a highly localized, intensely cold section right at the inlet header, while the vast majority of the coil down the line operates at a much warmer, high-superheat state.³⁰ A flooded coil, caused by an overcharge or a stuck-open expansion valve, will exhibit a uniform, overly cold signature extending all the way through the coil and down into the suction line, signaling a high risk of liquid slugging at the compressor.³¹

Diagnostic Scenario: Evaporator Coil Freezing A client reports zero airflow from their registers. Upon opening the air handler, a thermal scan of the A-coil is taken. Instead of a uniform cool gradient, the bottom third of the coil presents as a deep, solid black/blue in the

Ironbow palette, indicating temperatures well below 32°F (0°C), while the top two-thirds is warm room air. The visual indicates an iced section blocking airflow. Because the freezing pattern is concentrated entirely on the lowest circuits fed by the distributor, the thermographer diagnoses a severe restriction in the specific capillary tubes feeding those lower circuits, causing a localized pressure drop and freezing, rather than a whole-system low charge which would typically starve the entire coil more uniformly.³²

3.2 Locating Liquid Line Restrictions

Liquid line restrictions represent a classic diagnostic challenge in refrigeration.³³ Contaminants clogging a filter drier, a physical kink in the copper line, solder blocking a joint, or debris caught in a solenoid valve orifice act as unintended metering devices.³⁴

When liquid refrigerant traveling under high pressure encounters a restriction, it experiences a sudden, localized pressure drop. Due to the thermodynamic principles of the Joule-Thomson effect, a portion of the high-pressure liquid flashes into vapor, absorbing latent heat and causing a corresponding sudden drop in the sensible temperature of the pipe.³³

While traditional diagnostic procedures involve carefully strapping dual-temperature probes

across a filter drier and waiting for stabilization to hunt for a $> 3^{\circ}\text{F}$ differential, a thermal imaging camera makes the invisible pressure drop instantaneously visible.³⁵ Analytically, a normal, functioning filter drier exhibits a negligible temperature drop across its body, typically mapping uniformly from inlet to outlet.³⁵ In stark contrast, a restricted drier acts as an unintended metering device. The thermal data reveals localized flashing and a distinct

temperature drop—often exceeding 3°F —across the component, transitioning abruptly from a warm to a cool palette.³⁶ The thermographer visually observes a stark thermal gradient on the camera screen: a hot, bright color on the high-pressure inlet side that abruptly transitions to a dark, cold shade precisely at the physical point of the restriction.²⁴

3.3 Thermostatic Expansion Valve (TXV) Diagnostics

The Thermostatic Expansion Valve (TXV) is a highly dynamic mechanical component that throttles refrigerant based on the precise balancing of three continuous forces: bulb pressure (which pushes down on the diaphragm to open the valve), spring pressure (which pushes up to close the valve), and evaporator pressure (which also pushes up to close the valve).³⁸

When diagnosing an air conditioning system exhibiting high superheat, low evaporator pressure, and low compressor amp draw, technicians frequently jump to the conclusion that the TXV has failed.³⁰ However, thermal imaging provides a nuanced, multi-point view of the valve's operation without connecting gauges. By observing the TXV body, the capillary distributor tubes, and the sensing bulb simultaneously, technicians can diagnose the specific mode of failure:

- **Bulb Failure vs. Valve Blockage:** If the thermal sensing bulb loses its internal chemical charge due to a microscopic leak, it can no longer generate downward pressure against the diaphragm. Consequently, the internal spring forces the valve permanently shut, starving the evaporator.³⁷ A thermal image of this scenario will confirm that the valve body itself remains relatively warm, as no liquid refrigerant is passing through to flash and drop the temperature.³⁷ Conversely, if the valve is receiving pressure but the inlet screen is heavily clogged with debris, the thermal camera will show the temperature drop occurring unnaturally early—across the strainer body before the actual valve seat.³¹
- **TXV Hunting:** During system start-up or sudden load changes, a TXV will naturally "hunt," rapidly opening and closing as the bulb pressure and evaporator pressure struggle to find equilibrium. A thermal camera, particularly when utilizing video recording features, vividly visualizes this thermal inertia and hysteresis.⁴⁰ The operator can watch rapid, oscillating waves of cold and warm refrigerant pulsing through the distributor tubes and across the coil surface until the system stabilizes.⁴⁰

3.4 Suction Line Insulation Integrity

The suction line carries cold, low-pressure refrigerant vapor from the evaporator back to the compressor. Because this line runs below the dew point of the ambient air, it must be thoroughly insulated to prevent condensation, water damage, and the absorption of unwanted

sensible heat from the environment. Thermal imaging allows technicians to rapidly assess the integrity of this insulation over long runs.⁴² If the elastomeric insulation has degraded, ripped, or was improperly sealed at the joints, the thermal camera will instantly highlight the exposed copper pipe as a brilliant cold spot against the warm ambient background. Detecting and repairing these failed insulation points prevents energy loss and eliminates the risk of condensation dripping onto ceiling tiles or sensitive building materials below.

3.5 Visualizing Condenser Subcooling

The outdoor condenser coil serves three sequential thermodynamic functions: desuperheating the hot discharge gas exiting the compressor, condensing the saturated vapor into a liquid, and finally, subcooling that liquid refrigerant below its saturation temperature.²⁴

Scanning a condenser coil with a thermal imager yields a profound visual map of these three physical phases:

1. **Desuperheating Zone:** The topmost circuits of the condenser appear intensely hot, glowing brightly as sensible heat is violently rejected from the high-temperature superheated vapor.²⁴
2. **Condensing (Saturation) Zone:** The middle, and largest, section of the coil displays a massive, thermally uniform band. Because the phase change from vapor to liquid occurs at a constant saturation temperature, the thermal camera registers a wide plateau where latent heat is rejected without any change in sensible temperature.²⁴
3. **Subcooling Zone:** Near the very bottom rows of the coil, the temperature abruptly drops again. This signifies that the refrigerant has become **100%** liquid, and the condenser is now removing sensible heat to achieve subcooling before sending the liquid to the expansion valve.²⁴

Thermal imaging is extraordinarily valuable when diagnosing liquid stacking, a condition where an overcharge of refrigerant or a restriction causes liquid to back up excessively into the condenser coil.⁴⁴ This robs the system of internal condensing volume and skyrockets the compressor head pressure.⁴⁴ A thermal scan instantly reveals an abnormally large subcooling zone at the bottom of the coil relative to the condensing zone.³

Furthermore, modern low-GWP refrigerant blends (such as R-454B) introduce complex diagnostic challenges like temperature glide and fluid density stratification within the condenser.⁴⁵ Traditional pressure-to-temperature gauge conversions struggle to accurately capture this complex reality, whereas thermal imaging provides a direct, pressure-independent visual verification of the actual liquid state exiting the condenser.⁴⁵

4. Building Envelope and Ductwork Assessment

The efficiency and cooling capacity of an HVAC system are inextricably linked to the integrity of the building envelope it conditions and the ductwork responsible for distributing the air. Thermography excels at exposing structural failures in the thermal boundary that are entirely invisible to the naked eye.

4.1 Air Infiltration and Exfiltration

Thermal imaging does not "see" air; rather, it reveals air movement by capturing the convection signatures that the air leaves on solid surfaces.⁴⁶ In the winter, cold exterior air leaking into the building around poorly sealed window casings, degraded door weather-stripping, or plumbing penetrations cools the adjacent interior wall surfaces. The thermal camera clearly identifies these cold streaks radiating inward from the breach.⁴⁷ During the summer, hot, unconditioned attic air being pulled down into the living space through recessed lighting fixtures, ceiling chases, or poorly sealed attic hatches creates distinct, abnormal hot spots on the ceiling drywall.⁴⁶

The efficacy of an air leakage survey relies heavily on establishing proper environmental conditions. A minimum temperature differential of **10°F** to **15°F** between the interior conditioned space and the exterior environment is generally required to produce a sufficient thermal contrast for reliable leak detection.⁴⁷

4.2 Insulation Deficiencies and Thermal Bridging

Thermal cameras are highly adept at mapping hidden wall and ceiling cavities. Voids, material settling, or completely missing fiberglass batts or spray foam insulation result in stark geometric temperature anomalies that perfectly mirror the framing of the wall stud bays.⁴⁶ Additionally, thermography highlights the phenomenon of thermal bridging—where highly conductive structural materials, such as steel studs or solid wood framing, bypass the insulation layer and transfer heat directly between the exterior and interior.⁴³ Technicians use this data to identify complex building chases and top-plate leakage, allowing for targeted air sealing and insulation remediation that can improve overall HVAC system efficiency by up to 30%.⁴⁶

4.3 Ductwork Integrity and Supply Distribution

Ductwork routed through hostile, unconditioned spaces (such as 130°F attics or freezing crawlspaces) represents a massive potential vector for capacity loss. Thermal imaging quickly and decisively evaluates the integrity of both supply and return ducting:

- **Supply Leaks:** Conditioned air escaping from disconnected sheet metal joints, unsealed plenums, or torn flex duct creates a highly visible thermal plume. The camera captures the anomalous temperature of the escaping air cooling or heating the surrounding attic structure against the extreme ambient background.²
- **Return Leaks:** Leaky return ducts are particularly devastating. Because they operate under negative pressure, a leak sucks extreme ambient heat, humidity, or frigid winter air directly into the air handler, drastically increasing the latent and sensible load on the system.⁴⁸ While the leak itself is drawing air *in*, the thermal camera will highlight the casing of the return duct and the surrounding structural members experiencing abnormal temperature shifts due to the massive volumetric draw.⁴⁷
- **Missing Insulation:** Sections of ductwork with compromised, wet, or missing exterior

insulation will show widespread surface temperatures closely matching the internal air temperature, indicating severe, continuous heat transfer with the unconditioned space.⁴²

- **Verifying Supply Air Distribution:** Beyond the ductwork itself, thermography is used to verify the performance of diffusers and registers within the conditioned space. By pointing the camera at a ceiling register, a technician can visualize the throw and drop of the conditioned air as it washes over the ceiling and walls. This confirms whether the diffuser is properly mixing the air or if a damper is closed, creating stagnant zones.

5. Motor and Mechanical Equipment Assessment

Mechanical degradation in HVAC systems—whether in heavy commercial chillers, cooling towers, or simple blower assemblies—primarily manifests through increased friction and subsequent thermal emission. By utilizing thermography in conjunction with vibration analysis and ultrasound, facilities can identify root causes and preempt catastrophic failures in rotating equipment, aligning closely with ISO 18434-1 and ISO 17359 condition monitoring standards.²³

5.1 Rolling Element Bearing Monitoring

Bearings represent the most ubiquitous point of failure in motors and blowers. Abnormal heat generation in a bearing assembly can result from multiple distinct failure modes, all of which are detectable via thermal imaging:

- **Lack of Lubrication:** Insufficient grease leads to direct metal-on-metal friction, generating immediate, intense localized heat.⁴⁹
- **Over-Lubrication:** Pumping excess grease into a bearing housing creates severe fluid friction and prevents the bearing from shedding heat properly. The excess grease acts as an insulating blanket, driving up internal temperatures and causing early failure.⁴⁹
- **Mechanical Wear or Contamination:** Physical damage such as spalling, brinelling, or particulate contamination within the raceway drastically increases friction coefficients.⁴⁹

As a baseline diagnostic standard, the exterior bearing housing temperature should typically

operate 5°F to 10°F (3°C to 5°C) warmer than the motor's end-bell housing.⁵⁰ If a

thermal scan reveals that the bearing is running 20°C (68°F) or more above its established baseline, it constitutes a severe, actionable fault.²³ A proactive thermal scan identifying an

early-stage 20°C elevation allows a facility to perform a planned bearing replacement for

roughly $\$2,500$. Left undetected, that exact same bearing will seize, causing catastrophic shaft damage that requires an emergency crane lift and expedited parts, potentially exceeding

$\$75,000$ in repair costs and lost production.²³

5.2 Mechanical Couplings and Alignment

Couplings are designed to mechanically transmit torque from a driver (such as a motor) to a driven component (such as a chilled water pump) while accommodating marginal amounts of parallel or angular misalignment without damaging the shafts.⁴ Thermography provides vital

intelligence regarding the health of these connections.

- **Normal Signatures:** A healthy mechanical flex coupling generally acts as a heat sink. Spinning rapidly, it undergoes significant convective cooling and should appear relatively cool on a thermal scan, roughly matching the ambient air temperature. The adjoining shafts will appear progressively warmer the closer they get to the motor or pump bearings.⁴
- **Misalignment Faults:** Severe parallel or angular misalignment dramatically reduces the life of a coupling, causing excessive radial load, bending moments, and tremendous internal friction within the coupling insert (the spider).⁴ Diagnostically, a failing mechanical coupling will characteristically display **one-sided heating**. Because the air gap between the two metal hubs prevents heat transfer, the side enduring the highest physical stress will heat up significantly more than the other.⁴
- **Fluid and Magnetic Couplings:** Unlike mechanical flex couplings, fluid and magnetic couplings natively operate at elevated temperatures due to continuous fluid shear and magnetic eddy currents.⁴ When diagnosing a failing fluid coupling (e.g., due to low fluid level causing excessive slip), the camera will show elevated temperatures uniformly distributed across the entire fluid cavity, rather than asymmetrically.⁴

5.3 Belt Drives and Sheaves

Belt-driven blowers and exhaust fans suffer heavily from poor maintenance practices, requiring precise tensioning and alignment to function efficiently.

- **Belt Tension Issues:** Over-tensioned belts exert immense radial loads on the shafts, causing the pulley and motor bearings to overheat intensely.⁵¹ Conversely, under-tensioned belts slip loosely within the sheave grooves, generating extreme friction. A thermal camera will reveal dangerously high temperatures running consistently along the length of the belt itself and across the outer rim of the sheave.⁵¹
- **Sheave Misalignment:** Angular (pitch) or parallel (offset) misalignment creates highly uneven friction. An angular misalignment of just $1/2$ degree causes the belt to scrub violently against the sidewall of the sheave groove.⁵² When a sheave suffers from angular misalignment, the drive belt scrubs aggressively against one sidewall of the groove. This concentrated friction generates an asymmetrical thermal signature clearly visible to an infrared camera, with radiant heat concentrated entirely on the scrubbing edge rather than distributed evenly across the sheave.⁵²

5.4 Industrial Pumps and Seals

For large-scale chilled water, condenser water, or boiler feed pumps, thermal imaging is used to monitor the entire pump casing, the seal flush systems, and the underlying hydraulic behavior.²³ Mechanical seal degradation produces highly localized hot spots directly around the shaft seal, providing early warning of critical leaks.²³ Furthermore, severe hydraulic restrictions, such as intake blockages or damaging cavitation, reveal themselves as highly uneven thermal gradients across the pump volute casing, indicating that the fluid dynamics within the pump are violently

unbalanced and chaotic.²³

6. Best Practices for HVAC Thermography

The fundamental accuracy and diagnostic value of any thermographic survey depend entirely on the operator's methodological rigor, precise camera configuration, and deep awareness of how environmental variables manipulate infrared physics.

6.1 Camera Settings: Palette, Range, and Focus

Thermal cameras algorithmically map calculated temperature data points to a visual color gradient known as a palette. Selecting the correct palette is critical for highlighting specific diagnostic anomalies⁵⁸:

- **Ironbow (Iron):** The absolute standard for electrical and mechanical inspections.⁶⁰ It utilizes dark, cool colors (purples and blues) for background ambient temperatures and transitions sharply through reds, oranges, and bright yellows for hot spots.⁶⁰ It is exceptionally good at drawing the human eye to isolated, high-contrast thermal anomalies, such as a single loose lug on a terminal block or an overheating bearing.⁶⁰
- **Rainbow:** Similar to Ironbow but injects a much wider, more complex spectrum of colors.⁶¹ The Rainbow palette is superior for environments with minimal heat differences, as the varied, tight color bands forcefully exaggerate subtle temperature gradients.⁶¹ It is highly effective for building envelope surveys, mapping ductwork leaks, or tracing the subtle cooling effect of moisture intrusion.⁶¹
- **Greyscale (White Hot / Black Hot):** Maps temperatures linearly to shades of grey. This palette offers the highest level of structural detail and crisp mechanical resolution.⁵⁸ It is often used to orient the user to complex mechanical assemblies before switching to a high-contrast palette like Ironbow to pinpoint the specific heat source.

Beyond palettes, technicians must manually control the **Temperature Range (Level and Span)**. Relying purely on the camera's auto-scaling feature can mask subtle issues if a highly extreme hot or cold object is in the background, as the camera stretches the palette to accommodate the extreme outlier. Manually narrowing the span over a specific target drastically increases the color contrast of that specific component. Finally, precise **Focus Distance** is non-negotiable. An out-of-focus thermal image is not just blurry; it mathematically compromises the spatial resolution and results in highly inaccurate temperature calculations.⁹

6.2 Environmental Interference and Error Mitigation

Thermographers must aggressively manage environmental variables that can skew radiometric data or entirely obscure underlying mechanical issues.

- **Solar Loading:** Direct sunlight imparts massive amounts of radiant energy onto equipment casings, roofs, and exterior walls. A thermal scan of an outdoor condensing unit or a rooftop disconnect under direct solar load is highly unreliable, as the immense solar heating easily masks internal electrical or mechanical faults.² Building exterior inspections should be conducted under heavy cloud cover, in the early morning, or after sunset to ensure the thermal signatures observed are internally generated rather than

solar reflections.²

- **Convective Cooling (Wind):** Moderate to high winds rapidly strip heat away from component surfaces via convective cooling. A failing, hot electrical connection measured during a **15 mph** wind will read significantly cooler than it actually is—potentially dropping it down an entire NETA severity tier—falsely indicating safety and masking a critical fault.²
- **Reflectivity and the Narcissus Effect:** When inspecting highly reflective, low-emissivity targets (e.g., bare aluminum condenser fins or polished steel panels), the camera acts as a mirror for background radiation. If the thermographer stands at a direct **90°** perpendicular angle to the target, the camera may reflect the thermographer's own body heat or the heat of the camera core itself (known as the Narcissus effect), creating a false hotspot.² Best practice dictates viewing reflective targets at a slight angle (**5°** to **30°** off-perpendicular) to ensure reflections bounce off harmlessly to a known, stable background temperature.⁶³

6.3 Comprehensive Report Generation and CMMS Integration

The final deliverable of a professional thermographic survey is the inspection report. The quality of the report dictates the actionable value of the data. A high-quality report must always include a standard, visible-light digital photograph taken from the exact same angle and distance directly alongside the thermal image.² This side-by-side comparison is absolutely essential for the repair electrician or HVAC mechanic to definitively identify the faulted component within a crowded panel or complex mechanical room.⁹

Reports must explicitly document all relevant parameters: the environmental conditions (ambient temperature, wind speed), the equipment's load factor at the time of inspection, the assumed emissivity values programmed into the camera, and the calculated ΔT severity rating.¹⁰ Furthermore, modern predictive reliability programs require that these thermal findings be integrated directly into a Computerized Maintenance Management System (CMMS).¹² Transforming an isolated thermal image into a trackable CMMS work order ensures that lower-level Priority 1 or 2 anomalies are consistently monitored, trended over time, and systematically resolved during planned outages, rather than being forgotten until they result in a catastrophic system failure.¹²

Referências citadas

1. Facilities Instructions, Standards, and Techniques Volume 4-13 - Thermal Analysis - Bureau of Reclamation, acessado em junho 13, 2026, https://www.usbr.gov/power/data/fist/fist4_13/vol4-13.pdf
2. Thermal Imaging Camera Training for HVAC Techs - YouTube, acessado em junho 13, 2026, <https://www.youtube.com/watch?v=4yn2Wf9s3oY&vl=en>
3. Thermal camera TH267 FLIR . Compressor and condenser & lines chill as

- refrigerant is recovered - YouTube, acessado em junho 13, 2026,
<https://www.youtube.com/watch?v=lgemhvKqKig>
4. The Snell Group Thermographic Inspection of Mechanical Couplings, acessado em junho 13, 2026,
<https://www.thesnellgroup.com/sites/default/files/2021-06/thermographic-inspection-mechanical-couplings.pdf>
 5. Microbolometer - Wikipedia, acessado em junho 13, 2026,
<https://en.wikipedia.org/wiki/Microbolometer>
 6. What is a microbolometer? - Sierra-Olympia Tech., acessado em junho 13, 2026,
<https://sierraolympia.com/what-is-a-microbolometer/>
 7. VOx vs Amorphous Silicon Infrared Detectors | Key Differences & Performance Comparison, acessado em junho 13, 2026,
<https://www.sytophotonics.com/blog/differences-between-vanadium-oxide-and-amorphous-silicon-infrared-detector-technologies.html>
 8. Uncooled Infrared Detectors: VOx Vs. α -Si, acessado em junho 13, 2026,
<https://www.gst-ir.net/news-events/infrared-knowledge/357.html>
 9. Troubleshoot HVAC/R with affordable thermal imaging - Flir, acessado em junho 13, 2026, <https://www.flir.com/instruments/hvac-r/>
 10. NFPA 70B 2023 Update: Annual Infrared Thermography Inspections Now Required, acessado em junho 13, 2026,
<https://www.assuredndt.com/post/nfpa-70b-2023-update-annual-infrared-thermography-inspections-now-required>
 11. Understanding the colors on the NFPA 70B and NETA Severity Scale for Electrical Thermography - YouTube, acessado em junho 13, 2026,
<https://www.youtube.com/watch?v=tXUtcgdpcls>
 12. Infrared Thermography for Electrical Maintenance: Prevent Arc Flash ..., acessado em junho 13, 2026,
<https://oxmaint.com/blog/post/blog-post-infrared-thermography-electrical-maintenance>
 13. Reviewing the Specific Thermography Regulations within NFPA 70B 2023, acessado em junho 13, 2026,
<https://www.infraredtraining.com/en-US/home/free-learning/blog/reviewing-the-specific-thermography-regulations-within-nfpa-70b-2023/>
 14. Infrared Thermography for Electrical Distribution Systems - Articles ..., acessado em junho 13, 2026,
<https://wiki.testguy.net/t/infrared-thermography-for-electrical-distribution-systems/75>
 15. Thermal Imaging Reference - PowersYourTeam, acessado em junho 13, 2026,
https://powersyourteam.com/thermal_imaging
 16. What is a Delta T (ΔT) in Thermography? - The Drone Life, acessado em junho 13, 2026, <https://thedronelifenj.com/delta-t-thermography/>
 17. Infrared Thermography Quarterly Route Checklist (Power Plant) - Oxmaint, acessado em junho 13, 2026,
<https://oxmaint.com/industries/power-plant/infrared-thermography-quarterly-route-checklist-power-plant>

18. Using thermal imaging to troubleshoot motors and drives
www.MyFlukeStore.com, acessado em junho 13, 2026,
<https://www.myflukestore.com/pdfs/cache/www.myflukestore.com/ti300-60hz/bonuscontent/ti300-60hz-bonuscontent.pdf>
19. Electrical Safety in the Workplace Pt 3 – The Electrical Thermographer and IR Windows, acessado em junho 13, 2026,
<https://jmttest.com/electrical-safety-in-the-workplace-pt-3-the-electrical-thermographer-and-ir-windows/>
20. Infrared Electrical Inspection Guide: Techniques & Best Practices - IRISS, Inc., acessado em junho 13, 2026,
<https://iriss.com/discover/blog/infrared-electrical-inspection-a-complete-guide-for-professionals/>
21. Should panel covers be removed to perform an IR survey of electrical switchgear?, acessado em junho 13, 2026,
https://reliabilityweb.com/articles/entry/should_panel_covers_be_removed_to_perform_an_ir_survey_of_electrical_switch
22. Covers and Panels: Should They Really Be Taken Off? - Infrared Consulting Services, acessado em junho 13, 2026,
<https://irtest.com/covers-panels-really-taken-off/>
23. Thermal Imaging for Industrial Pumps | Industrial Equipment News, acessado em junho 13, 2026,
<https://www.ien.com/operations/article/22953873/thermal-imaging-for-industrial-pumps>
24. The Many Uses of Thermal Imaging Cameras in HVAC, acessado em junho 13, 2026,
<http://www.hvacrschool.com/the-many-uses-of-thermal-imaging-cameras-in-hvac/>
25. HVAC Diagnosis Using Thermal Imaging | Snap-on Diagnostics - YouTube, acessado em junho 13, 2026, <https://www.youtube.com/watch?v=fEw6ll9eWP0>
26. Common Issues in Fin Tube Evaporator Coils and Troubleshooting Tips, acessado em junho 13, 2026,
<https://www.welltechcoolingsystems.com/common-issues-in-fin-tube-evaporator-coils-and-troubleshooting-tips/>
27. Fixing Uneven Cooling: Could Your Evaporator Coil Be Partially Blocked? - Micro Coils, acessado em junho 13, 2026,
<https://microcoils.in/fixing-uneven-cooling-could-your-evaporator-coil-be-partially-blocked/>
28. Analysis of Refrigerant Flow Distribution in Evaporators - Purdue e-Pubs, acessado em junho 13, 2026,
<https://docs.lib.purdue.edu/cgi/viewcontent.cgi?article=1965&context=iracc>
29. Refrigerant distribution in microchannel evaporator at multiport tube level | Insights - Kaltra, acessado em junho 13, 2026,
<https://www.kaltra.com/single-post/2025/02/18/mche-refrigerant-distribution-tube-level>
30. The Symptoms of a Restricted TXV | 2017-01-09 | ACHRNEWS, acessado em

junho 13, 2026,

<https://www.achrnews.com/articles/134216-the-symptoms-of-a-restricted-txv>

31. How to Tell Whether Your TXV is Bad - techtown forum, acessado em junho 13, 2026,
<https://www.techtownforum.com/knowledge-base/equipment-appliances/refrigeration/how-to-tell-whether-your-txv-is-bad/>
32. How I Diagnose a Bad TXV | Thermostatic Expansion Valve - YouTube, acessado em junho 13, 2026, <https://www.youtube.com/watch?v=fkU-fRs5QXY>
33. Experimental Quantification of Liquid Line Temperature Drop As a Feature to Detect Liquid Line Restriction Faults in a Residential Heat Pump - Purdue e-Pubs, acessado em junho 13, 2026,
<https://docs.lib.purdue.edu/cgi/viewcontent.cgi?article=3244&context=iracc/1000>
34. Diagnosing and Finding a Refrigerant Restriction - HVAC School, acessado em junho 13, 2026,
<http://www.hvacrschool.com/diagnosing-finding-refrigerant-restriction/>
35. Determining the Cause of a Liquid Line Restriction Problem! - AC Service Tech, acessado em junho 13, 2026,
<https://www.acservicetech.com/post/determining-the-cause-of-a-liquid-line-restriction-problem>
36. The Professor: Systematic Troubleshooting of a Restricted Liquid Line - ACHR News, acessado em junho 13, 2026,
<https://www.achrnews.com/articles/117937-the-professor-systematic-troubleshooting-of-a-restricted-liquid-line->
37. Liquid Line Restriction on AC Unit Explained! Found Bad TXV! - YouTube, acessado em junho 13, 2026, https://www.youtube.com/watch?v=_yLMv7T2hhM
38. How thermostatic expansion valves work - Danfoss, acessado em junho 13, 2026,
<https://www.danfoss.com/en-us/service-and-support/case-stories/dcs/how-thermostatic-expansion-valves-work/>
39. How to Diagnose a TXV Failure - HVAC School, acessado em junho 13, 2026,
<http://www.hvacrschool.com/how-to-diagnose-a-txv-failure/>
40. Thermal image of R410a TXV evaporator on startup - YouTube, acessado em junho 13, 2026, <https://www.youtube.com/watch?v=ZWcF8YPhf0c>
41. How TXV thermal Inertia and Hysteresis will effect the Evaporator super heat and how to calculate these parameters based on 4-quadrant Chart? | ResearchGate, acessado em junho 13, 2026,
https://www.researchgate.net/post/How_TXV_thermal_Inertia_and_Hysteresis_will_effect_the_Evaporator_super_heat_and_how_to_calculate_these_parameters_based_on_4-quadrant_Chart
42. 6 Ways to Use Thermal Imaging for HVAC Maintenance - HIKMICRO, acessado em junho 13, 2026,
<https://www.hikmicrotech.com/th/explore/industrial-blog/6-ways-to-use-thermal-imaging-for-hvac-maintenance/>
43. Thermographic Inspection: An In-Depth Guide [New for 2026], acessado em junho 13, 2026, <https://mfe-is.com/thermographic-inspection/>
44. What is your series of operations for diagnosing and then locating a restriction? -

- Reddit, acessado em junho 13, 2026,
https://www.reddit.com/r/HVAC/comments/ol579c/what_is_your_series_of_operations_for_diagnosing/
45. Subcooling with R-454B: Measurement and Troubleshooting - HVAC School, acessado em junho 13, 2026,
<http://www.hvacrschool.com/videos/subcooling-with-r-454b-measurement-and-troubleshooting/>
 46. What Is Thermal Imaging for Insulation? | How FLIR Scans Find Hidden Problems, acessado em junho 13, 2026,
<https://allstar-insulation.com/blog/what-is-thermal-imaging-insulation>
 47. The Role of Thermal Imaging in Identifying Home Energy Leaks - Rogers Insulation, acessado em junho 13, 2026,
<https://www.rogersinsulation.com/the-role-of-thermal-imaging-in-identifying-home-energy-leaks/>
 48. Infrared Camera Finds Air Leaks & Missing Insulation! - YouTube, acessado em junho 13, 2026, <https://www.youtube.com/watch?v=9QVFhjmMwXg>
 49. Utilizing Infrared Thermography on Mechanical Assets to Increase Reliability, acessado em junho 13, 2026,
<https://www.cbmconnect.com/utilizing-infrared-thermography-on-mechanical-assets-to-increase-reliability/>
 50. Using Infrared Thermography on Bearings | The Snell Group, acessado em junho 13, 2026,
<https://www.thesnellgroup.com/featured-tips/using-infrared-thermography-bearings>
 51. Sheave Alignment and Belt Tension: It Matters More Than You Think! - Ludeca, acessado em junho 13, 2026,
<https://ludeca.com/blog/alignment/12551/sheave-alignment-and-belt-tension-it-matters-more-than-you-think/>
 52. belt drive system tensioning and maintenance - JC Steele, acessado em junho 13, 2026,
https://www.jcsteele.com/wp-content/uploads/TSB_GEN_0007_BELT_TENSIONING_AND_MAINTENANCE_OF_DRIVE_SYSTEMS.pdf
 53. Optimize Belt & Sheave Alignment: Expert Tips for 2026 - benchmark pdm, acessado em junho 13, 2026,
<https://benchmarkpdm.com/its-about-time-we-treat-our-belts-sheaves-with-more-respect/>
 54. V-Belt Sheave Alignment Tolerances and Why They Matter - Acoem USA, acessado em junho 13, 2026,
<https://acoem.us/blog/belt-alignment/v-belt-sheave-alignment-tolerances-and-why-they-matter/>
 55. How can we utilise thermal imaging tools? | Fluke Corporation - Professional Electrician, acessado em junho 13, 2026,
<https://professional-electrician.com/technical/how-can-we-utilise-thermal-imaging-tools-fluke-corporation/>
 56. Thermal Imaging Analysis for Pumps - ProPump Services, acessado em junho 13,

2026,

<https://www.propumpservices.com/pump-testing/thermal-imaging-analysis-for-pumps/page.aspx?id=1021>

57. Monitoring of Mechanical Seals in Process Pumps - DiVA portal, acessado em junho 13, 2026,
<https://www.diva-portal.org/smash/get/diva2:1255405/FULLTEXT01.pdf>
58. Your Perfect Palette | Flir, acessado em junho 13, 2026,
<https://www.flir.com/discover/ots/outdoor/your-perfect-palette/>
59. Thermal imaging palette - Stack Overflow, acessado em junho 13, 2026,
<https://stackoverflow.com/questions/28495390/thermal-imaging-palette>
60. Thermal Palettes Explained | How to Choose the Best Palette - Thermascan Ltd, acessado em junho 13, 2026,
<https://www.thermascan.co.uk/blog/thermal-palettes>
61. Picking a Thermal Color Palette - Flir, acessado em junho 13, 2026,
<https://www.flir.com/discover/industrial/picking-a-thermal-color-palette/>
62. In Living Color? The Colorful & Confusing Thermal Imaging Fire Service Color Palette World: - Insight Training LLC, acessado em junho 13, 2026,
<https://insighttrainingllc.com/uncategorized/in-living-color-the-colorful-confusing-thermal-imaging-fire-service-color-palette-world/>
63. THERMAL CAMERA LOOKING @ SUBCOOLING Pass on Condenser temp drop - YouTube, acessado em junho 13, 2026,
<https://www.youtube.com/watch?v=ChHyPg5Ygw4>