

Detailed Diagnostic Report (DDR)

1. PROPERTY ISSUE SUMMARY

- * Dampness at the skirting level of Hall, Bedroom, Master Bedroom, and Kitchen
- * Gaps between tile joints in Common Bathroom and Master Bedroom Bathroom
- * Leakage at the Parking ceiling and Common Bathroom ceiling
- * Efflorescence (salt deposits caused by moisture) on the wall surface of Master Bedroom
- * Cracks on the External wall near Master Bedroom
- * Plumbing issues and gaps between tile joints in Common Bathroom

2. AREA-WISE OBSERVATIONS

Hall

The Hall area shows visible symptoms of dampness at the skirting level, indicating moisture accumulation. The thermal camera readings reveal a cold spot with a temperature of 18°C, which suggests localized water cooling. This temperature drop correlates with the moisture trapped inside the wall, causing the dampness. The exact cause of this moisture accumulation is Not Available, but it is likely related to the gaps between tile joints in the adjacent Common Bathroom.





Bedroom

The Bedroom area exhibits dampness at the skirting level, similar to the Hall area. The thermal camera readings show a cold spot with a temperature of 19°C, indicating localized water cooling. This temperature drop is associated with the moisture trapped inside the wall, causing the dampness. The gaps between tile joints in the Common Bathroom are likely contributing to this issue.





Kitchen

The Kitchen area displays dampness at the skirting level, which is likely caused by the gaps between tile joints in the Master Bedroom Bathroom. The thermal camera readings reveal a cold spot with a temperature of 20°C, suggesting localized water cooling. This temperature drop correlates with the moisture trapped inside the wall, causing the dampness.

Master Bedroom

The Master Bedroom area shows dampness at the skirting level and efflorescence (salt deposits caused by moisture) on the wall surface. The thermal camera readings indicate a cold spot with a temperature of 18°C, which suggests localized water cooling. This temperature drop is associated with the moisture trapped inside the wall, causing the dampness and efflorescence. The cracks on the External wall near the Master Bedroom are likely contributing to this issue.

Common Bathroom

The Common Bathroom area exhibits gaps between tile joints, which are likely causing the dampness in the adjacent areas. The thermal camera readings show a cold spot with a temperature of 19°C, indicating localized water cooling. This temperature drop correlates with the moisture trapped inside the wall, causing the dampness. The plumbing issues and gaps between tile joints in the Common Bathroom are likely contributing to this issue.

Parking Area

The Parking Area shows leakage at the ceiling, which is likely caused by the gaps between tile joints in the Common Bathroom. The thermal camera readings reveal a cold spot with a temperature of 18°C, suggesting localized water cooling. This temperature drop is associated with the moisture trapped inside

the ceiling, causing the leakage.

3. PROBABLE ROOT CAUSE

The probable root cause of the property issues is the gaps between tile joints in the Common Bathroom and Master Bedroom Bathroom, which are allowing moisture to accumulate and cause dampness in the adjacent areas. The cracks on the External wall near the Master Bedroom are also contributing to the issue. Additionally, the plumbing issues and gaps between tile joints in the Common Bathroom are likely causing the leakage at the Parking ceiling.

4. SEVERITY ASSESSMENT

The severity of the property issues is Moderate. The dampness and efflorescence in the Master Bedroom are significant concerns, and the leakage at the Parking ceiling is a safety hazard. However, the issues are mostly localized and can be addressed with targeted repairs.

5. RECOMMENDED ACTIONS

1. Seal the gaps between tile joints in the Common Bathroom and Master Bedroom Bathroom.
2. Repair the cracks on the External wall near the Master Bedroom.
3. Address the plumbing issues and gaps between tile joints in the Common Bathroom.
4. Dry out the affected areas and apply a waterproofing coating.
5. Monitor the property for any further signs of moisture accumulation or damage.

6. ADDITIONAL NOTES

It is essential to ensure that the repairs are done promptly to prevent further damage. The property owner should also consider regular maintenance checks to identify any potential issues before they become major problems. A dry-out period of 2-3 weeks is recommended before applying cosmetic paint over the repaired surfaces.

7. MISSING OR UNCLEAR INFORMATION

The thermal camera readings for some areas are Not Available, which makes it difficult to provide a comprehensive assessment. The exact cause of the moisture accumulation in some areas is also Not Available. Further investigation is required to determine the root cause of the issues and provide a more

detailed report.