

TEST & INSPECTION PLAN - Rev 7

MVA Number:	DAoF1234	Prepared By:	Joe Barber
Date:	27/05/2026	Input Method:	Automated

ITEM 1 Op: 1150 Sampling: 100% Type: Variable Spec: >= 50 mm Bubble #: 1

Make sure that the blend radius is more than 50x the depth of the damage at the bottom.

Ref: TP-A-72-11-00-02AAA-663A-B		Process Ref:	
TAR HOLDER - PLEASE COMPLETE:			
Verification Method:	MANUAL	Equipment Type:	CALIPER - DIGITAL
MSA Verification Method:		MSA Ref / Justification:	
Responsible Person:	J Barber	Control Method:	
Reaction Plan:		Comments:	

ITEM 2 Op: 1150 Sampling: 100% Type: Variable Spec: >= 10.00 mm Bubble #: 2

The minimum blend length is 10.00 mm

Ref: TP-A-72-11-00-02AAA-663A-B		Process Ref:	
TAR HOLDER - PLEASE COMPLETE:			
Verification Method:		Equipment Type:	
MSA Verification Method:		MSA Ref / Justification:	
Responsible Person:		Control Method:	
Reaction Plan:		Comments:	

ITEM 3 Op: 1150 Sampling: 100% Type: Variable Spec: <= 100.00 mm Bubble #: 3

The total repair area after the blending is a maximum of 100.00 mm²

Ref: TP-A-72-11-00-02AAA-663A-B		Process Ref:	
TAR HOLDER - PLEASE COMPLETE:			
Verification Method:		Equipment Type:	
MSA Verification Method:		MSA Ref / Justification:	
Responsible Person:		Control Method:	
Reaction Plan:		Comments:	

ITEM 4 Op: 1150 Sampling: 100% Type: Variable Spec: <= 0.20 mm Bubble #: 4

The maximum local planarity on the pad surface is 0.20 mm

Ref: TP-A-72-11-00-02AAA-663A-B		Process Ref:	
TAR HOLDER - PLEASE COMPLETE:			
Verification Method:		Equipment Type:	
MSA Verification Method:		MSA Ref / Justification:	
Responsible Person:		Control Method:	
Reaction Plan:		Comments:	

ITEM 5 Op: 1170 Sampling: 100% Type: Attribute Bubble #: 5

Visually examine the repair area with a magnifying glass with a 10x magnification. Make sure that all the damage has been removed

Ref: TP-A-72-11-00-02AAA-663A-B		Process Ref:	
TAR HOLDER - PLEASE COMPLETE:			
Verification Method:		Equipment Type:	
MSA Verification Method:		MSA Ref / Justification:	
Responsible Person:		Control Method:	
Reaction Plan:		Comments:	

ITEM 6 Op: 1180 Sampling: 100% Type: Attribute Bubble #: 6

Do a high sensitivity fluorescent penetrant inspection of the repair area

Ref: TP-A-72-11-00-02AAA-663A-B

Process Ref:

TAR HOLDER - PLEASE COMPLETE:

Verification Method:		Equipment Type:	
MSA Verification Method:		MSA Ref / Justification:	
Responsible Person:		Control Method:	
Reaction Plan:		Comments:	

ITEM 7 Op: 1210 Sampling: 100% Type: Attribute Bubble #: 7

Visually examine the repair area to make sure that the surface finish is smooth and constant

Ref: TP-A-72-11-00-02AAA-663A-B

Process Ref:

TAR HOLDER - PLEASE COMPLETE:

Verification Method:		Equipment Type:	
MSA Verification Method:		MSA Ref / Justification:	
Responsible Person:		Control Method:	
Reaction Plan:		Comments:	

ITEM 8 Op: 1210 Sampling: 100% Type: Attribute Bubble #: 8

Visually examine the repair area to make sure that the surface finish is smooth and constant

Ref: TP-A-72-11-00-02AAA-663A-B

Process Ref:

TAR HOLDER - PLEASE COMPLETE:

Verification Method:		Equipment Type:	
MSA Verification Method:		MSA Ref / Justification:	
Responsible Person:		Control Method:	
Reaction Plan:		Comments:	

AUTHORISATION & APPROVAL

Role	Full Name	Signature	Date	Emp No.
Approved By (TAR Holder)				