NOTIONAL EXAMPLE FOR DEMONSTRATION ONLY - NOT A REAL REPORT - NO REAL PARTS, SYSTEMS OR AIRCRAFT DATA

Product Quality Deficiency Report (PQDR)

Deficiency alert - Category I - Action requested of all fleet owners

REPORT CONTROL NO.	DATE ISSUED	CATEGORY	RESPONSE REQUESTED BY
PQDR-26-0417	28 Sep 2026	I (potential mission-critical impact)	12 Oct 2026

1. ORIGINATOR AND DISTRIBUTION

ORIGINATOR	POINT OF CONTACT
Notional Depot Engineering Activity, Product Quality Branch	Notional Quality Engineer, DSN 000-0000
ACTION ADDRESSEES	**INFORMATION**
ISR/SOF Portfolio Engineering; E-7 Program Office; RC-135 Program Office; CV-22 Program Office	Notional Item Manager; Notional Supply Chain Management

2. SUSPECT ITEMS

Item	NSN	Part no. / source	Suspect lot range
Relay, electromagnetic	**5945-01-999-0101**	NTL-RLY-0101 Example Electromechanical Corp (CAGE 00000, notional)	**L24-0310 through L24-0345**
Valve, check	**4810-01-999-0202**	NTL-VLV-0202 Example Fluid Controls Inc. (CAGE 00000, notional)	**V25-0112 through V25-0140**

3. DESCRIPTION OF DEFICIENCY

Relay, NSN 5945-01-999-0101. During depot-level inspection of an unrelated platform, relays from the suspect lot range were found with contact welding and intermittent coil continuity under thermal cycling. Failure analysis attributes the condition to a plating process deviation at the source. Affected units can fail to transfer a load when commanded, which may degrade or interrupt the circuits they serve.

Valve, check, NSN 4810-01-999-0202. Check valves from the suspect lot range were found with seat defects that allow reverse flow below the specified cracking pressure. Inspection of returned units shows the seat finish is out of tolerance. Affected units may permit backflow and loss of system pressure isolation.

4. BASIS FOR SUSPECT LOT RANGE

Lot ranges above are the ranges delivered by the source during the affected production window. Units outside these ranges are not currently suspect. Lot or serial data for installed units must be confirmed against as-installed configuration records, as supply-chain lot data may not reflect installation history.

5. ACTION REQUESTED

1.	Identify every installation of the NSNs above across your fleet, by tail number, installed assembly, location, and lot or serial number.
2.	Compare installed lot or serial numbers to the suspect lot ranges and report which installed units fall inside them.
3.	State the coverage of your response: which tails and records were searched, the report dates, and any tails or records not checked.
4.	Hold suspect-lot spares from issue pending disposition. Do not return suspect units to stock.
5.	Respond to the originator by the date above. Respond even if no installations are found.

6. REFERENCES

Failure analysis report FA-26-0417 (notional). Supplier corrective action request SCAR-26-0092 (notional). Related GIDEP Alert reference: GIDEP-26-A-0417 (notional).