10 CFR 50.73

Jennifer L. Spina
Vice President
Nuclear Regulatory & Oversight

Palo Verde
Nuclear Generating Station
P.O. Box 52034
Phoenix, AZ 85072
Mail Station 7602
Tel: 623.393.4621

102-09044-JLS/TMG
March 05, 2026

U.S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, DC 20555-0001

Subject: **Palo Verde Nuclear Generating Station (PVNGS) Unit 3**
Docket No. STN 50-530
Licensee Event Report 2025-002-00

Enclosed, please find the Licensee Event Report (LER) 50-530/2025-002-00 that has been prepared and submitted pursuant to 10 CFR 50.73(a)(2)(i)(B). This LER reports Unit 3 Technical Specification Violation Limiting Condition of Operation 3.6.3 Condition 'A' for Service Air Manual Containment Isolation Valve.

In accordance with 10 CFR 50.4, copies of this LER are being forwarded to the Nuclear Regulatory Commission (NRC) Regional Office, NRC Region IV, and the Senior Resident Inspector.

Should you need further information regarding this submittal, please contact Cuauhtemoc Orozco, Department Leader, Nuclear Regulatory Affairs, at (623) 393-6717.

Sincerely,

Spina, Jennifer (Z08962)
Digitally signed by Spina, Jennifer (Z08962)
Date: 2026.03.05 08:39:10 -07'00'

JLS/TMG/cr

Enclosure: Unit 3 Licensee Event Report 2025-002-00

cc:	J. Monninger	NRC Region IV Regional Administrator
	W. T. Orders	NRC NRR Project Manager for PVNGS
	E. Lantz	NRC Resident Inspector for PVNGS

ENCLOSURE

Units 3 Licensee Event Report
2025-002-00

NRC FORM 366 (04-02-2024) | U.S. NUCLEAR REGULATORY COMMISSION | APPROVED BY OMB: NO. 3150-0104 | EXPIRES: 04/30/2027

LICENSEE EVENT REPORT (LER)

(See Page 2 for required number of digits/characters for each block)

(See NUREG-1022, R.3 for instruction and guidance for completing this form http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Library, and Information Collections Branch (T-6 A10M), U. S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by email to Infocollects.Resource@nrc.gov, and the OMB reviewer at: OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk Officer for the Nuclear Regulatory Commission, 725 17th Street NW, Washington, DC 20503. The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.

1. Facility Name		2. Docket Number	3. Page
Palo Verde Nuclear Generating Station (PVNGS) Unit 3	■ 050 / ☐ 052	00530	1 OF 3

4. Title
VIOLATION OF TECHNICAL SPECIFICATION LIMITING CONDITION OF OPERATION 3.6.3

5. Event Date			6. LER Number			7. Report Date			8. Other Facilities Involved		
Month	Day	Year	Year	Sequential Number	Revision No.	Month	Day	Year	Facility Name	☐ 050	Docket Number
12	02	2025	2025	- 002 -	00	03	05	2026	Facility Name	☐ 052	Docket Number

9. Operating Mode	10. Power Level
3	0%

11. This Report is Submitted Pursuant to the Requirements of 10 CFR §: *(Check all that apply)*

10 CFR Part 20	☐ 20.2203(a)(2)(vi)	**10 CFR Part 50**	☐ 50.73(a)(2)(ii)(A)	☐ 50.73(a)(2)(viii)(A)	☐ 73.1200(a)
☐ 20.2201(b)	☐ 20.2203(a)(3)(i)	☐ 50.36(c)(1)(i)(A)	☐ 50.73(a)(2)(ii)(B)	☐ 50.73(a)(2)(viii)(B)	☐ 73.1200(b)
☐ 20.2201(d)	☐ 20.2203(a)(3)(ii)	☐ 50.36(c)(1)(ii)(A)	☐ 50.73(a)(2)(iii)	☐ 50.73(a)(2)(ix)(A)	☐ 73.1200(c)
☐ 20.2203(a)(1)	☐ 20.2203(a)(4)	☐ 50.36(c)(2)	☐ 50.73(a)(2)(iv)(A)	☐ 50.73(a)(2)(x)	☐ 73.1200(d)
☐ 20.2203(a)(2)(i)	**10 CFR Part 21**	☐ 50.46(a)(3)(ii)	☐ 50.73(a)(2)(v)(A)	**10 CFR Part 73**	☐ 73.1200(e)
☐ 20.2203(a)(2)(ii)	☐ 21.2(c)	☐ 50.69(g)	☐ 50.73(a)(2)(v)(B)	☐ 73.77(a)(1)	☐ 73.1200(f)
☐ 20.2203(a)(2)(iii)		☐ 50.73(a)(2)(i)(A)	☐ 50.73(a)(2)(v)(C)	☐ 73.77(a)(2)(i)	☐ 73.1200(g)
☐ 20.2203(a)(2)(iv)		✓ 50.73(a)(2)(i)(B)	☐ 50.73(a)(2)(v)(D)	☐ 73.77(a)(2)(ii)	☐ 73.1200(h)
☐ 20.2203(a)(2)(v)		☐ 50.73(a)(2)(i)(C)	☐ 50.73(a)(2)(vii)		

☐ **OTHER** (Specify here, in abstract, or NRC 366A).

12. Licensee Contact for this LER

Licensee Contact	Phone Number (Include area code)
Cuauhtemoc Orozco, Department Leader, Nuclear Regulatory Affairs	(623) 393-6717

13. Complete One Line for each Component Failure Described in this Report

Cause	System	Component	Manufacturer	Reportable to IRIS	Cause	System	Component	Manufacturer	Reportable to IRIS

14. Supplemental Report Expected		15. Expected Submission Date	Month	Day	Year
✓ No	☐ Yes (If yes, complete 15. Expected Submission Date)				

16. Abstract (Limit to 1326 spaces, i.e., approximately 13 single-spaced typewritten lines)

On December 01, 2025, Unit 3 Operations found a Service Air Containment Isolation Valve open in Mode 3. The required position for this valve in Mode 1 through Mode 4 is locked closed or under administrative controls per Technical Specification (TS) Limiting Condition for Operation (LCO) 3.6.3. At the time the valve was found open, Operations entered the TS LCO Condition and then exited when the valve was closed, locked and independently verified. The valve was open for a total of 114 hours and 50 minutes from the time Unit 3 entered Mode 4 until the time the valve was closed.

After evaluating Technical Specifications, the TS Bases, and the Updated Final Safety Analysis Report (UFSAR) the time of discovery for the TS Violation was established on January 07, 2026.

The root cause of this event is due to a human performance error.

No similar events have occurred at Palo Verde Nuclear Generating Station (PVNGS) in the prior three years.

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Library, and Information Collections Branch (T-6 A10M), U. S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by email to Infocollects.Resource@nrc.gov, and the OMB reviewer at: OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk Officer for the Nuclear Regulatory Commission, 725 17th Street NW, Washington, DC 20503. The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.

1. FACILITY NAME		2. DOCKET NUMBER	3. LER NUMBER		
			YEAR	SEQUENTIAL NUMBER	REV NO.
Palo Verde Nuclear Generating Station (PVNGS) Unit 3	■ 050 ☐ 052	00530	2025	- 002 -	00

NARRATIVE

All times are Mountain Standard Time and approximate unless otherwise indicated.

1. REPORTING REQUIREMENT(S):

This Licensee Event Report is being submitted pursuant to 10 CFR 50.73(a)(2)(i)(B): Any operation or condition which was prohibited by the plant's Technical Specification. TS LCO 3.6.3 Condition A was not entered as required on November 27, 2025, and subsequently required actions were not met.

2. DESCRIPTION OF STRUCTURE(S), SYSTEM(S), AND COMPONENT(S):

The Service Air system (EIIS: LF) supplies oil free, dry breathing quality air at a maximum pressure of 125 pounds per square inch (psi) to Service Air stations located throughout the generating unit. Service Air stations are provided for the operation of miscellaneous pneumatic tools, stud tensioner, stud tension hoists, resin transfer, refueling machine manual operation, and other service requirements. A single air compressor and two air receivers supply this subsystem. A flanged piping connection is provided to use a portable air compressor in the event the permanent air compressor is unavailable. Plant Service Air is isolated from the Containment building except during shutdown conditions, so no automatic isolation valves are provided in its Containment building supply header.

There is containment penetration that ports Service Air into Containment. This penetration consists of a single three (3) inch pipe isolated by one manual isolation valve and one check valve. Service Air is aligned into Containment through this penetration when the manual isolation valve is opened per the standard operating procedure.

3. INITIAL PLANT CONDITIONS:

Unit 3 was in MODE 3, 0% power. Unit 3 was undergoing refueling outage 3R25.
Unit 1 and Unit 2 were online at 100% and were not affected by this event.

4. EVENT DESCRIPTION:

On November 21, 2025, at 21:43 Operations aligned Service Air to Containment. This was to remove the Pressurizer manway to depressurize the Reactor Coolant System (EIIS: AB)(RCS) for ongoing maintenance. Once the maintenance was complete the manway cover was restored and Unit 3 began to repressurize the RCS.

At 05:18 on November 27, 2025, Unit 3 entered Mode 4 and at 22:15 on November 27, 2025, Unit 3 entered Mode 3. On December 01, 2025, Unit 3 Control Room found the manual isolation valve for Service Air to Containment, was not signed as being closed and locked per the Locked Valve, Breaker, and Component Tracking procedure. Area Operators confirmed the Service Air Containment Isolation Valve was open at 00:02 on December 02, 2025. The Control Room immediately entered TS LCO 3.6.3 Condition A. On December 2, 2025, at 00:08 Area Operators closed, locked and independently verified the valve and the Control Room exited TS LCO 3.6.3 Condition A. The time lapse between entering the Mode of Applicability (Mode 4) and closing the manual isolation valve was calculated to be 114 hours and 50 minutes.

1. FACILITY NAME		2. DOCKET NUMBER	3. LER NUMBER		
			YEAR	SEQUENTIAL NUMBER	REV NO.
Palo Verde Nuclear Generating Station (PVNGS) Unit 3	■ 050 ☐ 052	00530	2025	- 002 -	00

NARRATIVE

The Service Air Containment Isolation Valve can be opened during Modes 1-4 if administrative controls are established. Technical Specification Bases Revision 82, Containment Isolation Valves B 3.6.3, states, in part: “Manual containment isolation valves include those specified in Technical Requirements Manual (TRM), manual valves used to isolate a penetration (including a deactivated, non-automatic valve), and all vents, drains, and test connections located within a containment penetration. Manual containment isolation valves may be opened intermittently under administrative controls." During the modes of applicability until the valve was closed on December 02, 2025, no administrative controls were established. Therefore, Unit 3 violated TS LCO 3.6.3 Condition A required actions and completion times.

After evaluating Technical Specifications, the TS Bases, and the Updated Final Safety Analysis Report (UFSAR) the time of discovery for the TS Violation was established on January 07, 2026.

5. ASSESSMENT OF SAFETY CONSEQUENCES:

This event did not result in a potential transient more severe than those analyzed in chapters 6 and 15 of the Updated Final Safety Analysis Report (UFSAR) or result in the release of radioactive materials to the environment. There were no actual safety consequences or negative effects to the health and safety of the public as a result of this condition.

6. CAUSE OF THE EVENT:

The Service Air Containment Isolation Valve was rendered inoperable due to human performance errors. Prior to entering the modes of applicability this valve should have been identified as open on the mode change checklist. The procedural guidance is information use and, although referenced, this did not ensure recognition of the TS applicability for this valve. This was a procedure use and adherence error.

7. CORRECTIVE ACTIONS:

Compliance was restored at 00:08 on December 02, 2025, when the Service Air Containment Isolation Valve was closed, locked and independently verified.

Additionally, briefings were conducted on procedural adherence with a focus on attention to detail. Additional training will be conducted to provide clarification and guidance with regards to the performance of reviewing the Locked Valve Book.

8. PREVIOUS SIMILAR EVENTS:

No similar events have occurred in the prior three years.