

# Technical Support & Troubleshooting Reference

In-depth diagnostic reference for the active 10-item catalog

---

This reference covers product-specific malfunction diagnosis, root-cause explanations, safety handling, and escalation criteria. It is written as continuous descriptive text rather than question-and-answer pairs, so each section stands on its own with full context even when only part of it is retrieved for a customer's issue.

# 1. Electronics & Accessories

This category covers the Redmi Note 13, boAt Rockerz 450, and Fantech Fighter Mechanical Keyboard. These products share common failure patterns around power delivery, wireless connectivity, and hardware wear — most issues can be isolated to either an accessory problem (cable, adapter, port) or a genuine internal fault by working through cause elimination in the order described below.

## Redmi Note 13 — Performance, Overheating & Battery Drain

Slow performance, overheating during use or charging, and faster-than-expected battery drain are the three most frequently reported issues for this device. They are often related — an overheating device throttles its processor to protect itself, which is then perceived by the customer as "running slow," and a battery under thermal stress degrades faster over time. Isolating whether the root issue is software, accessory-related, or hardware-level is the key diagnostic task.

### Common Symptoms

- Noticeable lag or stutter during normal app use
- Device becomes hot to the touch, especially during charging or gaming
- Battery percentage drops significantly faster than in prior weeks
- Device restarts unexpectedly or shuts down before reaching 0%

### Likely Root Causes

- Background apps consuming CPU/RAM without the user's awareness
- Pending OS or app updates that include unresolved performance bugs
- Use of a non-original or underpowered charging adapter/cable, which can cause inefficient power delivery and excess heat generation during charging
- Battery cell degradation from age, heat exposure, or repeated deep discharge cycles
- A stuck or runaway background process, sometimes tied to a recently installed app

### Diagnostic Steps

- Check Settings > System Updates for any pending Android/MIUI updates and install them
- Force-close all background apps and restart the device fully (not just screen-off)
- Confirm the customer is using the original Xiaomi fast charger and cable — swap to the original set if a third-party charger is in use and observe whether overheating persists
- Check Settings > Battery for a list of apps consuming disproportionate battery in the background, and have the customer uninstall or restrict the worst offender
- If overheating happens even at idle with no charging and no heavy app in use, this points toward a hardware-level battery or component fault rather than software

### When to Escalate

If battery health remains severely degraded after a factory reset and elimination of third-party accessories, or if the device won't hold a charge at all within the warranty period, file a warranty claim rather than continuing further troubleshooting. A device that overheats even while idle and unplugged should be escalated promptly.

## Prevention Tips

Always charge using the original Xiaomi adapter and cable — this is the single most common preventable cause of overheating. Keep the OS updated, and periodically review battery usage stats to catch a misbehaving app before it becomes a persistent drain.

## boAt Rockerz 450 — Pairing, Audio Drops & Charging Failures

This headphone model reports three distinct failure clusters that should be diagnosed separately rather than treated as one issue: connection/pairing failures, in-use audio interruptions, and charging failures. Each has a different likely cause and a different resolution path, so the first diagnostic step is always to clarify exactly which of the three the customer is experiencing.

### Common Symptoms

- Device does not appear in the phone's Bluetooth device list
- Pairs successfully but audio cuts in and out during use
- One or both ear cups produce no sound despite a successful pairing
- LED charging indicator does not illuminate when connected to power
- Headphones will not hold a charge or die quickly after a full charge

### Likely Root Causes

- Stale Bluetooth pairing cache on the phone from a previous, now-invalid connection
- Physical distance or interference (walls, other 2.4GHz devices) disrupting the Bluetooth signal during use
- Worn or damaged charging cable/port preventing power delivery
- Internal battery degradation after extended use, reducing charge retention over time
- A genuine internal fault causing one-sided audio loss or dead charging circuitry

### Diagnostic Steps

- Put the headphones into pairing mode (LED flashing pattern) and remove/forget the "boAt Rockerz 450" entry from the phone's Bluetooth settings before re-pairing from scratch
- For audio drops during use, ask the customer to stay within roughly 5-8 meters of the source device and away from other active Bluetooth/WiFi devices to rule out interference
- For charging issues, try an alternate Micro-USB/Type-C cable and a different power adapter or USB port before concluding the headphones themselves are faulty
- If the LED does not light up on any cable/adaptor combination, this points to an internal charging fault

### When to Escalate

If the LED charging indicator does not light up at all across multiple cables and power sources, or if one side is permanently dead with no sound despite a clean pairing, escalate for a warranty claim rather than continuing troubleshooting.

## Prevention Tips

Keep the headphones within the recommended Bluetooth range during use, and avoid leaving them fully depleted for extended periods, which can accelerate battery degradation.

## Fantech Fighter Mechanical Keyboard — Detection, Backlighting & Dead Keys

Issues with this keyboard generally fall into three categories: the keyboard is not recognized by the PC at all, the RGB backlighting is off or behaving unexpectedly, or specific individual keys have stopped responding while the rest of the keyboard functions normally. Each points to a different layer of the problem — connection, firmware/software setting, or physical switch hardware.

### Common Symptoms

- PC does not detect the keyboard at all (no input registers)
- RGB lighting is off or stuck on a single color/mode
- One or more individual keys produce no input while others work normally
- Keyboard disconnects intermittently during use

### Likely Root Causes

- Connection through an unpowered USB hub, which may not supply sufficient power for a full-size mechanical keyboard with RGB lighting
- Backlighting toggled off via a function-key shortcut, either accidentally or by default firmware behavior
- A failed individual mechanical switch under one or more keys — a hardware-level fault specific to that key, not the keyboard as a whole
- A loose or marginal USB connection causing intermittent dropouts

### Diagnostic Steps

- Confirm the USB cable is connected directly to the PC's motherboard header or a laptop's built-in port, not through an unpowered hub
- Check the keyboard's printed manual for the specific FN + function-key shortcut that toggles RGB backlighting on and off
- Test the affected key(s) again after reconnecting directly to rule out a hub-related power issue
- If specific keys remain dead after ruling out connection issues, this indicates a hardware switch fault under those keys specifically

### When to Escalate

Individual dead keys that persist after confirming a direct, powered USB connection should be treated as a hardware switch fault and filed as a warranty claim — this is not something that can be resolved through software or DIY repair.

### Prevention Tips

Always connect directly to a powered USB port rather than through a hub, and avoid liquid or excessive dust exposure near the switches, which can contribute to individual key failure over time.

## 2. Home & Kitchen Appliances

This category covers the LG 260L Double Door Refrigerator, Baltra Electric Rice Cooker (1.8L), and CG Table Fan High Speed. These are electromechanical appliances where physical installation conditions (clearance, surface flatness, seal integrity) are frequently the actual root cause behind what initially presents as a functional defect — ruling these out first avoids unnecessary warranty claims for issues that are really installation-related.

### LG 260L Double Door Refrigerator — Cooling Failure

Inadequate cooling is the primary reported issue for this appliance. Because a refrigerator depends on several interacting conditions — correct thermostat setting, an intact door seal, and sufficient airflow clearance around the unit — a large share of reported cooling complaints trace back to one of these external factors rather than the compressor itself.

#### Common Symptoms

- Interior temperature noticeably warmer than expected
- Food spoiling faster than normal
- Freezer compartment not maintaining a hard freeze
- Compressor running constantly without the interior reaching target temperature

#### Likely Root Causes

- Thermostat/temperature dial accidentally set too low or to a "winter"/economy mode
- Door seal damaged, dirty, or obstructed by food items, preventing a full magnetic seal
- Insufficient clearance behind or around the unit restricting heat dissipation
- A genuine compressor or refrigerant-circuit fault

#### Diagnostic Steps

- Verify the thermostat/temperature dial is set to a normal cooling level, not minimum or winter mode
- Inspect the door seal for damage or obstruction by food items preventing a full seal
- Confirm at least 5-10cm of clearance is maintained behind and around the unit for proper ventilation
- If cooling issues persist after all three checks, this points to a compressor or refrigerant issue

#### When to Escalate

Persistent cooling failure after confirming thermostat setting, door seal integrity, and adequate clearance should be filed as a warranty claim — LG compressors on this model carry a 10-year compressor-only warranty, so this coverage should be referenced when filing.

#### Prevention Tips

Maintain the recommended clearance around the unit at all times, keep the door seal clean and unobstructed, and avoid repeatedly leaving the door open for extended periods, which forces the compressor to work harder than necessary.

## Baltra Electric Rice Cooker (1.8L) — Won't Turn On or Won't Keep Warm

This appliance uses a weight/heat sensor against the heating plate to determine when to trigger the automatic keep-warm switch-over. Most reported issues relate either to that sensor not being triggered correctly due to inner pot placement, or to a genuine internal thermostat fault. There is also a distinct and important safety dimension to this product's troubleshooting given it is an electrical heating appliance.

### Common Symptoms

- Cooker does not power on at all
- Cooker cooks but never switches to "Keep Warm" mode automatically
- Rice burns or overcooks despite normal water-to-rice ratios
- Unusual smell or sparking near the plug during use

### Likely Root Causes

- Inner pot not seated flat against the heating plate, preventing the weight sensor from triggering correctly
- A dented pot or debris on the heating plate interfering with proper contact
- A faulty internal thermostat that fails to detect the cooking-complete state
- In rare cases, an electrical fault in the heating element or wiring

### Diagnostic Steps

- Confirm the inner pot is seated flat and fully against the heating plate
- Check for dents in the pot or debris on the heating plate that could prevent full contact
- If the pot sits flat and clean but the cooker still burns rice or fails to switch to keep-warm mode, the internal thermostat is likely faulty

**Safety Note:** If there is any burning smell (electrical, not food) or sparking at the plug, instruct the customer to stop use immediately and unplug the unit before any further troubleshooting.

### When to Escalate

If a faulty thermostat is suspected after confirming correct pot placement, do not continue using the appliance — file a warranty claim immediately rather than attempting further use or DIY repair.

### Prevention Tips

Always ensure the inner pot is undamaged and seated flat before each use, and avoid using metal utensils that could dent the non-stick surface and interfere with plate contact.

## CG Table Fan High Speed — Noise, Wobbling & Motor Failure

Reported issues with this fan generally fall into three types: physical instability (wobbling), the motor not driving the blades despite power being present, and abnormal operating noise. These map to distinct causes — surface placement, electrical/mechanical motor failure, and internal wear — and should be

diagnosed in that order since placement is the simplest and most common fix.

### **Common Symptoms**

- Fan wobbles or shakes during operation
- Motor hums but blades do not spin
- Grinding or scraping noise during operation
- Fan does not respond at all when switched on

### **Likely Root Causes**

- Fan placed on an uneven or soft surface, causing vibration and wobble
- Seized motor bearings preventing the blades from turning despite power reaching the motor
- A failed capacitor, which can cause the motor to hum without generating rotational force
- Internal mechanical wear producing a grinding sound

### **Diagnostic Steps**

- Ensure the fan is placed on a completely flat, hard surface to rule out placement-related wobble
- Check that the power outlet itself is functioning correctly
- If the motor hums but the blades do not spin, this points to seized bearings or a failed capacitor rather than a simple power issue
- Do not manually force the blades to spin, as this does not resolve the underlying mechanical or electrical fault

### **When to Escalate**

A humming motor with non-spinning blades, or any grinding noise, should be filed as a warranty claim if the unit is within its coverage period rather than continuing to operate the fan in that condition.

### **Prevention Tips**

Always use a flat, stable surface for placement, and avoid running the fan continuously for extended periods without occasional rest, which can accelerate bearing wear.

## 3. Books & Media

This category covers the Bestseller Book Set of 4. Unlike the electromechanical categories above, issues here are quality/completeness issues rather than malfunctions — missing titles, print defects, and transit damage each have a distinct resolution path.

### Bestseller Book Set of 4 — Missing Titles, Print Defects & Transit Damage

The four-book bundle (Atomic Habits, The Psychology of Money, The Subtle Art of Not Giving a F\*ck, and Rich Dad Poor Dad) is shipped as a single set, and issues typically surface as one of three distinct problems: one or more titles missing from the box, a printing defect within a specific book, or physical transit damage to the packaging and book spines.

#### Common Symptoms

- One or more of the four titles missing from the delivered box
- Blank pages, upside-down printing, or other printing defects within a specific title
- Crushed box or bent/damaged book spines and covers on arrival

#### Likely Root Causes

- Fulfillment/packing error resulting in an incomplete set
- A manufacturing print defect isolated to a specific copy
- Rough handling during transit compressing the box or bending spines

#### Diagnostic Steps

- Ask the customer to identify exactly which of the four titles are missing, damaged, or defective — do not process a full-set replacement when only one book is affected
- For printing defects (blank or misprinted pages), confirm which specific title is affected
- For transit damage, ask whether the outer box itself shows crushing, which confirms a shipping-related cause versus a pre-existing defect

#### When to Escalate

Missing titles and printing defects are resolved as a replacement of the specific affected book, not the entire set. Transit damage confirmed by a crushed outer box should be logged as a shipping issue and processed as a replacement of the damaged item(s).

#### Prevention Tips

No customer-side prevention applies here; this is a packing and transit-handling responsibility. Encourage customers to report visible box damage immediately upon delivery rather than after unpacking, where possible.

## 4. FMCG, Groceries & Dairy (Quality Issues)

This category covers DDC Standard Milk (1 Liter), Wai Wai Chicken Noodles, and Kurkure Masala Munch. These are consumable items, so the correct approach is fundamentally different from the electromechanical categories above: there is no troubleshooting step to walk the customer through, only a quality/safety assessment that determines whether a refund or replacement applies, and how urgently.

### DDC Standard Milk (1 Liter) — Spoilage, Curdling & Leaking Packets

As the most perishable item in the catalog, milk quality issues are treated with the strictest reporting window of any product. The three most common reports are spoilage (off smell/taste), curdling when boiled, and physical packet leakage — each requires the same urgent, no-troubleshooting response given the food-safety dimension.

#### Common Symptoms

- Milk has an off smell or taste on opening
- Milk curdles when boiled, indicating it has already turned
- Packet arrives torn, punctured, or leaking

#### Likely Root Causes

- Cold-chain interruption during transit or storage
- Packet nearing or past its expiration date
- Physical damage to the packet during handling causing a leak and contamination

#### Diagnostic Steps

- Ask for the expiration date and batch number printed on the packet
- Confirm how soon after delivery the issue was noticed

#### When to Escalate

Since milk is a highly perishable daily supply, issue an immediate refund or replacement credit if the issue is reported within 24 hours of delivery. Reports outside that window cannot be processed as a quality issue. Leaking packets are logged specifically as a transit/handling defect rather than a product quality issue.

#### Prevention Tips

Advise customers to refrigerate milk immediately upon delivery and to check the packet for damage before storing, so any transit-related leak is caught right away rather than after storage.

### Wai Wai Chicken Noodles & Kurkure Masala Munch — Packet Condition Issues

Both products are commonly flagged by customers for their packaging appearance, but the correct response differs sharply depending on which product it is. A puffed Kurkure packet is normal and expected; a puffed Wai Wai packet or a broken seal on either product is not.

#### Common Symptoms

- Kurkure packet appears puffed or inflated
- Either product's packet arrives open or with a broken seal
- Product tastes stale despite being within the printed expiry date

### **Likely Root Causes**

- Kurkure puffing is caused by intentional nitrogen flushing during packaging to preserve crispness — this is not a defect
- A broken seal allows air and moisture ingress, leading to staleness regardless of the printed expiry date
- A manufacturing seal defect independent of transit handling

### **Diagnostic Steps**

- For Kurkure specifically, confirm the seal is intact — a puffed but sealed packet is expected packaging behavior, not a defect
- For either product, check whether the packet arrived already open or with a visibly broken seal
- If stale despite an intact seal and valid expiry date, treat this as a quality issue regardless of appearance

### **When to Escalate**

A broken seal on arrival, or a stale product despite being within its expiry date, should be processed as a replacement or refund. A puffed-but-sealed Kurkure packet should not be escalated — this is expected and requires no action beyond reassuring the customer.

### **Prevention Tips**

No customer-side prevention applies; this is a packaging and transit-handling matter. Customers should be encouraged to report seal issues at time of delivery rather than after the product has been stored for some time.

## Escalation Triggers — Full Summary

Across all categories above, escalate to the human technical support or warranty team immediately, without further troubleshooting, whenever any of the following apply:

- Safety hazards: any sparking, electrical burning smell, smoke, or overheating beyond normal operating limits — particularly relevant to the LG Refrigerator, Baltra Rice Cooker, and CG Table Fan given their electrical heating/motor components
- Persistent hardware failure: the product continues to fail after all documented, non-safety-risk troubleshooting steps for that specific product have been completed
- Dead on Arrival (DOA): any electronics item (Redmi Note 13, boAt Rockerz 450, Fantech Fighter Mechanical Keyboard) fails to power on straight out of the box
- Perishable safety window: any DDC Milk quality issue reported after the 24-hour window has closed should still be logged, but routed to a supervisor for a case-by-case decision rather than auto-approved