

Staging Heavy Duty - 9919

9919 Shepard Road SE
Calgary, Alberta
T2C 4M5
(403) 523 - 0488



Estimate:
EST-S2-17466

Estimate date: Sep 9, 2026

ADDRESSES

BILL TO

East Moline Diesel Repair
71014 Chapman Road
Shelbyville, Ontario P6A 7N5

REMIT PAYMENT TO

Punta Gorda Truck Service & Repair
057 Graham Crossroad, Apt. 318
Ryanfort, Yukon Territory Y5E 2E2
519-531-1194

ASSET	UNIT	PLATE	MILEAGE	ENG HRS
1992 BLUEBIRD Bb Conventional	53	UDE-8747	108,405	6,294
VIN / SERIAL GXSKH3FMA9DN0NPLF				

Work Order **S2-17466**

Customer PO **5331082026**

Authorizer **Anthony Jackson**

Terms **Net 30**

WORK SUMMARY

01 Service - CVIP inspection single or tandem axle Annual inspection

SCOPE OF WORK

Testing

LABOR

Service - CVIP inspection single or tandem axle \$400.00

Labor **\$400.00** | Line total **\$400.00**

02 Service - Wheels off single or tandem axle Annual inspection

SCOPE OF WORK

MW: Raised bus onto axle stands, removed wheels, rear wheels were stuck and could not be removed with sledge hammer, required wheel separator to remove inner wheels. After inspection was completed, reinstalled wheels, lowered bus and torqued lug nuts. Job complete.

LABOR

Service - Wheels off single or tandem axle \$150.00

Labor **\$150.00** | Line total **\$150.00**

03 Service - Perform LOF and inspection Preventative maintenance

LABOR			
Service - Perform LOF and inspection			\$224.93
PARTS			
WWF - Windshield Washer Fluid 4L	1	\$7.07	\$7.07
BRAKECLEAN - Brake & Parts Cleaner	1	\$7.99	\$7.99
GREASETUBE - EP2 Grease Tube, 390G	1	\$11.50	\$11.50
LF3970 - Engine Oil Filter, ISB, PX-6/7	1	\$28.21	\$28.21
HDEO14 - 15W40 Bulk- Mobil 1 Delvac HDEO	1	\$0.00	\$0.00
Labor		\$224.93	
Parts		\$54.77	
Line total			\$279.70

04 Service - Replace fuel filters

LABOR			
Service - Replace fuel filters			\$119.96
PARTS			
FS1098 - Fuel/Water Separator, Cummins B6.7/L9	1	\$120.42	\$120.42
FF63054NN - Fuel Filter, Cummins B6.7/L9	1	\$80.87	\$80.87
Labor		\$119.96	
Parts		\$201.29	
Line total			\$321.25

05 Service - Air filter Preventative maintenance

LABOR			
Service - Air filter			\$74.98
PARTS			
49519 - Engine Air Filter	1	\$164.48	\$164.48
Labor		\$74.98	
Parts		\$164.48	
Line total			\$239.46

06 Service - Cabin air filter **PROVIDE SAMPLE TO PARTS**

Preventative maintenance

LABOR

Service - Cabin air filter **PROVIDE SAMPLE TO PARTS** \$44.99

PARTS

Sample - Cabin air filter 1 \$0.00 \$0.00

Labor \$44.99 | Line total \$44.99

07 Service - Adjust tire pressures Out of specification (Safety)

LABOR

Service - Adjust tire pressures \$0.00

Line total \$0.00

08 Diagnose - Traction control Light illuminated

SCOPE OF WORK

TV: Wabco not connecting. Traction light probably due to corroded tone rings. Will need to verify when wheels pulled during CVIP.

LABOR

Diagnose - Traction control \$299.90

Labor \$299.90 | Line total \$299.90

09 Diagnose - DEF Codes Client states: Codes that are elated to the DEF system are currently on. But would like to see if this unit would be able to be deleted

SCOPE OF WORK

TV: Found 8 active fault codes, with 7 related to the aftertreatment system. Suspect a communication fault. Power and ground circuits for the aftertreatment system will need to be checked. Further diagnostic time is required. Recommend providing a quote for a delete kit as well.

LABOR

Diagnose - DEF Codes \$116.96

PARTS

PATC-10 - 10 AMP ATC FUSE 1 \$0.85 \$0.85

Labor \$116.96 Parts \$0.85 | Line total \$117.81

10 Service - Modify pipe and block EGR flow

LABOR			
Service - Modify pipe and block EGR flow			\$674.78
PARTS			
3944593 - Exhaust Manifold Bolt	2	\$12.16	\$24.32
5402022 - EGR Cooler Inlet Gasket, ISB	1	\$35.97	\$35.97
Labor \$674.78		Parts \$60.29	Line total \$735.07

11 Service - Aftertreatment delete Remove DPF material and SCR

LABOR			
Service - Aftertreatment delete			\$1,199.60
PARTS			
CL1340 - Cummins 12.91" V-Band Clamp, ATD	3	\$161.58	\$484.74
GSK1070 - Cummins 11.75" ID X 12.625" OD DPF Gasket	3	\$54.19	\$162.57
5418557 - Gasket, Aftertreatment Device	1	\$117.92	\$117.92
N35-40PLA - 4" Step Clamp, Aluminized Steel, Pre-Formed	1	\$26.38	\$26.38
CL1070 - Cummins 4.75" V-Band Clamp	1	\$95.91	\$95.91
GSK1020 - Cummins 3.75" ID X 4.625" OD Pipe Flange Gasket	1	\$13.87	\$13.87
Labor \$1,199.60		Parts \$901.39	Line total \$2,100.99

12 Diagnose and repair - Low coolant level Pressure test and inspect for leaks (Non-safety)

SCOPE OF WORK			
JL: Pressure tested cooling system and inspected for leaks. Noted leak forming at heater core outlet hose clamp. Tightened clamp, verified leak is no longer present. Topped up coolant level as necessary. Repair complete.			
LABOR			
Diagnose and repair - Low coolant level			\$149.95
Labor \$149.95		Line total \$149.95	

13 Diagnose - Power steering fluid leak at reservoir Level 2 (Safety)

SCOPE OF WORK			
JL: Inspected power steering reservoir. Verified leak is forming from reservoir return hose. Hose is hardened and brittle, requires replacement. Also recommend performing power steering fluid flush due to fluid condition. Diagnosis complete.			
LABOR			
Diagnose - Power steering fluid leak at reservoir			\$149.95
PARTS			
BRAKECLEAN - Brake & Parts Cleaner	1	\$7.99	\$7.99
Labor \$149.95		Parts \$7.99	Line total \$157.94

14 Replace - Power steering reservoir return hose Work hardened, brittle, level 2 leak (Safety)

LABOR			
Replace - Power steering reservoir return hose			\$224.93
PARTS			
NL1363-050 - 1/2" CONTITECH RED ORTAC GP HOSE (.89" OD)	6	\$5.94	\$35.64
N62ET-12 - Stainless Liner Gear Clamp, 0.75-1.14" (19-29mm)	2	\$1.90	\$3.80
Labor \$224.93		Parts \$39.44	Line total \$264.37

15 Service - Power steering flush Dirty/ Preventative maintenance (Non-safety)

LABOR			
Service - Power steering flush			\$224.93
PARTS			
ATFMVDD - ATF Bulk- Mobil 1 Multi Vehicle	1	\$11.16	\$11.16
870807A - Power Steering Filter	1	\$79.60	\$79.60
Q79699 - Power Steering Reservoir Gasket	1	\$12.71	\$12.71
Labor \$224.93		Parts \$103.47	Line total \$328.40

16 Diagnose - Engine oil leak Noted near fuel pump mount/rear of engine - Level 2 (Non-safety)**SCOPE OF WORK**

JL: Cleaned residual oil from area on left and rear sides of engine. Put UV dye into oil fill cap in order to identify leak. Ran unit to operating temperature while inspecting for leaks. Verified leak is forming from fuel pump mounting gasket. Recommend re-sealing fuel pump. Diagnosis complete.

LABOR

Diagnose - Engine oil leak	\$299.90
----------------------------	----------

PARTS

45001 - Aerosol Engine Shampoo	1	\$16.12	\$16.12
BRAKECLEAN - Brake & Parts Cleaner	1	\$7.99	\$7.99
892.76404 - MULTI PURPOSE DYE 1OZ	2	\$14.63	\$29.26

Labor \$299.90	Parts \$53.37	Line total \$353.27
-----------------------	----------------------	----------------------------

17 Replace - Fuel pump mounting o-ring Leaking - Level 2**LABOR**

Replace - Fuel pump mounting o-ring	\$1,199.60
-------------------------------------	------------

PARTS

2830977 - Fuel Pump O-Ring	1	\$30.41	\$30.41
4896897 - Air Compressor Mounting Gasket	1	\$91.03	\$91.03
5260936 - Water Outlet Hose	1	\$128.36	\$128.36
4988280 - Power Steering Gasket	1	\$12.16	\$12.16

Labor \$1,199.60	Parts \$261.96	Line total \$1,461.56
-------------------------	-----------------------	------------------------------

18 Replace - Drag link Excessive play at steering knuckle (Safety)**LABOR**

Replace - Drag link	\$224.93
---------------------	----------

PARTS

346-635 - Drag Link	1	\$346.29	\$346.29
---------------------	---	----------	----------

Labor \$224.93	Parts \$346.29	Line total \$571.22
-----------------------	-----------------------	----------------------------

19 Sublet - Replace passenger side windshield

Multiple large chips/cracks in wiper path (Safety)

LABOR

Sublet - Replace passenger side windshield \$0.00

PARTS

Sublet - Replace passenger windshield 1 \$353.32 \$353.32

Parts \$353.32 | Line total \$353.32

20 Sublet - Program ECM

LABOR

Sublet - Program ECM \$0.00

PARTS

sublet - ECM programming 1 \$3,000.00 \$3,000.00

Parts \$3,000.00 | Line total \$3,000.00

21 Quality control check over QC

LABOR

Quality control check over

Line total \$0.00

22 Monitor - Kingpin vertical wear Minimal vertical wear noted during inspection

SCOPE OF WORK

Client to monitor.

LABOR

Monitor - Kingpin vertical wear \$0.00

Line total \$0.00

SUMMARY

THIS IS OUR DISCLAIMER!!!!!!!!!!!!!!!!!!!!!!!!!!!!!!

Labor	\$5,780.29
Parts	\$5,548.91
Shop supplies (10.5% of labor)	\$350.00
Subtotal	\$11,679.20
GST (5%)	\$584.01
Total	\$12,263.21

ESTIMATED TOTAL **\$12,263.21**

CUSTOMER SIGNATURE

PRINTED NAME

DATE