

WO #S2-13958

Paid

Staging Heavy Duty - 9919

Customer: Susan Vargas
Company: Aoboro Works
VIN: 5KKPAVDV5NPNK9939
Date: Mar 20, 2026
Service Advisor: Kimberly Barnes
Lead Technician: Kellie Ayers

Vehicle: 2022 Western Star 4700
Unit: 18398
Mileage: 69298
Engine Hours: 5421
Licence Plate: CWD-5990

	Name/Description	Actual/Estimate	Status
1	Service - CVIP inspection tri-axle Annual inspection	4.13 / 4.75	Complete
Labor	Colleen Guerrero		
Tech Story	JL: Completed CVIP inspection. Added list of repairs to service order. Failed unit on eFacility. Uploaded failed inspection to service order. JL: Issued CVIP decal CV8638888 upon completion of repairs. Job complete.		
2	Service - Wheels off tri-axle Annual inspection	3.61 / 1.75	Complete
Labor	Alyssa Randall		
Tech Story	MW: Raised truck onto jackstands, removed lug nut covers, removed wheels and drums for inspection. Once inspection was complete, reinstalled drums and wheels, lowered truck onto ground. Torqued wheels, applied service sticker. Job complete.		
3	Service - Top up power steering fluid Low - (Safety)	0.25 / 0.30	Complete
Labor	Margaret Garcia		
Tech Story	AZ: Topped up power steering fluid. Job complete.		
Parts	(ATFMVDD) ATF Bulk- Mobil 1 Multi Vehicle 1		

	Name/Description	Actual/Estimate	Status
4	Service - Air filter Preventative maintenance	0.23 / 0.50	Complete
Labor	Margaret Garcia		
Tech Story	AZ: Removed old air filter and replaced with new air filter. Job complete.		
Parts	(AF4331) Engine Air Filter, Freightliner/Western Star	1	

5	Service - Remove pintle hitch Seized - (Safety)	0.97 / 0.50	Complete
Labor	Mark Morris		
Tech Story	SK: Removed the mounting bolts for the pintle, The bolts were seized and required heat and lubrication. Removed the pintle hitch. Secured the hitch chamber and disposed of the hitch. Job complete.		

6	Diagnose - Side mounted hood turn signals Not working - (Safety)	1.35 / 2.00	Complete
Labor	Mark Morris		
Tech Story	CM: Check operation of the side mounted hood turn signals. The signal lights above the steer tires are working normally. The signal/ marker lights on the side of the headlights are also working normally. Confirm that it is a 3 wire harness going to the lights above the steer tires. They should have marker light functionality as well. Troubleshooting on going.		
	JL: Continued diagnostics. Removed inner fenders/splash shields to access light connectors. Disconnected lights. Verified lights are receiving proper voltage and ground on marker and turn signal circuits. Indicates internal failure of lights. Both hood-mounted marker/turn signal lights require replacement. Diagnosis complete.		

	Name/Description	Actual/Estimate	Status
7	Replace - Hood mounted marker/turn signal lights Failed internally - (Safety)	0.36 / 1.00	Complete
Labor	Colleen Guerrero		
Tech Story	SK: Removed and replaced lights. Tested the lights; lights function as intended. Job completed.		
Parts	(564.464002) Turn/Marker Lamp, Fender Mounted, RH	1	
	(564.464001) Turn/Marker Lamp, Fender Mounted, LH	1	
8	Diagnose - Axle #1 wheel bearings Excessive play - (Safety)	1.58 / 2.00	Complete
Labor	Mark Morris		
Tech Story	CM: Lift steer axle, Confirmed both wheel bearings are loose. Removed the passenger side hub cap, no sign of oil contamination. Remove the snap rings and spindle nut. Remove the outer bearing and inspect. Bearing and spindle look ok. Clean up all components and reinstall. Torque spindle nut to spec. And install snap rings. Install a new hub cap gasket and fill with oil. Remove the drivers side hub cap and found the oil very milky and contaminated . Remove the snap rings and spindle nut, remove the steer tire and drum. Remove the hub and wheel seal. Clean both bearings and inspect. Bearings and spindle look ok. Wheel seal will need to be replaced. Diagnosis complete.		
Parts	(3009) Hub Cap Gasket, 6 Bolt, 5.5" Bolt Pattern	2	

	Name/Description	Actual/Estimate	Status
9	Replace - Wheel seal Oil is Contaminated- Axle 1 left - (Safety)	1.57 / 2.00	Complete
Labor	Mark Morris		
Tech Story	MW: Installed bearing and wheel seal, installed hub onto spindle, installed crush sleeve and fastened axle nut. Filled hub, lowered truck onto ground, torqued wheels. Job complete.		
Parts	(3595915) HUB CAP PLUG	1	
	(BRAKECLEAN) Brake & Parts Cleaner	1	
	(MDS79DD) 75W90 Bulk- Mobil Delvac 1 Gear Oil	1	
	(3009) Hub Cap Gasket, 6 Bolt, 5.5" Bolt Pattern	1	
	(ABP10081519) Conmet Hubseal & Preset Spacer Kit, FL, Front	1	
10	Diagnose - Auxiliary trailer power Flashing with turn signals/hazard lights - (Safety)	1.60 / 2.00	Complete
Labor	Mark Morris		
Tech Story	JL: Disconnected and removed trailer plug. Removed trailer cord from loom, found left and right turn signal wires are spliced into a separate harness that runs into hydrovac panel. Traced harness into panel, found they are part of a safety circuit that prevents operation without hazard lights active. Due to trailer hitch being disabled, no further diagnosis is required.		
11	Diagnose - Axle #2 and #4 brake strokes Excessively mismatched - (Safety)	0.82 / 2.00	Complete
Labor	Alyssa Randall		
Tech Story	CM: Inspected and confirmed mismatched brake strokes on axle #2 and axle #4. Inspected brake chamber condition and sizing. Inspected all clevis pins, found axle #2 left and axle #4 right clevis pins seized. Free up both pins. Inspected s-cams for movement. No further issues found. Read adjusted all brakes on axle #2 and axle #4 and checked the operation of the slack adjusters. Brakes adjusted to 1.5" with no issue. Job complete.		

	Name/Description	Actual/Estimate	Status
12	Diagnose - Right side center dome light Not working - (Non-safety)	1.05 / 2.00	Complete
Labor	Alyssa Randall		
Tech Story	CM: Check for right center dome light out. No interior lights are working. Check fuse for interior lights, fuse is ok. Low battery voltage warning is illuminated on the dash. Hook up the battery charger. Will recheck after the batteries are fully charged. Low voltage disconnect may be causing the interior lights to not turn on. After charging the batteries for 30 minutes the low voltage light is still staying on. Proceed to load test the batteries. Disconnect all positive and negative cables from the batteries located under the passenger seat. After load tests found that 2 batteries fail. Will need to replaced all 4 batteries to continue diagnosis lines. JL: Continued diagnostics. Removed lens from right side center dome light, found bulb to be burnt out. Installed replacement bulb. Verified operation. Repair complete.		
Parts	(B194) 194 LIGHT BULB	1	
13	Replace - Batteries Failed load test - (Safety)	1.56 / 2.00	Complete
Labor	Mark Morris, Margaret Garcia		
Tech Story	AZ: Removed battery hold-down and old batteries. Installed new batteries, secured with hold-down clamps, connected cables, and installed zip ties to properly secure wiring. Job complete.		
Parts	(ABP AE9F31) In-Cab Battery	4	
14	Diagnose - Low coolant level Pressure test and inspect for leaks - (Non-safety)	0.35 / 2.00	Complete
Labor	Alyssa Randall		
Tech Story	CM: Pressure test cooling system to 15 psi. Found a large leak at the top radiator hose. Recommend replacing both upper radiator hoses and clamps at this time. Diagnosis complete.		

	Name/Description	Actual/Estimate	Status
15	Repair - Lower radiator mount hardware Loose - (Safety)	1.31 / 0.50	Complete
Labor	Brittany Anderson		
Tech Story	JP: Lubed and adjusted lower radiator mount hardware. SK: attempted to tighten. Took apart and found that the shoulder of the bolt has worn allowing the bushing to spin. Monitor bushings. Job completed.		
16	Repair - Coolant hoses Rubbing on passenger side cab airbag - (Non-safety)	0.62 / 0.75	Complete
Labor	Thomas Jones		
Tech Story	SK: Secured hoses and reoriented them so they are no longer rubbing. Job complete.		
17	Replace- Upper radiator hoses Leaking - (Non-safety)	0.88 / 2.50	Complete
Labor	Colleen Guerrero, Mark Morris		
Tech Story	JL: Drained cooling system. Removed and replaced upper radiator hoses with new clamps. Vacuum filled cooling system, topped up as necessary. Repair complete.		
Parts	(SHL55057739) Shell Red Coolant- 50/50 Antifreeze 4L	2	
	(N64CT-40) CONSTANT TENSION GEAR CLAMP 2.05" - 2.99" (52-76MM)	4	
	(05-18145-000) Hose, Elbow, 45 Degree	1	
	(05-16836-204) Hose, 2.5"	1	

	Name/Description	Actual/Estimate	Status
18	Diagnose - Level 2 hydraulic leaks Noted behind cab - (Non-safety)	0.97 / 1.00	Complete
Labor	Alyssa Randall		
Tech Story	JL: Inspected unit for hydraulic leaks. Found oil collecting on bottom of front vacuum pump assembly. Traced oil to passenger side fill plug, found fill plug to be loose, causing fluid to leak out during operation. Removed and cleaned plug, re-installed. Diagnosis complete.		
19	Diagnose - Level 2 engine oil leak Noted at injector pass-through seals/injector harness seals - (Non-safety)	0.27 / 0.50	Complete
Labor	Alyssa Randall		
Tech Story	CM: Inspect for oil leaks. Found injector pass through seals #2,3,4,5,6 are leaking. Found oil leaking from the cam position sensor seal. Diagnosis complete		
20	Replace - Cam position sensor Leaking oil - (Non-safety)	0.44 / 1.50	Complete
Labor	Mark Morris		
Tech Story	JL: Removed and replaced camshaft position sensor. Ran unit, verified oil leak is no longer present. Job complete.		
Parts	(A0071535928) Cam Position Sensor	1	
21	Replace- Injector Pass through seals 2,3,4,5 Leaking oil - (Non safety)	1.70 / 3.50	Complete
Labor	Mark Morris		
Tech Story	JL: Removed and replaced injector pass-through seals on cylinders 2, 3, 4, and 5. Torqued pass-through seal mounting hardware and high pressure fuel lines to specification. Primed fuel system. Ran unit, verified no leaks are present from pass-through seals or fuel lines. Repair complete.		
Parts	(A4720780680) Injector Pass Through Seal	4	

	Name/Description	Actual/Estimate	Status
22	Repair - Right side front toolbox latch Loose - (Safety)	1.30 / 0.50	Complete
Labor	Brittany Anderson		
Tech Story	JP: Adjusted latch box would not close. Top of box was catching on frame. Grinded down until closed. Adjusted latch rod length to tighten up adjustment. Job complete. SK: bent the top of the rod a little bit towards the inside of the cabinet to pull the door in and bent the frame towards the door to allow the rod to slide with ease. The reason the door is not closing properly is because the latch is missing the rod that anchors the middle of the door to the frame and pulling the door tight. Recommend replacing the latch the next time the unit is at the shop. Photos attached to the workorder. Job completed.		
23	Replace - Right side rear reflector Damaged - (Safety)	0.50 / 0.50	Complete
Labor	Margaret Garcia, Brittany Anderson		
Tech Story	AZ: Removed broken component. Waiting for part. CM: Ground off broken bolts. Cleaned up surface, installed new reflector, and mounted with new hardware. Job complete.		
Parts	(98003R) 3" Rectangle Red Reflectors	1	
24	Replace - Right side midship reflector Missing - (Safety)	0.26 / 0.50	Complete
Labor	Alyssa Randall		
Tech Story	CM: Install new reflector.		
Parts	(98003Y) Amber Reflector	1	

	Name/Description	Actual/Estimate	Status
25	Replace - Axle #2 spring eye bushings and u-bolts Bushings worn excessively, springs contacting hangers - (Safety)	8.49 / 6.00	Complete
Labor	Thomas Jones		
Tech Story	SK: Lifted unit and placed on axle stands. Lifted frame and placed on frame stands. Removed beauty covers, lug nuts, and wheels. Disconnected torque rod. Disconnected spring pin bushing. Cut U-bolts. Attempted to install new U-bolts and found they were incorrect size. Cleaned saddle and plate. Installed correct U-bolts loosely. Torched collar off bushing. Set up Tiger Tool and removed bushing. Lubricated and installed new bushing in same orientation. Removed air bag bracket bolts. Cleaned shims for pin. Secured spring pin bushing using new hardware. Aligned and tightened U-bolts. Installed air bag bracket to spring using new hardware. Ensured spring was aligned properly. Repeated process on opposite side. Connected torque rod using new hardware. Marked and torqued U-bolts. Job complete.		
Parts	(CS8SC-075-350) 3/4"X3-1/2" NC BOLT (GR8, HEX)	4	
	(SUW-78) U-BOLT WASHER	8	
	(DN-78) 7/8 DEEP NUT	8	
	(8T7838) THREADED UBOLT ROD 7/8X38"	4	
	(SLCSC-075) 3/4" NC STOVER LOCKNUT	8	
	(8WS-075) 3/4" FLAT WASHER	16	
	(CS8SC-075-500) 3/4"X5" NC BOLT (GR8, HEX)	4	
	(500.016) WEAR PAD; HANGER; RH (334-1994/16-16456-001)	2	
	(500.015) WEAR PAD; HANGER; LH (334-1993/16-16456-000)	2	
	(CS-RB-268) Airliner Bushing	2	

	Name/Description	Actual/Estimate	Status
26	Replace - Axle #3 spring eye bushings and u-bolts Bushings worn excessively, springs contacting hangers - (Safety)	5.03 / 6.00	Complete
Labor	Thomas Jones		
Tech Story	SK: Disconnected the torque rod. Disconnected the spring pin bushing. Cut the the U-bolts. Cleaned the saddle and plate. Installed U-bolts loosely. Torched the collar off of the bushing. Set up the tiger tool and removed the bushing. Lubricated and installed the new bushing in the same orientation. Removed the air bag bracket bolts. Cleaned the shims for the pin. Secured the Spring pin bushing using new hardware. Aligned and tightened the U- bolts. Installed the air bag bracket to spring using new hardware. Ensured the spring was lined up properly. Repeated process on the other side Connected the torque rod using new hardware. Marked and torqued the u bolts to spec. Job complete.		
Parts	(CS8SC-075-350) 3/4"X3-1/2" NC BOLT (GR8, HEX)	4	
	(SUW-78) U-BOLT WASHER	8	
	(DN-78) 7/8 DEEP NUT	8	
	(8T7838) THREADED UBOLT ROD 7/8X38"	1	
	(8T7838) THREADED UBOLT ROD 7/8X38"	3	
	(SLCSC-075) 3/4" NC STOVER LOCKNUT	8	
	(8WS-075) 3/4" FLAT WASHER	16	
	(CS8SC-075-500) 3/4"X5" NC BOLT (GR8, HEX)	4	
	(500.016) WEAR PAD; HANGER; RH (334-1994/16-16456-001)	2	
	(500.015) WEAR PAD; HANGER; LH (334-1993/16-16456-000)	2	
	(CS-RB-268) Airliner Bushing	2	

	Name/Description	Actual/Estimate	Status
27	Replace - Axle #4 spring eye bushings and u-bolts Bushings worn excessively, springs contacting hangers - (Safety)	5.87 / 6.00	Complete
Labor	Thomas Jones, Alyssa Randall		
Tech Story	SK: Disconnected the torque rod. Disconnected the spring pin bushing. Cut the the U-bolts. Cleaned the saddle and plate. Installed U-bolts loosely. Torched the collar off of the bushing. Set up the tiger tool and removed the bushing. Lubricated and installed the new bushing in the same orientation. Removed the air bag bracket bolts. Cleaned the shims for the pin. Secured the Spring pin bushing using new hardware. Aligned and tightened the U- bolts. Installed the air bag bracket to spring using new hardware. Ensured the spring was lined up properly. Repeated process on the other side Connected the torque rod using new hardware. Marked and torqued the U bolts to spec. Installed wheels, tightened the lug nuts. Lifted the axles and removed stands. Took unit off of frame stands. Torqued wheels. Installed re-torque stickers. Installed beauty covers. Job complete.		
Parts	(CS8SC-075-350) 3/4"X3-1/2" NC BOLT (GR8, HEX)	4	
	(SUW-78) U-BOLT WASHER	8	
	(DN-78) 7/8 DEEP NUT	8	
	(8T7838) THREADED UBOLT ROD 7/8X38"	4	
	(SLCSC-075) 3/4" NC STOVER LOCKNUT	8	
	(8WS-075) 3/4" FLAT WASHER	16	
	(CS8SC-075-500) 3/4"X5" NC BOLT (GR8, HEX)	4	
	(500.016) WEAR PAD; HANGER; RH (334-1994/16-16456-001)	2	
	(500.015) WEAR PAD; HANGER; LH (334-1993/16-16456-000)	2	
	(CS-RB-268) Airliner Bushing	2	
28	Sublet - Windshield chip repair Chip in passenger side wiper path (Safety)	0.00 / 0.00	Complete
Labor	Alyssa Randall		
Tech Story	SUBLET		
Parts	(SUBLET) Windshield Chip Repair	1	

	Name/Description	Actual/Estimate	Status
29	Quality control check over QC	0.82 / 0.00	Complete
Labor	Joel Parker		
Tech Story	JC: Performed quality control inspection. Job complete.		
30	Replace - Pintle hitch Seized (Safety)	0.00 / 0.50	Declined
Parts	(10000135) 467 Air Chamber Bracket	1	
	(F24SC) T24 Service Chamber	1	
	(10004757) 370 Pintle Coupler	1	
31	Monitor - Kingpins Vertical play forming	0.00 / 0.00	Declined
Tech Story	..		
32	Replace - Injector harness pass-through seals Leaking - Level 1	0.00 / 2.00	Declined
Labor	Mark Morris		
Parts	(A4710160521) Valve Cover Gasket	1	
	(A4711508333) Injector Harness, Rear	1	
	(A4711508233) Injector Harness, Front	1	

	Name/Description	Actual/Estimate	Status
33	Repair - Crossmember rear of cab Mounting bolts loose	0.00 / 0.00	Declined
Labor	Kellie Ayers		
Tech Story	..		
Parts	1/2 stover	16	
	1/2 " grade 8 washer	32	
	1/2" x 2" grade 8 bolt	16	

Total Actual Time: 47.89

Total Estimated Time: 57.05

Printed: Sep 1, 2026 10:43 AM