

Heavy Duty - 9919

9919 Shepard Road SE
Calgary, Alberta, T2C 4M5
(403) 523 - 0488



Invoice: INV-S2-10056

Invoice Date: Oct 2, 2025
Due date: Nov 1, 2025

Bill To

American Heavy Duty Truck Repair (IBS#:
850239)
40807 Clark Locks Apt. 699
Apt. 011
South Karen, Nunavut, E5T7S1

Remit payment to

Foothills Group Inc c/o Interstate Billing Service
C/O T04220C PO Box 4220, STN A
Toronto, Ontario, M5W 3B9
(403) 523 - 0488

Unit	VIN/Serial #	Asset	Mileage	Eng Hrs
49	KZUGZYRTJV6G5L64N	2006 Peterbilt 335	411,591	2,306

Service Order	Terms	Due date	Customer PO	Authorizer
S2-10056	Net 30	Nov 1, 2025	49	

Description	Quantity	Rate	Amount
Service - Adjust Clutch			
Labor Out of adjustment SK: Removed clutch cover and inspected clutch, found it out of spec. Checked free play and also found it out of spec. Adjusted clutch to specification and rechecked free play, now measuring within spec. Job complete.	1.35	\$149.95	\$202.43
		Parts Total	\$0.00
		Labor Total	\$202.43
		Line Total	\$202.43

Diagnose and Repair - Coolant leak from upper rad			
Labor hose Customer complaint of leak from rad hose LK: Pressure tested system and verified leak coming from the upper radiator hose between radiator and coolant pipe. BH: Drained coolant and removed upper radiator hose. Section of hose required cutting due to being baked onto fittings. Cleaned mating surfaces and installed new hose with new clamps. Refilled system with collected coolant and tested for leaks. No leaks found. JC: Fabricated a mounting bracket for upper rad hose. Installed new bracket and clamp. Had to modify excising bracket to allow for clearance. Tested and cleaned up area. Job complete	2.78	\$149.95	\$416.86
Parts HE7043 - Upper Radiator Hose	1	\$47.04	\$47.04
Parts N64CT-36 - CONSTANT TENSION GEAR CLAMP 1.81" -2.76" (46-70MM)	2	\$8.86	\$17.72

Description	Quantity	Rate	Amount
Parts 89542K - 2-1/4" EXHAUST CLAMP	1	\$8.91	\$8.91
		Parts Total	\$73.67
		Labor Total	\$416.86
		Line Total	\$490.53

Diagnose - Clunking in front end and pulling to the right

Labor LK: Lifted front end and suspended steer axle. Found play in rear spring pin bushings on steer axle, most notable at upper left and lower right spring pins. All pins showed play. Determined new spring pins are required. Suspect failure due to lack of grease over time.	1.15	\$149.95	\$172.44
		Parts Total	\$0.00
		Labor Total	\$172.44
		Line Total	\$172.44

Diagnose - Bed comes down slow and leaking fluid from bottom of piston

Labor Customer complaint of leak forming and bed coming down slow LK: Inspected dump box function and confirmed it raises and lowers at normal speed. Found leak coming from seals at the top of the first stage of the mast cylinder. Determined mast cylinder will need to be removed for repairs.	1.12	\$149.95	\$167.94
		Parts Total	\$0.00
		Labor Total	\$167.94
		Line Total	\$167.94

Replace - Axle #1 rear spring pins and shackles

Labor Worn out AZ: Removed rear pins and bushings. Found hanger worn out. Replaced spring eye bushings and removed hangers. Installed new hangers and pins, tightened all bolts, and greased pins. Job complete.	6	\$149.95	\$899.70
Parts 327-483 - PIN BUSHING RNK-BM	4	\$31.45	\$125.80
Parts RNK-BM - BUSHING SPRING	2	\$12.83	\$25.66
Parts 330-187 - Axle 1 Shackle Side Bar	2	\$62.02	\$124.04
Parts 330-187 - Axle 1 Shackle Side Bar	2	\$62.02	\$124.04
Parts CS8SC-050-600 - 1/2"X6" NC BOLT (GR8, HEX)	4	\$2.97	\$11.88
Parts SLCSC-050 - 1/2" NC STOVER LOCKNUT	4	\$0.45	\$1.80
Parts 8WS-050 - 1/2" FLAT WASHER	8	\$0.18	\$1.44
Parts M1817 - RH Spring Hangar	2	\$131.00	\$262.00
Parts 8WS-075 - 3/4" FLAT WASHER	12	\$0.40	\$4.80
Parts SLCSC-075 - 3/4" NC STOVER LOCKNUT	6	\$1.38	\$8.28
Parts CS8SC-075-600 - 3/4"X6" NC BOLT (GR8, HEX)	6	\$7.45	\$44.70
		Parts Total	\$734.44
		Labor Total	\$899.70
		Line Total	\$1,634.14

	Description	Quantity	Rate	Amount
Replace - Axle #1 front spring pin bushings				
Labor	Suggest to be done with the rears AZ: Pulled front pins and bushings, replaced bushings and pins, tightened bolts, and greased components. Job complete.	6	\$149.95	\$899.70
Parts	327-483 - PIN BUSHING RNK-BM	2	\$31.45	\$62.90
Parts	RNK-BM - BUSHING SPRING	2	\$12.83	\$25.66
			Parts Total	\$88.56
			Labor Total	\$899.70
			Line Total	\$988.26
Replace - Right side axle #2 suspension air bag				
Labor	Leaking at top plate SK: Lifted rear of truck, disconnected air line, removed air bag, cleaned and transferred fitting to new air bag. Installed new air bag with new hardware and reconnected air line. Job complete.	2.1	\$149.95	\$314.90
Parts	AS90690 - Air Spring	1	\$224.70	\$224.70
Parts	HN8SC-050 - 1/2" NC HEX NUT	1	\$0.43	\$0.43
Parts	8LWS-050 - 1/2" LOCK WASHER	1	\$0.51	\$0.51
			Parts Total	\$225.64
			Labor Total	\$314.90
			Line Total	\$540.54
Replace - Axle #3 right longitudinal torque rod				
Labor	Bushing pushed out BH: Lifted #3 axle and installed stands. Removed right-side wheels and old torque rod. Extra time required due to seized hardware and excess bushing material covering securing hardware. Cleaned all mating faces and partially mounted new torque rod. Installed new front securing hardware, applied anti-seize and Loctite, and fully secured torque rod. Reinstalled right-side wheels. Job complete.	2.5	\$149.95	\$374.88
Parts	TQRAA2-440 - TORQUE ROD	1	\$240.61	\$240.61
Parts	CS8SC-062-700 - 5/8 X 7 GR8 PL NC BOLT	2	\$6.53	\$13.06
Parts	SLCSC-062 - 5/8" NC STOVER LOCKNUT	2	\$0.80	\$1.60
Parts	8WS-062 - 5/8" FLAT WASHER	4	\$0.33	\$1.32
			Parts Total	\$256.59
			Labor Total	\$374.88
			Line Total	\$631.47
Repair - Extract bolts for left torque rod				
Labor	MC: Inspected unit for extraction of broken torque rod bolts. Center-punched broken studs and drilled through with progressively larger bits. Used burr bits to remove remaining material until threads were visible. Removed remaining threads with pick and pliers. Chased threads with a tap and verified by test fitting a bolt. Threads confirmed good. Job complete.	5.66	\$149.95	\$848.72
			Parts Total	\$0.00

Description		Quantity	Rate	Amount
			Labor Total	\$848.72
			Line Total	\$848.72
Replace - Service brake glad hand seal				
Labor	Rubber missing (red)			
	BH: Replaced glad hand seals. Job complete.	0	\$149.95	\$0.00
Parts	PHL01212100 - GLADHAND SEAL	3	\$0.85	\$2.55
			Parts Total	\$2.55
			Labor Total	\$0.00
			Line Total	\$2.55
Replace - Axle #3 left longitudinal torque rod				
Labor	Suggest to be done in pairs per axle			
	MC: Inspected unit for replacement of longitudinal torque rod. Removed old rod prior to starting job.			
	Installed new longitudinal torque rod, using jack as necessary. Fastened new torque rod, reinstalled wheels, and torqued to 500 ft-lbs. Job complete.	2.5	\$149.95	\$374.88
Parts	TQRAA2-440 - Longditudinal Torque Rod	1	\$240.61	\$240.61
Parts	CS8SC-062-700 - 5/8 X 7 GR8 PL NC BOLT	2	\$6.53	\$13.06
Parts	SLCSC-062 - 5/8" NC STOVER LOCKNUT	2	\$0.80	\$1.60
Parts	8WS-062 - 5/8" FLAT WASHER	4	\$0.33	\$1.32
Parts	890.200004 - ROST OFF PLUS 400ML	1	\$29.55	\$29.55
			Parts Total	\$286.14
			Labor Total	\$374.88
			Line Total	\$661.02
Replace - Clutch brake				
Labor	Faulty clutch brake			
	AZ: Pulled inspection plate and checked clutch brake.			
	Found broken tabs and clutch brake spinning.			
	Replaced clutch brake. Job complete.	1.75	\$149.95	\$262.41
Parts	SB200 - BABCOCK 2.00" CLUTCH BRAKE	1	\$88.65	\$88.65
			Parts Total	\$88.65
			Labor Total	\$262.41
			Line Total	\$351.06
Quality control check over				
Labor	QC			
	TK: Performed quality control inspection. Job complete.			
			Line Total	\$0.00

Labor	\$4,934.86
Parts	\$1,756.24
Shop supplies	\$350.00
Subtotal	\$7,041.10
GST (5%)	\$352.07
Total	\$7,393.17
Payments	
Oct 6, 2025 - EFT	\$7,393.17
Balance	\$0.00

Any warranties on the parts and accessories sold hereby are made by the manufacturer. You understand and agree that we make no warranties of any kind unless expressed in writing. You hereby authorize us to perform the repair work herein set forth and to purchase the necessary material and parts to perform such repair work. You agree that we are not responsible for loss or damage to your vehicle or articles left in your vehicle in case of fire, theft, or any other cause beyond our control or for any delays caused by unavailability of parts or delays in part shipments by the supplier or transporter. In addition, you agree that we are not responsible for damages to your vehicle from freezing due to lack of antifreeze. You hereby grant our employees permission to operate your vehicle on streets, highways, or elsewhere for the purpose of testing and/or inspection. You acknowledge and agree that an express mechanic's lien on your vehicle is granted to secure payment of this invoice for the repair work detailed in this invoice.

Customer signature: _____

Printed name: _____ **Date:** _____