

Staging Heavy Duty - 9919

9919 Shepard Road SE
Calgary, Alberta, T2C 4M5
(403) 523 - 0488



Invoice: INV-
S9901-16810

Invoice Date: Sep 11, 2026
Due date: Oct 11, 2026

Bill To

Mobile Truck & Trailer Repair Dover (IBS#:
783698)
891 Rodriguez Harbor Suite 664
Suite 452
South Oscar, Yukon Territory, E8T 9S7

Remit payment to

Punta Gorda Truck Service & Repair
057 Graham Crossroad
Ryanfort, Yukon Territory, Y5E 2E2
519-531-1194

Unit	VIN/Serial #	Asset	Mileage	Eng Hrs
	1LH930VH XK1E27469	2019 Landoll Corporation 930e	11	0
Service Order	Terms	Due date	Customer PO	Authorizer
S9901-16810	Net 30	Oct 11, 2026		

Description	Quantity	Rate	Amount
Service - Air brake trailer CVIP tri-axle			
Labor Annual inspection CM: CVIP inspection with wheels removed. Measure shoes, drums, tire PSI and tread depth. Fail unit on efacity. Issue sticker CV8721008			\$400.00
	Parts Total		\$0.00
	Labor Total		\$400.00
	Line Total		\$400.00
Service - Wheels off trailer tri-axle			
Labor Annual inspection CK: Lifted the unit and secured it safely using jack stands and frame stands. Removed the auto-inflation system and wheels. Backed off the brakes and removed the brake drums. Unit was prepared and ready for inspection. Following inspection, reinstalled the brake drums and wheels. Adjusted and set the brakes, lowered the unit, and torqued the wheels to specification. AZ: Verified and re-torqued the wheels to specification. Job complete.			\$350.00
	Parts Total		\$0.00
	Labor Total		\$350.00
	Line Total		\$350.00
Service - Caging bolts	0.25	\$149.95	\$37.49

	Description	Quantity	Rate	Amount
Labor	Missing - axle #1 left and axle #2 left - (Safety) AZ replaed cage bolts job complatead			
Parts	RT1 - CAGING BOLT all DDSB† except 3036 and 3636	2	\$16.49	\$32.98
			Parts Total	\$32.98
			Labor Total	\$37.49
			Line Total	\$70.47

Diagnose - Brake adjustment on Axle #2 right side

Labor	Brake wont adjust CM: Check axle 2 brakes. After tightening slacks adjusters, they both need to be backed off over a 1/4 turn until they start ratcheting. Both slack adjusters need to be replaced. Diag complete.	1	\$149.95	\$149.95
			Parts Total	\$0.00
			Labor Total	\$149.95
			Line Total	\$149.95

Replace - Axle #2 Slack adjusters

Labor	Worn out - axle 2 both sides - (Safety) MW: Removed slack adjusters for sample. Installed slack adjusters and reconnected grease lines to new slack adjusters. Set brake strokes.. Greased auto grease line to new slack adjusters. Job complete.			
	Had to find new fittings for axle #1 slack adjuster for grease lines. Awaitin.G	2	\$149.95	\$299.90
Parts	N216-013BR - 115-A 1/8" BRASS EXTRUDED 90 STREET ELBOW	2	\$2.18	\$4.36
Parts	MK22153S - Slack Adjuster	2	\$243.32	\$486.64
			Parts Total	\$491.00
			Labor Total	\$299.90
			Line Total	\$790.90

Diagnose and repair - Marker light

Labor	Not working- right side rear - (Safety) SK: Ensured good source voltage. Confirmed light was inoperative. Checked for voltage at the light. Had 0V the the light. Checked for voltage further back in the circuit and had source voltage. Had a drop of 12v across both wires. Followed the harness and found an area where the harness had torn. Repair the cable. Job completed.	1	\$149.95	\$149.95
			Parts Total	\$0.00
			Labor Total	\$149.95
			Line Total	\$149.95

Replace - Center tire inflator

Labor	Was damaged trying to take the drum off **Policy CK: Threaded in new inflator envelope and reattached air lines. Job complete.	0	\$149.95	\$0.00
-------	---	---	----------	--------

	Description	Quantity	Rate	Amount
Parts	31317-03 - Hub Mounted Tire Inflator	1	\$0.00	\$0.00
			Parts Total	\$0.00
			Labor Total	\$0.00
			Line Total	\$0.00

Replace - Wheel studs

Labor	Damaged **Policy CK: Removed the old damaged stud and installed the new one. Job complete.	0	\$149.95	\$0.00
Parts	201.3014 - FLANGED CAP NUT (E6000A, R006000A)	1	\$0.00	\$0.00
Parts	E6034 - Wheel Stud	3	\$0.00	\$0.00
			Parts Total	\$0.00
			Labor Total	\$0.00
			Line Total	\$0.00

Replace - Air springs

Labor	Exposed cords - all 4 springs - (Safety) SK: Unbolted the bottom bolt from the air bags and pulled the pedestal. Cut the air line to the air bag fitting and pulled the fitting. Removed both upper mounting bolts and pulled the air bag. Axle 2 air bags required extra labor as both of the upper bolts are located in a piece of tubing with access slots. The slots were extremely clogged with hardened dirt and dust. Chipped away at the dirt to free it up. Vacuumed and blew out debris had to cut the air line at the fitting and spin the fitting out. Cleaned out more debris to access the big nut. Scraped off any rust to allow socket to fit. Pulled the nut. For the outer nut had to use a pick to get rid of hardened debris. Lubricated and wrenched off the nut. On the left side the nut was extremely seized and rounded off. Had to be gouged out. Sample provided to parts. Mounted the air bags using new hardware. Secured the hardware. Trimmed the air lines. Installed the air fittings using pipe sealant. Supplied air to the fittings to inflate the bags. Guided the rod end of the bags through the bottom mounting hole. Tightened the bottom nut. Job completed.	8.9	\$149.95	\$1,334.56
Parts	ER9807 - Air Spring	4	\$157.76	\$631.04
Parts	FREIGHT - Freight	1	\$100.00	\$100.00
Parts	NN8SC-050 - 1/2" NC NYLON LOCKNUT	4	\$0.53	\$2.12
Parts	8LWS-075 - 3/4" LOCK WASHER	4	\$0.55	\$2.20
Parts	8WS-050 - 1/2" FLAT WASHER	8	\$0.28	\$2.24
Parts	PC1468-6B - 3/8" BRASS DOT TUBE PUSH-IN X 1/4" MALE NPT	2	\$5.90	\$11.80
Parts	1469-6B - 3/8" BRASS TUBE X 1/4" MALE NPT 90 ELBOW FOR NYLON DOT	2	\$5.00	\$10.00
			Parts Total	\$759.40
			Labor Total	\$1,334.56
			Line Total	\$2,093.96

	Description	Quantity	Rate	Amount
Replace - Shocks on Axle #1 and Axle #2				
Labor	Bushings loose - Axle #1 both sides, axle #2 right, recommend replacing as a set - (Safety) SK: Attempted to remove the shock mount bolts and found the hardware severely seized. Axle #1 shock bolts had to be cut to remove the shocks. Axle #2 hardware was also extremely seized and required cutting. The left-side bolt was seized so tightly that the shock would not rotate. Multiple cuts were required to remove the bolt, and portions of the shock had to be trimmed. The shock mount bracket also had to be spread to allow removal. All shocks were successfully removed, and a sample was provided to the parts department. Installed the replacement shocks into the upper and lower mounts. Found the axle #1 left-side lower shock mount bent inward and requiring adjustment back into position. Tightened the upper mounting hardware; however, the mounting bolt would not accept the existing nut and square nuts were required to complete the installation. AZ: Installed the lower shock mounting bolts and nuts and secured the shock assemblies. All required hardware was tightened and secured. Job complete.			
		4.75	\$149.95	\$712.26
Parts	83130 - Shock Absorber	4	\$78.09	\$312.36
Parts	CS8SC-075-300 - 3/4"X3" NC BOLT (GR8, HEX)	4	\$4.33	\$17.32
Parts	CS8SC-075-400 - 3/4"X4" NC BOLT (GR8, HEX)	4	\$5.36	\$21.44
Parts	8WS-075 - 3/4" FLAT WASHER	12	\$0.60	\$7.20
Parts	SLCSC-075 - 3/4" NC STOVER LOCKNUT	4	\$1.87	\$7.48
Parts Total				\$365.80
Labor Total				\$712.26
Line Total				\$1,078.06

Replace - Axle #1 Brake chamber				
Labor	Unable to cage - axle #1 right - (Safety) SK: Pulled cotter pins. Removed the clevis pins. Marked and cut the air lines. Unbolted the brake pot and brought as sample to parts. Measured push rod length and cut the new one to size. Installed clevis to the rod and jammed it tight. installed brake pot using new hardware. Secured to the slack using new clevis pins and cotter pins. Installed air lines and secured. Job completed.			
		1.95	\$149.95	\$292.40
Parts	FLT3030SCB20 - 30/30 STANDARD/REGULAR STROKE BRAKE CHAMBER (SB3030S2500)	1	\$72.20	\$72.20
Parts	S100 - STROKE INDICATOR	1	\$1.69	\$1.69
Parts	179.YK5005 - CLEVIS KIT MERITOR TYPE 5/8"Straight, 5/8in-18 Threads, 1/2in and 1/4in Pins, Pin C to C is 1-3/8in(E11430A, R810019)	1	\$11.09	\$11.09
Parts	SLCSC-062 - 5/8" NC STOVER LOCKNUT	2	\$1.26	\$2.52
Parts	8WS-062 - 5/8" FLAT WASHER	2	\$0.50	\$1.00

Description		Quantity	Rate	Amount
			Parts Total	\$88.50
			Labor Total	\$292.40
			Line Total	\$380.90
Replace - Axle #1 Brake shoes and drums				
Labor	Irregular wear- axle 1 left and right - (Safety) AZ: Removed and replaced the brake shoes. Installed the inner bearing and new seal, then installed the hub and outer bearing. Tightened and torqued the hub nut to the manufacturer's specifications. Reinstalled the brake components and drums, secured all hardware, and verified the components were properly installed. Job complete.	3.26	\$149.95	\$488.84
Parts	SSD2787 - 12.25x7.5 Brake Drum	2	\$191.69	\$383.38
Parts	XSS504692DFCII - Brake Shoe Kit, 12.25" x 7.5", Dana/Spicer Fast Change II, 1.25" Anchor Pin, HDW Kit E-10756	2	\$149.99	\$299.98
			Parts Total	\$683.36
			Labor Total	\$488.84
			Line Total	\$1,172.20
Replace - Brake hoses to #1 right side brake pot				
Labor	Hoses cant be re used due to the old clamp type that was used. SK: Pulled the plate securing the air lines. Bolt broke off upon removal. Marked the hoses and disconnected from the relay valve and brought to part as a sample. Built new hoses based off of the old ones. Ensuring the fittings sealed well. Installed into the valve and sealed using pipe sealant. Secured the hoses using zipties and handcuff ties. Job completed.	2	\$149.95	\$299.90
Parts	1492-6C - 3/8" X 3/8" BRASS MALE NPT FOR RUBBER DOT HOSE	2	\$8.50	\$17.00
Parts	1493-6C - 3/8" RUBBER DOT HOSE X 3/8" MALE NPT	2	\$9.06	\$18.12
Parts	NL4550-038 - 3/8" AIR BRAKE HOSE, RUBBER J1402 DOT AIRBRAKE 225 PSI	5	\$2.17	\$10.85
Parts	76-2946 - 13" Dual Clamp Cable Tie	2	\$3.33	\$6.66
			Parts Total	\$52.63
			Labor Total	\$299.90
			Line Total	\$352.53
Repair - Axle #1 left side lower shock mount bracket				
Labor	Straighten - Bent inwards not allowing shock head through it CK: Using torch, heated up lower shock mount and bent into straight position with a crescent wrench. Job complete.	0.73	\$149.95	\$109.46
			Parts Total	\$0.00
			Labor Total	\$109.46
			Line Total	\$109.46

	Description	Quantity	Rate	Amount
Replace - Axle #2 Brake chamber				
Labor	Leaking air - axle 2 right - (Safety) SK: Removed the cotter pins and clevis pins. Marked and cut the air lines, then unbolted and removed the brake chamber. Provided the brake chamber to the parts department as a sample. Repair ongoing. AZ: Measured the brake chamber push rod and cut it to the required length. Installed the clevis and new brake chamber, then installed new fittings and reconnected the air lines. Secured all components and verified proper installation. Job complete.	2.12	\$149.95	\$317.89
Parts	FLT3030SCB20 - 30/30 STANDARD/REGULAR STROKE BRAKE CHAMBER (SB3030S2500)	1	\$72.20	\$72.20
Parts	S100 - STROKE INDICATOR	1	\$1.69	\$1.69
Parts	179.YK5005 - CLEVIS KIT MERITOR TYPE 5/8" Straight, 5/8in-18 Threads, 1/2in and 1/4in Pins, Pin C to C is 1-3/8in(E11430A, R810019)	1	\$11.09	\$11.09
Parts Total				\$84.98
Labor Total				\$317.89
Line Total				\$402.87

Replace - Axle #2 Brake shoes and drums				
Labor	Irregular wear - drum and shoes- axle 2 right - axle 2 left - brake shoes have irregular wear - (Safety) AZ: Removed and replaced the left rear brake shoes. Installed the inner bearing and new seal, then installed the hub and outer bearing. Tightened and torqued the hub nut to the manufacturer's specifications. Installed the bearings and seal on the opposite wheel end, then reinstalled the hub and outer bearing. Tightened and torqued the hub nut to the manufacturer's specifications. Installed the hub caps and filled the hubs with the proper oil level. Reinstalled the brake components and drums, secured all hardware, and verified the components were properly installed. Job complete.	3.11	\$149.95	\$466.34
Parts	SSD2787 - 12.25x7.5 Brake Drum	2	\$191.69	\$383.38
Parts	XSS504692DFCII - Brake Shoe Kit, 12.25" x 7.5", Dana/Spicer Fast Change II, 1.25" Anchor Pin, HDW Kit E-10756	1	\$149.99	\$149.99
Parts	XSS504692DFCII - Brake Shoe Kit, 12.25" x 7.5", Dana/Spicer Fast Change II, 1.25" Anchor Pin, HDW Kit E-10756	1	\$149.99	\$149.99
Parts Total				\$683.36
Labor Total				\$466.34
Line Total				\$1,149.70

Replace - Axle #2 S-cam and bushings				
Labor	Worn out - axle 2 left and right - (Safety) SK: Removed the hub caps and drained the hub oil. Removed the hub retaining hardware, covered and protected the bearings, and removed the hubs. Removed the snap rings and S-cams from their	6.67	\$149.95	\$1,000.17

Description		Quantity	Rate	Amount
mounts. Drove out the existing S-cam bushings and provided them to the parts department as samples.				
Disassembled the right-side wheel end and caged the left-side brakes before removing the brake drum and shoes. Removed the left-side hub cap, drained the oil, and removed the hub retaining hardware and hub. Cleaned and inspected both hubs. Found the left inner bearing race spinning freely inside the hub, indicating the hub is damaged and requires replacement.				
Removed the retaining rings, cotter pins, slack adjuster, and camshaft. Removed the existing seals and bushings. Cleaned the mounting plates and bushing bores, then installed new seals and bushings. Reinstalled the mounting plates using new bushings and hardware. Repair ongoing.				
AZ: Replaced both S-cams and installed the slack adjusters. Installed the required snap rings and shims and secured all components. Job complete.				
Parts	E-2469 - Camshaft Repair Kit	1	\$47.82	\$47.82
Parts	3009 - Hub Cap Gasket, 6 Bolt, 5.5" Bolt Pattern	2	\$5.08	\$10.16
Parts	MDS79DD - 75W90 Bulk- Mobil Delvac 1 Gear Oil	2	\$15.60	\$31.20
Parts	372-7097 - STEMCO GRIT-GUARD 2PC WHEEL SEAL (46305/46300, 370025A/380025A, 307-0743, 373-0143, 10045888)	2	\$87.88	\$175.76
Parts	3418905 - RH S-Cam	1	\$257.13	\$257.13
Parts	341885 - LH S-Cam	1	\$257.13	\$257.13
Parts	FREIGHT - Freight	1	\$103.21	\$103.21
Parts	R810027 - Clevis Pin Kit	1	\$4.71	\$4.71
			Parts Total	\$887.12
			Labor Total	\$1,000.17
			Line Total	\$1,887.29

Repair - Axle #2 left side Hub

Labor Inner race spinning freely

SK: Removed the bearing races from the hub for inspection. Found the races were extremely loose within the hub. Further inspection revealed extensive damage and wear to the hub where the races seat. Repair ongoing.

AZ: Installed new bearing races, bearings, and seal. Installed the hub and filled it with the required oil. Torqued the hub nuts to the manufacturer's specifications and secured all components. Job complete.

		1	\$149.95	\$149.95
Parts	SET414 - Bearing Set	1	\$80.64	\$80.64
Parts	182.427 - WHEEL BEARING KIT, PRE ADJUST	1	\$71.48	\$71.48
Parts	BRAKECLEAN - Brake & Parts Cleaner	1	\$7.99	\$7.99
			Parts Total	\$160.11
			Labor Total	\$149.95

Description		Quantity	Rate	Amount
			Line Total	\$310.06
Replace - Axle #2 ABS sensor				
Labor	Broken - axle #2 right side AZ: Removed and replaced the ABS sensor. Secured the sensor and wiring, then verified proper installation. Job complete.	0.92	\$149.95	\$137.95
Parts	4410309182 - ABS Sensor Kit	1	\$113.30	\$113.30
			Parts Total	\$113.30
			Labor Total	\$137.95
			Line Total	\$251.25
Replace - Brake hoses to #2 right side brake pot				
Labor	Hoses cant be re used due to the old clamp type that was used. SK: Pulled the plate securing the air lines. Bolt broke off upon removal. Marked the hoses and disconnected from the relay valve and brought to part as a sample. Built new hoses based off of the old ones. Ensuring the fittings sealed well. Installed into the valve and sealed using pipe sealant. Job completed.	1.5	\$149.95	\$224.93
Parts	1492-6C - 3/8" X 3/8" BRASS MALE NPT FOR RUBBER DOT HOSE	2	\$8.50	\$17.00
Parts	1493-6C - 3/8" RUBBER DOT HOSE X 3/8" MALE NPT	2	\$9.06	\$18.12
Parts	NL4550-038 - 3/8" AIR BRAKE HOSE, RUBBER J1402 DOT AIRBRAKE 225 PSI	8	\$2.17	\$17.36
Parts	N221-038BR - 124-C 3/8" BRASS EXTRUDED 45 STREET ELBOW	1	\$4.73	\$4.73
			Parts Total	\$57.21
			Labor Total	\$224.93
			Line Total	\$282.14
Replace - Hydraulic quick connect fitting				
Labor	Level 3 leak - male fitting - (Safety) SK: Removed the fitting and provided as a sample to parts. Installed new fitting. Sealed using pipe sealant. Job completed.	0.5	\$149.95	\$74.98
Parts	AC-800501006 - ISO A Coupler	1	\$64.55	\$64.55
			Parts Total	\$64.55
			Labor Total	\$74.98
			Line Total	\$139.53
Replace - Mudflap				
Labor	Torn - right rear - (Safety) AZ: Removed the torn mud flap and replaced it with a new one. Cut the new mud flap to the required size and installed it using new mounting hardware. Removed and replaced the mud flap end mounting bolts, secured all hardware, and verified the mud flap was properly mounted. Job complete.	3	\$149.95	\$449.85

	Description	Quantity	Rate	Amount
Parts	CHHD2436 - PLAIN MUD FLAP 24"x36" - CUTTABLE	1	\$38.80	\$38.80
Parts Total				\$38.80
Labor Total				\$449.85
Line Total				\$488.65

Replace - Install winch

Labor	Customer supplied JC: Removed the temporary decking on the trailer. Lifted the winch onto the trailer. Switched over hydraulic motor fittings. Mounted hydraulic motor and connected lines, took some extra time to determine line position and secure due to limited access. Lined up and mounted the winch assembly. Removed the cable cover assembly from the old winch. Mounted main winch cover assembly. Cleaned up area. AZ: Removed and cleaned the winch panel, removing rust and surface corrosion. Prepared and painted the panel to protect it from further corrosion. Reinstalled the panel using new mounting bolts and secured all hardware. Job complete.	5	\$149.95	\$749.75
Parts	N60012-910 - #10 ORB REPLACEMENT O-RING	2	\$0.48	\$0.96
Parts	BRAKECLEAN - Brake & Parts Cleaner	1	\$7.99	\$7.99
Parts	CS8SC-050-150 - 1/2"X1-1/2" NC BOLT (GR8, HEX)	4	\$1.14	\$4.56
Parts	CS8SC-050-200 - 1/2"X2" NC BOLT (GR8, HEX)	8	\$1.38	\$11.04
Parts	SLCSC-050 - 1/2" NC STOVER LOCKNUT	8	\$0.73	\$5.84
Parts	8WS-050 - 1/2" FLAT WASHER	22	\$0.28	\$6.16
Parts Total				\$36.55
Labor Total				\$749.75
Line Total				\$786.30

Repair - Axle #2 Spindle has lots of indentations and protrusions

Labor	Clean surface to limit contamination AZ: Cleaned and prepared the bearing and hub surfaces using a suitable grade of sandpaper and brake cleaner. Lubricated the bearing and confirmed proper fitment. Installed the hub and torqued the spindle nuts to the manufacturer's specifications. Reinstalled the wheels and secured all hardware. Job complete.	1	\$149.95	\$149.95
Parts Total				\$0.00
Labor Total				\$149.95
Line Total				\$149.95

Repair - Marker light wiring

Labor	Broken cable causing an open and inoperative light MW: Re-established connection in marker light wiring, used an extra two-wire section. Crimped connections, secured wiring and tested marker light function. All marker lights work as expected. Job complete.	1	\$149.95	\$149.95
-------	---	---	----------	----------

	Description	Quantity	Rate	Amount
Parts	84-4005PK - 3/16 BLACK SHRINK TUBE	2	\$1.40	\$2.80
Parts	76-2405PK - 16-14GA Non-Insulated Butt Splice Connector	4	\$0.40	\$1.60
Parts	76-8430 - 16/2, Grey Jacketed Flat Cable	2	\$4.29	\$8.58
			Parts Total	\$12.98
			Labor Total	\$149.95
			Line Total	\$162.93

Repair - Marker light

Labor	Left front hanging down - (Safety) AZ: Repaired the left-front marker light, which was hanging down due to a missing mounting grommet. Installed a new grommet and secured the light in place. Verified the light is properly mounted and intact. Job complete.	0.91	\$149.95	\$136.45
			Parts Total	\$0.00
			Labor Total	\$136.45
			Line Total	\$136.45

Repair - Replace the broken studs for the hose mounting brackets under units

Labor	Studs snapped when removing nuts SK: Cut the broken studs. Prepped surface. Made a good ground location. Welded two bolts where the broken ones had been. Painted all bare metal. Job completed.	1.2	\$149.95	\$179.94
			Parts Total	\$0.00
			Labor Total	\$179.94
			Line Total	\$179.94

Sublet - Welding - gouge out axle #2 left side air bag mounting bolt

Labor	Rounded and seized Completed.	0	\$149.95	\$0.00
			Parts Total	\$0.00
			Labor Total	\$0.00
			Line Total	\$0.00

Sublet - Tires

Labor	Cupping/ low tread - Axle #1 left - (Safety) Sublet repair: completed.	0	\$149.95	\$0.00
Parts	SUBLET - Tire Replacement	1	\$987.83	\$987.83
			Parts Total	\$987.83
			Labor Total	\$0.00
			Line Total	\$987.83

Quality control check over

Labor	QC JL: Completed quality control workmanship inspection.			
			Line Total	\$0.00

Labor	\$8,812.81
Parts	\$5,600.46
Shop supplies	\$350.00
Subtotal	\$14,763.27
GST (5%)	\$738.20
Total	\$15,501.47
Payments	
Sep 11, 2026 - Debit	\$15,501.47
Balance	\$0.00

Any warranties on the parts and accessories sold hereby are made by the manufacturer. You understand and agree that we make no warranties of any kind unless expressed in writing. You hereby authorize us to perform the repair work herein set forth and to purchase the necessary material and parts to perform such repair work. You agree that we are not responsible for loss or damage to your vehicle or articles left in your vehicle in case of fire, theft, or any other cause beyond our control or for any delays caused by unavailability of parts or delays in part shipments by the supplier or transporter. In addition, you agree that we are not responsible for damages to your vehicle from freezing due to lack of antifreeze. You hereby grant our employees permission to operate your vehicle on streets, highways, or elsewhere for the purpose of testing and/or inspection. You acknowledge and agree that an express mechanic's lien on your vehicle is granted to secure payment of this invoice for the repair work detailed in this invoice.

Customer signature: _____

Printed name: _____ **Date:** _____