

Summary report

Wellbore: 15/9-F-15 C

Period: 2009-02-06 00:00 - 2009-02-07 00:00

Status:	normal
Report creation time:	2018-05-03 13:52
Report number:	20
Days Ahead/Behind (+/-):	26.6
Operator:	StatoilHydro
Rig Name:	MÆRSK INSPIRER
Drilling contractor:	Mærsk Contractors
Spud Date:	2009-01-19 00:00
Wellbore type:	
Elevation RKB-MSL (m):	54.9
Water depth MSL (m):	91
Tight well:	Y
HPHT:	Y
Temperature (I):	
Pressure (I):	
Date Well Complete:	2009-02-14

Dist Drilled (m):	-999.99
Penetration rate (m/h):	-999.99
Hole Dia (I):	
Pressure Test Type:	formation integrity test
Formation strength (g/cm3):	1.56
Dia Last Casing (I):	

Depth at Kick Off mMD:	
Depth at Kick Off mTVD:	
Depth mMd:	2920
Depth mTVD:	2748
Plug Back Depth mMD:	
Depth at formation strength mMD:	2562
Depth At Formation Strength mTVD:	2418
Depth At Last Casing mMD:	2914.8
Depth At Last Casing mTVD:	

Summary of activities (24 Hours)

None

Summary of planned activities (24 Hours)

None

Operations

Start time	End time	End Depth mMD	Main - Sub Activity	State	Remark
06:00	09:00	0	drilling -- bop/wellhead equipment	ok	Removed and POOH with handling slings from surface riser. RU scaffolding in moonpool to be able to MU NT2 connector on BOP. Meanwhile changed out saver sub on TDS and continued with house keeping.
09:00	14:15	0	drilling -- bop/wellhead equipment	ok	Moved BOP to well centre and MU NT2 connector. Installed BOP tension cylinders. Meanwhile continued to chang out saver sub on TDS, repaired spinners on iron roughneck and LO PR RT with cut riser section.
14:15	15:15	0	drilling -- bop/wellhead equipment	ok	Prepared to run diverter. Meanwhile trouble shot tension cylinder failure on F-15.
15:15	17:45	0	drilling -- bop/wellhead equipment	ok	Held tool box talk before running overshot and diverter. Removed outer ring and master bushings. Ran overshot. Moved BOP into well centre to re-align with diverter. NU diverter. Installed outer ring and master bushings. Removed long slings and installed BX elevator and rotating adaptor.
17:45	20:00	0	drilling -- bop/wellhead equipment	ok	Filled riser with SW using cmt unit. MU, inspected seals and greased surface test plug. RIH with test plug and landed in suface WH at 20.5 m.
20:00	22:45	0	interruption -- repair	ok	Attempted to pressure test all connection between multibowl and BOP to 35 bar/5 min. No go. Opened lower pipe ram and closed middle pipe ram. Re-tested. No go. Re-sat test plug. No go, due to test plug was leaking. POOH with test plug. No damage seen on test plug. MU, RIH and landed back-up test plug. Filled pipe with SW. Attempted to pressure test all connections between multibowl and BOP to 35 bar/5 min. No go, due to test plug was leaking. Meanwhile RD broken tension cylinder on F-15.
22:45	23:30	0	drilling -- bop activities	ok	PU TDS and re-landed test plug. Applied 3 mT of block weight down on plug. Pressure tested all connections between multibowl and BOP to 35 bar/345 bar for 5/10 min. Had 2 bar (0.6%) drop in 10 min.
23:30	00:00	0	drilling -- bop activities	ok	Function tested BOP rams. Opened BOP ram and POOH with test plug strapping the length to be 20.515 m down to landing point in surface wellhead.