

Summary report

Wellbore: 15/9-F-15 D

Period: 2015-08-12 00:00 - 2015-08-13 00:00

Status:	normal
Report creation time:	2018-05-03 13:52
Report number:	8
Days Ahead/Behind (+/-):	
Operator:	Statoil
Rig Name:	MÆRSK INSPIRER
Drilling contractor:	Altus Intervention
Spud Date:	2013-11-10 14:00
Wellbore type:	
Elevation RKB-MSL (m):	54.9
Water depth MSL (m):	91
Tight well:	Y
HPHT:	Y
Temperature (I):	
Pressure (I):	
Date Well Complete:	2013-12-02

Dist Drilled (m):	-999.99
Penetration rate (m/h):	-999.99
Hole Dia (I):	
Pressure Test Type:	formation integrity test
Formation strength (I):	
Dia Last Casing (I):	

Depth at Kick Off mMD:	
Depth at Kick Off mTVD:	
Depth mMd:	-999.99
Depth mTVD:	
Plug Back Depth mMD:	
Depth at formation strength mMD:	
Depth At Formation Strength mTVD:	
Depth At Last Casing mMD:	4683.6
Depth At Last Casing mTVD:	3212

Summary of activities (24 Hours)

RIH with BHA#3 perf.run#1. Perforated with top shot at 3748 m and bottom shot at 3766 m. POOH and L/D BHA. Prepared and RIH with BHA#4 for perf.run#2.

Summary of planned activities (24 Hours)

POOH with BHA#4 perf.run#2. Prepare next BHA.

Operations

Start time	End time	End Depth mMD	Main - Sub Activity	State	Remark
00:00	01:00	0	interruption -- other	ok	Leak tested QTS to 20/345 bar 5/10 min. Equalized SV and HMV using MEG. WHP 75 bar.
01:00	05:00	3390	interruption -- other	ok	RIH w/BHA #3 by gravity from 0 m to 3390 m, WHP 75 bar. Toolstring stopped at 3390 m. Depth: P/U Weight: 400 m 3200 lbs 1200 m 4100 lbs 2000 m 5500 lbs 2800 m 6600 lbs 3200 m 6200 lbs Friction factor 0,25.
05:00	05:25	3520	workover -- perforate	ok	RIH with tractor activated from 3390 m to 3520 m.
05:25	06:00	3442	workover -- perforate	ok	Correlated from 3520 m across pup joint at 3472 m at 10 m/min. Stopped at 3442 m. Activated tractor.
06:00	06:50	3810	workover -- perforate	ok	Tractored down at 10 m/min from 3442 m to 3810 m.
06:50	09:00	3810	workover -- perforate	ok	Performed correlation, 5 passes in interval 3810 m to 3708 m, used tractor when RIH.
09:00	09:10	3772	workover -- perforate	ok	P/U at 10 m/min to 3743 m CCL depth. Bottom BHA at 3772 m Placing top shot at 3748 m and bottom shot at 3766 m. HW 5880 lbs. WHP 75,1 bar. BHP 281 bar.
09:10	09:15	3772	workover -- perforate	ok	Perforated well in interval 3748 m to 3766 m. WHP increased to 79 bar and BHP increased to 285 bar.
09:15	09:30	3572	workover -- perforate	ok	POOH at 10 m/min and logged CCL up to 3572 m.
09:30	10:55	500	workover -- perforate	ok	Continued POOH to 500 m. Prepared for handling explosives on surface.
10:55	11:25	0	workover -- perforate	ok	POOH to surface.
11:25	13:10	0	workover -- perforate	ok	OOH, closed SV and HMV inflow tested same. Bled of pressure in R/U to closed drain. Flushed R/U with N2.
13:10	16:00	0	workover -- perforate	ok	Disconnected lubricator. Production measured benzene to > 10 ppm inside riser and 0 ppm outside riser. L/D BHA#3 .
16:00	17:40	0	workover -- perforate	ok	Prepared tools for BHA#4 for perf.run#2.
17:40	19:30	0	workover -- perforate	ok	Observed gas in cablehead, megging not satisfied. Had to ventilate gas out of cable.
19:30	20:50	0	workover -- perforate	ok	Performed Altus / Schlumberger tractor check.
20:50	21:00	0	workover -- perforate	ok	Performed TBT for R/U toolstring.
21:00	22:55	0	workover -- perforate	ok	R/U toolstring perf.run#2. Added 40 litr Ramex 50/50 MEG in riser. Leak tested QTS to 20/345 bar 5/10 min. Equalized SV and HMV using MEG. WHP: 79 bar
22:55	00:00	700	workover -- perforate	ok	RIH w/BHA #4 (3 1/8" tractor and 4 1/2" perf.guns) by gravity from surface to 1200 m.

Equipment Failure Information

Start time	Depth mMD	Depth mTVD	Sub Equip - Syst Class	Operation Downtime (min)	Equipment Repaired	Remark
00:00	3355		service equ -- other	0	00:00	Da vi skulle trekke ut av brønnen F-15D, kom WL Add on Drum ut av posisjon. Dette resulterte i skade på 7/16" kabel.Skaden på 7/16" kabel er det ikke tatt bilde av pga denne allerede var spolet inn på trommelen og det ble vurdert at det ikke var hensiktsme
00:00	3592		service equ -- other	0	00:00	Det oppsto en elektronikk feil på 318 traktor mens vi hold på med dybde korrelering før perforering. Traktor ble forsøkt startet flere ganger og software p å overflaten sjekket. Altus support på land forsøkte også å feilsøke ved å logge seg på. Serie nr på

Perforation Information

Time of Opening Well Perf	Time of Closing Well Perf	Top of Perf mMD	Bottom of Perf mMD	Top of Perf TVD	Bottom of Perf TVD
13:10		3748	3766		