

Summary report

Wellbore: 15/9-F-1 B

Period: 2014-02-01 00:00 - 2014-02-02 00:00

Status:	normal
Report creation time:	2018-05-03 13:51
Report number:	8
Days Ahead/Behind (+/-):	
Operator:	Statoil
Rig Name:	MÆRSK INSPIRER
Drilling contractor:	Maersk Drilling
Spud Date:	2013-08-29 15:30
Wellbore type:	
Elevation RKB-MSL (m):	54.9
Water depth MSL (m):	91
Tight well:	Y
HPHT:	Y
Temperature (°):	
Pressure (°):	
Date Well Complete:	2013-09-07

Dist Drilled (m):	-999.99
Penetration rate (m/h):	-999.99
Hole Dia (°):	
Pressure Test Type:	formation integrity test
Formation strength (°):	
Dia Last Casing (°):	

Depth at Kick Off mMD:	
Depth at Kick Off mTVD:	
Depth mMD:	3147
Depth mTVD:	2948
Plug Back Depth mMD:	3147
Depth at formation strength mMD:	
Depth At Formation Strength mTVD:	
Depth At Last Casing mMD:	3090.1
Depth At Last Casing mTVD:	2895

Summary of activities (24 Hours)

Performed fault finding on TDS brake system.
Removed brake disc and re-installed brake assembly on TDS.
Prepared TDS for operation.
P/U and M/U THRT, RIH with same to 21 m.

Summary of planned activities (24 Hours)

Engage TH with running tool and pull free.
POOH with completion on TH and THRT. Release RT from hanger and L/O same.
Release communication collar from hanger.
R/U 7" running equipment.
POOH completion.

Operations

Start time	End time	End Depth mMD	Main - Sub Activity	State	Remark
00:00	05:00	0	interruption -- repair	ok	Maintenance department stripped down TDS brake system for investigation/removal of brake disc.
05:00	12:45	0	interruption -- repair	ok	Maintenance department removed disc from brake. Re-assembled brake system and installed same on TDS. Meanwhile performed cleaning and housekeeping.
12:45	13:30	0	interruption -- repair	ok	Tested the TDS at various heights in both spin and drill mode. Erratic torque observed but TDS spin function not stopped.
13:30	15:00	0	interruption -- repair	ok	Tested TDS at connection height in derrick. Observed high torque in reverse mode and no turning. Selected forward mode, high torque and no turning. Maintenance engineer and electrician inspected TDS at height. Lowered TDS down. Function tested same, ok. Meanwhile layed out 2 7/8" DP on pipe deck.
15:00	19:00	0	interruption -- repair	ok	Isolated TDS. Inspected gear box on TDS and replaced gear box filter. Meanwhile performed maintenance and housekeeping. Preserved BOP test stump in moonpool.
19:00	19:45	0	interruption -- repair	ok	Perform TBT and checked TDS for PDOs. Installed TDS cage.
19:45	20:30	0	interruption -- repair	ok	Performed megger testing of the TDS umbilical at various heights, unable to replicate fault.
20:30	22:30	0	interruption -- repair	ok	Isolated equipment. Checked and wire locked bolts on TDS. De-isolated equipment.
22:45	23:00	0	interruption -- repair	ok	Reinstalled link tilt and elevators, tested same.
23:00	23:15	0	interruption -- repair	ok	Performed TBT for running THRT.
23:15	23:45	0	interruption -- repair	ok	P/U THRT and landed same in rotary. Installed bushings. M/U 5 1/2" DP stand to THRT.
23:45	00:00	21	workover -- bop/wellhead equipment	ok	RIH w/ THRT on 5 1/2" DP stand from surface to 21 m.

Drilling Fluid

Sample Time	16:00
Sample Point	Active pit
Sample Depth mMD	3465
Fluid Type	Enviromul Yellow
Fluid Density (g/cm3)	1.37
Funnel Visc (s)	-999.99
Mf (°)	
Pm (°)	
Pm filtrate (°)	
Chloride (°)	
Calcium (°)	
Magnesium (°)	
Ph	
Excess Lime (°)	
Solids	
Sand (°)	
Water (°)	
Oil (°)	
Solids (°)	
Corrected solids (°)	
High gravity solids (°)	

Low gravity solids ()	
Viscometer tests	
Plastic visc. (mPa.s)	31
Yield point (Pa)	6.5
Filtration tests	
Pm filtrate ()	
Filtrate Lthp ()	
Filtrate Hthp ()	
Cake thickn API ()	
Cake thickn HPHT ()	
Test Temp HPHT (degC)	120
Comment	