

Summary report

Wellbore: 15/9-F-1 C

Period: 2016-06-27 00:00 - 2016-06-28 00:00

Status:	normal
Report creation time:	2018-05-03 13:51
Report number:	13
Days Ahead/Behind (+/-):	1.1
Operator:	Statoil
Rig Name:	MÆRSK INSPIRER
Drilling contractor:	Maersk Drilling
Spud Date:	2014-02-21 14:30
Wellbore type:	
Elevation RKB-MSL (m):	54.9
Water depth MSL (m):	91
Tight well:	Y
HPHT:	Y
Temperature (I):	
Pressure (I):	
Date Well Complete:	2014-03-15

Dist Drilled (m):	-999.99
Penetration rate (m/h):	-999.99
Hole Dia (I):	
Pressure Test Type:	formation integrity test
Formation strength (g/cm3):	1.6
Dia Last Casing (I):	

Depth at Kick Off mMD:	
Depth at Kick Off mTVD:	
Depth mMd:	-999.99
Depth mTVD:	
Plug Back Depth mMD:	3100
Depth at formation strength mMD:	3059
Depth At Formation Strength mTVD:	2874.4
Depth At Last Casing mMD:	4087.1
Depth At Last Casing mTVD:	3178

Summary of activities (24 Hours)

- Perforated below 10 3/4in subsea csg hanger, circulate possible gas, flow checked
- M/U and RIH w/ milling BHA, started milling 10 3/4 subsea csg hanger
- Milled approximately 20 cm. Due to slow progress POOH to inspect mill

Summary of planned activities (24 Hours)

- Finish milling 10 3/4 subsea csg hanger
- M/U and RIH w/ spear
- Pull 10 3/4 x 9 5/8 csg

Operations

Start time	End time	End Depth mMD	Main - Sub Activity	State	Remark
00:00	00:15	0	plug abandon -- perforate	ok	Broke connection, dropped ball, RIH to firing depth. Perforated interval 141m - 147,4m
00:15	00:30	0	plug abandon -- perforate	ok	Closed BOP, lined via fully open choke, pressured up string to 135 bar, observed shear
00:30	01:15	0	plug abandon -- perforate	ok	Circulated via poor boy to check for gas with 250 lpm, 1 bar. Pumped 2.3m3 to get stable returns
01:15	01:45	0	plug abandon -- perforate	ok	Flow check via choke
01:45	02:15	0	plug abandon -- perforate	ok	Opened BOP, lined up and flow checked on trip tank, well static
02:15	02:45	0	plug abandon -- perforate	ok	POOH from 148 m to 16m
02:45	03:15	0	plug abandon -- perforate	ok	Inspected and layed down BHA. All shots fired
03:15	03:30	0	plug abandon -- perforate	ok	Change handling gear back to 5.5 elevators and iron roughneck
03:30	03:45	0	plug abandon -- perforate	ok	R/D perforation handling equipment and cleared rig floor.
03:45	04:00	0	plug abandon -- mill	ok	Pickup milling BHA from cantilever, RIH from surface to 5m
04:00	04:15	0	plug abandon -- mill	ok	Performed Pre-job Meeting for handling milling BHA and rig tongs
04:15	05:15	0	plug abandon -- mill	ok	R/U tongs and M/U magnet to 68knm
05:15	05:30	0	plug abandon -- mill	ok	R/D rig tongs
05:30	07:00	0	plug abandon -- mill	ok	Continued P/U milling BHA
07:00	07:15	0	plug abandon -- mill	ok	M/U TDS and fill pipe
07:15	07:30	0	plug abandon -- mill	ok	Recorded parameters 2000lts/ min 5-7 bar. Up wt. 78T, down wt. 74T without rotation, free rotation torque with 80 rpm, 0-3 KNM, rotating weight 76T. Run in and tagged at 140.86m bit depth
07:30	15:30	0	plug abandon -- mill	ok	Pulled up 1.5m, established parameters and commenced milling, 2000lts/ min 5-7 Bar, 80 RPM, 2-4 KNM, WOB 1.3T. Milled from 141.26m to 141.46m. Picked off btt m and spaced out due to leaking fittings on BOP
15:30	18:00	0	interruption -- repair	ok	Repaired leaking fitting on BOP
18:00	19:00	0	plug abandon -- mill	ok	Lined up and started milling from 141.06m to 141.07m, 2000 lpm, 5 bar, 120 rpm, 5-15 knm
19:00	22:30	0	plug abandon -- mill	ok	Continued milling @100-120RPM, 1-3t WOB, 2000lpm, 3-11KNM, 5-7bar. Stopped due to no progress
22:30	23:45	0	plug abandon -- mill	ok	Attempted to R/B DP stand, no success. Observed connection above saver sub broke when trying to break out stand from TDS
23:45	00:00	0	plug abandon -- mill	ok	R/B stand of DP with saver sub. Broke connection with 150KNM

Equipment Failure Information

Start time	Depth mMD	Depth mTVD	Sub Equip - Syst Class	Operation Downtime (min)	Equipment Repaired	Remark
00:00	811		pipe handling equ syst -- vertical pipe handling equ syst	0	00:00	Tugger wire caught up in FWD PRS causing damages to PRS.
00:00	21		pipe handling equ syst -- elevator	0	00:00	Issues with rotator on elevator
00:00	1393		pipe handling equ syst -- elevator	0	00:00	Elevator not latching properly. Changed elevator.
00:00	2179		drill floor -- draw works	0	00:00	fault on draw works motor 3
00:00	1313		pipe handling equ syst -- other	0	00:00	HTS not feeding pipe correctly. DP was not fed all the way to the elevator.

00:00	144		drillstring downhole -- fishing tools	0	00:00	Two unsuccessful attempts to fish tieback adapter were carried out, did not get fish
-------	-----	--	---------------------------------------	---	-------	--