

Summary report

Wellbore: 15/9-F-1 C

Period: 2016-09-18 00:00 - 2016-09-19 00:00

Status:	normal
Report creation time:	2018-05-03 13:51
Report number:	3
Days Ahead/Behind (+/-):	
Operator:	Statoil
Rig Name:	MÆRSK INSPIRER
Drilling contractor:	Maersk Drilling
Spud Date:	2014-02-21 14:30
Wellbore type:	
Elevation RKB-MSL (m):	54.9
Water depth MSL (m):	91
Tight well:	Y
HPHT:	Y
Temperature (I):	
Pressure (I):	
Date Well Complete:	2014-03-15

Dist Drilled (m):	-999.99
Penetration rate (m/h):	-999.99
Hole Dia (I):	
Pressure Test Type:	formation integrity test
Formation strength (g/cm3):	1.6
Dia Last Casing (I):	

Depth at Kick Off mMD:	
Depth at Kick Off mTVD:	
Depth mMD:	-999.99
Depth mTVD:	
Plug Back Depth mMD:	614
Depth at formation strength mMD:	3059
Depth At Formation Strength mTVD:	2874.4
Depth At Last Casing mMD:	2507.7
Depth At Last Casing mTVD:	2445.8

Summary of activities (24 Hours)

- N/D BOP

CONTINUE REPORTING ON F-11B

Summary of planned activities (24 Hours)

None

Operations

Start time	End time	End Depth mMD	Main - Sub Activity	State	Remark
00:00	00:15	0	plug abandon -- cement plug	ok	Cleaned and cleared rig floor. Meanwhile performed AAR
00:15	00:30	0	plug abandon -- other	ok	Prepared to N/D diverter system. Carried out TBT
00:30	02:00	0	plug abandon -- other	ok	N/D diverter
02:00	02:45	0	plug abandon -- other	ok	Shifted load to BOP carrier. Removed tension cylinders and broke off NT-2 connector
02:45	03:15	0	plug abandon -- other	ok	Lifted BOP. Skidded and landed BOP onto test stump
03:15	03:45	0	plug abandon -- other	ok	Removed scaffolding in moonpool. Meanwhile loosen HP riser on wellhead and prepared for to rig up bleed off manifold.
03:45	04:15	0	plug abandon -- other	ok	Installed lifting gear on HP riser and lifted same to the drill floor
04:15	05:45	0	plug abandon -- other	ok	Removed half moon hatch and installed hatch on F-1. Meanwhile prepared for skidding CONTINUE REPORTING ON F-11B

Equipment Failure Information

Start time	Depth mMD	Depth mTVD	Sub Equip - Syst Class	Operation Downtime (min)	Equipment Repaired	Remark
00:00	550		pipe handling equ syst -- elevator	0	00:00	Opened elevator while not holding with PRS arm which resulted in loose stand of pipe in derrick. Secured stand. Checked upper PRS head. Incident happened due to miscommunication/error of PRS operator giving false information that stand was secured