

Summary report

Wellbore: 15/9-F-4

Period: 2008-02-27 00:00 - 2008-02-28 00:00

Status:	normal
Report creation time:	2018-05-03 13:52
Report number:	52
Days Ahead/Behind (+/-):	6
Operator:	StatoilHydro
Rig Name:	MÆRSK INSPIRER
Drilling contractor:	Mærsk Contractors
Spud Date:	2007-03-10 00:00
Wellbore type:	
Elevation RKB-MSL (m):	54.9
Water depth MSL (m):	91
Tight well:	Y
HPHT:	Y
Temperature (degC):	110.2
Pressure (psig):	4729.4
Date Well Complete:	2008-02-28

Dist Drilled (m):	-999.99
Penetration rate (m/h):	-999.99
Hole Dia (in):	8.5
Pressure Test Type:	formation integrity test
Formation strength (g/cm3):	1.65
Dia Last Casing (i):	

Depth at Kick Off mMD:	
Depth at Kick Off mTVD:	
Depth mMD:	3510
Depth mTVD:	3138.8
Plug Back Depth mMD:	
Depth at formation strength mMD:	2760
Depth At Formation Strength mTVD:	2599
Depth At Last Casing mMD:	2760.5
Depth At Last Casing mTVD:	2598.7

Summary of activities (24 Hours)

POOH with MDT toolstring to 9 5/8" shoe depth at 2750 m MD. Broke out side entry sub. Retrieved WL and checked cable - ok. Circulated bottoms up in shoe to remove gas. POOH from shoe to surface. Broke out and laid down MDT logging toolstring. Changed to 5 1/2" saver sub on TDS. Broke pup and x-overs. Positioned casing running equipment on drillfloor.

Summary of planned activities (24 Hours)

Install HTS roller section. Remove WL sheave in derrick. Drift pipe on setback. Hook up liner running equipment. Run 850 m of 7" liner. Make up liner hanger.

Operations

Start time	End time	End Depth mMD	Main - Sub Activity	State	Remark
00:00	00:45	3417.5	formation evaluation -- log	ok	Performed fluid sampling at 3417,5 m MD. Obtained 2 ea 450 cc samples. Monitored well on trip tank.
00:45	02:45	3412.5	formation evaluation -- log	ok	Pumped 6 m3 slug and allowed active to stabilize. Correlated and took station at 3412,5 m MD.
02:45	04:30	3412.5	formation evaluation -- log	ok	Performed fluid sampling at 3412,5 m MD. Monitored well on trip tank. Observed downhole tool failure. Adequate sample not obtained from this station.
04:30	05:15	3412.5	interruption -- repair	ok	Troubleshoot tool failure. Not able to function probe and pumps indicating problems with high voltage circuit. Checked surface equipment and confirmed ok. Discussed situation. Decided to start pulling out of hole.
05:15	06:00	3244	interruption -- repair	ok	Pulled logging tool free with ~5 MT overpull on block. Got overpull alarm 18 000 lbs on downhole tension. Communication with logging tools ok, but still unable to function high voltage circuit. POOH with 5" DP from 3412,5 m to 3244 m MD. Maintained 2500 lbs pull in wireline while pulling out.
06:00	08:15	2757	interruption -- repair	ok	POOH with 5" DP from 3244 m to 2757 m MD. Hole in good condition - no significant drag observed.
08:15	10:15	2757	interruption -- repair	ok	Removed clamps from side entry sub. Took overpull on wireline and released locomotive from docking head.
10:15	10:45	2755	interruption -- repair	ok	Broke out side entry sub and laid down locomotive.
10:45	11:30	2755	interruption -- repair	ok	Checked locomotive and cable - ok. Cut cable loose from side entry sub.
11:30	13:00	2755	formation evaluation -- log	ok	Circulated bottoms up at 2000 lpm / 82-95 bar SPP. Gas peaked at 6,6% at bottoms up. MW in/out 1,45 sg.
13:00	13:30	2755	formation evaluation -- log	ok	Flow checked well - well static - ok.
13:30	14:00	2755	formation evaluation -- log	ok	Pumped 6 m3 1,62 sg slug and chased to drillfloor. Allowed active to stabilize.
14:00	15:00	2751	formation evaluation -- log	ok	Held toolbox talk. Changed inserts in PS-30 automatic slips. Broke out and laid down 5" pup joint and 4 1/2" IF x 5 1/2" FH x-over.
15:00	15:30	2550	formation evaluation -- log	ok	POOH with MDT toolstring on 5 1/2" DP from 2751 m to 2550 m MD. Got problems with drawwork.
15:30	16:00	2550	interruption -- other	ok	Troubleshoot problems with drawwork.
16:00	20:00	734	formation evaluation -- log	ok	POOH with MDT toolstring on 5 1/2" DP from 2550 m to 734 m MD.
20:00	20:15	734	formation evaluation -- log	ok	Changed handling equipment from 5 1/2" to 5". Broke out and laid down 4 1/2" IF x 5 1/2" FH x-over.
20:15	21:30	41	formation evaluation -- log	ok	POOH with MDT toolstring on 5" DP from 334 m to 41 m MD.
21:30	23:00	0	formation evaluation -- log	ok	Parted and pulled MDT toolstring sections using C-plate and tugger. Found signs of short circuit in bulkhead coupling. Inner rubber packing on quicksilver probe was worn and torn.
23:00	00:00	0	formation evaluation -- log	ok	Cleared and tidied drillfloor. Ran stand of 5" DP to help breaking off 5" saver sub.

Equipment Failure Information

Start time	Depth mMD	Depth mTVD	Sub Equip - Syst Class	Operation Downtime (min)	Equipment Repaired	Remark
00:00	3412.5		service equipment -- electrical logging equipment	0	00:00	Downhole tool failure. Still unknown cause.
00:00	2550		drill floor -- draw works	0	00:00	A problem with the drawwork was detected when pulling out DP on completion of the MDT/TLC job. There was a problem with a valve in the pneumatic booster system for the drawwork controls. The problem was fixed by the mechanic. Downtime 0,5 hrs.

Drilling Fluid

Sample Time	15:00
Sample Point	Active pit

Sample Depth mMD	3510
Fluid Type	OBM-Standard
Fluid Density (g/cm3)	1.45
Funnel Visc (s)	-999.99
Mf ()	
Pm ()	
Pm filtrate ()	
Chloride ()	
Calcium ()	
Magnesium ()	
Ph	
Excess Lime ()	
Solids	
Sand ()	
Water ()	
Oil ()	
Solids ()	
Corrected solids ()	
High gravity solids ()	
Low gravity solids ()	
Viscometer tests	
Plastic visc. (mPa.s)	28
Yield point (Pa)	12
Filtration tests	
Pm filtrate ()	
Filtrate Lthp ()	
Filtrate Hthp ()	
Cake thickn API ()	
Cake thickn HPHT ()	
Test Temp HPHT (degC)	120
Comment	

Pore Pressure

Time	Depth mMD	Depth TVD	Equ Mud Weight (g/cm3)	Reading
00:00	3195		1.28	estimated
00:00	3417.5		1.08	measured

Log Information

Run No	Service Company	Depth Top mMD	Depth Bottom mTVD	Tool	BHST (degC)
3	Schlumberger	3352	3417.5	MDT - GR - ACTS	-999.99