

Summary report

Wellbore: 15/9-F-9 A

Period: 2015-01-30 00:00 - 2015-01-31 00:00

Status:	normal
Report creation time:	2018-05-03 13:53
Report number:	5
Days Ahead/Behind (+/-):	
Operator:	Statoil
Rig Name:	MÆRSK INSPIRER
Drilling contractor:	Maersk Drilling
Spud Date:	2009-06-23 00:00
Wellbore type:	
Elevation RKB-MSL (m):	54.9
Water depth MSL (m):	91
Tight well:	Y
HPHT:	Y
Temperature (I):	
Pressure (I):	
Date Well Complete:	2009-07-08

Dist Drilled (m):	-999.99
Penetration rate (m/h):	-999.99
Hole Dia (I):	
Pressure Test Type:	
Formation strength (g/cm3):	0
Dia Last Casing (I):	

Depth at Kick Off mMD:	
Depth at Kick Off mTVD:	
Depth mMD:	1206
Depth mTVD:	
Plug Back Depth mMD:	
Depth at formation strength mMD:	0
Depth At Formation Strength mTVD:	0
Depth At Last Casing mMD:	1201
Depth At Last Casing mTVD:	1012

Summary of activities (24 Hours)

Attempted to pressure test casing to 34 bar without success. Released Timelock plug and RIH to top of screen hanger with same to drift 9 5/8" liner. Re-set Timelock plug in 9 5/8" liner. Made new attempt to pressure test casing. No good test. Released Timelock plug and POOH with same. M/U and RIH backup Timelock plug to 168 m.

Summary of planned activities (24 Hours)

Nipple down diverter and surface riser. Install tubing bonnet. R/U cement unit to tubing bonnet. Pressure test casing.
Nipple down tubing bonnet. Install surface riser and diverter.

Operations

Start time	End time	End Depth mMD	Main - Sub Activity	State	Remark
00:00	01:15	415	interruption -- repair	ok	Continued troubleshoot loss off pressure. Narrowed causes to a open needle valve on surface wellhead. Closed needle valve.
01:15	01:45	415	interruption -- repair	ok	Lined rig pumps down string and pumped drill water to above diverter packer and closed same.
01:45	02:45	415	drilling -- casing	ok	Lined up cement unit to drill string. Pressured up well to 11 bar reference pressure. Pressured up to 34 bar using 101 litre. Pressure dropped and stabilized at 24 bar. Re-pressurized well to 34 bar using 34 litres 3 times while checking valves, diverter packer and well head for leaks. Pressure dropped and stabilized at 24 bar at every attempt.
02:45	03:00	415	interruption -- repair	ok	Discussed situation with onshore duty. Meanwhile continued to check for possible leaking valves.
03:00	03:30	442	interruption -- other	ok	Opened diverter. Engaged and released Timelock plug.
03:30	03:45	442	interruption -- other	ok	Performed TBT for RIH with Timelock plug as drift using manual slips.
03:45	07:00	935	interruption -- other	ok	RIH with Timelock plug from 442 m to 935 m to drift 9 5/8" liner.
07:00	07:30	935	interruption -- other	ok	Performed TBT with new crew for drifting 9 5/8" liner
07:30	09:15	935	interruption -- other	ok	Lined up manifold and shakers for washing down.
09:15	10:00	940	interruption -- other	ok	Started pumping drill water from rig pumps, 300 lpm. RIH to 938 m. Increased rate to 1100 lpm and washed from 938 m to 940 m.
10:00	10:15	940	interruption -- other	ok	Performed TBT prior to POOH.
10:15	12:30	572	interruption -- other	ok	POOH with Timelock plug from 940 m to 572 m while filling pipe with trip tank pump. Pulled at restricted speed to prevent swabbing.
12:30	14:45	572	interruption -- other	ok	Lined up to perform line test from cement unit against IBOP. Tested same to 500psi, no good test. Troubleshot and re-tested line-up from cement unit. Not able to get good test through standpipe. Performed line test against valve K-1 on kill manifold, good test.
14:45	15:15	572	interruption -- other	ok	Performed TBT for setting Timelock plug. Recorded up/down weights prior to setting plug.
15:15	15:45	602	interruption -- other	ok	Sat Timelock plug at 600 m according to Archer procedures.
15:45	16:00	595	interruption -- other	ok	Closed ball valve and pressured up string to 35 bar to verify same closed. P/U and released RT from plug.
16:00	16:45	595	interruption -- other	ok	R/U side-entry assy and TIW valve. Performed line test with cement unit. Test ok.
16:45	17:30	595	interruption -- other	ok	Filled well with drill water above diverter packer, closed same.
17:30	18:00	595	interruption -- other	ok	Pressure tested casing with drill water from cement unit through side entry in drill string. Pressured up to 10 bar reference pressure using 190 ltr. Pressured up to 24 bar using 65 ltr and held pressure for 5 minutes. Pumped up to 28 bar using 16 ltr and held pressure for 5 min. Continued pressuring up to 32 bar using 16 ltr. Pressure broke off and dropped to 22 bar, pressure stable at 22 bar.
18:00	18:30	595	interruption -- other	ok	Evaluated situation.
18:30	19:15	595	interruption -- other	ok	Bled off 22 bar pressure on casing. R/D side entry assembly. Performed TBT with new crew.
19:15	19:45	602	interruption -- other	ok	Opened diverter packer. Engaged and released Timelock plug according to Archer procedures.
19:45	20:45	425	interruption -- other	ok	POOH with Timelock plug from 602 m to 425 m while filling pipe with trip tank pump. Pulled at restricted speed to prevent swabbing.
20:45	22:45	8	interruption -- other	ok	POOH with Timelock plug from 425 m to 8 m. Pulled at restricted speed to avoid swabbing.
22:45	23:00	0	interruption -- other	ok	L/D primary Timelock plug and inspected same. No damages observed on packer elements.
23:00	23:15	8	interruption -- other	ok	P/U backup Timelock plug.
23:15	00:00	168	interruption -- other	ok	RIH Timelock plug on 5 1/2" DP from 8 m to 168 m. Avg. tripping speed 213 m/hr.