

## **Tray 2 Lifting Message HP 4240, 4250, 4350**

## Problem:

Printer will not lift trays and will continuously display "waiting for tray 2 to lift, without going to appropriate error code:"60.x"

Or

When sent a print job printer will continuously display "processing job"

Fix:

These situations have occurred due to PS 109's (paper width sensor, located under the registration lid toward the right side) sensor flag being obstructed or sensor being defective.

The "normal" situation for this is the printer to display 13.20 paper jam check under toner cartridge.

