FIELD-DRIVEN QUALITY

Weld Map Field Card

Every field the map carries, and the three checks before you leave for the day

Side A

Side A: Pipeline mainline

One line per weld, written at the joint from what is on the pipe, before the coating crew gets there.

FIELD	WHAT GOES HERE	EXAMPLE
Weld number	One number per weld, never reused on the job. Scheme per project spec: prefix + sequence; T series for tie-ins; R1, R2 for repairs	2-0418 · T-07 · 2-0419 R1
Station	Location along the route from the alignment sheet, hundreds of feet. Up-station is the lower number, whichever way the crew is laying	486+40
Joints, up / down	Joint number on each side, read off the pipe. Pups carry their own joint number	2041 / 2042 · 2044 / 2044A
Heats, up / down	Mill heat number on each side, read from the stencil, not from the tally. Read it twice	Y60184 / Y60191
Wall and grade, each side	Different walls or grades across the weld make it a transition weld with its own WPS	0.562 X70 / 0.750 X70
Welders by pass	IDs stenciled on the pipe: root and hot pass, then fill and cap. Each ID on the qualified list, continuity current	31 / 22 · 07 / 09
WPS and date	The procedure this weld was made to, and the day it was completed	WPS-36-01 · 08-25
NDE	Method, film or scan number, result. Repairs keep the weld number: defect, clock, repair welder, re-shoot film, closure	RT 0418-A ACC · R1 0419-B ACC
Coating and holiday	Field joint coating, applicator, jeep voltage and result, lowered-in date	FBE JD 12 kV 0 hol.
Flags	Tie-in, pup up or down, cut-out replacement, void (with reason and film), golden weld, transition	pup down · VOID crack · golden

BEFORE YOU LEAVE FOR THE DAY

- [ ] Counts balance: every joint strung today is welded in, a pup, cut out, or carried over; pieces welded in equal live welds
- [ ] Every weld line is complete: both joints, both heats, welders by pass, WPS, date, station; nothing from memory or the crew sheet
- [ ] Every NDE result received today is on the log by weld number; open items are on tomorrow's list; the inspector signed the day

FIELD-DRIVEN QUALITY

Weld Map Field Card

Every field the map carries, and the three checks before you leave for the day

Side B: Facility and station

The isometric is the map. Shop welds arrive with their record; field welds are yours, and every one lands in a test package.

FIELD	WHAT GOES HERE	EXAMPLE
Weld number	SW for shop welds (from the fab package), FW for field welds, numbered per line or per iso as the project spec says	SW-101-2 · FW-1101-02
Line and iso	Line number and isometric sheet the weld is drawn on. This is the location; there is no station	24"-NG-1101 · ISO 1101-SH1
Side A / side B	Spool number, equipment tag, or field-cut piece on each side of the weld	SP-101 / SP-102 · V-1101-A / FP-01
Heats, each side	From the spool sheet for spool pieces; read off the piece for loose pipe and fittings; owner's record for existing lines, never guessed	P4471 / V8831
Welder and WPS	Usually one welder. Qualified under ASME IX for this process, position, thickness and P-number; continuity current	M-14 · WPS-24-G1
PMI	Positive material identification on alloy pieces and welds where the spec calls for it, result by weld or spool	PMI 08 ACC
PWHT and hardness	Heat treatment chart number and hardness readings when required, filed by weld	PWHT-22 · HB 215
NDE	Method, report or film number, result, repair cycle on the same weld number	RT 04-A REJ · R1 04-B ACC
Test package	Exactly one package per weld. Golden welds made after the test are outside every package, flagged, with RT and UT	TP-04 · golden: none
Not on this map	Flanged joints go on the bolted-joint log (gasket, bolts, torque, sequence). Supports and lugs go on the attachment log	see torque log

BEFORE YOU LEAVE FOR THE DAY

- [ ] Every field weld on the iso has a line and every line points at the iso; each spool package was checked before its first field weld
- [ ] Every weld is in exactly one test package; no package you touched has a weld without accepted NDE or with an open repair
- [ ] Every welder ID matches an ASME IX qualification for the process, position, thickness and material, continuity current; inspector signed