

General Summary



Cameron Home Inspections LLC
226 Martins Creek Rd
Barnardsville, NC 28709
860-961-3359

Customer

Mahlian Carmichael
Steven Carmichael

Address

38 Forest Knoll Dr
Weaverville NC 28787

The following items or discoveries indicate that these systems or components **do not function as intended** or **adversely affects the habitability of the dwelling; or warrants further investigation by a specialist, or requires subsequent observation.** This summary shall not contain recommendations for routine upkeep of a system or component to keep it in proper functioning condition or recommendations to upgrade or enhance the function or efficiency of the home. This Summary is not the entire report. The complete report may include additional information of concern to the customer. It is recommended that the customer read the complete report.

1. ROOFING

1.0 ROOF COVERINGS

REPAIR OR REPLACE



Some of the nail heads on the roof shingles along the ridge caps are exposed and need to be sealed with caulking or roofing tar. Failure to repair may lead to a roof leak. A qualified person should repair as needed.

1.3 ROOF DRAINAGE SYSTEMS

REPAIR OR REPLACE

-  (1) The gutter system is installed incorrectly at the rear of the home in one area and at the chimney chase. There should be a 1 inch gap between the gutter end cap and the siding, and kickout flashing should be installed to divert water away from the siding. Failure to repair may lead to deterioration of siding or water intrusion into the home. A qualified contractor should perform the work.
-  (2) Downspout is missing a buried drainpipe at the rear right corner of the home. Buried drainpipes should carry roof rain water away from the home at least 10 feet. Failure to repair may allow erosion or water penetration into the crawlspace. Repairs are needed by a qualified contractor.
-  (3) The gutter screens are missing next to the chimney and right side (facing front). If gutter screens are not properly in place leaves can contribute to a clog which can cause deterioration of fascia, soffit or roof edge. It can also cause gutters to pull loose and lead to possible water intrusion. A qualified person should repair as needed.

2. EXTERIOR

2.0 WALL CLADDING FLASHING AND TRIM

REPAIR OR REPLACE

-  (1) The wood siding and trim at the chimney chase is deteriorated in several areas. Further deterioration can occur if not corrected. A qualified contractor should inspect and repair as needed.
-  (2) The wood siding and trim at the upstairs front guest bedroom is deteriorated in a couple areas. Further deterioration can occur if not corrected. A qualified contractor should inspect and repair as needed.

2.1 DOORS (EXTERIOR)

INSPECTED

-  The main entry door rubs at jamb when closing. A repair or adjustment is needed. A qualified person should repair as needed.

2.3 DECKS, BALCONIES, STOOPS, STEPS, AREAWAYS, PORCHES, PATIO/ COVER AND APPLICABLE RAILINGS

REPAIR OR REPLACE

-  (1) The stair stingers have nails pulling away from the band joist at the top of the rear deck. Adding joist hangers should ensure stability. A qualified person should perform the work.
-  (2) The stairs under the deck at the rear of the home are missing risers. A fall or injury could occur if not corrected. A qualified contractor should repair as needed.
-  (3) The guardrail on the front porch is slightly damaged (small carpenter bee damage). Further deterioration can occur if not repaired. A qualified person should perform the work.
-  (4) Several of the deck boards on the rear deck are warped and/or raised at the end cuts. Further deterioration can occur if not repaired. A qualified contractor should repair as needed.
-  (5) The deck was built enough below the living room sliding glass door to require a step. A fall or injury may occur if not installed. A qualified contractor should perform the work.

3. GARAGE OR CARPORT

3.2 GARAGE FLOOR

REPAIR OR REPLACE

-  The concrete floor in the garage is cracked in areas. These cracks do not appear significant and seem typical. I recommend adding an approved concrete sealant to these areas to prevent chipping.

3.3 GARAGE DOOR (S)

 REPAIR OR REPLACE

-  The garage door reveals daylight where the weather-stripping is damaged a couple small areas. This can cause water or pest intrusion if not corrected. A qualified person should repair as needed.

4. INTERIORS

4.5 DOORS (REPRESENTATIVE NUMBER)

 REPAIR OR REPLACE

-  The entry door rubs at floor when closing at the laundry room. A repair or adjustment is needed. A qualified person should repair as needed.

4.6 WINDOWS (REPRESENTATIVE NUMBER)

 REPAIR OR REPLACE

-  (1) One window will not stay up without a prop at the upstairs office. Repairs are needed. A qualified contractor should inspect and repair as needed.
-  (2) One window is stuck or painted shut at the laundry room. This is a maintenance issue and is for your information. A qualified person should repair as needed.

6. PLUMBING SYSTEM

6.2 PLUMBING DRAIN, WASTE AND VENT SYSTEMS

 INSPECTED

-  The plumbing waste line drains slowly which may be partially clogged at the downstairs guest bathroom sink on the right. Repairs are needed. A qualified person should repair as necessary.

6.3 PLUMBING WATER SUPPLY AND DISTRIBUTION SYSTEMS AND FIXTURES

 REPAIR OR REPLACE

-  (1) Polybutylene plastic plumbing supply lines (PB) are installed in the basement utility closet above the water heater and under the kitchen sink and some of the bathrooms. Polybutylene has been used in this area for many years, but has had a higher than normal failure rate, and is no longer being widely used. Copper and Brass fittings used in later years (copper used on this house) have apparently reduced the failure rate. Although there were no leaks, a licensed plumber should inspect these areas to determine if any repairs are necessary at this time.
-  (2) The outside water faucet is loose (missing screws), and needs securing to wall at the rear of the home. This is a small repair. A qualified person should repair as necessary.
-  (3) The sink faucet handle on the left is loose (missing screw) at the upstairs bathroom. Repairing this problem now may prevent a future leak. A qualified person should repair as necessary.

7. ELECTRICAL SYSTEM

7.2 SERVICE AND GROUNDING EQUIPMENT, MAIN OVERCURRENT DEVICE, MAIN AND DISTRIBUTION PANELS

 REPAIR OR REPLACE

-  (1) Uncapped conductors are present inside the basement sub panel. All unused conductors inside electrical panels should be capped or removed for safety (live or not). Repairs are needed by a licensed electrician.
-  (2) Screw(s) are missing from the main circuit panel cover. All screws must be present to ensure a proper seal of this panel. This is a fire safety concern.
-  (3) Some labels are present, but some are missing or confusing. I recommend correcting for safety reasons by a licensed electrician.

7.3 BRANCH CIRCUIT CONDUCTORS, OVERCURRENT DEVICES AND COMPATIBILITY OF THEIR AMPERAGE AND VOLTAGE

 INSPECTED

-  There are conductors exposed inside the kitchen island. These conductors are susceptible to damage. All electrical conductors must be concealed behind finished spaces or installed inside of protective conduit. All electrical repairs are hazardous until fixed. I recommend repair by a licensed electrician.

7.4 CONNECTED DEVICES AND FIXTURES (OBSERVED FROM A REPRESENTATIVE NUMBER OPERATION OF CEILING FANS, LIGHTING FIXTURES, SWITCHES AND RECEPTACLES LOCATED INSIDE THE HOUSE, GARAGE, AND ON THE DWELLING'S EXTERIOR WALLS)

 REPAIR OR REPLACE

-  (2) One of the fluorescent light fixtures does not work (try replacing bulb first) at the garage. This is for your information. I recommend repair as needed.
-  (3) The light fixture does not work (try replacing bulb first) at the master bathroom above the tub area. This is for your information. I recommend repair as needed.

7.5 POLARITY AND GROUNDING OF RECEPTACLES WITHIN 6 FEET OF INTERIOR PLUMBING FIXTURES, AND ALL RECEPTACLES IN GARAGE, CARPORT, EXTERIOR WALLS OF INSPECTED STRUCTURE

 REPAIR OR REPLACE

-  (1) One GFCI (Ground Fault Circuit Interrupter) outlet at the rear of the home did not work (possible defective outlet) or there is no power to outlet. Electrical issues are considered a hazard until repaired. I recommend repair as needed.
-  (2) The exterior light fixture does not work (try replacing bulb first) above the basement side entry door. This is for your information. I recommend repair as needed.

7.7 SMOKE DETECTORS

 REPAIR OR REPLACE

-  The smoke detectors are inoperable or old throughout the home. Without working smoke detectors in your home you have no first alert to a possible fire. A qualified person should replace as needed.

7.8 CARBON MONOXIDE DETECTORS

 REPAIR OR REPLACE

-  There is no working carbon monoxide detector found in the home (only one in the basement that was not working when tested). It is recommended that one be installed on each floor according to the manufacturer's instructions.

8. HEATING / CENTRAL AIR CONDITIONING

8.4 DISTRIBUTION SYSTEMS (INCLUDING FANS, PUMPS, DUCTS AND PIPING, WITH SUPPORTS, INSULATION, AIR FILTERS, REGISTERS, RADIATORS, FAN COIL UNITS AND CONVECTORS)

 REPAIR OR REPLACE

-  (2) The condensation pipe for the main HVAC system is not extended to an approved distance from the foundation. This pipe is allowing moisture to reach the foundation wall. Have a qualified contractor extend this pipe to an approved distance.
-  (3) The insulation found on the refrigerant pipe at the outdoor compressor unit (upstairs unit) does not completely cover the pipe. This insulation must remain intact, completely cover the refrigerant pipe and remain undamaged. Have a qualified contractor repair this insulation.
-  (4) The metal fins on the condenser unit (main unit) outside are clogged in areas due to excessive dryer lint blowing on it. This restricts proper air flow when in operation. A licensed HVAC contractor should inspect further and repair as needed.
-  (5) The air handler inside the attic had a drip pan installed under the evaporator but I did not see a sensor installed that would automatically shut the unit off in the case of a leak. Failure to repair would allow damage to surrounding building materials if a leak occurred. The pan is also filled with insulation or other debris which can clog the overflow pan drain in the event of a leak. Repair is needed by a licensed HVAC contractor.
-  (6) The return air filter for the upstairs unit is located at the upstairs hallway ceiling. The filter is dirty and needs replaced. Check this filter for replacement every 90 days. Failure to keep this filter changed can shorten the life span of the HVAC unit.

8.6 CHIMNEYS, FLUES AND VENTS (FOR FIREPLACES, GAS WATER HEATERS OR HEAT SYSTEMS)

REPAIR OR REPLACE

-  The metal liner in chimney for fireplace at the living room has build-up of creosote (can cause chimney fire). If creosote is not cleaned a chimney or house fire could result. A qualified chimney sweep should inspect and repair as needed.

8.8 COOLING AND AIR HANDLER EQUIPMENT

REPAIR OR REPLACE

-  (1) The upstairs HVAC system uses the older style R-22 Freon. Due to it's harmful effects on the environment, R-22 is no longer being manufactured or imported into the U.S. It is advised that repairs and maintenance to the HVAC systems may become increasingly expensive as the available supply of R-22 diminishes. For this reason, a licensed HVAC contractor should inspect further to give replacement options.
-  (2) The HVAC system is very old (original, 31 years old) and may last a few years more, but maybe not. I have seen units fail shortly after a home inspection during the seasonal change from mild to hot weather. I cannot determine how long your HVAC system will last before a replacement is necessary. Due to the age of the system I recommend a licensed HVAC contractor inspect further to determine if this system needs replacement.

9. INSULATION AND VENTILATION

9.3 VENTING SYSTEMS (KITCHENS, BATHS AND LAUNDRY)

REPAIR OR REPLACE

-  The dryer vent piping has excessive lint at the outside vent cover which may indicate either a clogged vent pipe. Vent pipes should be cleaned regularly if they are longer than normal (10 feet or more) or vented vertically. I recommend repair as needed.

Home inspectors are not required to report on the following: Life expectancy of any component or system; The causes of the need for a repair; The methods, materials, and costs of corrections; The suitability of the property for any specialized use; Compliance or non-compliance with codes, ordinances, statutes, regulatory requirements or restrictions; The market value of the property or its marketability; The advisability or inadvisability of purchase of the property; Any component or system that was not observed; The presence or absence of pests such as wood damaging organisms, rodents, or insects; or Cosmetic items, underground items,

or items not permanently installed. Home inspectors are not required to: Offer warranties or guarantees of any kind; Calculate the strength, adequacy, or efficiency of any system or component; Enter any area or perform any procedure that may damage the property or its components or be dangerous to the home inspector or other persons; Operate any system or component that is shut down or otherwise inoperable; Operate any system or component that does not respond to normal operating controls; Disturb insulation, move personal items, panels, furniture, equipment, plant life, soil, snow, ice, or debris that obstructs access or visibility; Determine the presence or absence of any suspected adverse environmental condition or hazardous substance, including but not limited to mold, toxins, carcinogens, noise, contaminants in the building or in soil, water, and air; Determine the effectiveness of any system installed to control or remove suspected hazardous substances; Predict future condition, including but not limited to failure of components; Since this report is provided for the specific benefit of the customer(s), secondary readers of this information should hire a licensed inspector to perform an inspection to meet their specific needs and to obtain current information concerning this property.

Prepared Using HomeGauge <http://www.HomeGauge.com> : Licensed To Patrick Cameron 3720