



Service Engineering Operations
Customer Service Division

Ford Motor Company
PO Box 1904
Dearborn, Michigan 48121

July 25, 2025

TO: All U.S. Ford and Lincoln Dealers

SUBJECT: Customer Satisfaction Program 25P21
Certain 2025 Model Year Super Duty and Escape Vehicles
A/C Compressor Inspection

PROGRAM TERMS

This program will be in effect through July 25, 2026 for vehicles under 10,000 miles.

AFFECTED VEHICLES

Vehicle	Model Year	Assembly Plant	Build Date Range
Super Duty	2025	Kentucky Truck	January 28, 2025 through June 23, 2025
		Ohio Assembly	
Escape		Louisville	January 28, 2025 through March 18, 2025

U.S. population of affected vehicles: 160,271. Affected vehicles are identified in OASIS and FSA VIN Lists.

REASON FOR THIS PROGRAM

Some of the affected vehicles with 10,000 miles or less may experience an internal failure of the Air Conditioning (A/C) compressor that can cause loss of A/C performance or function. Upon loss of A/C performance or function, there may be an audible squeal if the A/C compressor seizes causing the drive belt to slip on the A/C compressor pulley.

SERVICE ACTION

Customer satisfaction P-type programs are to be performed on impacted vehicles already in for other service work (either mobile repair or in dealership). On vehicles with 10,000 miles or less, dealers are to perform an A/C compressor inspection to verify proper A/C compressor operation. If the A/C compressor is verified to not be operating properly, the A/C compressor is to be replaced. This service must be performed on all affected vehicles at no charge to the vehicle owner. For new vehicle storage guidelines, refer to EFC13033, Storage Guidelines for New Vehicles.

ESSENTIAL SPECIAL SERVICE TOOLS

If you do not have the special tools needed, please contact 1-800 ROTUNDA and choose option 3 to place an order to purchase.

OWNER NOTIFICATION MAILING SCHEDULE

Owner letters will not be mailed for this program.

ATTACHMENTS

- Administrative Information
- Labor Allowances and Parts Ordering Information
- Technical Instructions

QUESTIONS & ASSISTANCE

For questions and assistance, contact the Special Service Support Center (SSSC) via the SSSC Web Contact Site. The SSSC Web Contact Site can be accessed through the Professional Technician System (PTS) website using the SSSC link listed at the bottom of the OASIS VIN report screen or listed under the SSSC tab.

Customer Service Division

Customer Satisfaction Program 25P21

MOBILE SERVICE REPAIR ASSESSMENT LEVEL

- All repairs in this program have the following assessment level:
 - Ⓢ - Not a Mobile Service Repair
- Customer satisfaction P-type programs are to be performed on impacted vehicles already in for other service work (either mobile repair or in dealership) and Remote Experience reimbursement for just this repair is not allowed.

OASIS ACTIVATION

OASIS will be activated on July 25, 2025.

FSA VIN LISTS ACTIVATION

FSA VIN Lists will be available through <https://web.fsavinlists.dealerconnection.com> on July 25, 2025.

SOLD VEHICLES

- Correct affected vehicles identified in OASIS which are brought to your dealership within the applicable bumper-to-bumper warranty coverage period.
- Dealers are to prioritize repairs of customer vehicles over repairs of new and used vehicle inventory.

STOCK VEHICLES

- Correct all affected units in your new vehicle inventory before delivery.
- Use OASIS to identify any affected vehicles in your used vehicle inventory.

BRANDED / SALVAGED TITLE VEHICLES

Branded / salvaged title vehicles are eligible for this service action.

OWNER REFUNDS

Refunds are not approved for this program.

RENTAL VEHICLES

Dealers are pre-approved for up to 2 days for a comparable rental vehicle. Follow Customer Loyalty Program (CLP) guidelines for dollar amounts. Rentals will only be reimbursed for the day(s) the vehicle is at the dealership for part replacement. Prior approval for more than 2 rental day(s) is required from the Centralized Loaner Support Team. Contact the Centralized Loaner Support Team via the CRC Dealer Portal for consideration and approval if appropriate.

Customer Satisfaction Program 25P21

REPAIR PHOTO SUBMISSION

Ford has requested photos and evidence prior to performing the repair and of repair completion for this FSA. **For parts ordering and claim reimbursement, please submit photos that clearly show the vehicle VIN and mileage on the same FDRS screenshot; vehicle VIN, external temperature and evaporator temperature on the same FDRS screenshot and pinpoint test results supporting the repair. Also include photos of A/C compressor labels if the A/C compressor is replaced.**

- The SSSC must provide approval prior to performing the repair.
- Contact the SSSC and upload the necessary photo or copy of documentation as an attachment for review and add requested photo list: **FDRS screenshots of the vehicle mileage and VIN, and of the external temperature, evaporator temperature and VIN.** This can be done in two ways:
 - Directly in the SSSC contact request form while submitting your contact on your desktop.
 - Via PTS Mobile under the Images / Files Upload menu selection.
 - You should select SSSC in the sub-menu and ensure your P&A code is correct. Upload the photo(s) by selecting the appropriate FSA with the option to use a prior contact ID. These photo(s) will be associated with your SSSC contact during submission.
 - If you have not submitted a SSSC contact yet, then you can still upload the photo(s) via PTS Mobile, and the photo(s) will be available when opening your SSSC contact for this VIN and recall.
- Photos can be attached using the Mobile PTS “Report a Vehicle Concern”. You can access Mobile PTS using your mobile device at: <https://www.fordtechservice.dealerconnection.com/>.
 - Note:** If you have never used the Web-Based report a vehicle concern- you will need to create your User Profile before accessing “Report a Vehicle Concern” on Mobile PTS. Instructions on how to create a user profile and submit photos can be found in the Global Concern Reporting (GCR) Video Snack on FMCDDealer.
 - Note:** Ensure that your “User Profile” is added/updated to include your STARS ID. This can be done by accessing your User Profile directly at: <https://www.gcr.dealerconnection.com/asp/DealerProfile.asp>
- After completing the report entry form you can upload a maximum of 5 attachments at once.
 - If submitting more than one attachment (photo), the files must be saved to the mobile device you’re using, before submitting the report.
 - If submitting one attachment (photo), you can capture the photo during the report submission when asked to add the attachment.

Customer Satisfaction Program 25P21**ADDITIONAL REPAIR (LABOR TIME AND/OR PARTS)**

Additional repairs identified as necessary to complete the FSA should be managed as follows:

- For related damage and access time requirements, refer to the Warranty and Policy Manual / Section 6 – Ford & Lincoln Program Policies / General Information & Special Circumstances for FSA's / Related Damage.
- **For vehicles within new vehicle bumper-to-bumper warranty coverage, no SSSC approval is required**, although related damage must be on a separate repair line with the "Related Damage" radio button checked.
 - Ford vehicles – 3 years or 36,000 miles
- **For vehicles outside new vehicle bumper-to-bumper warranty coverage:**
 - Submit an Approval Request to the SSSC Web Contact Site before completing the repair.

CLAIMS PREPARATION AND SUBMISSION

- **Technician Competency Requirement:** The STST Competency 10 certification requirement in the U.S. market only will be enforced starting with repair orders opened on or after August 31, 2024. FSA repairs will reject and the claim will not be paid if the repairing technician is not certified in STST Competency 10 FSA. See EFC15936 for more details.
- **Claim Entry:** Enter claims using Dealer Management System (DMS) or One Warranty Solution (OWS) online.
 - When entering claims:
 - Claim type 31: Field Service Action
 - Sub Code: 25P21
 - Customer Concern Code (CCC): C05
 - Condition Code (CC): 42
 - Causal Part Number: 19703, Quantity 0
 - For additional claims preparation and submission information, refer to the Recall and Customer Satisfaction Program (CSP) Repairs in the OWS User Guide.
- **Related Damage/Additional labor and/or parts:** Must be claimed as Related Damage on a separate repair line from the FSA with the same claim type and subcode as described in Claim Entry above.

IMPORTANT: Click the Related Damage Indicator radio button.
- **Rentals:** For rental vehicle claiming, follow Customer Loyalty Program (CLP) guidelines for dollar amounts. Enter the total amount of the rental expense under the Miscellaneous Expense code RENTAL.

Customer Satisfaction Program 25P21

LABOR ALLOWANCES

All Vehicles

Description	Labor Operation	Labor Time
Perform A/C compressor operation test and measure evaporator temperature using FDRS – PASS repair complete	25P21A	1.4 Hours
Perform A/C compressor operation test and measure evaporator temperature using FDRS – FAIL Replace A/C compressor (Use labor operations for compressor replacement below). NOTE: This labor operation will keep the program open if parts are not available and cannot be claimed with 25P21A. NOTE: Refer to vehicle specific labor chart for additional repair labor operations.	25P21B	1.4 Hours
Time allowed to submit photos. If VOR is required and vehicle must be present in dealership to complete repair: 1. FDRS screenshot with VIN and vehicle mileage. 2. FDRS screenshot with VIN, exterior temperature and evaporator temperature. If the vehicle is off road, then refer to EFC14236. VOR escalation is required in DOW.	25P21ZZ	0.2 Hours

Super Duty

NOTE: SSSC approval is required for A/C compressor replacement under this program.

Description	Labor Operation	Labor Time
Replace A/C compressor ONLY – 6.7L	25P21C	2.0 Hours
Flush evaporator, condenser and replace A/C compressor and lines – 6.7L	MT25P21D	M-Time up to 6.4 Hours
Replace A/C system without flush equipment – 6.7L	MT25P21E	M-Time up to 12.1 Hours
Replace A/C compressor ONLY – 6.8L / 7.3L	MT25P21F	1.7 Hours
Flush evaporator, condenser and replace A/C compressor and lines – 6.8L / 7.3L	MT25P21G	M-Time up to 4.5 Hours
Replace A/C system without flush equipment – 6.8L / 7.3L	MT25P21H	M-Time up to 8.2 Hours

Customer Satisfaction Program 25P21

LABOR ALLOWANCES (continued)

Escape

NOTE: SSSC approval is required for A/C compressor replacement under this program.

Description	Labor Operation	Labor Time
Replace A/C compressor ONLY – 1.5L	25P21J	1.6 Hours
Flush evaporator, condenser and replace A/C compressor and lines – 1.5L	MT25P21K	M-Time up to 6.0 Hours
Replace A/C system without flush equipment – 1.5L	MT25P21L	M-Time up to 9.8 Hours

PARTS REQUIREMENTS / ORDERING INFORMATION

Restricted Part Ordering:

Inspection required, see Technical Instructions.

To place an order for an A/C compressor, submit a VIN-specific Part Order contact via the SSSC Web Contact Site.

The VIN-specific part order must provide the following:

1. Attach a photo of vehicle mileage.
2. Attach the FDRS screenshot showing the VIN, exterior temperature and evaporator temperature.
3. If the vehicle is off road, then refer to EFC14236. VOR escalation is required in DOW.

Service Part Number	Claim Quantity	Package Order Quantity	Number in Package	Description
LC3Z-19703-G	1	1	1	A/C Compressor Super Duty 6.7L Diesel
PC3Z-19703-A	1	1	1	A/C Compressor Super Duty 6.8L/7.3L
JX6Z-19703-S	1	1	1	A/C Compressor Escape 1.5L

Dealers will be notified via a DOES II communication if circumstances warrant a change in part supply strategy and when open ordering resumes.

Order the parts below through normal order processing channels:

Inspection required, see Technical Instructions.

Customer Satisfaction Program 25P21

PARTS REQUIREMENTS / ORDERING INFORMATION (continued)

Super Duty – 6.7L Diesel

Service Part Number	Claim Quantity	Package Order Quantity	Number in Package	Description
DS7Z-19B596-A	1	1	1	AC Compressor Seal Kit High Side
DL3Z-19B596-B	1	1	1	AC Compressor Seal Kit Low Side
W716343-S440	1	1	4	Idler Arm Nut - SD Diesel
PC3Z-19849-A	As Needed		1	TXV Valve
FC3Z-19C836-A	As Needed		1	Desiccant Bag
PC3Z-19712-A	As Needed		1	Condenser
PC3Z-19850-A	As Needed		1	Evaporator A
PC3Z-19850-B	As Needed		1	Evaporator B
PC3Z-19850-C	As Needed		1	Evaporator C
PC3Z-19850-D	As Needed		1	Evaporator D
PC3Z-19867-C	As Needed		1	A/C Compressor Inlet Line
PC3Z-19972-A	As Needed		1	A/C Compressor Outlet Line
LC3Z-19E631-AA	As Needed		1	Condenser Inlet Line
PC3Z-19A834-A	As Needed		1	Evaporator Inlet/Outlet Line
W718633-S451	As Needed		4	Seat Bolts
W505275-S451	As Needed		4	Center Seat Bolts
W714409-S439	As Needed		4	Steering Column Shaft Bolt
YN-12-D	As Needed		1	Motorcraft® PAG Refrigerant Compressor Oil
YN-23	As Needed		1	Motorcraft® A/C System Flushing Solvent
D9AZ-6731-A	As Needed		1	FL-1A Filter

To guarantee the shortest delivery time, an emergency order for parts must be placed.

Customer Satisfaction Program 25P21

PARTS REQUIREMENTS / ORDERING INFORMATION (continued)

Super Duty – 6.8L & 7.3L Gas

Service Part Number	Claim Quantity	Package Order Quantity	Number in Package	Description
DS7Z-19B596-A	1	1	1	AC Compressor Seal Kit High Side
DL3Z-19B596-B	1	1	1	AC Compressor Seal Kit Low Side
PC3Z-8620-E	1	1	1	AC Belt - SD Gas
PC3Z-19849-A	As Needed		1	TXV Valve
FC3Z-19C836-A	As Needed		1	Desiccant Bag
PC3Z-19712-B	As Needed		1	Condenser
PC3Z-19850-A	As Needed		1	Evaporator A
PC3Z-19850-B	As Needed		1	Evaporator B
PC3Z-19850-H	As Needed		1	Evaporator C
PC3Z-19850-D	As Needed		1	Evaporator D
LC3Z-19E572-A	As Needed		1	Condenser Seal
HC3Z-19E572-B	As Needed		1	Condenser Seal
PC3Z-19867-B	As Needed		1	A/C Compressor Inlet Line
PC3Z-19972-B	As Needed		1	A/C Compressor Outlet Line
HC3Z-19E631-B	As Needed		1	Condenser Inlet Line
PC3Z-19A834-B	As Needed		1	Evaporator Inlet/Outlet Line
PC3Z-19A834-C	As Needed		1	Evaporator Inlet/Outlet Line
W718633-S451	As Needed		4	Seat Bolts
W505275-S451	As Needed		4	Center Seat Bolts
W714409-S439	As Needed		4	Steering Column Shaft Bolt
YN-12-D	As Needed		1	Motorcraft® PAG Refrigerant Compressor Oil
YN-23	As Needed		1	Motorcraft® A/C System Flushing Solvent
D9AZ-6731-A	As Needed		1	FL-1A Filter

To guarantee the shortest delivery time, an emergency order for parts must be placed.

Customer Satisfaction Program 25P21

PARTS REQUIREMENTS / ORDERING INFORMATION (continued)

Escape – 1.5L

Service Part Number	Claim Quantity	Package Order Quantity	Number in Package	Description
DS7Z-19B596-A	1	1	1	A/C Compressor Seal Kit High Side
HL3Z-19B596-A	1	1	1	A/C Compressor Seal Kit Low Side
JX6Z-19849-A	As Needed		1	TXV Valve
LX6Z-19C836-A	As Needed		1	Desiccant Bag
LX6Z-19712-D	As Needed		1	Condenser
LX6Z-19860-A	As Needed		1	Evaporator
PZ1Z-19D742-D	As Needed		1	A/C Compressor Inlet Line
PZ1Z-19972-A	As Needed		1	A/C Compressor Outlet Line
LX6Z-19A834-BF	As Needed		1	Condenser to TXV Line
LX6Z-19835-D	As Needed		1	Condenser Inlet Line
W718843-S439	As Needed		4	Steering Column Shaft Bolt
W719675-S451	As Needed		4	Seat Bolts
YN-35	As Needed		1	Motorcraft® R-1234yf Refrigerant PAG Oil
YN-23	As Needed		1	Motorcraft® A/C System Flushing Solvent
D9AZ-6731-A	As Needed		1	FL-1A Filter

To guarantee the shortest delivery time, an emergency order for parts must be placed.

DEALER PRICE

For the latest prices, refer to DOES II.

PARTS RETENTION, RETURN, & SCRAPPING

Follow the provisions of the Warranty and Policy Manual, Section 1 - WARRANTY PARTS RETENTION AND RETURN POLICIES. If a replaced part receives a scrap disposition, the part must be scrapped by all applicable local, state, and federal environmental protection and hazardous material regulations. Federal law prohibits selling motor vehicle parts or components that are under safety, compliance, or emissions recall.

EXCESS STOCK RETURN

The excess stock returned for credit must have been purchased from Ford Customer Service Division by Policy Procedure Bulletin 4000.

Customer Satisfaction Program 25P21

REPLACED FSA PARTS INSPECTION AND SIGN OFF

Effective March 1st, 2021 all parts replaced as part of an FSA repair with a repair order open date of March 1st, 2021, or later must be inspected and signed off on the repair order by a member of your dealer fixed operations management team or an employee of the task has been delegated to. If the task is to be delegated to a non-management employee, the employee needs to be someone other than the technician who completed the repair and needs to understand the importance of completing this task consistently and accurately.

- All parts replaced as part of an FSA repair should be returned to the parts department following the Warranty Parts Retention and Return Policies.
- Inspect the replaced parts to verify the FSA repair was completed.
- If the FSA repair is found to be complete, the designated employee signs the repair order line or parts return stamp area (electronic or hand signed) for the FSA repair indicating the parts were inspected and validated to have been replaced.
- After the parts have been inspected, they should be handled based on the guidance in the parts status report in the Online Warranty System (Hold, Return, CORE, Scrap, etc.). Please visit FMCDEALER > PARTS & SERVICE > WARRANTY ADMINISTRATION & WARRANTY PARTS RETURN for the latest Immediate Scrap List information.
- This process is subject to review during warranty audits for FSA repairs with a repair order open date of March 1st, 2021, or later. Any eligible FSA claims requiring parts replacement found not to have been inspected and signed off during a warranty audit will be subject to chargeback and consideration for enrollment into the Dealer Incomplete Recall Repair Process.

Note: Other approvals (electronic or handwritten) for add-on repair lines, dealer-owned vehicle repairs, and repeat repairs do not qualify as FSA parts inspection approvals. The post-repair FSA parts inspection process (electronic or handwritten) is independent of other warranty approval requirements. The approval by the designated employee implies that the FSA parts were found to be replaced and must be able to be identified on the Repair Order. If multiple FSAs require approval on a single Repair Order, each applicable occurrence will require individual post-repair approval by the designated employee.