



IDENTIFICAÇÃO

Cartão: 920

Nome: WP 0336 (ROT)

Tarefa: 70000000054

Duração : 24:00

Bater? N

Concor? N

Tipo: INSPEÇÃO

OM: ALA 4

PN: UH-60L

CFF: 78286

Nomenclatura: AERONAVE, ASA ROTATIVA, H-60 BLACK

Identif: 4 200 200

Type: SPECIAL DETAILED INSPECTION

Categoria:

Publicação: EM 0013

CFF : AL66\$

Seção:

Rev: 2019

Cap: EINSF

CFF:

Nomenclatura:

Posição:

Obs: ESTE CARTÃO POSSUI REQUISITOS MÍNIMOS.

A INSPETORIA PODE ACRESCENTAR TAREFAS QUE JULGAR NECESSÁRIAS NA INSPEÇÃO ESPECIAL ATRAVÉS DAS WPS DO SPECIAL/CONDITIONAL INSPECTIONS DO EM 0013.

Área: 006 - MAIN ROTOR PYLON SECTION**Zona:** 006 - MAIN ROTOR AREA

TEXTO

INSPECTION-ACCEPTANCE AND REJECTION CRITERIA (ROT)

Main Rotor Blades Sudden Stoppage

NOTE

The following inspections are required whenever a blade is damage by striking an object.

1. If damage to blades is less than the accept/reject criteria, repair blades and return to service (WP 0760).
2. Inspect droop stop ears for cracks. If ear is cracked, replace spindle. Tag removed spindle "DAMAGE OCCURRED DUE TO EXCESSIVE BLADE FLAPPING".
3. If damage to blades includes severing blades inboard of tip cap, remove transmission and rotor head assembly and send to overhaul facility. Clearly tag all components "BLADE DAMAGE OCCURRED WHILE ROTOR HEAD IN MOTION". Also explain what the blades hit, if known, and how badly helicopter parts were damaged.
4. If damage to blades is greater than main rotor blade accept/reject criteria (WP 0760) and includes damage to primary structural components (cuff, spacer assembly, and spar assembly), do this:
 - a. Remove blades and spindles and send to overhaul facility. Clearly tag all components "BLADE DAMAGE OCCURRED WHILE ROTOR HEAD IN MOTION". Also explain what the blades hit, if known, and how badly helicopter parts were damaged.
 - b. Inspect elastomeric bearings for damage (WP 0765).
 - c. Inspect blade attachment lugs and damper lugs on spindle for damage. Cracking of paint on lugs is evidence of damage.
 - d. Inspect hub arm ID (4 places) for damage. If evidence of contact is



found, replace hub. Clearly tag hub "DAMAGE OCCURRED DUE TO EXCESSIVE BLADE FLAPPING".

e. Inspect dampers, control horns, pitch control rods, rotating swashplate and swashplate scissors for damage.

f. Inspect airframe attachment points for deformation and damage.

g. Visually inspect input drive shafts, tail drive shafts, oil cooler shaft area, all associated flexible couplings, bearings, and supports for cracks and distortion.

5. If damage to blades is greater than main rotor accept/reject criteria (WP 0760) but damage is limited to pocket skin assembly, trim tab, abrasion strip, and balance block and does not include damage to primary structural components, remove blades and send to approved overhaul facility. Clearly tag all components "BLADE DAMAGE OCCURRED WHILE ROTOR HEAD IN MOTION". Also explain what blades hit, if known, and how badly helicopter parts were damaged.

6. If damage to tip cap is greater than tip cap accept/reject criteria (WP 0760), remove tip cap and inspect adjacent blade structure (tip block, Rosan inserts, tip weights, weight studs, tip rib and skin adjacent tip rib) for damage. Disposition of blade shall be based on repairability of these components.

TAREFA ESPECIFICA AOS SEGUINTE EQUIPAMENTOS

Matrícula SN

Aplicada a todos os equipamentos

TAREFA ESPECIFICA AOS SEGUINTE MODELOS

Sigla Descrição

Aplicada a todos os Modelos

RECURSOS HUMANOS

Especialidade/Subespecialidade	Atividade	H/h	Qtde Recursos	Total
ROT - ROTORES	TÉCNICO	8:00	3	24:00

QUALIFICAÇÕES

Código	Descrição
H60L	CURSO DE MECÂNICA GERAL DO HELICÓPTERO H-60 (BLACKHAWK)

NSPEÇÕES ONDE A TAREFA É UTILIZADA

INSPEÇÃO	DESCRIÇÃO	FASE	DESCRIÇÃO
EP3	INSPEÇÃO ESPECIAL 3 - PARADA BRUSCA	1	FASE ÚNICA

FIM DA TAREFA



IDENTIFICAÇÃO

Cartão: 922

Nome: WP 0336 (ROT)

Tarefa: 70000000056

Duração : 16:00

Bater? N

Concor? N

Tipo: INSPEÇÃO

OM: ALA 4

PN: UH-60L

CFF: 78286

Nomenclatura: AERONAVE, ASA ROTATIVA, H-60 BLACK

Identif: 4 200 200

Type: SPECIAL DETAILED INSPECTION

Categoria:

Publicação: EM 0013

CFF : AL66\$

Seção:

Rev: 2019

Cap: EINSF

CFF:

Nomenclatura:

Posição:

Obs: ESTE CARTÃO POSSUI REQUISITOS MÍNIMOS.

A INSPETORIA PODE ACRESCENTAR TAREFAS QUE JULGAR NECESSÁRIAS NA INSPEÇÃO ESPECIAL ATRAVÉS DAS WPS DO SPECIAL/CONDITIONAL INSPECTIONS DO EM 0013.

Área: 005 - TAIL ROTOR PYLON SECTION**Zona:** 005 - STA 648.0

TEXTO

INSPECTION-ACCEPTANCE AND REJECTION CRITERIA (ROT)

Tail Rotor Blades Sudden Stoppage

NOTE

The following inspections are required whenever a blade is damage by striking an object.

1. If damage to blades is less than tail rotor blade accept/reject criteria (WP 0815) do this:

- a. Inspect all four tail gear box mounting lugs.
- b. Visually inspect intermediate gear box mounting, all drive shaftings, flexible couplings, drive shaft bearings, oil cooler axial fan, and drive shaft supports for cracks and distortion.
- c. Perform oil cooler spline wear inspection.
- d. Repair tail rotor blade (WP 0815).

2. If damage to blades is greater than tail rotor blade accept/reject criteria (WP 0815) and includes amage to spar and/or severing blade inboard of tip weights, dents or gouges in leading edge over 1/4-inch deep in either polyurethane or nickel abrasion strips, or damage to attachment block, do this:

- a. Remove pitch beam, pitch change links, blades, retention plates, tail gear box, intermediate gear box, oil cooler axial fan, and all tail drive shaft assemblies from helicopter and send with all attaching hardware to overhaul facility for detail inspection and overhaul. Clearly tag all components "DAMAGE OCCURRED WHILE TAIL ROTOR IN MOTION". Also explain what the blades hit, if known, and how badly the helicopter parts were damaged.
- b. Visually inspect tail pylon for possible structural damage such as



loose rivets, cracks, etc. Inspect gear box attachment points for deformation and other signs of damage.

3. If damage to blades is greater than tail rotor blade accept/reject criteria (WP 0815) but is limited to damage to tip weights or tip block studs, and/or skin and honeycomb in Region A, Region B, or Region C, do this:

- a. Inspect all four tail gear box mounting lugs.
- b. Visually inspect intermediate gear box mounting, all drive shafting flexible couplings, drive shaft bearings, oil cooler axial fan, and drive shaft supports for cracks and distortion.
- c. Perform oil cooler spline wear inspection.
- d. Remove blades from helicopter and send to overhaul facility. Clearly tag all components "DAMAGE OCCURRED WHILE TAIL ROTOR IN MOTION". Also explain what blades hit, if known, and how badly helicopter parts were damaged.

TAREFA ESPECIFICA AOS SEGUINTE EQUIPAMENTOS

Matrícula SN

Aplicada a todos os equipamentos

TAREFA ESPECIFICA AOS SEGUINTE MODELOS

Sigla Descrição

Aplicada a todos os Modelos

RECURSOS HUMANOS

Especialidade/Subespecialidade	Atividade	H/h	Qtde Recursos	Total
ROT - ROTORES	TÉCNICO	8:00	2	16:00

QUALIFICAÇÕES

Código	Descrição
H60L	CURSO DE MECÂNICA GERAL DO HELICÓPTERO H-60 (BLACKHAWK)

INSPEÇÕES ONDE A TAREFA É UTILIZADA

INSPEÇÃO	DESCRIÇÃO	FASE	DESCRIÇÃO
EP3	INSPEÇÃO ESPECIAL 3 - PARADA BRUSCA	1	FASE ÚNICA

FIM DA TAREFA