

SAMPLE EDITION — ABB + HOSHIZAKI SECTIONS ONLY. THE FULL EDITION COVERS 17 BRANDS AND 869 CODE ENTRIES:
[HTTPS://ERRORCODEFIXES.COM/FIELD-REFERENCE/](https://errorcodefixes.com/field-reference/)

INDUSTRIAL FAULT-CODE FIELD REFERENCE

SAMPLE EDITION

The offline fault-code reference for industrial and facilities technicians: 2 brand sections of code tables, meanings, first checks, and when-to-call-a-pro flags — compiled from the published, source-checked diagnostic guides at errorcodefixes.com.

2 BRAND SECTIONS	180 CODE ENTRIES	45 SOURCE GUIDES	Jun 2026 CONTENT UPDATED
----------------------------	----------------------------	----------------------------	------------------------------------

How to use it: keep this file on your phone or print it into the shop binder. Each brand section opens with its code tables, then condensed per-code field notes. Every table and entry cites the full step-by-step guide on errorcodefixes.com for when you are back on the network.

Independence: errorcodefixes.com is an independent reference. It is not affiliated with or endorsed by any equipment manufacturer named in this document, and it does not sell parts or repair services. Brand names are used for identification only.

Safety: industrial equipment can injure or kill. Follow your site's lockout/tagout procedure and the manufacturer's service documentation. Entries flagged PRO SERVICE involve work that should be left to qualified technicians.

CONTENTS

VFDS & INDUSTRIAL DRIVES

§	BRAND SECTION	CODES
01	ABB Drives (ACS / ACH)	141

ICE MACHINES & REFRIGERATION

§	BRAND SECTION	CODES
02	Hoshizaki Ice Machines	39

01 ABB DRIVES (ACS / ACH)

VFDS & INDUSTRIAL DRIVES

141 code entries · 28 source guides · Series: ABB ACS150 Micro Drive · ABB ACS550 Complete · ABB ACS580 · ABB ACS880 Complete · ABB ACS880 · ABB VFD · Baldor/ABB VS1 VFD · ABB ACH580 HVAC VFD · ...

ABB ACS150 Micro Drive — ABB ACS150 Common Fault Code Reference

FAULT CODE	MEANING
0001	Overcurrent
0002	DC overvoltage
0003	DC undervoltage
0004	Short circuit
0005	Overtemperature
0006	Output phase loss
0007	Motor stall
0008	Motor overload
0009	Panel communication fault
0010	AI1 analog input loss
0012	External fault
0016	Earth fault
0018	Internal control fault

Full diagnostics: <https://errorcodefixes.com/posts/abb-ac150-fault-codes/>

ABB ACS550 Complete — ABB ACS550 Alarm Codes (Axxx)

ALARM	MEANING
A2010	Overcurrent warning
A2011	DC bus overvoltage warning
A2013	Device temperature warning (heatsink)
A2023	Earth fault warning
A5010	AI1 signal lost (warning)
A5030	Panel communication lost (warning)
A8110	Motor overload warning

Full diagnostics: <https://errorcodefixes.com/posts/abb-ac550-complete-guide/>

ABB ACS550 Complete — ABB ACS550 Fault Codes (Fxxx)

FAULT	MEANING
F0001	Overcurrent — motor phase current too high
F0002	DC overvoltage — DC bus voltage too high
F0003	Device temperature — heatsink overtemperature
F0005	DC undervoltage — supply voltage too low
F0006	DC link fault
F0007	AI1 loss — analog input 1 signal lost
F0009	Underload — motor drawing less current than expected
F0010	Panel loss — control panel communication lost
F0013	Ext fault 1 — external fault input active
F0021	IGBT fault — drive output bridge fault
F0023	Earth fault (ground fault) — motor phase to ground
F0029	Motor phase loss — one output phase missing
F0030	Motor stall — motor drawing high current at low speed

FAULT	MEANING
F0035	Safe torque off (STO) — safety input activated
F0041	Thermistor fault — motor thermistor overtemp
F0065	Motor speed feedback fault
F0070	Fieldbus communication fault
F0121	Motor overload (I _{2t}) — thermal model overload
F0130	Control board fault

Full diagnostics: <https://errorcodefixes.com/posts/abb-ac550-complete-guide/>

ABB ACS580

FAULT CODE	NAME	SHORT DESCRIPTION
2310	Output overcurrent	Output current exceeded 200% of drive rated current
2330	Earth fault	Ground fault detected on motor or output cable
3130	Input phase loss	One of the three input phases is missing or severely unbalanced
3210	DC link overvoltage	DC bus exceeded maximum (usually 800–900 VDC for 480V drives)
3220	DC link undervoltage	DC bus below minimum operating level
4110	Heatsink overtemperature	Heatsink exceeded maximum temperature (typically 115°C)
4290	Overtemperature (internal)	Ambient or internal drive temperature exceeded limit
5010	DC overvoltage	DC link overvoltage (alternative/legacy code)
6310	Panel loss	Control panel communication lost (ACS-AP-I disconnected or cable broken)
7121	Fan feedback fault	Internal cooling fan failed or fan feedback signal lost
7510	Communication fault	Fieldbus communication loss (EtherNet/IP, PROFIBUS, etc.)
9300	External fault 1	Digital input programmed as external fault was activated
9301	External fault 2	Second external fault input activated
FA81	Safe Torque Off (STO)	STO function activated — safety circuit opened

Full diagnostics: <https://errorcodefixes.com/posts/abb-ac580-fault-codes/>

ABB ACS880 Complete — ABB ACS880 Alarm Codes (Warnings)

ALARM	MEANING
A2310	Overcurrent warning
A3130	Input phase loss warning
A3210	DC overvoltage warning
A4110	Drive temperature warning
A7011	Motor thermal overload warning
A9300	External fault warning

Full diagnostics: <https://errorcodefixes.com/posts/abb-ac880-complete-guide/>

ABB ACS880 Complete — ABB ACS880 Common Fault Codes

FAULT	MEANING
2310	Overcurrent — motor current exceeded limit
2321	Earth fault (ground fault)
2330	Short circuit — output phase-to-phase short
3130	Input phase loss — one input phase missing
3210	DC overvoltage
3220	DC undervoltage
4110	Control board temperature too high
5010	Fan fault — cooling fan failed
5090	Motor connection or cable fault
6100	FPGA fault — drive logic fault

FAULT	MEANING
6310	Fieldbus communication fault
7010	Motor stall
7011	Motor overload (thermal model)
7012	Motor underload
9300	External fault (via digital input or fieldbus)
FA81	Safe Torque Off (STO) active

Full diagnostics: <https://errorcodefixes.com/posts/abb-ac880-complete-guide/>

ABB ACS880 — More ABB 880 fault codes

CODE	WHAT IT MEANS	LIKELY CAUSE	HOW TO FIX
3220	DC link undervoltage	Intermediate (DC bus) voltage too low, usually from a missing supply phase, blown input fuse, low line voltage, or a fault in the rectifier bridge.	Check the incoming supply voltage on all three phases, inspect input fuses and the main contactor, and verify supply cabling. Correct any missing phase or low-voltage condition before restarting.
3130	Input phase loss	One of the incoming supply phases is missing, or the DC bus voltage is rippling because of an open phase, blown fuse, or loose supply connection.	Measure all three input phases at the drive terminals, check input fuses and disconnect contacts, and tighten supply-side terminations. Restore the missing phase before resetting.
3381	Output phase loss	The drive detects that a motor output phase (U, V or W) is missing, typically an open motor cable conductor, loose output terminal, or an open motor winding.	Power down and lock out, then check continuity of each output phase from the drive to the motor and inspect the motor windings. Repair the open conductor or connection.
2381	IGBT overload	Excessive IGBT junction-to-case temperature. Protects the output IGBTs and can be triggered by a short circuit in the motor cable, excessive load, or too high a switching frequency for the load.	Check the motor cable and motor for shorts with a megohmmeter, reduce load or acceleration demand, and verify cooling. Confirm switching frequency and drive sizing match the application.
4210	IGBT overtemperature	Estimated IGBT temperature is excessive, usually from blocked cooling airflow, a failed cooling fan, high ambient temperature, or sustained overload.	Clean or replace air filters, verify all cooling fans spin freely, clear dust from the heatsink, and confirm the ambient temperature is within the drive rating. Reduce load if the drive is undersized.
5091	Safe torque off	The Safe Torque Off function is active because a safety-circuit signal on connector XSTO is broken during start or run, or the drive is stopped with STO diagnostics set to Fault.	Check the STO wiring and both XSTO channels, verify the safety relay/E-stop chain is closed, and confirm parameter 31.22 STO diagnostics configuration. Restore the safety circuit before resetting.
5090	STO hardware failure	The Safe Torque Off hardware self-diagnostic has detected an internal fault in the STO circuitry.	Cycle power to clear a transient. If it persists, the STO hardware or control unit needs service. Contact ABB or a certified drive technician; do not bypass STO.
7081	Panel port communication (control panel / keypad communication lost)	The control panel (keypad) or PC tool selected as the active control location has stopped communicating with the drive over the panel port.	Reseat the control panel and its cable, check the panel connector, and confirm the panel/PC tool communication settings. Replace a damaged panel cable if needed.
7310	Overspeed	Motor speed has exceeded the allowed limit, often because of an overhauling/high-inertia load, wrong speed-limit parameters, or an encoder/feedback problem.	Check the speed limit parameters, verify encoder feedback and scaling, and confirm the load is not driving the motor faster than commanded. Add a braking resistor for overhauling loads if required.
7510	FBA A communication	Cyclic communication is lost between the drive and a fieldbus adapter module (FBA A), from adapter cabling, configuration, or master faults.	Check the fieldbus adapter connection and network cabling, verify the adapter configuration and the comm-loss action parameters, and confirm the PLC/master is communicating.
FA81	Safe torque off 1	Loss of the Safe Torque Off channel 1 signal at the STO input.	Inspect the STO channel 1 wiring and the safety device driving it (E-stop, safety relay, gate), and restore the signal. Both STO channels must be healthy to run.

Full diagnostics: <https://errorcodefixes.com/posts/abb-880-fault-codes/>

ABB VFD

FAULT CODE	MEANING	COMMON FIX
0001	Overcurrent	Check motor/cable; reduce accel ramp

FAULT CODE	MEANING	COMMON FIX
2201	Overcurrent (short circuit)	Motor winding short or cable fault
2310	Overcurrent (peak)	Check for mechanical jam
3130	Input phase loss	Check all 3 input phases
3210	DC bus overvoltage	Extend decel ramp; add brake resistor
3300	DC bus undervoltage	Check input power supply
4110	Drive overtemperature	Clean cooling fan; check ambient temp
5010	Overload	Reduce continuous load; check motor FLA
7121	Analog I/O fault	Check signal wiring
9300	Communication fault	Check fieldbus adapter or wiring
AF10	Heatsink overtemperature	Clean fan; check airflow

Full diagnostics: <https://errorcodefixes.com/posts/abb-vfd-fault-codes/>

ABB VFD — More ABB VFD fault codes

CODE	WHAT IT MEANS	LIKELY CAUSE	HOW TO FIX
2340	Short circuit in the motor cable(s) or motor.	Cabling error or a shorted winding/cable between output phases.	Check motor and motor cable for wiring errors. Confirm no PFC capacitors or surge absorbers are in the motor cable, then cycle power to the drive.
2381	IGBT overload. Excessive IGBT junction-to-case temperature.	Protects the IGBTs; can be triggered by a short circuit in the motor cable or by an undersized drive for the motor.	Check the motor cable, ambient conditions, airflow and fan operation, heatsink fins for dust, and drive power rating against motor power.
3181	Wiring or earth fault. Incorrect input-power and motor-cable connection.	Input power cable is connected to the drive's motor (output) terminals, or a similar wiring error.	Check input power connections and confirm supply is landed on the input terminals and the motor on the output terminals. This fault is programmable via par 31.23.
3220	DC link undervoltage. Intermediate-circuit DC voltage is insufficient.	Missing supply phase, blown fuse, or a fault in the rectifier bridge.	Check supply cabling, fuses and switchgear. Measure incoming voltage under load.
3381	Output phase loss. Motor-circuit fault from a missing motor connection.	All three motor phases are not connected (open output phase, loose lug, or open contactor on the motor side).	Connect/verify the motor cable on all three output phases. Programmable via par 31.19 Motor phase loss.
4210	IGBT overtemperature. Estimated drive IGBT temperature is excessive.	Poor cooling, high ambient, clogged heatsink, failed fan, or drive undersized for the motor.	Check ambient conditions, airflow and fan operation, clear dust from heatsink fins, and verify drive power rating versus motor power.
4290	Cooling. Drive module temperature is excessive.	Ambient above the derating threshold, blocked cooling airflow, dust in the heatsink, or a failing fan.	Verify ambient temperature and derating, check module cooling airflow and fan operation, and clean the cabinet interior and heatsink.
5090	STO hardware failure. STO hardware diagnostics detected a hardware failure.	Internal Safe Torque Off hardware fault.	Contact ABB for hardware replacement. Do not attempt to defeat or bypass the STO circuit.
5091	Safe torque off. The STO function is active because a safety-circuit signal to the STO connector opened during start or run.	STO circuit input(s) broken/opened (e-stop, safety relay, gate, or wiring), or control-board supply issue.	Check safety-circuit connections to the STO terminals and verify par 95.04 Control board supply. Programmable via par 31.22 STO indication run/stop.
6681	EFB comm loss. Communication break on the embedded fieldbus (EFB).	Fieldbus master offline or in error, or a broken RS-485 connection.	Check the fieldbus master status and the cable connections to the EIA-485/X5 terminals 29, 30 and 31 on the control unit. Programmable via par 58.14.
7081	Control panel loss. The control panel or PC tool set as active control location stopped communicating.	Disconnected or faulty control panel, loose panel connector, or lost PC-tool link.	Check the PC-tool/control-panel connection and connector; disconnect and reconnect the panel. Action is programmable via par 49.05.
7181	Brake resistor broken or not connected.	Missing, damaged, or incorrectly dimensioned dynamic braking resistor.	Confirm a brake resistor is connected, check its condition, and verify it is correctly sized for the drive.
7310	Overspeed. Motor is turning faster than the highest allowed speed.	Incorrectly set min/max speed, insufficient braking torque, or load changes when using torque reference.	Check min/max speed settings (par 30.11/30.12), motor braking torque, and whether a brake chopper/resistor is needed.

CODE	WHAT IT MEANS	LIKELY CAUSE	HOW TO FIX
7510	FBA A communication. Cyclic communication between the drive and fieldbus adapter module A (or PLC to adapter) is lost.	Fieldbus adapter or cabling fault, master offline, or mis-set fieldbus parameters.	Check fieldbus status and cabling, verify the master is communicating, and review parameter groups 50-53. Programmable via par 50.02.
80A0	AI supervision. An analog input signal is outside its configured limits.	Broken or shorted analog signal wiring, or a transmitter out of range (aux codes identify AI1/AI2 under-min or over-max).	Check the analog input signal level and wiring, and review the min/max limits in parameter group 12. Programmable via par 12.03.
FA81	Safe torque off 1. STO circuit 1 is broken.	One STO channel input is open (e-stop, safety relay, or wiring on channel 1).	Check STO safety-circuit connections and verify par 95.04 Control board supply.
FA82	Safe torque off 2. STO circuit 2 is broken.	The second STO channel input is open (e-stop, safety relay, or wiring on channel 2).	Check STO safety-circuit connections and verify par 95.04 Control board supply.
FF61	ID run. The motor identification run did not complete successfully.	Incorrect motor nameplate data, an external control system connected during ID run, a locked motor shaft, or limits blocking completion.	Verify motor data in group 99, disconnect any external control, ensure the shaft is free, restore defaults, and rerun the ID run.

Full diagnostics: <https://errorcodefixes.com/posts/abb-vfd-fault-codes/>

Baldor/ABB VS1 VFD

FAULT CODE	MEANING	COMMON CAUSE	QUICK FIX
F0001	Overcurrent	Load too high; short circuit	Check motor wiring; reduce acceleration
F0002	DC Bus Overvoltage	Regen energy; high input voltage	Check input voltage; add braking resistor
F0003	DC Bus Undervoltage	Low input voltage; power dip	Check input voltage; check fuses
F0004	Drive overtemperature	Blocked cooling; ambient too hot	Clean heatsink; improve ventilation
F0005	Motor overtemperature	Motor overloaded; PTC fault	Check motor load; check PTC wiring
F0006	Emergency stop	External E-stop input activated	Check E-stop circuit; reset
F0007	Control board fault	Internal hardware fault	Power cycle; replace if persists
F0009	Underload fault	Load dropped below threshold	Check for broken belt or coupling
F0011	External fault	Digital input configured for external fault	Check external fault input wiring
F0013	Analog input loss	4–20mA signal lost	Check signal source; check wiring
F0014	Motor stall	Motor not turning at commanded speed	Check motor and mechanical load
F0016	Earth fault (ground fault)	Winding-to-ground insulation fault	Test motor insulation; check wiring
F0017	Motor phase loss	Missing motor output phase	Check U, V, W output wiring
F0022	Parameter CRC fault	Parameter checksum error	Reload parameters from backup
F0025	Input phase loss	Missing input phase	Check L1, L2, L3 input connections

Full diagnostics: <https://errorcodefixes.com/posts/baldor-vfd-fault-codes/>

FIELD DIAGNOSTICS — CODE BY CODE



ABB ACH580 HVAC VFD Fault Codes

ABB ACH580 drives use numeric fault families to flag power, motor, temperature, fieldbus, and configuration problems in HVAC applications.

Full guide: <https://errorcodefixes.com/posts/abb-ach580-fault-codes/>



ABB ACS550 AI1 LOSS

ABB ACS550 AI1 LOSS means analog input 1 has fallen below the configured minimum or the signal is lost.

MOST LIKELY No analog signal source or source is powered off

Full guide: <https://errorcodefixes.com/posts/abb-ac550-ai1-loss-fault-code/>

F0001 ABB ACS550 F0001 Fault

What ABB ACS550 F0001 overcurrent fault means, why it trips, and how to diagnose and fix it step by step.

MOST LIKELY Motor or cable short circuit

Full guide: <https://errorcodefixes.com/posts/abb-ac550-f0001-overcurrent/>

2310 ABB ACS580 Fault 2310

ABB ACS580 fault 2310 (Overcurrent) means the drive's output current exceeded the internal hardware overcurrent trip point — typically about 3.5× the...

Full guide: <https://errorcodefixes.com/posts/abb-ac580-2310-fault/>

3210 ABB ACS580 Fault 3210

ABB ACS580 fault 3210 DC Link Overvoltage means the intermediate DC bus exceeded 820 VDC on a 380–480V drive (or 1100 VDC on a 525–690V drive) and the...

Full guide: <https://errorcodefixes.com/posts/abb-ac580-fault-3210/>

3220 ABB ACS580 Fault 3220

ABB ACS580 fault 3220 DC Link Undervoltage means the intermediate DC bus dropped below approximately 320 VDC on a 380–480V drive (185 VDC on a 200–240V...

Full guide: <https://errorcodefixes.com/posts/abb-ac580-fault-3220/>

A0 ABB ACS580 A0 Fault Code

ABB ACS580 A0 is likely a misread of A5A0 or 5091, meaning Safe Torque Off is active.

MOST LIKELY Open or missing STO jumper

Full guide: <https://errorcodefixes.com/posts/abb-ac580-a0-fault-code/>

A2B3 ABB ACS580 A2B3 Fault

A2B3 means earth leakage detected.

MOST LIKELY Motor insulation breakdown to ground

Full guide: <https://errorcodefixes.com/posts/abb-ac580-vfd-a2b3-fault-code/>

A3A2 ABB ACS580 A3A2 Fault

PRO SERVICE

A3A2 means DC link undervoltage: the drive's internal DC bus is too low.

MOST LIKELY Blown input fuse or missing supply phase

- CHECK FIRST**
1. Measure AC voltage at L1, L2, and L3 input terminals with a multimeter to confirm all three phases are present and within 10% of the drive's rated voltage
 2. Check parameter 95.01 (Supply voltage) on the drive's control panel and verify it matches the actual measured incoming voltage
 3. Inspect input terminal connections for loose or corroded wiring

Full guide: <https://errorcodefixes.com/posts/abb-ac580-vfd-a3a2-fault-code/>

A7CE ABB ACS580 A7CE Fault Code

ABB ACS580 A7CE means embedded fieldbus (EFB) communication loss.

MOST LIKELY Fieldbus master offline or in error

Full guide: <https://errorcodefixes.com/posts/abb-ac580-a7ce-fault-code/>

FA81 ABB ACS580 FA81 Fault — Safe Torque Off 1 Active

FA81 on ABB ACS580 means STO circuit 1 is open.

MOST LIKELY Open or disconnected STO wiring

Full guide: <https://errorcodefixes.com/posts/abb-ac580-fa81-fault-code/>

2310 ABB ACS880 Fault 2310

Diagnose and fix the ABB ACS880 fault 2310 overcurrent fault.

Full guide: <https://errorcodefixes.com/posts/abb-ac880-fault-2310/>

ABB ACS880 — What Does ACS880 Fault 2310 Mean?

FAULT	MEANING
2310	Overcurrent (instantaneous trip)
2330	Earth (ground) fault
2340	Short circuit
2350	Overcurrent (thermal overload)
3210	DC overvoltage
3220	DC undervoltage

Full diagnostics: <https://errorcodefixes.com/posts/abb-ac880-fault-2310/>

- ABB ACS880 Drive Maintenance Guide**

Complete ABB ACS880 drive maintenance guide covering fan replacement intervals, capacitor reforming, IGBT checks, cooling system cleaning, firmware updates, and how to prevent common faults 4110, 4210, and 2310.

Full guide: <https://errorcodefixes.com/posts/abb-ac880-complete-maintenance-guide/>

0001 ABB VFD Fault 0001 Overcurrent

What ABB VFD fault 0001 means, why it happens, and how to fix it step by step.

MOST LIKELY Mechanical jam or overload

Full guide: <https://errorcodefixes.com/posts/abb-vfd-fault-0001-overcurrent/>

2201 ABB VFD Fault 2201

ABB VFD fault 2201 means overcurrent during acceleration on ACS550, ACS310, and ACS355 drives — here's how to diagnose and fix it.

Full guide: <https://errorcodefixes.com/posts/abb-vfd-fault-2201-overcurrent/>

2310 ABB VFD Fault 2310

What ABB VFD fault 2310 means, why it happens, and how to fix it step by step.

MOST LIKELY Motor winding insulation failure

Full guide: <https://errorcodefixes.com/posts/abb-vfd-fault-2310/>

3210 ABB VFD Fault 3210

What ABB VFD fault 3210 means, why it happens, and how to fix it step by step.

MOST LIKELY Input power sag or interruption

Full guide: <https://errorcodefixes.com/posts/abb-vfd-fault-3210/>

3300 ABB VFD Fault 3300

What ABB VFD fault code 3300 means, why earth leakage trips the drive, and how to fix it.

MOST LIKELY Degraded motor winding insulation

Full guide: <https://errorcodefixes.com/posts/abb-vfd-fault-3300/>

5010 ABB VFD Fault 5010

What ABB VFD fault 5010 means, why Safe Torque Off activates, and how to fix it.

MOST LIKELY Safety relay or safety PLC opened the STO circuit

Full guide: <https://errorcodefixes.com/posts/abb-vfd-fault-5010/>

7121 ABB VFD Fault 7121

What ABB VFD fault 7121 means, why it happens, and how to fix it step by step.

MOST LIKELY Mechanical overload or jam

Full guide: <https://errorcodefixes.com/posts/abb-vfd-fault-7121/>

02 HOSHIZAKI ICE MACHINES

ICE MACHINES & REFRIGERATION

39 code entries · 17 source guides · Series: Hoshizaki DKM · Hoshizaki F · Hoshizaki KM · Hoshizaki C · Hoshizaki E1 · Hoshizaki E7 · Hoshizaki F1 · Hoshizaki F2 · ...

Hoshizaki DKM — Hoshizaki DKM-500 Error Code Reference

CODE	FAULT
E1	Freeze cycle time exceeded — over-time
E2	High-pressure cutout
E3	Low-pressure cutout / loss of charge
E4	Evaporator temperature sensor fault
E5	Water inlet temperature sensor fault
E6	Control board communication fault
E7	Dispenser mechanism fault
E8	Water supply fault
E9	Float switch fault — water level
F1	Condenser fan motor fault
F2	Hot gas valve fault
F3	Harvest assist motor fault (dispenser)

Full diagnostics: <https://errorcodefixes.com/posts/hoshizaki-dkm-500-error-codes/>

Hoshizaki F — Hoshizaki F-450 Error Code Reference

CODE	FAULT
E1	Freeze cycle time exceeded — evaporator temperature not reached
E2	High-pressure cutout — HP switch trip
E3	Low-pressure cutout — LP switch or loss of charge
E4	Evaporator temperature sensor fault
E5	Inlet water sensor fault
E6	Outlet water sensor fault (where equipped)
E7	Gearmotor overcurrent — auger drive overload
E8	Water supply fault — insufficient water flow
E9	Control board communication fault
F1	Fan motor fault
F2	Refrigerant system high discharge temp

Full diagnostics: <https://errorcodefixes.com/posts/hoshizaki-f450-error-codes/>

Hoshizaki KM — Hoshizaki KM-330 Error Codes — What They Mean

CODE	MEANING	URGENCY
E1	Ice making cycle too long	Medium
E2	Harvest cycle too long	High
E3	Harvest assist fault	High
E5	High evaporator temperature	Medium
E9	Compressor/refrigeration fault	High
F1	Drain pump fault	Medium
F2	Ice full sensor fault	Low

Full diagnostics: <https://errorcodefixes.com/posts/hoshizaki-km-330-error-codes/>

Hoshizaki KM — Hoshizaki KM-515 Error Codes — What They Mean

CODE	MEANING	URGENCY
E1	Ice making cycle too long	Medium
E2	Harvest cycle too long	High
E3	Harvest assist fault	High
E5	High evaporator temperature	Medium
E9	Compressor/refrigeration fault	High
F1	Drain pump fault	Medium
F2	Ice full sensor fault	Low

Full diagnostics: <https://errorcodefixes.com/posts/hoshizaki-km-515-error-codes/>

Hoshizaki KM — Quick-Reference Error Code Table

CODE	FAULT	PRIORITY
E1	Ice thickness sensor	Medium , clean probe first
E2	Float switch / water level	Medium , clean float assembly
E3	High refrigerant pressure	High , coil/fan issue
E4	Low refrigerant pressure	High , call technician
E5	Freeze cycle timeout	High , multiple causes
E6	Harvest cycle timeout	High , valve or water quality
E7	Evaporator sensor fault	Medium , sensor replacement
E8	Water too hot	High , source problem

Full diagnostics: <https://errorcodefixes.com/posts/hoshizaki-km-2000saj-error-codes/>

FIELD DIAGNOSTICS — CODE BY CODE

• Hoshizaki C-101BAH / C-201BAH Countertop Ice Maker Error Codes

Hoshizaki C-101BAH and C-201BAH countertop crescent cube ice maker error codes explained — diagnose and fix E1 through E6 and F-series safety faults on the most common compact commercial ice machine in hotels, bars, and...

Full guide: <https://errorcodefixes.com/posts/hoshizaki-c-101bah-error-codes/>

E1 Hoshizaki E1 Error Code

PRO SERVICE

E1 means the freeze cycle ran too long and timed out.

MOST LIKELY leaking inlet water valve or insufficient water supply pressure

CHECK FIRST

1. Confirm the water shutoff valve is fully open and the supply line is not kinked or restricted.
2. Inspect and clean the inlet water filter or strainer for debris that would reduce flow.
3. Reset the error code and watch one full freeze cycle to see if the machine runs continuously without forming ice.

Full guide: <https://errorcodefixes.com/posts/hoshizaki-ice-machine-e1-error-code/>

E7 Hoshizaki E7 Error Code

What Hoshizaki E7 error code means, why it happens, and how to fix it step by step.

MOST LIKELY Drain valve solenoid failed

Full guide: <https://errorcodefixes.com/posts/hoshizaki-e7-error-code/>

F1 Hoshizaki F1 Error Code

What Hoshizaki F1 means, why it happens, and how to fix it step by step.

MOST LIKELY Drain pump motor failed

Full guide: <https://errorcodefixes.com/posts/hoshizaki-f1-error-code/>

F2 Hoshizaki F2 Error Code

What Hoshizaki error code F2 means, why the ice full sensor faults, and how to fix it step by step.

MOST LIKELY Ice bridging over the bin sensor

Full guide: <https://errorcodefixes.com/posts/hoshizaki-f2-error-code/>

E8 Hoshizaki Ice Machine E8 Error Code

What Hoshizaki E8 low-side pressure switch fault means, why it trips, and how to diagnose and fix it step by step.

MOST LIKELY Low refrigerant charge

Full guide: <https://errorcodefixes.com/posts/hoshizaki-e8-error-code/>

• Hoshizaki KM-901 Error Codes

The Hoshizaki KM-901 ice machine displays fault codes E1 through E8 when it detects a problem — this guide explains each code, how to diagnose the cause, and what parts to order.

Full guide: <https://errorcodefixes.com/posts/hoshizaki-km-901-error-codes/>

• Hoshizaki KM-1301 Error Codes

Hoshizaki KM-1301 error codes: freeze cycle, harvest cycle, thermistor, and water system faults with causes and fixes.

MOST LIKELY Long freeze cycle

Full guide: <https://errorcodefixes.com/posts/hoshizaki-km-1301-error-codes/>

• Hoshizaki KM-1301SAH Error Codes

Hoshizaki KM-1301SAH error codes explained — this large crescent-cube commercial ice machine communicates faults through LED blink codes on the control board.

Full guide: <https://errorcodefixes.com/posts/hoshizaki-km-1301sah-error-codes/>

→ GET THE FULL FIELD REFERENCE

17 BRANDS

This sample covers ABB and Hoshizaki. The full edition adds every industrial brand section on errorcodefixes.com — Fanuc, Haas, ABB, Siemens, Yaskawa, Danfoss, Mitsubishi, SEW-Eurodrive, York, Trane, Hoshizaki, Manitowoc, Scotsman, Rational, Hobart, APC, Generac — 869 code entries compiled the same way, one file, works offline.

<https://errorcodefixes.com/field-reference/>

Industrial Fault-Code Field Reference — SAMPLE edition. Compiled from 45 published diagnostic guides at errorcodefixes.com. Content updated Jun 2026.

© errorcodefixes.com. Independent reference — not affiliated with any equipment manufacturer. Codes, thresholds, and procedures vary by model, firmware, and installation: always confirm against the unit's own service documentation before acting.