So, You Want to Replace a Super App 30p With an FW28

There is a b20 app ready to go for the replacement.

Please refer to your common sense as to where this is located.

The Tcom points do not work in the same way as they used to because of the new kit that is needed for the b20+ firmware.

You will have to find and replace each one of these Tcom COV addresses with their alternate in the points list of the unit in the TCom network.

Add a Normal Poll tuning policy and assign it to these points. Then Save the station.

Co2 485.4 / 551.1

Econ24 503.4 / 402.1

EconStatus 494.4 / 408.1

OAT 459.4 / 555.1

RAT 457.4 / 672.1

SaTemp 455.4 / 547.1

SpaceTemp 453.4 / 545.1

Status 488.4 / 592.1

Status2 489.4 / 589.1

Status3 492.4 / 584.1

UnitAmps 461.4 / 549.1