FS Firmware Update

Backup the app. Indicate the firmware in the filename.

Update the firmware.

Setup a ping. Reboot the controller. Wait five minutes.

Restore the app.

Update kits.

Check PIDs for 0 - 100 and direct / inverse.

In CPT:

BACnetS / BACnetC: writeOnStart and writeOnUp = true.

BacnetC: VAVs' minWriteTime = 1 sec, maxWriteTime = 1 min.

VAVs: All writeable points' enableMaxWrite, enableWriteOnUp, and

enableWriteOnStart = true.

Double-check the VAVs for whack-a-mole.

Backup the app. Indicate the new firmware in the filename.