



# Replace Front Door Latches

**Classification** Campaign Bulletin **Section/Group** 11 - Closures **Country/Region** All

**Year** 2016 **Model** Model X **Version** All

**Bulletin Classification:** This campaign bulletin addresses a known non-safety-related condition and provides recommended technical diagnosis and repair procedures. Apply this procedure to all vehicles in the affected VIN range listed. These instructions assume knowledge of motor vehicle and high voltage electrical component repairs, and should only be executed by trained professionals. Tesla Motors assumes no liability for injury or property damage due to a failure to properly follow these instructions or repairs attempted by unqualified individuals.

## Condition

Early front door latches are susceptible to water ingress, which might cause the touchscreen to show the door in the wrong position or prevent the door from opening and closing automatically. The door can still be opened with the inside handle.

## Correction

Replace the LH and RH front door latches with updated parts.

| Correction Description                                                    | Correction | Time |
|---------------------------------------------------------------------------|------------|------|
| SB-16-11-006 Not Applicable                                               | S011611006 | 0.00 |
| Install Updated LH and RH Front Door Latches                              | S021611006 | 0.90 |
| Install Updated LH and RH Front Door Latches; Additional Latches Required | S031611006 | 1.80 |

| Required Part(s): | Part Number  | Description                                    | Quantity |
|-------------------|--------------|------------------------------------------------|----------|
|                   | 1084918-80-D | RWK MX FR DR LH LATCH NDX180                   | 1-2      |
|                   | 1084917-80-D | RWK MX FR DR RH LATCH NDX180                   | 1-2      |
|                   | 1006772-00-A | FASTENER, SCREW, TORX30, M6-1.00X10MM          | 6-12     |
|                   | 1025401-00-A | HEART FLEX CLIP WITH WASHER - 70 LBS RETENTION | 18-36    |

These part numbers were current at the time of publication. Use the revisions listed or later, unless otherwise specified in the Parts Manual.

## Procedure

1. Replace the LH front door latch (refer to Service Manual procedure 11351002).

2. Ensure that the window is fully raised.
3. Gently close the door until the secondary latch engages. Verify that the door cinches properly.
4. Repeat the previous step 2 times:
  - If the door cinches properly each time, continue to the next step.
  - If the door fails to cinch properly, remove the door latch and repeat the procedure to install a new LH door latch.
  - If the door fails to cinch properly with the second new door latch installed, escalate a Toolbox session, as appropriate.
5. Repeat the procedure on the RH door.

---

**Affected VIN(s)** Affected Model X vehicles built before approximately August 29, 2016.

**NOTE:** This is a simplified summary of the affected VIN list. Refer to the VIN/Bulletin Tracker or Customer/Vehicle profile to determine applicability of this bulletin for a particular vehicle.

For feedback on the accuracy of this document, email [ServiceBulletinFeedback@tesla.com](mailto:ServiceBulletinFeedback@tesla.com).