

		Tesla, Inc. Service Bulletin		<i>Replace Front Body Controller Module</i>	
SB-25-17-010 October 3, 2025					
Classification		Section/Group	Mobile Service	Configuration	
Campaign Bulletin		17 - Electrical	Cannot Perform	All	
Model	Model Year	Country/Region	Build Location		
Model S	2021–2025	All	All		
Model X	2021–2025				
Model 3	2017–2023				
Model Y	2020–2024				
The model(s) and model year(s) listed are a general approximation of the affected VIN list. Refer to the VIN/Bulletin Tracker or Customer/Vehicle profile to determine applicability of this bulletin for a particular vehicle.					

Campaign Bulletin: This campaign bulletin addresses a non-safety-related condition and provides recommended technical diagnosis and repair procedures. Apply this procedure to the applicable vehicles.

Condition

On certain vehicles, the incorrect front vehicle controller module may be installed.

Correction

Replace the front vehicle controller module with a part compatible with the vehicle’s configuration.

 **NOTE:** If this bulletin is applicable to the vehicle, perform the correction without any need for inspection.

Correction Description	Correction	Time			
		Model S	Model X	Model 3	Model Y
Replace Front Body Controller Module (Heat Pump Vehicles) (Customer Pay)	S012517010	0.54	0.54	0.84	0.78
Replace Front Body Controller Module (Non-Heat Pump Vehicles) (Customer Pay)	S022517010	—	—	1.32	—
Replace Front Body Controller Module (Heat Pump Vehicles) (Tesla Pay)	S032517010	0.54	0.54	0.84	0.78
Replace Front Body Controller Module (Non-Heat Pump Vehicles) (Tesla Pay)	S042517010	—	—	1.32	—
Customer Declines Replacement Of Front Body Controller Module	S052517010	—	—	—	—

	Part Number	Description	Quantity
Parts As Required		Model S and Model X (2021–May 2025)	
		HW3:	
	1585663-00-C	FRONT CONTROLLER ASSEMBLY	1
		HW4:	
	1585663-20-D	FRONT CONTROLLER ASSEMBLY GEN 4, AP4	1
		Model 3 (2017–2023)	
		HW3:	
	1583991-10-D	ASSEMBLY - FRONT VEHICLE CONTROLLER GENERATION 3.1	1
		(Non-Heat Pump) Only:	
	1004378-00-B	NUT, FLG, HEX, M6x1.00[8]-14	6
		HW4 (see Table 2 for additional part compatibility criteria):	
	1866750-00-B	ASSEMBLY FRONT CONTROLLER GEN 3	1
		Or	
	1866750-20-B	ASSEMBLY FRONT CONTROLLER GEN 3	1
		Model Y (2020–2024)	
		HW3:	
	1583991-10-D	ASSEMBLY - FRONT VEHICLE CONTROLLER GENERATION 3.1	1
	1137934-00-C	BOLT, HF, M6x16, [109], G0109, ADH, MAT	2
		HW4 (see Table 2 for additional part compatibility criteria):	
	1866750-20-B	ASY. FRONT CONTROLLER GEN 3	1
		Or	
	1866750-21-B	ASY. FRONT CONTROLLER GEN 3	1
	1137934-00-C	BOLT, HF, M6x16, [109], G0109, ADH, MAT	2
These part numbers were current at the time of publication. Use the revisions listed or later, unless otherwise specified in the Parts Catalog .			
Special Tools As Required	1133367-00-A	Headlight Tester, Beissbarth, MLD 815	
	1114934-00-A	Laser Measure, Bosch GLM 35	
		Model X (2021–May 2025):	
	1785249-00-A	Extension, 1/4" Dr, 6", Locking, Insulated	
		Model 3 (2017–2023):	
	1115255-00-A	Ratchet, 1/4" Dr, M12, Bare Tool	
	1965406-00-A	Torque Wrench, Digital+Angle, 3/8" Dr, Flex Head, 13.5~135nm	
		(Dual-Motor) (Non-Heat Pump) Only:	
	1965119-00-A	Torq Wrnch, Dig+Ang, 1/4" Dr, Fixhd, 1.5~30nm	
		Model Y (2020–2024):	
	1115255-00-A	Ratchet, 1/4" Dr, M12, Bare Tool	
	1965119-00-A	Torq Wrnch, Dig+Ang, 1/4" Dr, Fixhd, 1.5~30nm	

Shop Supplies —

Procedure

1. Replace the front body controller module with a compatible part and make sure it is consistent with the vehicle's Auto Pilot (AP) hardware configuration, as outlined in Tables 1 and 2.
 - Refer to Toolbox Article [#9480157](#) for additional details on Model S (2021+) and Model X (2021+) controller module and AP hardware type compatibility.
 - Refer to Toolbox Article [#9449800](#) for additional details on Model 3 (2017–2023) and Model Y (2020–2024) controller module and AP hardware type compatibility.

Model	Procedure Title	Correction Code
Model S (2021–May 2025)	Module - Body Controller - Front (Remove and Replace)	17152912
Model X (2021–May 2025)	Module - Body Controller - Front (Remove and Replace)	17152912
Model 3 (2017–2023)	Module - Body Controller - Front (RWD) (Non-Heat Pump) (Remove and Replace)	17152902
	Module - Body Controller - Front (Dual Motor) (Non-Heat Pump) (Remove and Replace)	17152912
	Module - Body Controller - Front (Heat Pump) (Remove and Replace)	17152952
Model Y (2020–2024)	Module - Body Controller - Front (Remove and Replace)	17152912

Table 1 – Service manual procedures

Model	AP Hardware Type	Steering Rack Type	Front Body Controller Module Part Number
Model S (2021–May 2025)	HW3 variants only	N/A	1585663-00-C
	HW4 variants only	N/A	1585663-20-D
Model X (2021–May 2025)	HW3 variants only	N/A	1585663-00-C
	HW4 variants only	N/A	1585663-20-D
Model 3 (2017–2023)	HW3 and older variants only	Any	1583991-10-D
	HW4 variants only	Any	1866750-00-B (Country/Region-specific part configuration; use the part number indicated in the Parts Catalog)
			1866750-20-B (Country/Region-specific part configuration; use the part number indicated in the Parts Catalog)
Model Y (2020–2024)	HW3 variants only	Any	1583991-10-D
	HW4 variants only	Mando	1866750-20-B
		TK	1866750-21-B

Table 2 – AP hardware type, steering rack type, and front body controller module part number compatibility

2. Close out this document using the appropriate correction code based on the repair performed.