

表一: 电极帽直径13mm时, 电极柄的最大长度表(单位: mm, ×表示禁止使用)

电极角度(单位: 度)	材质	加压力(单位: N)							
		2000N	2500N	3000N	3500N	4000N	4500N	5000N	6000N
0	CRCU	100	100	100	100	100	100	×	×
	BECU-25E	100	100	100	100	100	100	×	×
	BECU-50E	100	100	100	100	100	100	×	×
1~5	CRCU	100	100	100	100	100	85	×	×
	BECU-25E	100	100	100	100	100	100	×	×
	BECU-50E	100	100	100	100	100	100	×	×
6~10	CRCU	100	80	65	55	50	×	×	×
	BECU-25E	100	100	100	85	75	×	×	×
	BECU-50E	100	100	85	70	65	×	×	×
11~15	CRCU	65	50	45	×	×	×	×	×
	BECU-25E	100	80	65	×	×	×	×	×
	BECU-50E	85	70	55	×	×	×	×	×
16~20	CRCU	50	40	×	×	×	×	×	×
	BECU-25E	75	60	50	×	×	×	×	×
	BECU-50E	65	50	40	×	×	×	×	×
21~25	CRCU	40	×	×	×	×	×	×	×
	BECU-25E	60	50	40	×	×	×	×	×
	BECU-50E	50	40	35	×	×	×	×	×
26~30	CRCU	×	×	×	×	×	×	×	×
	BECU-25E	50	40	35	×	×	×	×	×
	BECU-50E	45	35	×	×	×	×	×	×

表二:电极帽直径16mm时, 电极柄的最大长度表(单位: mm, ×表示禁止使用)

		加压力(单位: N)							
电极角度(单位: 度)	材质	2000N	2500N	3000N	3500N	4000N	4500N	5000N	6000N
0	CRCU	150	150	150	150	150	150	150	150
	BECU-25E	150	150	150	150	150	150	150	150
	BECU-50E	150	150	150	150	150	150	150	150
1~5	CRCU	150	150	150	150	150	150	150	125
	BECU-25E	150	150	150	150	150	150	150	150
	BECU-50E	150	150	150	150	150	150	150	150
6~10	CRCU	150	150	125	105	95	85	75	×
	BECU-25E	150	150	150	150	145	130	115	×
	BECU-50E	150	150	150	140	125	110	100	×
11~15	CRCU	125	100	85	70	60	55	×	×
	BECU-25E	150	150	130	110	95	85	×	×
	BECU-50E	150	130	110	95	80	70	×	×
16~20	CRCU	95	75	60	55	45	40	×	×
	BECU-25E	145	115	95	85	70	65	×	×
	BECU-50E	125	100	80	70	60	55	×	×
21~25	CRCU	75	60	50	45	35	35	×	×
	BECU-25E	120	95	80	65	60	50	×	×
	BECU-50E	100	80	65	55	50	45	×	×
26~30	CRCU	65	50	40	35	×	×	×	×
	BECU-25E	100	80	65	55	50	45	×	×
	BECU-50E	85	65	55	45	40	35	×	×

表三:握杆和电极柄CRCU材质时的压力使用许可表(√表示可以使用,×表示禁止使用)

[illegible]

表五:握杆和电极柄BECU-25E材质时的压力使用许可表(√表示可以使用,×表示禁止使用)

电极帽直径13mm	加压力(单位: N)												
电极角度(单位: 度)	2000N	2500N	3000N	3500N	4000N	4500N	5000N	5500N	6000N	6500N	7000N	7500N	8000N
0	√	√	√	√	√	√	×	×	×	×	×	×	×
1~5	√	√	√	√	√	√	×	×	×	×	×	×	×
6~10	√	√	√	√	√	√	×	×	×	×	×	×	×
11~15	√	√	√	√	×	×	×	×	×	×	×	×	×
16~20	√	√	√	×	×	×	×	×	×	×	×	×	×
21~25	√	√	×	×	×	×	×	×	×	×	×	×	×
26~30	√	×	×	×	×	×	×	×	×	×	×	×	×
电极帽直径16mm	加压力(单位: N)												
电极角度(单位: 度)	2000N	2500N	3000N	3500N	4000N	4500N	5000N	5500N	6000N	6500N	7000N	7500N	8000N
0	√	√	√	√	√	√	√	√	√	×	×	×	×
1~5	√	√	√	√	√	√	√	√	√	×	×	×	×
6~10	√	√	√	√	√	√	√	√	√	×	×	×	×
11~15	√	√	√	√	√	√	√	√	×	×	×	×	×
16~20	√	√	√	√	√	√	×	×	×	×	×	×	×
21~25	√	√	√	√	√	×	×	×	×	×	×	×	×
26~30	√	√	√	√	×	×	×	×	×	×	×	×	×
电极帽直径19mm	加压力(单位: N)												
电极角度(单位: 度)	2000N	2500N	3000N	3500N	4000N	4500N	5000N	5500N	6000N	6500N	7000N	7500N	8000N
0	√	√	√	√	√	√	√	√	√	√	√	√	√
1~5	√	√	√	√	√	√	√	√	√	√	√	√	√
6~10	√	√	√	√	√	√	√	√	√	√	√	√	√
11~15	√	√	√	√	√	√	√	√	√	√	√	√	×
16~20	√	√	√	√	√	√	√	√	√	×	×	×	×
21~25	√	√	√	√	√	√	√	×	×	×	×	×	×
26~30	√	√	√	√	√	√	×	×	×	×	×	×	×