

Blast Chiller Service Log — Unit BC-2

Field service summary attached to TKT-017.

Readings

Time	Product	Core temp	Cabinet temp	Note
14:05	Chili, 3 in pans	162°F	31°F	Hard chill started
15:05	Chili	118°F	38°F	Fan noise, E4 code shown
16:05	Chili	88°F	44°F	Stage 1 limit missed (needs 70°F by 2 h)

Technician findings

- Error **E4**: evaporator fan motor drawing low current.
- Condenser coil heavily soiled; airflow reduced.
- Door gasket torn at lower hinge corner.

Actions

1. Fan motor ordered (2 business days).
2. Coil cleaned on site.
3. Unit tagged *do not use for cooling* until the fan is replaced.