Township of NIPISSING
"Life the way it should be" Est. 1888

The Corporation of the Township of Nipissing Fire Department
45 Beatty Street
Nipissing ON P0H 1W0
Telephone 705-752-2772
www.nipissingtownship.com

TOWNSHIP OF NIPISSING
STAFF REPORT
Community Centre/Fire Station 1 Well Water Assessment and Recommendation

FROM: Will Bateman
DATE: November 13, 2025

Over the past several months, the Community Centre has run out of water on multiple occasions, which has impacted the Fitness Centre, community programming and events, as well as operations at the Fire Station. An initial inspection identified a leaking toilet in the Community Centre, which has since been replaced. Following this repair, further investigation was carried out to determine whether there were underlying issues with the water system itself. A qualified well company was contracted to conduct a pump test to evaluate the condition and performance of the Community Centre's well. The test involved operating the submersible pump at a fixed flow rate for one hour while recording water levels throughout the process. The well was then allowed to recover for an additional hour, with water levels recorded at set intervals during both phases. The results of the testing indicate that the well's current recovery rate is approximately 2 gallons per minute (GPM). The original well record listed a recovery rate of 8 GPM, suggesting a notable reduction in performance. Possible causes for this decline may include:

- The build up of iron deposits restricting water flow within the borehole,
- Natural changes in the aquifer over time, or
- Inaccuracies in the original well record.

To address these findings and improve water reliability at the Community Centre, the following actions are recommended:

1. **Hydrofracking Procedure**: Perform hydrofracking on the well to attempt to restore or increase its recovery rate. This process uses high-pressure water to open or clean out natural fissures in the rock, potentially improving water flow between aquifers.
2. **Pump Replacement**: Replace the existing pump with a ¾ horsepower model that is more appropriate for the current depth and operating conditions.
3. **System Maintenance**: Inspect and replace any fittings or wiring between the pump and pit less adapter that show signs of corrosion.
4. **Ongoing Maintenance Program**: Establish a service interval of every 2–5 years to inspect and clean the pump intakes to ensure continued optimal performance.

While hydrofracking often results in improved recovery rates, the outcome cannot be guaranteed. Following the hydrofracking, it is recommended that a second pump test be conducted to confirm any gains in well production.
The total estimated cost for the hydrofracking procedure, follow-up pump test, replacement pump, and any associated fitting or wiring replacements is approximately $8,250.00 plus applicable taxes.

Will Bateman, Fire Chief, CEMC, Municipal By-Law Officer

Will Bateman
Fire Chief, CEMC, Municipal By-law Officer
Township of Nipissing

firechief@nipissingtownship.com
705-752-2772

MacInnis Water Wells
200 North Waseosa Lake Rd
Huntsville ON P1H2J4
7053492622
connor@macinniswaterwells.com
Business Number 726558505

Estimate

ADDRESS
Nipissing Township
45 Beatty Street
Nipissing Ontario P0H1W0

ESTIMATE # 1052
DATE 13/11/2025

DATE	DESCRIPTION	TAX	QTY	RATE	AMOUNT
Hydroracking		HST ON	1	5,876.00	5,876.00
Pump Test		HST ON	1	440.00	440.00
3/4 Hp 5GPM 230v 3 wire pump		HST ON	1	1,424.00	1,424.00
Plumbing fittings (estimate)		HST ON	1	150.00	150.00
Onsite Labour	Hourly rate for onsite service	HST ON	4	90.00	360.00

SUBTOTAL	8,250.00
HST (ON) @ 13%	1,072.50
TOTAL	**$9,322.50**

TAX SUMMARY

RATE	TAX	NET
HST (ON) @ 13%	1,072.50	8,250.00

Accepted By

Accepted Date