

Diagnostic information - DME (DFI) control unit

Engine compartment purge fan 1 activation: electrical fault

- ♦ 911 Carrera - right
- ♦ 718 Boxster/Cayman - left

⚠ WARNING

Exposed running fan blades!

Danger of limbs being severed!

Risk of serious injury due to ejected foreign bodies!

- ♦ **ALWAYS** keep hair or clothing out of the rotating range of the fan.
- ♦ DO NOT reach into the rotating fan.
- ♦ **DO NOT** place tools or other items in the rotating range of the fan.
- ♦ Perform work on the fan only with the ignition switched off.
- ♦ Secure the ignition to prevent it from being switched on accidentally by other persons.

NOTE

Sensitive electronics!

Risk of irreparable damage to electronic components!

- ♦ **DO NOT** carry out electrical tests.
- ♦ **DO NOT** connect external power sources.

Diagnostic conditions

- Ignition on

Possible fault causes

- ♦ Short circuit to ground or open circuit in lines (power supply to radiator fan control unit terminal 30)
- ♦ Short circuit to B+/ground or open circuit in the line (radiator fan control unit activation)
- ♦ Engine compartment purge fan 1 faulty

Diagnostic information - DME (DFI) control unit

Engine compartment purge fan 1 activation: electrical fault

- ♦ 911 Carrera - right
- ♦ 718 Boxster/Cayman - left

⚠ WARNING

Exposed running fan blades!

Danger of limbs being severed!

Risk of serious injury due to ejected foreign bodies!

- ♦ **ALWAYS** keep hair or clothing out of the rotating range of the fan.
- ♦ DO NOT reach into the rotating fan.
- ♦ **DO NOT** place tools or other items in the rotating range of the fan.
- ♦ Perform work on the fan only with the ignition switched off.
- ♦ Secure the ignition to prevent it from being switched on accidentally by other persons.

NOTE

Sensitive electronics!

Risk of irreparable damage to electronic components!

- ♦ **DO NOT** carry out electrical tests.
- ♦ **DO NOT** connect external power sources.

Diagnostic conditions

- Ignition on

Possible fault causes

- ♦ Short circuit to ground or open circuit in lines (power supply to radiator fan control unit terminal 30)
- ♦ Short circuit to B+/ground or open circuit in the line (radiator fan control unit activation)
- ♦ Engine compartment purge fan 1 faulty

Diagnostic information - DME (DFI) control unit

Engine compartment purge fan relay activation

INFORMATION

The run-on duration of the engine compartment purge fan AFTER ignition off depends on the engine compartment temperature.

- ◆ It is as follows for the following engine compartment temperatures:
 - ◆ < 45 °C (113 °F) for approx. 50 seconds
 - ◆ 45 ... 70 °C (113 ... 158 °F) for approx. 200 seconds
 - ◆ > 70 °C (158 °F) for up to 20 minutes

Diagnostic conditions

- Vehicle voltage 10 ... 15 V
- Ignition on or engine running or control unit run-on
- **LOW** stage activated for > 25 seconds (drive links)

Possible fault causes

- ◆ Short circuit to B+/ground/between lines or open circuit in the lines ► Engine compartment purge fan relay activation
- ◆ Engine compartment purge fan relay activation faulty

Diagnostic information - DME (DFI) control unit

Engine compartment purge fan relay activation

INFORMATION

The run-on duration of the engine compartment purge fan AFTER ignition off depends on the engine compartment temperature.

- ◆ It is as follows for the following engine compartment temperatures:
 - ◆ < 45 °C (113 °F) for approx. 50 seconds
 - ◆ 45 ... 70 °C (113 ... 158 °F) for approx. 200 seconds
 - ◆ > 70 °C (158 °F) for up to 20 minutes

Diagnostic conditions

- Vehicle voltage 10 ... 15 V
- Ignition on or engine running or control unit run-on
- **LOW** stage activated for > 25 seconds (drive links)

Possible fault causes

- ◆ Short circuit to B+/ground/between lines or open circuit in the lines ► Engine compartment purge fan relay activation
- ◆ Engine compartment purge fan relay activation faulty

Diagnostic information - DME (DFI) control unit

Engine compartment purge fan 2 activation: electrical fault

- ♦ 911 Carrera - left
- ♦ 718 Boxster/Cayman - right

⚠ WARNING

Exposed running fan blades!

Danger of limbs being severed!

Risk of serious injury due to ejected foreign bodies!

- ♦ **ALWAYS** keep hair or clothing out of the rotating range of the fan.
- ♦ **DO NOT** reach into the rotating fan.
- ♦ **DO NOT** place tools or other items in the rotating range of the fan.
- ♦ Perform work on the fan only with the ignition switched off.
- ♦ Secure the ignition to prevent it from being switched on accidentally by other persons.

NOTE

Sensitive electronics!

Risk of irreparable damage to electronic components!

- ♦ **DO NOT** carry out electrical tests.
- ♦ **DO NOT** connect external power sources.

Diagnostic conditions

- Ignition on

Possible fault causes

- ♦ Short circuit to ground or open circuit in lines (power supply to radiator fan control unit terminal 30)
- ♦ Short circuit to B+/ground or open circuit in the line (radiator fan control unit activation)
- ♦ Engine compartment purge fan 2 faulty

Diagnostic information - DME (DFI) control unit

Engine compartment purge fan 2 activation: electrical fault

- ♦ 911 Carrera - left
- ♦ 718 Boxster/Cayman - right

⚠ WARNING

Exposed running fan blades!

Danger of limbs being severed!

Risk of serious injury due to ejected foreign bodies!

- ♦ **ALWAYS** keep hair or clothing out of the rotating range of the fan.
- ♦ **DO NOT** reach into the rotating fan.
- ♦ **DO NOT** place tools or other items in the rotating range of the fan.
- ♦ Perform work on the fan only with the ignition switched off.
- ♦ Secure the ignition to prevent it from being switched on accidentally by other persons.

NOTE

Sensitive electronics!

Risk of irreparable damage to electronic components!

- ♦ **DO NOT** carry out electrical tests.
- ♦ **DO NOT** connect external power sources.

Diagnostic conditions

- Ignition on

Possible fault causes

- ♦ Short circuit to ground or open circuit in lines (power supply to radiator fan control unit terminal 30)
- ♦ Short circuit to B+/ground or open circuit in the line (radiator fan control unit activation)
- ♦ Engine compartment purge fan 2 faulty

Diagnostic information - DME (DFI) control unit

Engine compartment purge fan 2 activation: electrical fault

- ♦ 911 Carrera - left
- ♦ 718 Boxster/Cayman - right

⚠ WARNING

Exposed running fan blades!

Danger of limbs being severed!

Risk of serious injury due to ejected foreign bodies!

- ♦ **ALWAYS** keep hair or clothing out of the rotating range of the fan.
- ♦ **DO NOT** reach into the rotating fan.
- ♦ **DO NOT** place tools or other items in the rotating range of the fan.
- ♦ Perform work on the fan only with the ignition switched off.
- ♦ Secure the ignition to prevent it from being switched on accidentally by other persons.

NOTE

Sensitive electronics!

Risk of irreparable damage to electronic components!

- ♦ **DO NOT** carry out electrical tests.
- ♦ **DO NOT** connect external power sources.

Diagnostic conditions

- Ignition on

Possible fault causes

- ♦ Short circuit to ground or open circuit in lines (power supply to radiator fan control unit terminal 30)
- ♦ Short circuit to B+/ground or open circuit in the line (radiator fan control unit activation)
- ♦ Engine compartment purge fan 2 faulty

P169B

Diagnostic information - DME (DFI) control unit

Transmission oil temperature sensor implausible during cold start

Diagnostic conditions

- Time since ignition off > 8

Possible fault causes

- ♦ Short circuit to B+/ground/between lines or open circuit in the lines
- ♦ Transmission oil temperature sensor faulty

Fault setting condition(s)

- The temperature measured by the transmission oil temperature sensor ([T145](#)) deviates too much from the mean value of the engine coolant, engine oil, intake air and ambient air temperatures ([T160](#)).

Fault effects

- ♦ Substitute value from model

Temperature sensor setpoints

Temperature	Resistance [Ohm]
♦ 0 °C (32 °F)	13,968
♦ 20 °C (68 °F)	6,068
♦ 25 °C (77 °F)	5,000
♦ 40 °C (104 °F)	2,887
♦ 50 °C (122 °F)	2,051
♦ 60 °C (140 °F)	1,484
♦ 80 °C (176 °F)	814
♦ 100 °C (212 °F)	473
♦ 120 °C (248 °F)	289
♦ 140 °C (284 °F)	184

P169C

Diagnostic information - DME (DFI) control unit

Transmission oil temperature too high

Diagnostic conditions

- Engine running

Fault setting condition(s)

- Transmission oil temperature > 150 °C (302 °F) (T145)

Fault effects

- ♦ Warning in instrument cluster
- ♦ Operating restrictions

P169D

Diagnostic information - DME (DFI) control unit

Transmission oil temperature too high

Diagnostic conditions

- Engine running

Fault setting condition(s)

- Transmission oil temperature > 150 °C (302 °F) (T145)

Fault effects

- ♦ Warning in instrument cluster
- ♦ Operating restrictions

P169E

Diagnostic information - DME (DFI) control unit

Transmission oil temperature sensor stuck

Diagnostic conditions

- Driving with different operating conditions
- None of the following faults stored: P169C, P169D

Possible fault causes

- ♦ Transmission oil temperature sensor faulty
- ♦ Resistor installed (instead of transmission oil temperature sensor)

Fault setting condition(s)

- Transmission oil temperature does not change or does not change sufficiently

P169F

Diagnostic information - DME (DFI) control unit

Transmission oil temperature sensor: electrical fault

Diagnostic conditions

- Ignition on

Possible fault causes

- ♦ Loose contact or corrosion on connectors or lines
- ♦ Short circuit to B+/ground/between lines or open circuit in the lines
- ♦ Transmission oil temperature sensor faulty

P16A0

Diagnostic information - DME (DFI) control unit

Transmission oil temperature sensor: electrical fault

Diagnostic conditions

- Ignition on

Possible fault causes

- ♦ Loose contact or corrosion on connectors or lines
- ♦ Short circuit to B+/ground/between lines or open circuit in the lines
- ♦ Transmission oil temperature sensor faulty

Diagnostic information - DME (DFI) control unit

Charge-air cooler water pump: live code implausible

INFORMATION

The charge-air cooler water pump reacts to requests from the DME control unit (PWM signal). It can determine various faults itself and send them as a PWM signal to the DME control unit via the signal line.

Diagnostic conditions

- Water pump activated

Possible fault causes

- ♦ Short circuit to ground or open circuit in power supply to the water pump
- ♦ Open circuit in ground line to the water pump
- ♦ Charge-air cooler water pump faulty

Fault setting condition(s)

The DME control unit expects to receive a signal cyclically on the signal line. The fault is set if this signal is not received even though the signal line itself is not faulty.

P1940

Diagnostic information - DME (DFI) control unit

Charge-air cooler water pump: signal line

INFORMATION

The charge-air cooler water pump reacts to requests from the DME control unit (PWM signal). It can determine various faults itself and send them as a PWM signal to the DME control unit via the signal line.

Diagnostic conditions

- Ignition on

Possible fault causes

- ♦ Short circuit to B+/ground/between lines or open circuit in the signal line between the DME control unit and water pump
- ♦ Charge-air cooler water pump faulty

P1941

Diagnostic information - DME (DFI) control unit

Charge-air cooler water pump: signal line

INFORMATION

The charge-air cooler water pump reacts to requests from the DME control unit (PWM signal). It can determine various faults itself and send them as a PWM signal to the DME control unit via the signal line.

Diagnostic conditions

- Ignition on

Possible fault causes

- ♦ Short circuit to B+/ground/between lines or open circuit in the signal line between the DME control unit and water pump
- ♦ Charge-air cooler water pump faulty

Diagnostic information - DME (DFI) control unit

Charge-air cooler water pump: signal line

INFORMATION

The charge-air cooler water pump reacts to requests from the DME control unit (PWM signal). It can determine various faults itself and send them as a PWM signal to the DME control unit via the signal line.

Diagnostic conditions

- Ignition on

Possible fault causes

- ♦ Short circuit to B+/ground/between lines or open circuit in the signal line between the DME control unit and water pump
- ♦ Charge-air cooler water pump faulty

P194A

Diagnostic information - DME (DFI) control unit

Charge-air cooler water pump: speed too high

INFORMATION

The charge-air cooler water pump reacts to requests from the DME control unit (PWM signal). It can determine various faults itself and send them as a PWM signal to the DME control unit via the signal line.

Diagnostic conditions

- Water pump activated

Possible fault causes

- ♦ Not enough coolant in the charge-air cooling system
- ♦ Charge-air cooler water pump faulty (pump wheel broken, ...)

P194B

Diagnostic information - DME (DFI) control unit

Charge-air cooler water pump: blocked

INFORMATION

The charge-air cooler water pump reacts to requests from the DME control unit (PWM signal). It can determine various faults itself and send them as a PWM signal to the DME control unit via the signal line.

Diagnostic conditions

- Water pump activated

Possible fault causes

- ♦ Foreign bodies in charge-air cooling system
- ♦ Charge-air cooler water pump faulty

P194C

Diagnostic information - DME (DFI) control unit

Charge-air cooler water pump: overheated

INFORMATION

The charge-air cooler water pump reacts to requests from the DME control unit (PWM signal). It can determine various faults itself and send them as a PWM signal to the DME control unit via the signal line.

Diagnostic conditions

- Water pump activated

Possible fault causes

- ♦ Charge-air cooler water pump sluggish (faulty)

P194D

Diagnostic information - DME (DFI) control unit

Charge-air cooler water pump: speed too low

INFORMATION

The charge-air cooler water pump reacts to requests from the DME control unit (PWM signal). It can determine various faults itself and send them as a PWM signal to the DME control unit via the signal line.

Diagnostic conditions

- Water pump activated

Possible fault causes

- ♦ Foreign bodies in charge-air cooling system
- ♦ Charge-air cooler water pump faulty

Diagnostic information - valid for all control units

Read out control unit fault memory content

INFORMATION

This fault code indicates one or more faults/notes in the fault memory of the designated control unit.

Existing faults/notes in the designated control unit must be processed first.

NOTE

Use the [F7] button to show/hide notes in the fault memory.

Possible fault causes

- ◆ Fault in the designated control unit
- ◆ Note in the designated control unit

Fault effects

- ◆ Functions in the control unit are available only with restrictions
- ◆ Functions in the control unit are not available

P199C

Diagnostic information - DME (DFI) control unit

Main water pump solenoid valve output stage: electrical fault

Diagnostic conditions

- Cold start, then engine running

Possible fault causes

- ♦ Short circuit to B+/ground/between lines or open circuit in power supply to solenoid valve (from DME control unit)
- ♦ Short circuit to B+/ground/between lines or open circuit in ground supply for solenoid valve (from DME control unit)
- ♦ Main water pump solenoid valve faulty

P199D

Diagnostic information - DME (DFI) control unit

Main water pump solenoid valve output stage: electrical fault

Diagnostic conditions

- Cold start, then engine running

Possible fault causes

- ♦ Short circuit to B+/ground/between lines or open circuit in power supply to solenoid valve (from DME control unit)
- ♦ Short circuit to B+/ground/between lines or open circuit in ground supply for solenoid valve (from DME control unit)
- ♦ Main water pump solenoid valve faulty

P199E

Diagnostic information - DME (DFI) control unit

Main water pump solenoid valve output stage: electrical fault

Diagnostic conditions

- Cold start, then engine running

Possible fault causes

- ♦ Short circuit to B+/ground/between lines or open circuit in power supply to solenoid valve (from DME control unit)
- ♦ Short circuit to B+/ground/between lines or open circuit in ground supply for solenoid valve (from DME control unit)
- ♦ Main water pump solenoid valve faulty

P2072

Diagnostic information - DME (DFI) control unit

Throttle valve adjusting unit stuck

Diagnostic conditions

- Throttle valve adjusting unit adapted
- Vehicle stationary
- No gear engaged or selector-lever position P or N
- Intake air temperature < 5 °C (41 °F)
- Idle speed
- then short acceleration
- then engine speed > 2,200 rpm

Possible fault causes

- ♦ Throttle valve adjusting unit frozen
- ♦ Throttle valve adjusting unit faulty

Diagnostic information - DME (DFI) control unit

Mass air flow implausibly high (leakage adaptation)

Diagnostic conditions

- Idling > 2 minute(s)
- Driving with different operating conditions
- None of the following faults stored: Intake manifold pressure sensor, throttle valve adjusting unit, ambient pressure sensor, intake air temperature sensor, rpm sensor, valve lift control, camshaft adjustment

Possible fault causes

- ♦ Oil filler cap leaking
- ♦ Positive crankcase ventilation hose leaking
- ♦ Leak in intake system - between throttle valve and engine (intake valve)
- ♦ Tank vent valve faulty (stuck open)
- ♦ Intake manifold pressure sensor - electric plug connection loose, oxidized, corroded, interrupted
- ♦ Fault in areas: intake manifold pressure sensor, throttle valve adjusting unit (bent), ambient pressure sensor, intake air temperature sensor, rpm sensor, valve lift control, camshaft adjustment

Fault setting condition(s)

- Unacceptably large deviation between measured mass air flow and calculated mass air flow, with increasing deviation over an extended period (see ⓘ)

ⓘ INFORMATION

This diagnostic function monitors the intake system between the throttle valve and engine (intake valves).

- ♦ A mass air flow is calculated from the signals from the throttle valve potentiometer, engine speed sensor, intake air temperature sensor and ambient pressure sensor as well as other engine operating values.
- ♦ The calculated mass air flow is compared with that measured by the pressure sensor.
- ♦ A deviation may be due to both the calculated mass air flow and the measured mass air flow.

Diagnostic information - DME (DFI) control unit

Mass air flow in upper load range implausible

Diagnostic conditions

- Driving with different operating conditions
- None of the following faults stored: Intake manifold pressure sensor, throttle valve adjusting unit, ambient pressure sensor, intake air temperature sensor, rpm sensor, valve lift control, camshaft adjustment

Possible fault causes

- ♦ Air cleaner dirty/blocked/frozen
- ♦ Air intake (ahead of air cleaner) constricted
- ♦ Air guide ahead of throttle valve blocked/cross-section constricted
- ♦ Exhaust system blocked/cross-section constricted
- ♦ Intake manifold pressure sensor - electric plug connection loose, oxidized, corroded, interrupted
- ♦ Fault in areas: intake manifold pressure sensor, throttle valve adjusting unit, ambient pressure sensor, intake air temperature sensor, rpm sensor, valve lift control, camshaft adjustment

Fault setting condition(s)

- Unacceptably large deviation between measured mass air flow and calculated mass air flow (see ⓘ).

ⓘ INFORMATION

This diagnostic function monitors the intake system between the throttle valve and engine (intake valves).

- ♦ A mass air flow is calculated from the signals from the throttle valve potentiometer, engine speed sensor, intake air temperature sensor and ambient pressure sensor as well as other engine operating values.
- ♦ The calculated mass air flow is compared with that measured by the pressure sensor.
- ♦ A deviation may be due to both the calculated mass air flow and the measured mass air flow.

Diagnostic information - DME (DFI) control unit

Exhaust temperature sensor, bank 1

Diagnostic conditions

- Driving under various conditions

Possible fault causes

- ♦ Loose contact or corrosion on connectors or lines
- ♦ Short circuit to B+/ground/between lines or open circuit in the lines
- ♦ Exhaust temperature sensor faulty

Fault setting condition(s)

- The measured exhaust gas temperature differs from the exhaust gas temperature model by more than 300 °C (572 °F).

Fault effects

- If an exhaust temperature sensor is faulty, the value of the sensor for the other bank plus a safety reserve is then used as the substitute value .
- If both exhaust temperature sensors are faulty, the value of the exhaust gas temperature model plus a safety reserve is then used as the substitute value .

Diagnostic information - DME (DFI) control unit

Exhaust temperature sensor, bank 2

Diagnostic conditions

- Driving under various conditions

Possible fault causes

- ♦ Loose contact or corrosion on connectors or lines
- ♦ Short circuit to B+/ground/between lines or open circuit in the lines
- ♦ Exhaust temperature sensor faulty

Fault setting condition(s)

- The measured exhaust gas temperature differs from the exhaust gas temperature model by more than 300 °C (572 °F).

Fault effects

- If an exhaust temperature sensor is faulty, the value of the sensor for the other bank plus a safety reserve is then used as the substitute value .
- If both exhaust temperature sensors are faulty, the value of the exhaust gas temperature model plus a safety reserve is then used as the substitute value .

P2088

Diagnostic information - DME (DFI) control unit

Intake camshaft adjustment output stage, bank 1

Diagnostic conditions

- Time since engine start > 10 second(s)
- None of the following faults stored: P1556, P1557, P1558

Possible fault causes

- ♦ Short circuit to B+/ground or open circuit in the line (activation)
- ♦ Short circuit to ground or open circuit in the lines (power supply)
- ♦ Fuse faulty
- ♦ Solenoid valve for hydraulic camshaft adjustment faulty

Diagnostic information - DME (DFI) control unit

Intake camshaft adjustment output stage, bank 1

Diagnostic conditions

- Time since engine start > 10 second(s)
- None of the following faults stored: P1556, P1557, P1558

Possible fault causes

- ♦ Short circuit to B+/ground or open circuit in the line (activation)
- ♦ Short circuit to ground or open circuit in the lines (power supply)
- ♦ Fuse faulty
- ♦ Solenoid valve for hydraulic camshaft adjustment faulty

Diagnostic information - DME (DFI) control unit

Bank 1 exhaust camshaft adjustment output stage

Diagnostic conditions

- Time since engine start > 10 second(s)
- None of the following faults stored: P1556, P1557, P1558

Possible fault causes

- ♦ Short circuit to B+/ground or open circuit in the line (activation)
- ♦ Short circuit to ground or open circuit in the lines (power supply)
- ♦ Fuse faulty
- ♦ Solenoid valve for hydraulic camshaft adjustment faulty

P2091

Diagnostic information - DME (DFI) control unit

Bank 1 exhaust camshaft adjustment output stage

Diagnostic conditions

- Time since engine start > 10 second(s)
- None of the following faults stored: P1556, P1557, P1558

Possible fault causes

- ♦ Short circuit to B+/ground or open circuit in the line (activation)
- ♦ Short circuit to ground or open circuit in the lines (power supply)
- ♦ Fuse faulty
- ♦ Solenoid valve for hydraulic camshaft adjustment faulty

Diagnostic information - DME (DFI) control unit

Intake camshaft adjustment output stage, bank 2

Diagnostic conditions

- Time since engine start > 10 second(s)
- None of the following faults stored: P1556, P1557, P1558

Possible fault causes

- ♦ Short circuit to B+/ground or open circuit in the line (activation)
- ♦ Short circuit to ground or open circuit in the lines (power supply)
- ♦ Fuse faulty
- ♦ Solenoid valve for hydraulic camshaft adjustment faulty

Diagnostic information - DME (DFI) control unit

Intake camshaft adjustment output stage, bank 2

Diagnostic conditions

- Time since engine start > 10 second(s)
- None of the following faults stored: P1556, P1557, P1558

Possible fault causes

- ♦ Short circuit to B+/ground or open circuit in the line (activation)
- ♦ Short circuit to ground or open circuit in the lines (power supply)
- ♦ Fuse faulty
- ♦ Solenoid valve for hydraulic camshaft adjustment faulty

P2094

Diagnostic information - DME (DFI) control unit

Bank 2 exhaust camshaft adjustment output stage

Diagnostic conditions

- Time since engine start > 10 second(s)
- None of the following faults stored: P1556, P1557, P1558

Possible fault causes

- ♦ Short circuit to B+/ground or open circuit in the line (activation)
- ♦ Short circuit to ground or open circuit in the lines (power supply)
- ♦ Fuse faulty
- ♦ Solenoid valve for hydraulic camshaft adjustment faulty

P2095

Diagnostic information - DME (DFI) control unit

Bank 2 exhaust camshaft adjustment output stage

Diagnostic conditions

- Time since engine start > 10 second(s)
- None of the following faults stored: P1556, P1557, P1558

Possible fault causes

- ♦ Short circuit to B+/ground or open circuit in the line (activation)
- ♦ Short circuit to ground or open circuit in the lines (power supply)
- ♦ Fuse faulty
- ♦ Solenoid valve for hydraulic camshaft adjustment faulty

Diagnostic information - DME (DFI) control unit

Oxygen sensor downstream of catalytic converter, bank 1

NOTE

Plug connection disconnected = reference-air duct open!

Damage to oxygen sensor!

♦ **DO NOT** use spray, grease, fluid or similar products on the oxygen sensor plug connections.

i INFORMATION

♦ Do not interchange oxygen sensor upstream of catalytic converter with oxygen sensor downstream of catalytic converter as this will result in implausible fault entries.

♦ The connectors themselves are coded and cannot be interchanged.

Diagnostic conditions

- Perform all short tests in sequence

or

- Engine temperature > 60 °C (140 °F)
- Time since engine start > 10 second(s)
- Catalytic converter temperature 540 ... 750 °C (1,004 ... 1,382 °C)
- Drive for 60 seconds with slight acceleration at 40 ... 130 km/h (24 ... 80 mph)
- Active carbon filter loading < 0.7
- Engine speed < 3,000 rpm
- Lambda control ahead of catalytic converter active
- Lambda control behind catalytic converter active
- None of the following faults stored: Oxygen sensor(s) - electrical fault, intake manifold pressure sensor or throttle valve adjusting unit

Possible fault causes

♦ Oxygen sensor downstream of catalytic converter, bank 1 faulty

Diagnostic information - DME (DFI) control unit

Oxygen sensor downstream of catalytic converter, bank 1

NOTE

Plug connection disconnected = reference-air duct open!

Damage to oxygen sensor!

♦ **DO NOT** use spray, grease, fluid or similar products on the oxygen sensor plug connections.

i INFORMATION

♦ Do not interchange oxygen sensor upstream of catalytic converter with oxygen sensor downstream of catalytic converter as this will result in implausible fault entries.

♦ The connectors themselves are coded and cannot be interchanged.

Diagnostic conditions

- Perform all short tests in sequence

or

- Engine temperature > 60 °C (140 °F)
- Time since engine start > 10 second(s)
- Catalytic converter temperature 540 ... 750 °C (1,004 ... 1,382 °C)
- Drive for 60 seconds with slight acceleration at 40 ... 130 km/h (24 ... 80 mph)
- Active carbon filter loading < 0.7
- Engine speed < 3,000 rpm
- Lambda control ahead of catalytic converter active
- Lambda control behind catalytic converter active
- None of the following faults stored: Oxygen sensor(s) - electrical fault, intake manifold pressure sensor or throttle valve adjusting unit

Possible fault causes

♦ Oxygen sensor downstream of catalytic converter, bank 1 faulty