

P181B

Diagnosis information PDK control unit

Pressure sensor 2 - short circuit to B+, to ground or open circuit

Diagnostic conditions

- Engine running

Possible fault causes

- ♦ Open circuit
- ♦ Short circuit to B+
- ♦ Short circuit to ground
- ♦ Loose contact or corrosion on connectors or lines
- ♦ Pressure sensor 2 faulty

Fault setting condition(s)

- Measured pressure > threshold value for short circuit to B+ (21 bar)
- Measured pressure < threshold value for short circuit to ground or open circuit (0.35 bar)
- If the faults relating to the oil temperature, pressure sensor 1 or pressure sensor 2 are entered, then the sensor ground is missing

Fault effects

- ♦ Transmission limp-home display in the instrument cluster control unit
- ♦ Driving with gear train half 1 (only 1st, 3rd, 5th, 7th and R gears possible)
- ♦ Moving off in all gears
- ♦ No start/stop
- ♦ Torque limitation
- ♦ No emergency program diagnostics
- ♦ Deactivate all adaptations
- ♦ Clutch-overlap function is deactivated, i.e. one clutch is not closed until the other clutch is opened during the gear-changing process.

P181C

Diagnosis information PDK control unit

Pressure sensor 3 (controlled transverse-differential lock) - short circuit to ground or open circuit

Diagnostic conditions

- Ignition on

Possible fault causes

- ♦ Open circuit
- ♦ Short circuit to B+
- ♦ Short circuit to ground
- ♦ Loose contact or corrosion on connectors or lines
- ♦ Pressure sensor 3 faulty

Fault setting condition(s)

- Measured pressure > threshold value for short circuit to B+ (21 bar)
- Measured pressure < threshold value for short circuit to ground or open circuit (0.35 bar)

Fault effects

- ♦ Controlled transverse-differential lock is deactivated
- ♦ Low-side electrical pressure adjuster 7 is switched off

P1830

Diagnostic information - PDK control unit

Supply voltage, electric pressure adjuster 1 (clutch 1)

Diagnostic conditions

- Ignition on

Possible fault causes

- ♦ Open circuit
- ♦ Short circuit to ground
- ♦ Short circuit to B+
- ♦ Loose contact or corrosion on connectors or lines

Fault finding information

- If the fault is still statically present after all possible fault causes have been checked and cannot be deleted, the PDK control unit might be faulty and have to be replaced.

Fault setting condition(s)

- Currently measured voltage of hydraulic control system 1 < 0.05 V
- Hydraulic control system open, current voltage > 4 V

Fault effects

- ♦ Transmission limp-home display in instrument cluster control unit
- ♦ Driving with gear train half 2 (only 2nd, 4th, 6th gears possible)
- ♦ No R gear
- ♦ Hydraulic control system 1 is switched off
- ♦ Low-side electric pressure adjuster 1 is switched off
- ♦ Moving off in 2nd gear
- ♦ No start/stop
- ♦ Torque limitation
- ♦ No limp-home program diagnostics
- ♦ Clutch-overlap function is deactivated, i.e. one clutch is not closed until the other clutch is opened during the gear-changing process.
- ♦ If short circuit to B+, then all hydraulic control elements are switched off
- Breakdown

Control unit setpoints

- ♦ Supply voltage at terminal 30 $9.1 \text{ V} \Rightarrow 16.4 \text{ V}$
- ♦ Voltage at terminal 15 $9.5 \text{ V} \Rightarrow 16.0 \text{ V}$

P1831

Diagnostic information - PDK control unit

Supply voltage, electric pressure adjusters 2 and 3

Diagnostic conditions

- Ignition on

Possible fault causes

- ♦ Open circuit
- ♦ Short circuit to ground
- ♦ Short circuit to B+
- ♦ Loose contact or corrosion on connectors or lines

Fault finding information

- If the fault is still statically present after all possible fault causes have been checked and cannot be deleted, the PDK control unit might be faulty and have to be replaced.

Fault setting condition(s)

- Currently measured voltage of hydraulic control system 2 < 0.3 V
- Hydraulic control system open, current voltage > 4 V
- No measured current at electric pressure adjusters 2 and 3

Fault effects

- ♦ Transmission limp-home display in instrument cluster control unit
 - ♦ Driving with gear train half 1 (only 1st, 3rd, 5th, 7th and R gears possible)
 - ♦ Hydraulic control 2 is switched off
 - ♦ Low-side electric pressure adjuster 2 is switched off
 - ♦ Low-side electric pressure adjuster 3 is switched off
 - ♦ Moving off in 3rd gear
 - ♦ No start/stop
 - ♦ Torque limitation
 - ♦ No limp-home program diagnostics
 - ♦ The maximum cooling activation pressure is increased to prevent activation of the emergency stop function
 - ♦ Clutch-overlap function is deactivated, i.e. one clutch is not closed until the other clutch is opened during the gear-changing process.
 - ♦ If short circuit to B+, then all hydraulic control elements are switched off
- Breakdown

Control unit setpoints

- ♦ Supply voltage at terminal 30 $9.1\text{ V} \Rightarrow 16.4\text{ V}$
- ♦ Voltage at terminal 15 $9.5\text{ V} \Rightarrow 16.0\text{ V}$

Diagnostic information - PDK control unit

Supply voltage, electric pressure adjusters 4, 5, 6 and solenoid valves 1 and 2

Diagnostic conditions

- Ignition on

Possible fault causes

- ♦ Open circuit
- ♦ Short circuit to ground
- ♦ Short circuit to B+
- ♦ Loose contact or corrosion on connectors or lines

Fault finding information

- If the fault is still statically present after all possible fault causes have been checked and cannot be deleted, the PDK control unit might be faulty and have to be replaced.

Fault setting condition(s)

- Currently measured voltage of hydraulic control system 3 < 0.3 V
- Hydraulic control system open, current voltage > 4 V
- No measured current at electric pressure adjusters 4, 5 and 6

Fault effects

- ♦ Transmission limp-home display in instrument cluster control unit
- ♦ Hydraulic control 3 is switched off
- ♦ Low-side electric pressure adjuster 4 is switched off
- ♦ Low-side electric pressure adjuster 5 is switched off
- ♦ Low-side electric pressure adjuster 6 is switched off
- ♦ Low-side solenoid valve 1 is switched off
- ♦ Low-side solenoid valve 2 is switched off
- ♦ Gear held
- ♦ Moving off in all gears
- ♦ No R gear
- ♦ No start/stop
- ♦ Top speed limitation via engine intervention (lowest engaged gear)
- ♦ One-touch operation and Sport program are deactivated
- ♦ All adaptations are deactivated
- ♦ Pressure adjusters 5 and 6 are depressurized; multiplexer is changed over to the locked shift

rod

- ◆ The maximum system pressure is increased to prevent activation of the emergency stop function

- ◆ If short circuit to B+, then all hydraulic control elements are switched off

- ▶ Breakdown

Control unit setpoints

- ◆ Supply voltage at terminal 30 $9.1\text{ V} \Rightarrow 16.4\text{ V}$

- ◆ Voltage at terminal 15 $9.5\text{ V} \Rightarrow 16.0\text{ V}$

Diagnostic information - PDK control unit

Power supply for shiftlock or electric pressure adjuster 7

Diagnostic conditions

- Ignition on

Possible fault causes

- ♦ Open circuit
- ♦ Short circuit to ground
- ♦ Short circuit to B+
- ♦ Loose contact or corrosion on connectors or lines

Fault finding information

- If the fault is still statically present after all possible fault causes have been checked and cannot be deleted, the PDK control unit might be faulty and have to be replaced.

Fault setting condition(s)

- Currently measured voltage of hydraulic control system 4 < 0.3 V
- Hydraulic control system open, current voltage > 4 V

Fault effects

- ♦ Transmission limp-home display in instrument cluster control unit
- ♦ Hydraulic control 4 is switched off
- ♦ Low-side electric pressure adjuster 7 is switched off
- ♦ Shiftlock solenoid is switched off (no shiftlock function)
- ♦ The selector lever is locked in position P and can only be unlocked mechanically (emergency release)
- ♦ If short circuit to B+, then all hydraulic control elements are switched off
- Breakdown

Control unit setpoints

- ♦ Supply voltage at terminal 30 9.1 V $\Rightarrow$ 16.4 V
- ♦ Voltage at terminal 15 9.5 V $\Rightarrow$ 16.0 V

Diagnostic information - PDK control unit

Supply voltage, electric pressure adjuster 1 (clutch 1)

Diagnostic conditions

- Ignition on

Possible fault causes

- ♦ Open circuit
- ♦ Short circuit to ground
- ♦ Short circuit to B+
- ♦ Loose contact or corrosion on connectors or lines

Fault finding information

- If the fault is still statically present after all possible fault causes have been checked and cannot be deleted, the PDK control unit might be faulty and have to be replaced.

Fault setting condition(s)

- Currently measured voltage of hydraulic control system 1 < 0.05 V
- Hydraulic control system open, current voltage > 4 V

Fault effects

- ♦ Transmission limp-home display in instrument cluster control unit
- ♦ Driving with gear train half 2 (only 2nd, 4th, 6th gears possible)
- ♦ No R gear
- ♦ Hydraulic control system 1 is switched off
- ♦ Low-side electric pressure adjuster 1 is switched off
- ♦ Moving off in 2nd gear
- ♦ No start/stop
- ♦ Torque limitation
- ♦ No limp-home program diagnostics
- ♦ Clutch-overlap function is deactivated, i.e. one clutch is not closed until the other clutch is opened during the gear-changing process.
- ♦ If short circuit to B+, then all hydraulic control elements are switched off
- Breakdown

Control unit setpoints

- ♦ Supply voltage at terminal 30 $9.1 \text{ V} \Rightarrow 16.4 \text{ V}$
- ♦ Voltage at terminal 15 $9.5 \text{ V} \Rightarrow 16.0 \text{ V}$

Diagnostic information - PDK control unit

Supply voltage, electric pressure adjusters 2 and 3

Diagnostic conditions

- Ignition on

Possible fault causes

- ♦ Open circuit
- ♦ Short circuit to ground
- ♦ Short circuit to B+
- ♦ Loose contact or corrosion on connectors or lines

Fault finding information

- If the fault is still statically present after all possible fault causes have been checked and cannot be deleted, the PDK control unit might be faulty and have to be replaced.

Fault setting condition(s)

- Currently measured voltage of hydraulic control system 2 < 0.3 V
- Hydraulic control system open, current voltage > 4 V
- No measured current at electric pressure adjusters 2 and 3

Fault effects

- ♦ Transmission limp-home display in instrument cluster control unit
 - ♦ Driving with gear train half 1 (only 1st, 3rd, 5th, 7th and R gears possible)
 - ♦ Hydraulic control 2 is switched off
 - ♦ Low-side electric pressure adjuster 2 is switched off
 - ♦ Low-side electric pressure adjuster 3 is switched off
 - ♦ Moving off in 3rd gear
 - ♦ No start/stop
 - ♦ Torque limitation
 - ♦ No limp-home program diagnostics
 - ♦ The maximum cooling activation pressure is increased to prevent activation of the emergency stop function
 - ♦ Clutch-overlap function is deactivated, i.e. one clutch is not closed until the other clutch is opened during the gear-changing process.
 - ♦ If short circuit to B+, then all hydraulic control elements are switched off
- Breakdown

Control unit setpoints

- ♦ Supply voltage at terminal 30 $9.1\text{ V} \Rightarrow 16.4\text{ V}$
- ♦ Voltage at terminal 15 $9.5\text{ V} \Rightarrow 16.0\text{ V}$

P183A

Diagnostic information - PDK control unit

Supply voltage, electric pressure adjusters 4, 5, 6 and solenoid valves 1 and 2

Diagnostic conditions

- Ignition on

Possible fault causes

- ♦ Open circuit
- ♦ Short circuit to ground
- ♦ Short circuit to B+
- ♦ Loose contact or corrosion on connectors or lines

Fault finding information

- If the fault is still statically present after all possible fault causes have been checked and cannot be deleted, the PDK control unit might be faulty and have to be replaced.

Fault setting condition(s)

- Currently measured voltage of hydraulic control system 3 < 0.3 V
- Hydraulic control system open, current voltage > 4 V
- No measured current at electric pressure adjusters 4, 5 and 6

Fault effects

- ♦ Transmission limp-home display in instrument cluster control unit
- ♦ Hydraulic control 3 is switched off
- ♦ Low-side electric pressure adjuster 4 is switched off
- ♦ Low-side electric pressure adjuster 5 is switched off
- ♦ Low-side electric pressure adjuster 6 is switched off
- ♦ Low-side solenoid valve 1 is switched off
- ♦ Low-side solenoid valve 2 is switched off
- ♦ Gear held
- ♦ Moving off in all gears
- ♦ No R gear
- ♦ No start/stop
- ♦ Top speed limitation via engine intervention (lowest engaged gear)
- ♦ One-touch operation and Sport program are deactivated
- ♦ All adaptations are deactivated
- ♦ Pressure adjusters 5 and 6 are depressurized; multiplexer is changed over to the locked shift

rod

- ◆ The maximum system pressure is increased to prevent activation of the emergency stop function

- ◆ If short circuit to B+, then all hydraulic control elements are switched off

- ▶ Breakdown

Control unit setpoints

- ◆ Supply voltage at terminal 30 $9.1 \text{ V} \Rightarrow 16.4 \text{ V}$

- ◆ Voltage at terminal 15 $9.5 \text{ V} \Rightarrow 16.0 \text{ V}$

P183B

Diagnostic information - PDK control unit

Power supply for shiftlock or electric pressure adjuster 7

Diagnostic conditions

- Ignition on

Possible fault causes

- ♦ Open circuit
- ♦ Short circuit to ground
- ♦ Short circuit to B+
- ♦ Loose contact or corrosion on connectors or lines

Fault finding information

- If the fault is still statically present after all possible fault causes have been checked and cannot be deleted, the PDK control unit might be faulty and have to be replaced.

Fault setting condition(s)

- Currently measured voltage of hydraulic control system 4 < 0.3 V
- Hydraulic control system open, current voltage > 4 V

Fault effects

- ♦ Transmission limp-home display in instrument cluster control unit
 - ♦ Hydraulic control 4 is switched off
 - ♦ Low-side electric pressure adjuster 7 is switched off
 - ♦ Shiftlock solenoid is switched off (no shiftlock function)
 - ♦ The selector lever is locked in position P and can only be unlocked mechanically (emergency release)
 - ♦ If short circuit to B+, then all hydraulic control elements are switched off
- Breakdown

Control unit setpoints

- ♦ Supply voltage at terminal 30 9.1 V $\Rightarrow$ 16.4 V
- ♦ Voltage at terminal 15 9.5 V $\Rightarrow$ 16.0 V

P1840

Diagnostic information - PDK control unit

Supply voltage, electric pressure adjuster 1 (clutch 1)

Diagnostic conditions

- Ignition on

Possible fault causes

- ♦ Open circuit
- ♦ Short circuit to ground
- ♦ Short circuit to B+
- ♦ Loose contact or corrosion on connectors or lines

Fault finding information

- If the fault is still statically present after all possible fault causes have been checked and cannot be deleted, the PDK control unit might be faulty and have to be replaced.

Fault setting condition(s)

- Currently measured voltage of hydraulic control system 1 < 0.05 V
- Hydraulic control system open, current voltage > 4 V

Fault effects

- ♦ Transmission limp-home display in instrument cluster control unit
- ♦ Driving with gear train half 2 (only 2nd, 4th, 6th gears possible)
- ♦ No R gear
- ♦ Hydraulic control system 1 is switched off
- ♦ Low-side electric pressure adjuster 1 is switched off
- ♦ Moving off in 2nd gear
- ♦ No start/stop
- ♦ Torque limitation
- ♦ No limp-home program diagnostics
- ♦ Clutch-overlap function is deactivated, i.e. one clutch is not closed until the other clutch is opened during the gear-changing process.
- ♦ If short circuit to B+, then all hydraulic control elements are switched off
- Breakdown

Control unit setpoints

- ♦ Supply voltage at terminal 30 $9.1 \text{ V} \Rightarrow 16.4 \text{ V}$
- ♦ Voltage at terminal 15 $9.5 \text{ V} \Rightarrow 16.0 \text{ V}$

Diagnostic information - PDK control unit

Supply voltage, electric pressure adjusters 2 and 3

Diagnostic conditions

- Ignition on

Possible fault causes

- ♦ Open circuit
- ♦ Short circuit to ground
- ♦ Short circuit to B+
- ♦ Loose contact or corrosion on connectors or lines

Fault finding information

- If the fault is still statically present after all possible fault causes have been checked and cannot be deleted, the PDK control unit might be faulty and have to be replaced.

Fault setting condition(s)

- Currently measured voltage of hydraulic control system 2 < 0.3 V
- Hydraulic control system open, current voltage > 4 V
- No measured current at electric pressure adjusters 2 and 3

Fault effects

- ♦ Transmission limp-home display in instrument cluster control unit
 - ♦ Driving with gear train half 1 (only 1st, 3rd, 5th, 7th and R gears possible)
 - ♦ Hydraulic control 2 is switched off
 - ♦ Low-side electric pressure adjuster 2 is switched off
 - ♦ Low-side electric pressure adjuster 3 is switched off
 - ♦ Moving off in 3rd gear
 - ♦ No start/stop
 - ♦ Torque limitation
 - ♦ No limp-home program diagnostics
 - ♦ The maximum cooling activation pressure is increased to prevent activation of the emergency stop function
 - ♦ Clutch-overlap function is deactivated, i.e. one clutch is not closed until the other clutch is opened during the gear-changing process.
 - ♦ If short circuit to B+, then all hydraulic control elements are switched off
- Breakdown

Control unit setpoints

- ♦ Supply voltage at terminal 30 $9.1\text{ V} \Rightarrow 16.4\text{ V}$
- ♦ Voltage at terminal 15 $9.5\text{ V} \Rightarrow 16.0\text{ V}$

Diagnostic information - PDK control unit

Supply voltage, electric pressure adjusters 4, 5, 6 and solenoid valves 1 and 2

Diagnostic conditions

- Ignition on

Possible fault causes

- ♦ Open circuit
- ♦ Short circuit to ground
- ♦ Short circuit to B+
- ♦ Loose contact or corrosion on connectors or lines

Fault finding information

- If the fault is still statically present after all possible fault causes have been checked and cannot be deleted, the PDK control unit might be faulty and have to be replaced.

Fault setting condition(s)

- Currently measured voltage of hydraulic control system 3 < 0.3 V
- Hydraulic control system open, current voltage > 4 V
- No measured current at electric pressure adjusters 4, 5 and 6

Fault effects

- ♦ Transmission limp-home display in instrument cluster control unit
- ♦ Hydraulic control 3 is switched off
- ♦ Low-side electric pressure adjuster 4 is switched off
- ♦ Low-side electric pressure adjuster 5 is switched off
- ♦ Low-side electric pressure adjuster 6 is switched off
- ♦ Low-side solenoid valve 1 is switched off
- ♦ Low-side solenoid valve 2 is switched off
- ♦ Gear held
- ♦ Moving off in all gears
- ♦ No R gear
- ♦ No start/stop
- ♦ Top speed limitation via engine intervention (lowest engaged gear)
- ♦ One-touch operation and Sport program are deactivated
- ♦ All adaptations are deactivated
- ♦ Pressure adjusters 5 and 6 are depressurized; multiplexer is changed over to the locked shift

rod

- ◆ The maximum system pressure is increased to prevent activation of the emergency stop function

- ◆ If short circuit to B+, then all hydraulic control elements are switched off

- ▶ Breakdown

Control unit setpoints

- ◆ Supply voltage at terminal 30 $9.1\text{ V} \Rightarrow 16.4\text{ V}$

- ◆ Voltage at terminal 15 $9.5\text{ V} \Rightarrow 16.0\text{ V}$

P186F

Diagnosis information PDK control unit

Data record invalid

Diagnostic conditions

- Ignition on

Possible fault causes

- ♦ Incorrect or faulty data version
- ♦ PDK control unit faulty

Fault setting condition(s)

- Internal diagnostic routine is faulty

Fault effects

- ♦ Transmission fault display in the instrument cluster control unit
- ♦ Emergency stop function

P1870

Diagnosis information PDK control unit

Data record for calibration of the shift rods is not valid

Diagnostic conditions

- Ignition on

Possible fault causes

- ♦ Incorrect or missing basic values
- ♦ Wrong or faulty data record

Fault effects

- ♦ Transmission fault display in the instrument cluster control unit
- ♦ None

P1871

Diagnosis information PDK control unit

Data record for calibration of the clutches is not valid

Diagnostic conditions

- Ignition on

Possible fault causes

- ♦ Incorrect or missing basic values
- ♦ Wrong or faulty data record

Fault effects

- ♦ Transmission fault display in the instrument cluster control unit
- ♦ None

P1872

Diagnosis information PDK control unit

Calibration

Diagnostic conditions

- Engine running

Possible fault causes

- ♦ Incorrect or missing basic values
- ♦ Wrong or faulty data record

Fault effects

- ♦ Transmission fault display in the instrument cluster control unit
- ♦ None

Fault finding notes

- ♦ The fault cannot be deleted from the memory until it has been reported as OK (inactive)

P1875

Diagnosis information PDK control unit

Tire circumference implausible

Diagnostic conditions

- Driving in all gears

Fault setting condition(s)

- Recognized tire diameter is outside the permissible range

Fault effects

- ♦ None

P1897

Diagnosis information PDK control unit

PDK control unit - internal fault

Diagnostic conditions

- Ignition on

Possible fault causes

- ♦ PDK control unit faulty

Fault setting condition(s)

- Internal diagnostic routine returns fault

Fault effects

- ♦ Transmission fault display in the instrument cluster control unit
- ♦ Emergency stop function

P189A

Diagnosis information PDK control unit

PDK control unit - internal fault

Diagnostic conditions

- Ignition on

Possible fault causes

- ♦ PDK control unit faulty

Fault setting condition(s)

- Internal diagnostic routine returns fault

Fault effects

- ♦ Transmission fault display in the instrument cluster control unit
- ♦ Emergency stop function

P189C

Diagnosis information PDK control unit

PDK control unit - internal fault

Diagnostic conditions

- Ignition on

Possible fault causes

- ♦ PDK control unit faulty

Fault setting condition(s)

- Internal diagnostic routine returns fault

Fault effects

- ♦ Transmission fault display in the instrument cluster control unit
- ♦ Emergency stop function

P189D

Diagnosis information PDK control unit

PDK control unit - internal fault

Diagnostic conditions

- Ignition on

Possible fault causes

- ♦ PDK control unit faulty

Fault setting condition(s)

- Internal diagnostic routine returns fault

Fault effects

- ♦ Transmission fault display in the instrument cluster control unit
- ♦ Emergency stop function

P18A5

Diagnosis information PDK control unit

Redundant selector lever position information implausible

Diagnostic conditions

- Ignition on

Possible fault causes

- ♦ Selector lever control unit faulty

Fault setting condition(s)

- Value for the position of the selector lever not valid

Fault effects

- ♦ None

P18B0

Diagnosis information PDK control unit

Software monitoring: Reset was triggered by operating system, application software monitoring A/B

Diagnostic conditions

- Ignition on

Possible fault causes

- ♦ Undervoltage at engine start
- ♦ PDK control unit faulty

Fault setting condition(s)

- Internal diagnostic routine returns fault

Fault effects

- ♦ Transmission fault display in the instrument cluster control unit
- ♦ No power transmission at a reference speed < 5 km/h (3 mph) and valid engaged transmission range

Fault finding notes

- ♦ Erase fault memory and carry out a test drive
- ♦ If the fault recurs, check the PDK control unit power supply
- ♦ If the power supply is OK, replace the PDK control unit

P18B4

Diagnosis information PDK control unit

Software monitoring: Reset was triggered by operating system, application software monitoring A/B

Diagnostic conditions

- Ignition on

Possible fault causes

- ♦ Undervoltage at engine start
- ♦ PDK control unit faulty

Fault setting condition(s)

- Internal diagnostic routine returns fault

Fault effects

- ♦ Transmission fault display in the instrument cluster control unit
- ♦ No power transmission at a reference speed < 5 km/h (3 mph) and valid engaged transmission range

Fault finding notes

- ♦ Erase fault memory and carry out a test drive
- ♦ If the fault recurs, check the PDK control unit power supply
- ♦ If the power supply is OK, replace the PDK control unit

P18B5

Diagnosis information PDK control unit

Software monitoring: Reset was triggered by operating system, application software monitoring A/B

Diagnostic conditions

- Ignition on

Possible fault causes

- ♦ Undervoltage at engine start
- ♦ PDK control unit faulty

Fault setting condition(s)

- Internal diagnostic routine returns fault

Fault effects

- ♦ Transmission fault display in the instrument cluster control unit
- ♦ No power transmission at a reference speed < 5 km/h (3 mph) and valid engaged transmission range

Fault finding notes

- ♦ Erase fault memory and carry out a test drive
- ♦ If the fault recurs, check the PDK control unit power supply
- ♦ If the power supply is OK, replace the PDK control unit

P18C0

Diagnosis information PDK control unit

Transverse-diff. lock lining monitoring

Diagnostic conditions

- Driving in all gears

Possible fault causes

- ♦ Lining of the transverse-differential lock is worn out

Fault setting condition(s)

- Activation of the transverse-differential lock during driving
- No change in the differential speed during lining monitoring

Fault effects

- ♦ Controlled transverse-differential lock deactivated
- ♦ Switch off low-side electric pressure adjuster 7

Diagnosis information PDK control unit

Setpoint torque of PTM implausible

Diagnostic conditions

- Driving in all gears

Possible fault causes

- ♦ Setpoint torque of PTM implausible
- ♦ PTM system (all-wheel-drive control) malfunctioning

Fault setting condition(s)

- Maximum torque when PSM is on: When the PSM is activated, a plausibility check is performed compared to the maximum torque supplied by the PSM
- Maximum torque when PSM is off: When the PSM is deactivated, a plausibility check is performed compared to a maximum value depending on the steering-wheel angle and lateral acceleration.

Fault effects

- ♦ Controlled transverse-differential lock deactivated
- ♦ Switch off low-side electric pressure adjuster 7

P18C6

Diagnosis information PDK control unit

Wrong software allocation (transverse-differential lock)

Diagnostic conditions

- Ignition on

Possible fault causes

- ♦ Vehicle equipment/vehicle order wrong (I number)
- ♦ Incorrect software version
- ♦ Incorrect coding

Fault setting condition(s)

- Software version does not match vehicles with transverse-differential lock

Fault effects

- ♦ None